

Not Notified  
 1-1-2019  
 Resurvey After Paint  
 3  
 4 days



**ESTIMATE TO REPAIR**

VEHICLE NO. : SKS 8017 U  
 MAKE : B.M.W.  
 MODEL : ACTIVEHYBRID 3 AT DSC 4DR SR NAV HUD  
 YEAR : 2012  
 CHASSIS NO : WBA3F92040F203416

SURVEYOR NAME :	
DATE OF SURVEY :	20 FEB 2019
TIME OF SURVEY :	

DATE : 14-Feb-19  
 DATE OF ACCIDENT : 10-Feb-19  
 THIRD PARTY REF : SKX 693 T / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			R	\$ 1,027.25
1 pc	O/S Front Bumper Retainer			D	\$ 19.25
1 pc	O/S Front Bumper Spray Nozzle Cover			D	\$ 43.25
1 pc	Front Bumper Reinforcement			R	\$ 378.10
1 pc	O/S Front Bumper Fog Lamp			S	\$ 292.80
1 pc	O/S Front Bumper Fog Lamp Cover				\$ 69.90
1/2 pcs	Front Bumper Sensor		\$ 368.80	M	\$ 737.60
1 pc	Front Bumper O/S Camera				\$ 681.10
1 pc	O/S Headlamp			M	\$ 2,501.25
1 pc	O/S Headlamp Lower Bracket				\$ 55.30
1 pc	O/S Headlamp Top Bracket				\$ 15.10
1 pc	O/S Headlamp Nozzle				\$ 159.85
1 pc	Front Emblem			M	\$ 71.25
1 pc	O/S Front Fender Emblem			M	\$ 46.30
					\$ 6,098.30
	To putty and spray painting			400	\$ 500.00
	To check front wiring and focus headlights			20	\$ 30.00
	Labour Charges			280	\$ 450.00
TG/RA-	<b>Total</b>				<b>\$ 7,078.30</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: