

Kh
Not Notified
1-2-19
Putty Spray Paint
3 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKS 8017 U
 MAKE : B.M.W.
 MODEL : ACTIVEHYBRID 3 AT DSC 4DR SR NAV HUD
 YEAR : 2012
 CHASSIS NO : WBA3F92040F203416

SURVEYOR NAME :	
DATE OF SURVEY :	20 FEB 2019
TIME OF SURVEY :	

DATE : 14-Feb-19
 DATE OF ACCIDENT : 10-Feb-19
 THIRD PARTY REF : SKX 693 T / AXA

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			R1	\$ 1,027.25
1 pc	O/S Front Bumper Retainer				\$ 19.25
1 pc	O/S Front Bumper Spray Nozzle Cover				\$ 43.25
1 pc	Front Bumper Reinforcement				\$ 378.10
1 pc	O/S Front Bumper Fog Lamp				\$ 292.00
1 pc	O/S Front Bumper Fog Lamp Cover				\$ 69.90
1/2 pcs	Front Bumper Sensor		\$ 368.80		\$ 737.60
1 pc	Front Bumper O/S Camera				\$ 681.10
1 pc	O/S Headlamp				\$ 2,501.25
1 pc	O/S Headlamp Lower Bracket				\$ 55.30
1 pc	O/S Headlamp Top Bracket				\$ 15.10
1 pc	O/S Headlamp Nozzle				\$ 159.85
1 pc	Front Emblem				\$ 71.25
1 pc	O/S Front Fender Emblem				\$ 46.30
					\$ 6,098.30
	To putty and spray painting				\$ 500.00
	To check front wiring and focus headlights				\$ 30.00
	Labour Charges				\$ 450.00
	Parts \$4322.20				
	Labour \$700.00				
	PBP \$502.20				
	03 days				
TG/RA-	Total				\$ 7,078.30

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd