

135210

INS. CASE OWNER:

CC 4/1 EQ/1900 2876, 49679 LKK: IDAC:

Surveyor:

MAVUS

ASSIGNMENT DOI: 18/2/19

Date / Time: 15/2/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No: GBD 3332C Claim No: _____
 Name of Insured: CONNECT ELECTRICAL EQUIPMENT Policy No: _____
 Insured Tel No: _____ HP: _____ Make / Model: VIKREW
 Excess Sec II :SS D.O.A: 13/2/19 Place of Accident: VE
 Is driver the owner? (YES / NO) Nature of Accident: _____
 IF NO, Driver Name / Age: MARYSEWAN OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Driver Tel No: _____ (V/L: YES / NO) Insured Liability: % Final ? Yes / No

GV 78116



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date / Time	STAGE	DATE / PIC
18/2/19	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
15/2/19	Notification ltr (if non-pickup):	
16/2/19	Call OE:	
17/2/19	After call ltr to OE:	
18/2/19	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OE	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input checked="" type="checkbox"/>
	Post-Repair Photos:	<input checked="" type="checkbox"/>
	Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: MAVUS

Repair Cost: 45 \$5 9150.00 (12 days) Reduction \$11,918.10 % 57. Email Call

FINAL SETTLEMENT Date/Time: 16/10/19 Confirm with: _____ Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 28

Repair Cost: (W/RT) \$5 9790.50

Loss of Rental (LOR): \$5 _____ (_____ days)

Loss of Use (LOU): \$5 460.00 (1869 x 10 days) 60x16 = 960

Loss of Income (LOI): \$5 _____ (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 _____

Disbursement: \$5 _____ (e.g Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

18/10/19

one

2/19

6/19

EQ/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GV 78116
 at Workshop m/s Spurf.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GV 78116 Yr Regn: 10102
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Car
 Make: Toyota Hyundai c.c 2184
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 719244 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: CR 425003698
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 185-1213

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 24
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 13/2/19 D.O.I. 15/2/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear & H.P.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>LTA 12698 31-8-2022 3yrs. 6mths. Dep 76.</u>
	<u>nett 11302</u>

US 491501 - (Red = \$11,918.10 / 57-1.)

* 17 repair days + 2 Sundays + 3 PRS = 17 days.

Date/Time, File Pass to? : Prel. Report
 : Final Report

Days Of Repair: _____

1) Date/Time, File Return to?
 2) _____

Resurvey No. of Trip: _____

Report Format : _____
 Lump Sum / I.B.I: (\$ _____)

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE, 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/EQ119002876/Ujb3

Date: 18.02.2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

GV7811G

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.02.2019 at the premises of M/s Specialists Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	21,068.10
Revised Estimate Amount	: S\$	7,661.05
"Check" Items Amount	: S\$	6,452.03
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 12 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$ 5,255.00
20	Radiator assy	1	1,841.60	\$ 1,841.60 ?
21	Radiator cowling	1	184.70	\$ 184.70 ?
22	Radiator fan motor	1	492.10	\$ 492.10 ?
23	Radiator fan blade	1	179.40	\$ 179.40 ?
24	Horn	1	94.20	\$ 94.20 ?
25	Rear boot cover	1	939.70	\$ 939.70 —
26	Rear boot lock	1	220.40	\$ 220.40 —
27	Rear boot weather strip	1	369.60	\$ 369.60 ?
28	Rear windscreen moulding	1	79.40	\$ 79.40 —
29	Rear end panel	1	416.70	\$ 416.70 —
30	Rear spare tyre bracket	1	217.20	\$ 217.20 ?
31	Rear floor panel	1	1,286.70	\$ 1,286.70 ?
32	Rear bumper fascia	1	371.60	\$ 371.60 —
33	Rear bumper bracket L&R	2	18.90	\$ 37.80 —
34	Rear wooden floor wood(s/nett)	1	1,586.00	\$ 1,586.00 ?
35	Front number plate (s/nett)	1set	50.00	\$ 50.00 20
36	Rear boot sticker (70km/h) (s/nett)	1	18.00	\$ 18.00 10
37	Rear boot sticker (6pax) (s/nett)	1	18.00	\$ 18.00 10
38	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00 40
39	Rear end panel sealer (s/nett)	1	80.00	\$ 80.00 40
				\$ 13,798.10

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

Balance b/f	\$ 13,798.10
<u>Labour Charges :-</u>	<u>Amounts</u>
Towing fee	\$ 180.00 60
Cut out, renew, knocking & welding front fender L&R, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body	\$ 1,280.00 800
Remove & install front radiator assy, engine cooling system & conduct pressure test ^{rebill a.r. 100005} 121	\$ 120.00 100
Tuff-kote on front damage parts	\$ 160.00 100
Spray painting on front damage parts	\$ 1,580.00 800
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install all damage parts, straighten & re-align body	\$ 1,880.00 1100
Tuff-kote on rear damage parts	\$ 120.00 80
Spray painting on rear damage parts	\$ 1,680.00 1000
Remove & refix rear bumper sensor	\$ 80.00 50
Remove & refix rear windscreen glass	\$ 140.00 120
Check all lighting after repairs	\$ 50.00 30
Labour Charge	\$ 7,270.00
Total Amount	\$ 21,068.10

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1919Z
Vehicle Details	
Vehicle No.:	GV7811G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5 DR
Primary Colour:	Silver
Manufacturing Year:	2002
Engine No.:	3C3962555
Chassis No.:	CR425003698
Maximum Power Output:	-
Open Market Value:	\$18,697.00
Original Registration Date:	31 Oct 2002
First Registration Date:	31 Oct 2002
Transfer Count:	1
Actual ARF Paid:	\$935.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$17,920.00
COE Rebate Amount:	\$12,698.00
Total Rebate Amount:	\$12,698.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 15 Feb 2019

OK



DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT www.scamalert.sg



liteace

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » Net Link Partners Pte Ltd » Toyota Liteace (COE till 08/2022)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Toyota Liteace (COE till 08/2022)

Overview Financial Accessories Similar Research Photos Map

NETLINK *Your Commercial S,*

Specialized in New & Used Commercial Vehicles. Insurance. Hire Purchase. Sc

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$24,800	?
Depreciation	\$7,010 /yr	?
Reg Date	30-Aug-2007 (3yrs 6mths 14days COE left)	
Lifespan	29-Aug-2027	
Manufactured	2007	?
Mileage	-	
Transmission	Auto	
Engine Cap	1,781 cc	
Curb Weight	1,260 kg	?
Fuel type	Petrol	
Features	-	
Accessories	-	
Description	5 Door Auto Van. Looking For Something Affordable And Reliable?. Call Us Now For Viewing.	
COE	\$17,920	?
OMV	\$19,733	?
ARF	\$987	?
Dereg Value	\$12,677 as of today (change)	?
No. of Owners	6	?
Type of Veh	Van	
Category	COE Car, Premium Ad Car	
Availability	Available	



Seller Information

Company	Net Li » deale » 114 v
Address	71 Woc #07-01 Search
Location	Wave9
Office No	675316

PREMIUM AD

Compare

Add to Shortlist

Add to Compare

Add a Note

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME


 CLICK HERE OR CALL
64

liteace

Price Range

Depreciation

> 10 year(s)

Vehicle Type



Home » Used Cars » William's Auto » Toyota Liteace (COE till 03/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Vehicle Number Plates

BUY & SELL
 Your AUSPICIOUS
 & UNIQUE Vehicle No.

Do you know? We are Singapore's
BIGGEST PLAYER
 with the most vehicle plate numbers for sale?

(Click here to see all Auspicious Numbers!)

Toyota Liteace (COE till 03/2022)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price	\$28,800	
Depreciation	\$9,220 /yr	?
Reg Date	08-Aug-2002 (3yrs 1mth 16days COE left)	
Lifespan	07-Aug-2022	
Manufactured	2002	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,184 cc	
Curb Weight	1,260 kg	?
Fuel type	Diesel	
Features	-	
Accessories	CD Player, Reverse Sensors.	
COE	\$24,394	?
OMV	\$18,082	?
ARF	\$905	?
Dereg Value	\$15,238 as of today (change)	?
No. of Owners	1	?
Type of Veh	Van	
Category	COE Car	
Availability	Available	

Add to Shortlist

Add to Compare

Add a Note

Posted on: 07-Feb-2019 | Last Updated on: 07-Feb-2019

 Tags: Toyota Townace, Toyota Liteace, toyota liteace, 2002 Toyota Liteace, 2002
 toyota liteace, Toyota, Liteace, liteace, Used Toyota

Upfront Payment

» more Financial info

Transfer Fee

\$25



Compare



Seller Information

Company	William's Auto » dealer » 6 veh
Address	61 Ubi Search
Location	Automotive
Office No	674361
Contact Person(s)	Mr Png

Useful Services

 Afraid of learning
 this car evaluation

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Date of Accident : 13th February 2019
Location : PIE towards Bradell Road

Third Party Claim Vehicle No : **GBD 3332 C**
Repair Cost For Vehicle No : **GV 7811 G Toyota Liteace**

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Bonnet <i>3pc</i>	1	509.80	\$ 509.80
2	Bonnet hinge L&RH <i>set</i>	2	45.20	\$ 90.40
3	Bonnet lock assy <i>tw</i>	1	79.90	\$ 79.90
4	Bonnet rubber <i>tw</i>	1	51.10	\$ 51.10
5	Front support panel <i>tw</i>	1	702.90	\$ 702.90
6	Front bridge panel <i>tw</i>	1	77.80	\$ 77.80
7	Front grille <i>one</i>	1	209.60	\$ 209.60
8	Headlamp assy L&R <i>2pc</i>	2	111.90	\$ 223.80
9	Headlamp cover L&R <i>one</i>	2	111.80	\$ 223.60
10	Headlamp lower bracket L&R <i>11</i>	2	16.90	\$ 33.80
11	Front side lamp L&R <i>11</i>	2	184.80	\$ 369.60
12	Front bumper fascia <i>D.J</i>	1	382.70	\$ 382.70
13	Front bumper clips <i>one</i>	1set	38.00	\$ 38.00
14	Front bumper reinforcement <i>set</i>	1	317.70	\$ 317.70
15	Front bumper bracket L&R <i>set</i>	2	95.10	\$ 190.20
16	Front bumper fog lamp cover L&R <i>11</i>	2	126.90	\$ 253.80
17	Air-con condenser <i>set/one</i>	1	1,216.10	\$ 1,216.10
18	Air-con pipe(condenser to cooling) <i>11</i>	1	369.70	\$ 369.70
19	Air-con pipe (compressor to cooling) <i>11</i>	1	424.30	\$ 424.30
				\$ 5,255.00

*Not Authorised
various other
15/2/19
1/5 \$ 9150
this job. Attempt
12 day.*

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 5,255.00
20	Radiator assy <i>and/pur</i>	1	1,841.60	\$ 1,841.60 <i>2</i>
21	Radiator cowling <i>one</i>	1	184.70	\$ 184.70 <i>2</i>
22	Radiator fan motor <i>jam</i>	1	492.10	\$ 492.10 <i>2</i>
23	Radiator fan blade <i>st</i>	1	179.40	\$ 179.40 <i>2x</i>
24	Horn <i>11</i>	1	94.20	\$ 94.20 <i>2x</i>
25	Rear boot cover <i>body</i>	1	939.70	\$ 939.70 <i>1</i>
26	Rear boot lock <i>twi/jam</i>	1	220.40	\$ 220.40 <i>1</i>
27	Rear boot weather strip <i>twi</i>	1	369.60	\$ 369.60 <i>1</i>
28	Rear windscreen moulding <i>nee</i>	1	79.40	\$ 79.40 <i>1</i>
29	Rear end panel <i>body</i>	1	416.70	\$ 416.70 <i>1</i>
30	Rear spare tyre bracket <i>2</i>	1	217.20	\$ 217.20 <i>2x</i>
31	Rear floor panel <i>2</i>	1	1,286.70	\$ 1,286.70 <i>2x</i>
32	Rear bumper fascia <i>DIS</i>	1	371.60	\$ 371.60 <i>1</i>
33	Rear bumper bracket L&R <i>st</i>	2	18.90	\$ 37.80 <i>1</i>
34	Rear wooden floor wood(s/nett) <i>11</i>	1	1,586.00	\$ 1,586.00 <i>2</i>
35	Front number plate (s/nett) <i>benf</i>	1set	50.00	\$ 50.00 <i>20</i>
36	Rear boot sticker (70km/h) (s/nett) <i>nee</i>	1	18.00	\$ 18.00 <i>10</i>
37	Rear boot sticker (6pax) (s/nett) <i>nee</i>	1	18.00	\$ 18.00 <i>10</i>
38	Rear windscreen sealant (s/nett) <i>nee</i>	1	60.00	\$ 60.00 <i>40</i>
39	Rear end panel sealer (s/nett) <i>nee</i>	1	80.00	\$ 80.00 <i>50</i>
				\$ 13,798.10

9446.0
 25%

 7085.18
 4370

 11455.18
 9164.14

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

Balance b/f	\$ 13,798.10	
<u>Labour Charges :-</u>	<u>Amounts</u>	
Towing fee	\$ 180.00	60
Cut out, renew, knocking & welding front fender L&R, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body	\$ 1,280.00	800
Remove & install front radiator assy, engine cooling system & conduct pressure test ^{refill & change}	\$ 120.00	100
Tuff-kote on front damage parts	\$ 160.00	100
Spray painting on front damage parts	\$ 1,580.00	800
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install all damage parts, straighten & re-align body	\$ 1,880.00	1100
Tuff-kote on rear damage parts	\$ 120.00	80
Spray painting on rear damage parts	\$ 1,680.00	1000
Remove & refix rear bumper sensor	\$ 80.00	50
Remove & refix rear windscreen glass	\$ 140.00	120
Check all lighting after repairs	\$ 50.00	30
Labour Charge	\$ 7,270.00	
Total Amount	\$ 21,068.10	4370

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

Nitha (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Friday, 15 February 2019 11:57 AM
To: assignments
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD
Attachments: GV 7811 G.PDF; GV 7811 G-gia report.pdf; IMG_0103.jpg; IMG_0105.jpg; IMG_0123.jpg; IMG_0126.jpg; SAS2552584.pdf

12.46pm @ 15/2/19
vehicle in
Hui Lin
MR@Marus

Dear all,

Please arrange to attend to the PRS as SJE.

Liability is cleared, proceed to direct settle if possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify t

From: SPECIALISTS MOTOR PTE LTD [mailto:cardoc@singnet.com.sg]
Sent: Friday, February 15, 2019 11:53 AM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: RE: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD

Dear Janet,

We choose **LKK Auto Consultants Pte Ltd.**

Kindly arrange the surveyor to survey the vehicle No. GV 7811 G on 15th February 2019 (Friday) at
Specialists Motor Pte Ltd
Blk 3018A, Ubi Road 1
#01-24/25/26
Singapore 408711

Thanks & Regards
Hui Lin

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]
Sent: Friday, 15 February, 2019 11:38 AM
To: SPECIALISTS MOTOR PTE LTD
Subject: RE: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD

Without Prejudice
Save As To Costs

Dear Sir/Madam,

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

Liability is cleared. We can agree on direct settlement.

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068	10) Appraisals Associates Pte Ltd Tel : 67472822

Fax: 63445328	Fax: 67470070
11) Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
 5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: SPECIALISTS MOTOR PTE LTD [<mailto:cardoc@singnet.com.sg>]
Sent: Friday, February 15, 2019 11:35 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD

To whom it may concern,

Please refer to the above matter.

Attached Estimate, GIA report & Damage photo for your perusal.

Our client (GV 7811 G) is claiming against your insured (GBD 3332 C).

Please check for us the above claim liability & OIC as soon as possible.

Kindly arrange the surveyor to survey the vehicle No. GV 7811 G on 15th February 2019 (Friday) at
 Specialists Motor Pte Ltd
 Blk 3018A, Ubi Road 1
 #01-24/25/26
 Singapore 408711



Thanks & Regards
Hui Lin
Specialists Motor Pte Ltd
6747 2112

Cecilia Chong (LKK Auto)

From: Specialists Motor Pte Ltd <cardoc@singnet.com.sg>
Sent: Wednesday, 16 October 2019 10:37 AM
To: Cecilia Chong (LKK Auto)
Subject: RE: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD

Without Prejudice

Dear Cecilia Chong

Please refer to the above matter.

Your offer to settle the above claim had been accepted.

Kindly let us have your DV or payment as soon as possible.

Thanks & Regards
Irene Ting
6747 2112

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Tuesday, 15 October, 2019 3:00 PM
To: SPECIALISTS MOTOR PTE LTD
Subject: RE: ACCIDENT INVOLVING GV 7811 G AND GBD 3332 C ON 13TH FEB 2019 AT PIE TOWARDS BRADELL ROAD

WITHOUT PREJUDICE

Dear Hui Lin,

We are pleased to offer total amount of \$10,758.50 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

08th March 2019

WITHOUT PREJUDICE

The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

**RE: ACCIDENT INVOLVING VEHICLES GV 7811 G AND GBD 3332 C ON 13TH
FEBRUARY 2019 AT 1550 HRS AT PIE TOWARDS BRADELL ROAD**

Dear Sirs,

We refer to the above matter.

Our Client Mopi Pte Ltd the registered owner of GV 7811 G.

You are the insurer of motor vehicle no. GBD 3332 C, which was involved in the above accident. Please be informed that the collision was caused by the negligent owner/driver of the motor vehicle no. GBD 3332 C, in consequence of which our client has suffered damages and consequential loss.

Attached a few documents for your reference:

- a) A Lump-sum repair bill
- b) GIA report & LTA search
- c) An authorisation letter from the owner (GV 7811 G)

We are claiming as follows: -

LTA search fee	S\$ 8.00
A Lump-sum repair bill	S\$ 9,790.50
Loss of use (21 Days)	S\$ 2,100.00

	S\$ 11,898.50


Dollar: Eleven Thousand Eight Hundred Ninety Eight And Cents Fifty Only.

Kindly let us know whether you are prepare to settle the claim within the next ten (10) days from the date herewith .

Please remit the cheque in favour to "Specialists Motor Pte Ltd" as soon as possible.

Thank you,

Yours faithfully,


Karen Ong



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: **CC4/EQ19002876/Ugb3**

16 AUGUST 2019

CONNECT ELECTRICAL ENGINEERING PTE LTD
2304 BEDOK RERSERVOIR ROAD
#01-01
SINGAPORE 479223

Dear Sir/Madam,

ACCIDENT INVOLVING GBD 3332C / GV 7811G / OTHERS ON 13/02/2019

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Your full co-operation in the handling of the claim is required and kindly submit the following to ceciliachong@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Driver's Work Permit
- Employment Letter/ Authorisation letter from your company
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

Please call us if you have further queries.

Yours faithfully,



Cecilia Chong
Case Handler
DID: 6749 4274
FAX: 6741 4108
EMAIL: Ceciliachong@lkkauto.com

*c.c. EQ INSURANCE COMPANY LIMITED
(Motor Claims Dept)*

ACCIDENT INVOLVING VEHICLE
EV 7811 G AND GBD 3332 C ON 13TH FEBRUARY 2019 AT 1550HRS
AT PIE TOWARDS BRADELL ROAD

Letter Of Authority And Undertaking

I/We MOD2 PTE LTD (NRIC NO) 197801919Z of
223 Ubi Ave 4 (Intrepid Warehouse Complex) Singapore 408813

the owner/driver of Vehicle No. EV 7811 G hereby authorise your
esteem company Specialists Motor Pte Ltd


as my repairer for my Damaged Vehicle involved in the above accident and to
claim against the negligent party and/or insurance company.

I/We hereby agreed to be bound by the following:-

1. You are authorised to use my/our name to claim against the negligent party and/or insurance company pertaining to the above accident including any other incidental losses. All payments/settlement monies shall be made in favour of your company M/S Specialists Motor Pte Ltd
2. All documents receive by me from third party or insurance company will be sent to your office for follow-up action.
3. Any offer of settlements by the insurer and/or negligent party will be accepted only with your concurrence and approval.
4. I/We agree to sign/execute the Discharge Receipt within 7 working days of issue of notice, by post, electronic mail, social media or text messaging, by your company.
5. If I/We fail to sign/execute the Discharge Notice after 7 working days from the Issue of notice, I/We hereby authorise your company's authorised representative to sign and execute the said Discharge Receipt on my/our behalf.
6. Throughout the process of claim, I/We will be obligated to assist and to provide your company with accurate and correct information.
7. I/We agree that I/We shall pay to your company all cost/expenses/damages incurred or suffered by you as a result of the unsuccessful recovery of the claims for the full repair cost and any other incidental cost/expenses by you on my/our behalf.
8. I/We warrant and undertake that all information and statement provided by me/us to you are true and accurate.

Thanking you in anticipation.

Yours faithfully


MOPI
PRIVATE LIMITED

Date: 13/02/2019

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

08th March 2019

TAX INVOICE


The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Date of Accident : 13th February 2019
Location : PIE towards Bradell Road
Third Party Claim Vehicle No : GBD 3332 C
Repair Cost For Vehicle No : GV 7811 G Toyota Liteace

A Lump-sum repair	S\$ 9,150.00
	<u>S\$ 9,150.00</u>
Add 7% GST	S\$ 640.50
	<u><u>S\$ 9,790.50</u></u>

S/Dollars :- Nine Thousand Seven Hundred Ninety And Cents Fifty Only.

SPECIALISTS MOTOR PTE LTD





**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-023705
Date of Request: 14/02/2019

Your Ref No: Online Purchase

Specialists Motor Pte Ltd
Blk 3018A Ubi Road 1
#01-24/25/26
Singapore 408711

Dear Sir/Madam,

Enquiry Date: 14/02/2019
Enquiry By: Tham Hui Lin
TP Vehicle No.: GBD3332C
Accident Date: 13/02/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBD3332C	EQ Insurance Company Ltd	29/11/2017-18/03/2019	6223 9433

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 14 October 2019 10:18 AM
To: CS A Team
Subject: FW: YOUR REF: DM19HO00478/JG -GBD 3332C (OUR REF: CC4/EQI19002876/Ugb3q2) *** ACCIDENT INVOLVING GBD 3332C (OI) & GV 7811G (TP) ON 13/02/2019 ***

From: Joel Goh
Sent: Monday, 14 October 2019 10:19:20 AM (UTC+08:00) Kuala Lumpur, Singapore
To: Cecilia Chong (LKK Auto)
Subject: RE: YOUR REF: DM19HO00478/JG -GBD 3332C (OUR REF: CC4/EQI19002876/Ugb3q2) *** ACCIDENT INVOLVING GBD 3332C (OI) & GV 7811G (TP) ON 13/02/2019 ***

Dear Cecilia

Please proceed and resolve this matter up to \$11,498.50.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Janet Tan
Sent: Friday, October 11, 2019 3:30 PM
To: Joel Goh
Cc: CeciliaChong@lkkauto.com
Subject: FW: YOUR REF: DM19HO00478/JG -GBD 3332C (OUR REF: CC4/EQI19002876/Ugb3q2) *** ACCIDENT INVOLVING GBD 3332C (OI) & GV 7811G (TP) ON 13/02/2019 ***

Joel,

For your necessary action.
Thank you.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 30/10/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBD 3332C (Insd Veh)	Your Ref. No. : DM19HO00478/JG
	GV 7811G (TP Veh)	Our Ref. No. : CC4/EQI19002876/Ugb3q2
Date of Accident	13/2/2019	

Liability	100%	
Final Repair Cost	: \$ 9,790.50	
Loss of Use	: \$ 960.00	16 days
Rental (If any)	: \$	days
Others:	: \$ 8.00	
	: \$	
	10,758.50	
Final Settlement Sum	: \$ 10,758.50	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	SPECIALISTS MOTOR PTE LTD	: \$ 10,758.50
		: \$

JOANNE LEE
LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI19002876/Ugb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 30-10-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 3332C	Veh. Inspected	GV 7811G ✓
Policy No.	DMCPHQ17-006804	Coverage (\$)	0.00
Claim No.	DM19HO00478/JG ✓	Excess (\$)	0.00
Assign From	JANET ✓	Assign Date	15/02/2019 ✓

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LITEACE (M) ✓	c.c	2184
Engine No.	HIDDEN	Year of Reg.	2002
Chassis No.	CR425003698 ✓	Colour	SILVER
Odometer	719244	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165 R13	FALKEN	6 mm
L/H Front Tyre	165 R13	FALKEN	6 mm
R/H Rear Tyre	165 R13 ✓	FALKEN	6 mm ✓
L/H Rear Tyre	165 R13	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2019	Inspection Date	15/02/2019
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **12 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GV 7811G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BUCKLED	509.80	509.80
2	BONNET HINGE L&RH @\$45.20	BENT	90.40	90.40
1	BONNET LOCK ASSY	TWISTED	79.90	79.90
1	BONNET RUBBER	TORN	51.10	51.10
1	FRONT SUPPORT PANEL	BENT / TWISTED	702.90	702.90
1	FRONT BRIDGE PANEL	TWISTED	77.80	77.80
1	FRONT GRILLE	CRACKED	209.60	209.60
2	HEADLAMP ASSY L&R @\$111.90	DAMAGED	223.80	223.80
2	HEADLAMP COVER L&R @\$111.80	CRACKED	223.60	223.60
2	HEADLAMP LOWER BRACKET L&R @\$16.90	NOT NECESSARY	33.80	-
2	FRONT SIDE LAMP L&R @\$184.80	NOT NECESSARY	369.60	-
1	FRONT BUMPER FASCIA	DISTORTED	382.70	382.70
1	SET FRONT BUMPER CLIPS	NECESSARY	38.00	38.00
1	FRONT BUMPER REINFORCEMENT	BENT	317.70	317.70
2	FRONT BUMPER BRACKET L&R @\$95.10	BENT	190.20	190.20
2	FRONT BUMPER FOG LAMP COVER L&R @\$126.90	NOT NECESSARY	253.80	-
1	AIR-CON CONDENSER	BENT / PUNCTURE	1,216.10	1,216.10
1	AIR-CON PIPE (CONDENSER TO COOLING)	NOT NECESSARY	369.70	-
1	AIR-CON PIPE (COMPRESSOR TO COOLING)	NOT NECESSARY	424.30	-
1	RADIATOR ASSY	BENT PUNCTURE	1,841.60	1,841.60
1	RADIATOR COWLING	CRACKED	184.70	184.70
1	RADIATOR FAN MOTOR	JAMMED	492.10	492.10
1	RADIATOR FAN BLADE	BENT	179.40	179.40
1	HORN	NOT NECESSARY	94.20	-
1	REAR BOOT COVER	BADLY DENTED	939.70	939.70
1	REAR BOOT LOCK	TWISTED / JAMMED	220.40	220.40
1	REAR BOOT WEATHER STRIP	TWISTED	369.90	369.90
1	REAR WINDSCREEN MOULDING	NECESSARY	79.40	79.40
1	REAR END PANEL	BADLY DENTED	416.70	416.70
1	REAR SPARE TYRE BRACKET	TO REPAIR SEE LABOUR	217.20	-

Report Ref No. CC4/EQ19002876/Ugb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	✓ 1,286.70	-
1	REAR BUMPER FASCIA	DISTORTED	✓ 371.60	371.60
2	REAR BUMPER BRACKET L&R @\$18.90	BENT	✓ 37.80	37.80
	LESS 25% DISCOUNT		-	-2,361.73
			12,496.20	7,085.17
	SPECIAL NETT ITEMS			
1	REAR WOODEN FLOOR WOOD (SN)	NOT NECESSARY	✓ 1,586.00	-
1	SET FRONT NUMBER PLATE (SN)	BENT	✓ 50.00	20.00
1	REAR BOOT STICKER (70KM/H) (SN)	NECESSARY	✓ 18.00	10.00
1	REAR BOOT STICKER (6PAX) (SN)	NECESSARY	✓ 18.00	10.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	✓ 60.00	40.00
1	REAR END PANEL SEALER (SN)	NECESSARY	✓ 80.00	50.00
			1,812.00	130.00
	LABOUR			
	TOWING FEE.		✓ 180.00	60.00
	CUT OUT ,RENEW ,KNOCKING & WELDING FRONT FENDER L&R ,FRONT BONNET ,FRONT SUPPORT PANEL,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & REALIGN BODY.		✓ 1,280.00	800.00
	REMOVE & INSTALL FRONT RADIATOR ASSY ,ENGINE COOLING SYSTEM & CONDUCT PRESSURE TEST.		✓ 120.00	100.00
	TUFF-KOTE ON FRONT DAMAGE PARTS.		✓ 160.00	100.00
	SPRAY PAINTING ON FRONT DAMAGE PARTS.		✓ 1,580.00	800.00
	CUT OUT ,RENEW KNOCKING & WELDING REAR BOOT COVER ,REAR END PANEL,REAR BOOT FLOOR PANEL,REMOVE & INSTALL ALL DAMAGE PARTS ,STRAIGHTEN & REALIGN BODY,INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE BRACKET AND REAR FLOOR PANEL.		1,880.00	1,100.00
	TUFF-KOTE ON REAR DAMAGE PARTS.		✓ 120.00	80.00
	SPRAY PAINTING ON REAR DAMAGE PARTS.		✓ 1,680.00	1,000.00
	REMOVE & REFIX REAR BUMPER SENSOR .		✓ 80.00	50.00
	REMOVE & REFIX REAR WINDSCREEN GLASS.		✓ 140.00	120.00

Report Ref No. CC4/EQ119002876/Ugb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK ALL LIGHTING AFTER REPAIRS.		50.00	30.00
			7,270.00	4,240.00
	GRAND TOTAL		21,578.20	11,455.17
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			9,150.00

Report Ref No. CC4/EQ19002876/Ugb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted by any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Thursday, 31 October 2019 4:17 PM
To: 'eqiprs@eqinsurance.com.sg'
Cc: 'CeciliaChong@lkkauto.com'
Subject: TP Direct Settlement - Accident Involving GBD 3332C (OI) and GV 7811G (TP) on 13/02/2019
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933