

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Not Acknowledged
previous letter
15/2/19
H/S \$
this photo taken
12 days.*

Date of Accident : 13th February 2019
Location : PIE towards Bradell Road

Third Party Claim Vehicle No : GBD 3332 C
Repair Cost For Vehicle No : GV 7811 G Toyota Liteace

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Bonnet <i>3cc</i>	1	509.80	\$ 509.80 /
2	Bonnet hinge L&RH <i>Bel</i>	2	45.20	\$ 90.40 /
3	Bonnet lock assy <i>twi</i>	1	79.90	\$ 79.90 /
4	Bonnet rubber <i>twi</i>	1	51.10	\$ 51.10 /
5	Front support panel <i>twi</i>	1	702.90	\$ 702.90 /
6	Front bridge panel <i>twi</i>	1	77.80	\$ 77.80 /
7	Front grille <i>one</i>	1	209.60	\$ 209.60 /
8	Headlamp assy L&R	2	111.90	\$ 223.80 ?
9	Headlamp cover L&R <i>one</i>	2	111.80	\$ 223.60 /
10	Headlamp lower bracket L&R	2	16.90	\$ 33.80 ?
11	Front side lamp L&R	2	184.80	\$ 369.60 ?
12	Front bumper fascia <i>D.J</i>	1	382.70	\$ 382.70 /
13	Front bumper clips <i>one</i>	1 set	38.00	\$ 38.00 ?
14	Front bumper reinforcement	1	317.70	\$ 317.70 ?
15	Front bumper bracket L&R	2	95.10	\$ 190.20 ?
16	Front bumper fog lamp cover L&R <i>17</i>	2	126.90	\$ 253.80 X
17	Air-con condenser	1	1,216.10	\$ 1,216.10 ?
18	Air-con pipe(condenser to cooling) <i>11</i>	1	369.70	\$ 369.70 X
19	Air-con pipe (compressor to cooling) <i>11</i>	1	424.30	\$ 424.30 X
				\$ 5,255.00

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

Balance b/f	\$ 13,798.10
<u>Labour Charges :-</u>	<u>Amounts</u>
Towing fee	\$ 180.00 60
Cut out, renew, knocking & welding front fender L&R, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body	\$ 1,280.00 800
Remove & install front radiator assy, engine cooling system & conduct pressure test ^{refill & r. con. test}	\$ 120.00 100
Tuff-kote on front damage parts	\$ 160.00 100
Spray painting on front damage parts	\$ 1,580.00 800
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install all damage parts, straighten & re-align body	\$ 1,880.00 1100
Tuff-kote on rear damage parts	\$ 120.00 80
Spray painting on rear damage parts	\$ 1,680.00 1000
Remove & refix rear bumper sensor	\$ 80.00 50
Remove & refix rear windscreen glass	\$ 140.00 120
Check all lighting after repairs	\$ 50.00 30
Labour Charge	\$ 7,270.00
Total Amount	\$ 21,068.10

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.