

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

The Manager
Motor Claim Department
EQ Insurance Company Ltd
5 Maxwell Road
#17-00 Tower Block
MND Complex
Singapore 069110

Date of Accident : 13th February 2019
Location : PIE towards Bradell Road

Third Party Claim Vehicle No : GBD 3332 C
Repair Cost For Vehicle No : GV 7811 G Toyota Liteace

Estimate Supply of Parts & Labours

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
1	Bonnet	1	509.80	\$ 509.80
2	Bonnet hinge L&RH	2	45.20	\$ 90.40
3	Bonnet lock assy	1	79.90	\$ 79.90
4	Bonnet rubber	1	51.10	\$ 51.10
5	Front support panel	1	702.90	\$ 702.90
6	Front bridge panel	1	77.80	\$ 77.80
7	Front grille	1	209.60	\$ 209.60
8	Headlamp assy L&R	2	111.90	\$ 223.80
9	Headlamp cover L&R	2	111.80	\$ 223.60
10	Headlamp lower bracket L&R	2	16.90	\$ 33.80
11	Front side lamp L&R	2	184.80	\$ 369.60
12	Front bumper fascia	1	382.70	\$ 382.70
13	Front bumper clips	1set	38.00	\$ 38.00
14	Front bumper reinforcement	1	317.70	\$ 317.70
15	Front bumper bracket L&R	2	95.10	\$ 190.20
16	Front bumper fog lamp cover L&R	2	126.90	\$ 253.80
17	Air-con condenser	1	1,216.10	\$ 1,216.10
18	Air-con pipe(condenser to cooling)	1	369.70	\$ 369.70
19	Air-con pipe (compressor to cooling)	1	424.30	\$ 424.30
				\$ 5,255.00

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

<u>No.</u>	<u>Particulars</u>	<u>Qty</u>	<u>Price</u>	<u>Amounts</u>
	Balance b/f			\$ 5,255.00
20	Radiator assy	1	1,841.60	\$ 1,841.60
21	Radiator cowling	1	184.70	\$ 184.70
22	Radiator fan motor	1	492.10	\$ 492.10
23	Radiator fan blade	1	179.40	\$ 179.40
24	Horn	1	94.20	\$ 94.20
25	Rear boot cover	1	939.70	\$ 939.70
26	Rear boot lock	1	220.40	\$ 220.40
27	Rear boot weather strip	1	369.60	\$ 369.60
28	Rear windscreen moulding	1	79.40	\$ 79.40
29	Rear end panel	1	416.70	\$ 416.70
30	Rear spare tyre bracket	1	217.20	\$ 217.20
31	Rear floor panel	1	1,286.70	\$ 1,286.70
32	Rear bumper fascia	1	371.60	\$ 371.60
33	Rear bumper bracket L&R	2	18.90	\$ 37.80
34	Rear wooden floor wood(s/nett)	1	1,586.00	\$ 1,586.00
35	Front number plate (s/nett)	1set	50.00	\$ 50.00
36	Rear boot sticker (70km/h) (s/nett)	1	18.00	\$ 18.00
37	Rear boot sticker (6pax) (s/nett)	1	18.00	\$ 18.00
38	Rear windscreen sealant (s/nett)	1	60.00	\$ 60.00
39	Rear end panel sealer (s/nett)	1	80.00	\$ 80.00
				<u>\$ 13,798.10</u>

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/GV7811G/1902021

14th February 2019

Balance b/f	\$ 13,798.10
<u>Labour Charges :-</u>	<u>Amounts</u>
Towing fee	\$ 180.00
Cut out, renew, knocking & welding front fender L&R, front bonnet, front support panel, remove & install all damage parts, straighten & re-align body	\$ 1,280.00
Remove & install front radiator assy, engine cooling system & conduct pressure test	\$ 120.00
Tuff-kote on front damage parts	\$ 160.00
Spray painting on front damage parts	\$ 1,580.00
Cut out, renew, knocking & welding rear boot cover, rear end panel, rear boot floor panel, remove & install all damage parts, straighten & re-align body	\$ 1,880.00
Tuff-kote on rear damage parts	\$ 120.00
Spray painting on rear damage parts	\$ 1,680.00
Remove & refix rear bumper sensor	\$ 80.00
Remove & refix rear windscreen glass	\$ 140.00
Check all lighting after repairs	\$ 50.00
	<hr/>
Labour Charge	\$ 7,270.00
Total Amount	\$ 21,068.10

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.