

SALES/RENT
MEAN

Mr Jim

ASSIGNMENT (Office)

From (Person)

Ong chin kiut

of

CTI

Date/Time

15/2/19 @ 2:13pm

Estimated Cost

Bill to

☒ TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No.

GBG 3240T

Insured

at Workshop m/s

Benz Bodywork

Tel

9759 4397

of

53 ubi Rd 1 # 05-15

Policy No.

DMCVSN1750211801

Claim No.

SNM19D200603C01

Sum Insured

Excess

\$350.06

Make of Veh.

(Client's Record)

D.O.A

11/2/2019

CA / REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time

3:13pm 15/2/19

Person Contacted

Joe Tan

Vehicle

☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	GBG 3240T - NA/CTI1900283/24 D.O.A: 11/2/19
15/2/19 @ 3:57pm	revert to Ong chin kiut via Neuman.
21/2/19 @ 14:32	authorise repair by Chang Boon Sen
21/2/19 @ 3:18pm	Inform Joe authorise repair with excess \$3507- By phone.

REF: CTI

ASSIGNMENT

Form:

Date:

15/2/19

Designated Code:

OD / TP / LWS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBG 3240 T

at Work Shop no:

Benz Bodywork

of

53 ubi Road # 05-15

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: \$350.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Est. or Market Value:

48K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG 3240 T

a/c Regd:

21/7/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN DX-2 1.6 Auto

c/s 1597

Colour:

SILVER

A/C:

Insured / Std / NI / NA

Sp. Reading:

21866

T/Radio:

Insured / Std / NI / NA

Eng/Ho:

HR16087305D

C/No:

NM20105133

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modt:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 165/80 R4

R: 165/80 R4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

01/02/19

D.O.I.

15/2/19

Survey held at

Benz Bodywork

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

Not authorise.

Range

6,000/2 - 7,000/2

Lump Sum Repair

16/5 Confirm lump sum \$43507 (red: 4939.40, 53%)

INV 48,000/2

PV 33,855/2

NV 14,145/2

RECEIVED 16 MAY 2019

Date/Time, File Pass to?



Preli. Report

16/5 Typst



Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$)



Interview (\$)



Techn Insp (\$)



Workshop (\$)

Report Format:

OD

Lump Sum / LB (\$)

43507

TOTAL

220

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 19 Feb 2019

Preliminary Advice

Vehicle No	: GBG3240T	Accident Date	: 01/02/2019
Make	: NISSAN NV200	Policy No.	: DMCVSN1750211801
Assignment Date	: 15/02/2019	Excess	: S\$350.00
Date of Inspection	: 15/02/2019	Est. Duration of Repair	: 5.00
Inspection At	: BENZ BODYWORK (HQ) 53 UBI RD 1 #05-15 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,289.40
Revised Amount	:S\$	5,913.20
Check Items (Estimated)	:S\$	1,163.50
Total	:S\$	7,076.70

Lump Sum Repair	:S\$	5,650.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	33,855.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,145.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON LUMP SUM BASIS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2019		15 Feb 2019 14:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: M/S OCTO-JET BUILDING MAINTENANCE SERVICES PTE LTD, Co. Reg. No.: 197602194Z		[Created by Insurer]	
Vehicle Reg. No.: GBG3240T	Date of Loss: 01/02/2019 07:00 - :59 [18 Months and 11 Days From LTA Reg Date (Man Yr)]	Policy/Cover Note No.: DMCVSN1750211801 (Comprehensive) Coverage: 25/07/2018 - 24/07/2019	Excess: S\$350.00
Claim Type: OD / SNM19D200603C01			
Repairer: Benz Bodywork (HQ) 53 UBI RD 1 #05-15 PAYA UBI INDUSTRIAL PARK, 408934 Ubi - Tel:			
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]			
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/02/2019]			
Driver/Custodian: TAN JOO MENG (CHEN YUMING) (40 / Male), NRIC: S7823216A, Tel: +6589999999			

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

To: lawrenceteo@tanchong.com
Subject: RE: HELP ME CHECK PART PRICE

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 10 May 2019 2:39 PM
To: lawrenceteo@tanchong.com
Subject: HELP ME CHECK PART PRICE

Dear Lawrence,

Please help me check part price

Nissan NV200 Van
GBG 3240T
VM20105133

Front LH Fender ~~504.70~~ 540.70
Front LH Fender Signal Lamp 448.50
Front LH fender quarter glass 228 S/N
Front LH door 1219.70
LH Headlamp 405.80

thanks

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Benz Bodywork

53 UBI AVENUE 1, PAYA UBI INDUSTRIAL PARK.

#05-15, SINGAPORE 408934, TEL: 68444617 FAX: 68444619

Email : benzbodykit@gmail.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Singapore

Car Made: Nissan NV200 Van

Vehicle No: GBG 3240 T

Policy No:-DMCVSN1750211801

Date:- 11-02-2019

Please kindly arrange to survey at this place
53, Ubi Avenue 1, #05-15, Paya Ubi Industrail Park,
Singapore

Person In charge Joe Tan
HP No 97594397

Thanks

Best Regards
Joe Tan





Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 BMW M Performance M235i Coupe.



Beautiful And Well-Kept, Low
 Mileage, Original BMW M
 Performance Add-ons.
 Direct Owner StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category








Sort by Date Posted

100 results/page

32 vehicles

Nissan NV200

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan NV200	Any	Any	2017	Any	Any	Any	All
	Nissan NV200 1.5M	\$54,988	\$6,270 /yr	28-Nov-2017	1,461 cc	-	Van	Available
Fuel Type: Diesel High Loan And Trade In Available, Cheapest In The Market, What You See Is What You Get. 100% No Gimmicks. No Hidden Charges. Call To Check Availability. ABWIN Bus Pte Ltd Posted: 18-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan NV200 1.6A	\$51,800	\$6,190 /yr	30-Jun-2017	1,597 cc	34,500 km	Van	Available
Fuel Type: Petrol 1 Owner, Agent Unit! Still Under Agent Warranty Till Year 2020! Just Service And Ready To Work For You Daily! Come Down To View Before You Intend To Look For New Unit. High COE Buy In But Sell Out Bel... Car (S) Pte Ltd Posted: 18-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan NV200 1.5M	\$55,800	\$6,340 /yr	06-Dec-2017	1,461 cc	-	Van	Available
Fuel Type: Diesel Agent Unit Condition, 1 Owner And Low Mileage 13K Plus Only! It's Still Under Tan Chong Motor Warranty! High Loan Available, High Trade In! Call Now To Find Out More! ABWIN Bus Pte Ltd Posted: 17-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan NV200 1.5M	\$51,800	\$6,400 /yr	22-Mar-2017	1,461 cc	29,600 km	Van	Available
Fuel Type: Diesel Flexible In House Loan. Prime Motor & Leasing Posted: 15-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	LED Scuff Plate							
LED scuff plate for sales! The cheapest LED Still Plate In Town! Hot sale & Free Installation! More info about this product								
	Nissan NV200 1.5M	-	N.A	23-Jun-2017	1,461 cc	45,008 km	Van	Available
Fuel Type: Diesel Auction Closing Time: 20th Feb 2019 at 11:00 PM With Key, This Vehicle Is Non GST Chargeable, Kindly Download The Non GST Chargeable Tender Form At This Link: https://goo.gl/F8mTB9 Posted: 14-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
	Nissan NV200 1.6A	\$49,888	\$5,910 /yr	27-Jul-2017	1,597 cc	32,600 km	Van	Available
Fuel Type: Petrol Compact, Car-Like Cabin, Good Cargo Space. 1 Careful Owner, Pristine Cond! Under Agent Warranty. Posted: 13-Feb-2019 Tags: 2017 Nissan NV200, 2017 nissan nv200, Nissan NV200, nissan nv200, Nissan, NV200, nv200, Used Nissan								
Compare	isan NV200 1.6A	\$50,800	\$6,100 /yr	20-Jun-2017	1,597 cc	29,900 km	Van	Available
Fuel Type: Petrol								

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2194Z
Vehicle Details	
Vehicle No.:	GBG3240T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 DX-2 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	HR16087905D
Chassis No.:	VM20105133
Maximum Power Output:	-
Open Market Value:	\$18,028.00
Original Registration Date:	21 Jul 2017
First Registration Date:	21 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$902.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jul 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$40,212.00
COE Rebate Amount:	\$33,855.00
Total Rebate Amount:	\$33,855.00

The information contained herein is correct as at 19 Feb 2019

OK

Dep 6190/yr
516/mth

MV 48,600/2
PV 33,855/2
NV 14,145/2

TG Lim
19/2/19

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/02/2019 14:23
Date Of Accident	01/02/2019 07:35
Exact Location Of Accident	UPP THOMSON RD NEAR THOMSON CC
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG3240T
Insured/Policyholder	
Name Of Registered Owner	M/S OCTO-JET BUILDING MAINTENANCE SERVICES PTE LTD
Co Reg No	197602194Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-89999999

Vehicle Particulars

Manufacturer	NISSAN
Model	NV200 DX-2 1.6 AUTO

Exact Purpose for which vehicle was being used at time of accident	WORKING
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	YES
--	-----

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1750211801
Cover Note Number	

Driver

Name of Driver	TAN JOO MENG (CHEN YUMING)
NRIC No	S7823216A
Date Of Birth	14/08/1978
Occupation	OUTDOOR
Date Of Driving Pass	11/09/1998
Driving Experience	20 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-89999999

Fax Number	
Contact Number	OFFICE-89999999
E-Mail Address	NOEMAIL
Address	54 SPRINGLEAF CRESCENT
Postcode	788382
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG6072S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Benz Bodywork

53 UBI AVENUE 1, PAYA UBI INDUSTRIAL PARK,
#05-15, SINGAPORE 408934. TEL: 68444617 FAX: 68444619
Email : benzbodykit@gmail.com

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Singapore

Car Made: Nissan NV200 Van

Vehicle No: GBG 3240 T

Policy No:-DMCVSN1750211801

Date:- 11-02-2019

S/No	DESCRIPTION	AMT S
	Estimate repair cost to vehicle Regn No:- GBG 3240 T	
	Nett Items	
1 pc	front bumper	\$ 563.10
1 pc	front bumper LH top pad	✓ 392.30
1 pc	front bumper LH retainer	✓ 35.30
1 pc	front LH fender	✓ 540.70
1 pc	front LH fender signal lamp	56.40
1 pc	front LH fender cowling	✓ 95.00
1 set	front LH fender cowling clip	✓ 30.00
1 pc	front LH fender bracket	✓ 45.30
1 pc	front LH fender quarter glass (228)	760.00
1 pc	front LH fender quarter glass lower garnish	56.25 283.30
1 pc	LH headlamp	463.60
1 pc	front LH door — closed-up photo 12/19-70 refer to resurvey	✓ 1,487.70
1 pc	front LH door weatherstrip	251.70
2 pcs	front LH door hinge	151.80
1 pc	LH wing mirror	✓ 401.10
1 pc	bonnet	782.70
		\$ 6,339.40
	Labour charges & misc @ 100%	3508.98
	To renew damaged parts, repair LH door pillar & align necessary parts.	228.00 + 3736.98 \$ 1,200.00
	To transfer front LH door glass & fittings	\$ 150.00
	To renew front LH fender quarter glass including supply sealant	\$ 120.00
	To spray paint on affected accident areas	\$ 1,200.00
	To respray rust proof on accident areas	\$ 200.00
	To check wiring & refocus headlamp	\$ -80.00
		\$ 9,289.40

LKK Auto Consultants have not
the Repairer of the following:

- To resurvey before/after spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SCR ✓
CUT ✓
MIS ✓
MIS ✓
MIS ✓
BR ✓
NECV ✓
BT ✓
NECV ✓
MIS ✓
CUT ✓
DD ✓
NNX ✓
NNX ✓
BR ✓
RX ✓

700.00
50.00
60.00
800.00
60.00
60.00
50.00
5456.98
1091.39
4365.59
? Photo
Lamp Sur
repair
Repair disp 5

L/s 4350/2

BENZ BODYWORK

53 UBI AVENUE 1, PAYA UBI INDUSTRIAL PARK.
#05-15, SINGAPORE 408934. TEL: 68444617 FAX: 68444619
Email : benzbodykit@gmail.com

Letter of Authorization for Lump Sum Repair.

I, Peto-Jet Building Maintenance Svc P.L. the owner of vehicle GBG 32401 do hereby authorize M/S Benz Body Work to repair my vehicle on a lump sum basis instead of part by part,

The workshop has explained to me the difference between lump sum repair & part by part.

I understand that lump sum repair the workshop may use original, OEM parts and second hand parts to carry out the repair.

Sign by



Policyholder
Date:-



Sign by



Workshop
Date:-

3/8/19



LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT19002884/BTD3N2

Date: 21/05/2019

REFERENCE

M/S OCTO-JET BUILDING
Insured/Claimant: MAINTENANCE SERVICES PTE LTD

Policy No: DMCVSN1750211801

Date of Loss: 01/02/2019

Nature of Claim: OD

Claim No: SNM19D200603C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG3240T	Engine No:	HR16087905D
Make & Model:	NISSAN NV200, 1.5 (M)	Chassis No:	VM20105133
Reg. Date:	21/07/2017 (Man. Year: 2016)	Odometer:	21866 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	S\$48,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165/80 R14	Rear Tyre Size:	165/80 R14
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,340.00	3,714.07	2,625.93	41.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,950.00	1,720.00	1,230.00	41.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,290.00	5,434.07	3,855.93	41.51
Approved Total (Overridden) (S\$)		4,350.00		
- Excess (S\$)	350.00	350.00	0.00	0.00
Nett Amount (S\$)	8,940.00	4,000.00	4,940.00	55.26

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 15/02/2019 Inspected At:

Benz Bodywork (HQ)
53 UBI RD 1 #05-15 PAYA UBI
INDUSTRIAL PARK
Singapore 408934

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 21 May 2019)	
Parts:	N/A	NISSAN NV200 1.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG3240T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	563.10 F	*563.10 FN
2	1		*FRONT BUMPER LH TOP PAD	Cut	392.30 F	*392.30 FN
3	1		*FRONT BUMPER LH RETAINER	Missing	35.30 F	*35.30 FN
4	1		*FRONT LH FENDER	Missing	540.70 F	*540.70 FN
5	1		*FRONT LH FENDER SIGNAL LAMP	Missing	56.40 F	*56.40 FN
6	1		*FRONT LH FENDER COWLING	Broken	95.00 F	*95.00 FN
7	1		*SET FRONT LH FENDER COWLING CLIP	Necessary	30.00 F	*30.00 FN
8	1		*FRONT LH FENDER BRACKET	Bent	45.30 F	*45.30 FN
9	1		*FRONT LH FENDER QUARTER GLASS	Necessary	760.00 F	*228.00 FN
10	1		*FRONT LH FENDER QUARTER GLASS LOWER GARNISH	Missing	283.30 F	*56.25 FN
11	1		*LH HEADLAMP	Cut	463.60 F	*463.60 FN
12	1		*FRONT LH DOOR	Dented	1,487.70 F	*1,219.70 FN
13	1		*FRONT LH DOOR WEATHERSTRIP	Not Necessary	251.70 F	*- FN
14	2		*FRONT LH DOOR HINGE	Not Necessary	151.80 F	*- FN
15	1		*LH WING MIRROR	Broken	401.10 F	*401.10 FN
16	1		*BONNET	Repair	782.70 F	*- FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	6,340.00	4,126.75
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	412.68
Total Parts (\$\$)	6,340.00	3,714.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS,REPAIR LH DOOR PILLAR & ALIGN NECESSARY PARTS	New	1,200.00	700.00
2	TO TRANSFER FRONT LH DOOR GLASS & FITTINGS	New	150.00	50.00
3	TO RENEW FRONT LH FENDER QUARTER GLASS INCLUDING SUPPLY SEALANT	New	120.00	60.00
4	TO SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,200.00	800.00
5	TO RESPRAY RUST PROOF ON ACCIDENT AREAS	New	200.00	60.00
6	TO CHECK WIRING & REFOCUS HEADLAMP	New	80.00	50.00
Gross Labour Cost (S\$)			2,950.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >