

AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 Shenton Way #07-16
Singapore 079120

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. : **SLN4736T**
CHASSIS NO : KPT30B1USGP105403
ENGINE NO : 67391002034397
MAKE / MODEL : SSANGYONG TIVOLI 1.6D 6AT 2WD ESP E5
DATE OF ACCIDENT : 02.02.2019 @ 01:30HRS
YOUR INSURED VEHICLE NUMBER : SLG9261A

Rasul
Hp 90010068
3 days
4/3
19/02/19 @ 1555
Repairing after repair

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>List Price</u>	<u>Total List Price</u>
FRONT BUMPER UPPER <i>SCA</i>	1pc	\$ 898.00	\$ 898.00
FRONT BUMPER LOWER LH <i>SCA</i>	1pc	\$ 350.00	\$ 350.00 <i>205</i>
FRONT BUMPER CLIPS <i>SCA</i>	1set	\$ 30.00	\$ 30.00
FRONT LH BUMPER SIDE RETAINER <i>X</i>	1pc	\$ 45.00	\$ 45.00 <i>x</i>
FRONT BUMPER SPONGE <i>?X</i>	1pc	\$ 115.00	\$ 115.00 <i>x</i>
		Total	\$ 1,438.00
		ADD 10%	\$ 143.80
		TOTAL PARTS	\$ 1,581.80

1133
+ 10%
1246.30

LABOUR CHARGES

TO REMOVE, REPLACE & REPAIR ALL DAMAGES PARTS DUE TO ACCIDENT	\$ 1,050.00 <i>350</i>
TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO THE ACCIDENT	\$ 300 <i>300.00</i> 200
TOTAL LABOUR	\$ 1,350.00 <i>650</i>
SUB TOTAL	\$ 2,931.80

LABOUR : \$350 per day
SPRAY PAINT : \$300 per panel

Prepared By : -

RAJ

Motor Claims

TEL: 6571 9635 FAX : 6278 5535

EMAIL: lynn@motorway.com.sg

LKK Auto Cons. hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts price and condition information
- Third party information
- No illegal work to be carried out
- Supply of materials and labour
- Is subject to insurance C

Acknowledged
Signature
Date:

1246.30
650.00
1896.30
20%
1517.04

4/3 - 1,500 3 days