



# MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

## Supplementary Items

Date: 13 February 2019  
Vehicle: SLT5332L  
Make / Model: HONDA/CIVIC  
Chassis: MRHFC5650HT000483

| No.                | Description                       | Unit | Unit Price   | Amount      |
|--------------------|-----------------------------------|------|--------------|-------------|
| Parts Replacement: |                                   |      |              |             |
| 1                  | BOOTLID GARNISH - CPA             | 1    |              | \$ 519.30   |
| 2                  | REAR RH TAILLAM PANEL - BUC       | 1    |              | \$ 313.40   |
| 3                  | REAR STIFFNER PANEL SIDE X Repair | 2    |              | \$ 492.40   |
| 4                  | REAR BUMPER UNDER SPOILER - el    | 2    |              | \$ 539.30   |
|                    |                                   |      |              | \$ 1,864.40 |
|                    |                                   |      | Less 20%     | \$ 372.88   |
|                    |                                   |      |              | \$ 1,491.52 |
|                    |                                   |      | Grand total: | \$ 1,491.52 |

385.2  
265.2  
X  
485.2

1135.6

20% : 908.48