



## Case Details

Case Reference Number : TAX/02/19/2063  
 Type of Repair : Accident Repair  
 Vehicle Registration Number : SHB1141P

Company Type : SMRT Taxis Pte Ltd  
 Estimation ID : EST-5701-ID  
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd  
 Accident Date and Time : 11/02/2019 02:23 PM  
 Vehicle Age(In Months) : 15

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair	
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	NEC
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	1	1,236.15	Replace	CRA
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	1	67.13	Replace	MIS
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	
One Time Key In	Main			DOOR OUTER HANDLE FRONT , RH	1	378.90	378.90	25.00	284.17	Replace	0	0	Not Give	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give	
One Time Key In	Main			EMBLEM, SIDE PANEL ( HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give	
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0	Not Give	

Total Spare Part Cost	6,648.30	Surveyor Total	1,342.95
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	0
Final Spare Part Cost	6,648.30	Final Sur Total	1,342.95

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	0	0	Not Give	
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	0	0	Not Give	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	0	0	Not Give	
One Time Key In	Main			DOOR OUTER HANDLE FRONT, RH	1	378.90	378.90	25.00	284.17	Replace	0	0	Not Give	
<b>Total Spare Part Cost</b>									6,648.30		<b>Surveyor Total</b>		1,342.95	
<b>Lump Sum Discount (%)</b>									0.00		<b>Lump Sum Dis (%)</b>		0	
<b>Final Spare Part Cost</b>									6,648.30		<b>Final Sur Total</b>		1,342.95	

**Labour's Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	845.00	250	
<b>Total:</b>			<b>845.00</b>	<b>250.00</b>	

**Spray Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO RESPRAY VIEW MIRROR	180.00	50	
3	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
4	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
5	Main	TO RESPRAY VIEW MIRROR	180.00	0	
6	Main	TO RESPRAY FRONT DOOR RH	378.00	0	
<b>Total:</b>			<b>1,872.00</b>	<b>250.00</b>	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
<b>Total:</b>			<b>240.00</b>	<b>40.00</b>	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	
3	Main	TO WASH AND VACUUM	60.00	0	
<b>Total:</b>			<b>240.00</b>	<b>40.00</b>	

## Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,648.30	1,342.95
Total Labour Cost	845.00	250.00
Total Spray Painting	1,872.00	250.00
Other	240.00	40.00
Overall Total	9,605.30	1,882.95
Lump Sum Repair Option		
Lump Sum Total	0.00	1,882.95
Surveyor Approved Amount		1,882.95
No of Repair Days*	5	2
Remarks	-	P/P REPAIR,PHOTO BEFORE PAINT.
Surveyor Name		Hwee jie
Signature		
Survey Date	14/02/2019	

Save Clear

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: