

21000001
21000001

REF es/smo19002899/Dtd3ⁿ²

Speed of Instruction

Surveyor

ASSIGNMENT (Office)

menimen

From (Person)

Henry shengyi

SMO

Date/Time 14/2/19 @ 2:11pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJE 3200A

Insured

GBD 1377L

at Workshop n/s

Teamwork Garage

Tel:

6844 2475

of

53 ubi Ave 1 #01-24

Policy No:

D18M1PCVE002347

Claim No:

CMTD1900829

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/2/19

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

18/2/19

H.O.D. Endorsement

Date/Time:

3:15pm @ 14/2/19

Person Contacted:

Jamen

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJE 3200A - NA/AIG19002450/24

DUA: 9/2/2019

GBD1377L - NA/AIG19002450/24

DUA: 9/2/2019

25/2/19 -

Revised via menimen preli advise.

REF:

ASSIGNMENT

COE April 2023


22 April 2008

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop No: _____
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: **8JE 3200A** Page: **1498**
 Type: **①** M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Hissen Latio**
 Colour: **Silver** A/C: _____ Insured / Std / NI / NA
 Sp. Reading: **174027** T/Radio: Insured / Std / NI / NA
 Eng No: **HR 15222517A**
 C.No: **JN1BAAC1180007196**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brake: **Good** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/S m / STD A/R m or
 Tyre Size: F: **185/65 R.15**
 R: **---**

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **Pirelli**

Front	Rear
R/Bal: S mm	R/Bal: S mm
L/Bal: S mm	L/Bal: S mm

D.O.A: **09/02/2019** D.O.I: **20/02/2019**
 Survey held at: **Tecmwork Paga Ubi**

Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or
Rear

The U/C / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Sampo #GBD 1377L**RECEIVED 29 APR 2019****MV 24K****using average depreciation of 6K x 4 yrs.****LTA 16.1K****HL 7.9K****RECEIVED 15 MAY 2019**

29/04/19 jnana L/S 7500/- at 6 days 7 rev (Red: 566.39.43%)

Date/Time, File Pass to?

29/4 Typist

Date/Time, File Return to?

Days Of Repair: **6**Resurvey No. of Trip: **2**

Survey Fee:

Transportation

) S + RS 3

) Prob

) Other

) ...

) ...

) ...

) ...

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Report Format

Lump Sum / L.B. (\$)

TP**7500/-****450****10****460**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

	Notified	Assigned	Adj. Rpt.	Adj. Rpt. Status	Ins. Act.	Remarks
Main	12 Feb 2019	14 Feb 2019 14:11				New Assignment Cancel Case

Main	Insurance	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	FUYEN FOOD PTE LTD, Co. Reg. No.: 199906054C		
Main Claimant:	SHEN JIE, ID: S2722639F		
Vehicle Reg. No.:	SJE3200A	Date of Loss:	09/02/2019 16:00 - :59
Claim Type:	TP / CMTD1900829	Policy/Cover Note No.:	D18MTPCVE002347 (Comprehensive)
Vehicle Reg. No. (Insured):	GBD1377L	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/02/2019]		
Adj. Ass. Remarks:	-PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

	View All	Search Tasks	Create New Task	Complete
No results.				

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 25 Feb 2019

Preliminary Advice

Insured Vehicle No	: GBD1377L	Accident Date	: 09/02/2019
TP Vehicle No	: SJE3200A	Assignment Date	: 14/02/2019
Make	: NISSAN LATIO	Est. Duration of Repair	: 6.00
Date of Inspection	: 20/02/2019		
Inspection At	: TEAMWORK GARAGE PTE LTD (HQ) 53 UBI AVE 1 #01-24, PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,166.39
Revised Amount	:S\$	8,958.95
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,958.95

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/02/2019 16:31
Date Of Accident	09/02/2019 16:55
Exact Location Of Accident	TELOK BLANGAH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE3200A
Insured/Policyholder	
Name Of Registered Owner	SHEN JIE
NRIC No	S2722639F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98265775
Alternative Phone No	OFFICE-98265775
Vehicle Particulars	
Manufacturer	NISSAN
Model	LATIO 1.5L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100073893-10
Cover Note Number	
Driver	
Name of Driver	SHEN JIE
NRIC No	S2722639F
Date Of Birth	09/07/1967
Occupation	INDOOR
Date Of Driving Pass	14/02/2007
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98265775
Fax Number	
Contact Number	OFFICE-98265775
Email Address	NOEMAIL

Address	BLK 425 CLEMENTI AVENUE 1 #33-293
Postcode	120425
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : SHEN JIA NING AMY GENDER: : FEMALE
Passenger 2	NAME: : WU YA JUN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD1377L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Accident Statement

1. I, the undersigned, hereby certify that the following is a true and correct statement of the facts and circumstances surrounding the accident described herein.

2. I am the driver of the vehicle involved in the accident described herein.

3. I am the owner of the vehicle involved in the accident described herein.

4. I am the insured of the vehicle involved in the accident described herein.

5. I am the policyholder of the vehicle involved in the accident described herein.

6. I am the reporting centre person of the vehicle involved in the accident described herein.

7. I am the witness of the accident described herein.

8. I am the driver of the vehicle involved in the accident described herein.

9. I am the owner of the vehicle involved in the accident described herein.

10. I am the insured of the vehicle involved in the accident described herein.

11. I am the policyholder of the vehicle involved in the accident described herein.

12. I am the reporting centre person of the vehicle involved in the accident described herein.

13. I am the witness of the accident described herein.

14. I am the driver of the vehicle involved in the accident described herein.

15. I am the owner of the vehicle involved in the accident described herein.

16. I am the insured of the vehicle involved in the accident described herein.

17. I am the policyholder of the vehicle involved in the accident described herein.

18. I am the reporting centre person of the vehicle involved in the accident described herein.

19. I am the witness of the accident described herein.

20. I am the driver of the vehicle involved in the accident described herein.

21. I am the owner of the vehicle involved in the accident described herein.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NEEDRY No.:

Accident Sketch Plan

[Faint, illegible handwritten notes and sketches at the top of the page, possibly showing a diagram of the accident scene.]

[A large rectangular area with horizontal lines for writing, containing faint handwritten notes.]

DECLARATION

I/We declare the foregoing particulars are true to every respect

[Signature]
 Policyholder's Signature
 Date & Time

[Signature]
 Driver's Signature
 (if driver is not the policyholder)
 Date & Time

[Signature]
 Reporting Centre Personnel's Signature
 Name
 ASIC/PCP No.:

[Small, faint text at the bottom left.]

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		7384.49
Balance B/F		
1 SET	REAR NUMBER PLATE <i>W12</i>	80.00 X
1 SET	REAR BUMPER CLIP <i>W12</i>	40.00 30/-
1 SET	REAR FENDER INNER TRIM CLIP <i>W12</i>	30.00 20/-
1 SET	REAR REVERSE SENSOR <i>Don</i>	400.00 220/-
1 SET	JOINT SEALANT <i>W12</i>	150.00 40/-
1	FLOOR INSULATOR <i>W12</i>	150.00 X
1	REAR BUMPER LOWER LIP <i>W12</i>	671.90 500/-
Subtotal		1521.90
Balance C/F		8906.39
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		8906.39
1	CHECK REAR WIRING AND LIGHTING	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
3	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00 60/-
4	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
5	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
6	REMOVE AND REFIT FUEL TANK	150.00 40/-
7	REMOVE AND RENEW FLOOR INSULATOR	150.00 X
8	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60/-
9	PANEL BEATING ON AFFECTED AREAS	1500.00 1200/-
10	SPRAY PAINTING ON AFFECTED AREAS	1400.00 1000/-
11	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
Subtotal		4260.00
Grand total		13166.39
		15589.64

20/02/2019 @ 1630hrs
 N/A Antons
 L/SNM

6 days.
 ya
 LKK Auto

8

Check MV

7999.60
 Supp 1909.08
 9908.68
 L/S 7500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Sompo Insurance Pte Ltd
50 Raffles Place , #05-01/06
Singapore Land Tower
Singapore 048623

Vehicle number	SJE3200A
Make / Model	NISSAN / LATIO
Chassis number	JN1BAAC11Z0007196
Accident date	09 February 2019
Reference	1902-04

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	REAR WINDSCREEN <i>Replaced</i>	1476.20
1	BOOTLID SPOILER <i>Replaced</i>	1875.50 ✓
1	WINDSCREEN MOULDING <i>Replaced</i>	645.00 ✓
		172.00 X
		2692.50
		269.25
		2423.25

2121.20
1909.08

LESS 10%

Eng 22/2/2019.
Lick And
[Signature]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19002899/DTD3N2

Date: 16/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTPCVE002347
Claimant Vehicle No :	SJE3200A	Insured Vehicle No :	GBD1377L
Date of Loss:	09/02/2019	Nature of Claim:	TP
		Claim No:	CMTD1900829

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE3200A	Engine No:	HR15222517A
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0007196
Reg. Date:	22/04/2008 (Man. Year: 2007)	Odometer:	174027 km
Colour:	Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,329.64	7,278.68	4,050.96	35.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,260.00	2,630.00	1,630.00	38.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,589.64	9,908.68	5,680.96	36.44
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	15,589.64	7,500.00	8,089.64	51.89
+ GST 7.00/7.00% (S\$)	1,091.27	525.00	566.27	51.89
Nett Amount (S\$)	16,680.91	8,025.00	8,655.91	51.89

INSPECTION

Date of Assignment:	14/02/2019	
Date Inspected:	20/02/2019 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 May 2019)
Parts:	143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE3200A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	609.90 FL	*609.90 FL
2	1		*END PANEL	Dented	542.60 FL	*542.60 FL
3	1		*REAR TAILLAMP PANEL	N/s Dented/O/s Not Necessary	364.80 FL	*182.40 FL
4	1		*REAR FENDER	N/s Dented/O/s Repair	2,520.70 FL	*954.00 FL
5	1		*BOOTLID	Bent/Dented	864.60 FL	*864.60 FL
6	1		*SPARE TYRE COMPARTMENT	Repair	871.40 FL	*- FL
7	1		*REAR EXHAUST SILENCER	Not Necessary	546.10 FN	*- FN
8	2		*REAR EXHAUST MOUNTING	Not Necessary	30.00 FN	*- FN
9	2		*REAR BUMPER RETAINER	Not Necessary	70.40 FN	*- FN
10	2		*REAR BUMPER BRACKET	Not Necessary	90.80 FN	*- FN
11	1		*REAR BUMPER SPONGE	Serviceable	65.60 FN	*- FN
12	1		*END PANEL TOP GARNISH	Bent	173.10 FN	*173.10 FN
13	1		*END PANEL KEYLESS CONTROL	Damaged	157.50 FN	*157.50 FN
14	2		*REAR TAILLAMP	Ns Broken/Os Mounting Cracked	519.30 FN	*519.30 FN
15	1		*REAR FENDER INNER TRIM	N/s Bent/O/s Not Necessary	482.80 FN	*241.40 FN
16	2		*REAR FENDER INNER SHIELD	Not Necessary	56.30 FN	*- FN
17	1		*REAR WINDSCREEN MOULDING	Necessary	130.10 FN	*130.10 FN
18	1		*BOOTLID WEATHERSTRIP	Deformed	159.90 FN	*159.90 FN
19	1		*BOOTLID EMBLEM LOGO-NISSAN	Necessary	45.60 FN	*45.60 FN
20	1		*BOOTLID EMBLEM-LATIO	Necessary	66.40 FN	*66.40 FN
21	1		*BOOTLID OUTER CHROME	Mounting Cracked	257.00 FN	*257.00 FN
22	1		*BOOTLID LOCK	Bent	197.90 FN	*197.90 FN
23	1		*BOOTLID LOCK STRIKER	Bent	60.30 FN	*60.30 FN
24	2		*BOOTLID HINGE	Bent	110.00 FN	*110.00 FN
25	1		*SPARE TYRE TOP BOARD	Bent	495.00 FN	*495.00 FN
26	1		*REAR WINDSCREEN	Shattered	1,875.50 FN	*1,476.20 FN
27	1		*BOOTLID SPOILER	Dented	645.00 FN	*645.00 FN
28	1		*WINDSCREEN MOULDING	Repeated	172.00 FN	*- FN
29	1		*SET REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
31	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	30.00 FS	*20.00 FS
32	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
33	1		*SET JOINT SEALANT	Necessary	150.00 FS	*40.00 FS
34	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS
35	1		*REAR BUMPER LOWER LIP	Distorted	671.90 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	13,702.50	8,698.20
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,732.20	946.05
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	640.66	473.47

Total Parts (\$\$) 11,329.64 7,278.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
-----	-----	-------------	-------------	-----------	------------	--------

Report was unsubmitted during this print-out.						
---	--	--	--	--	--	--

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	200.00	80.00
3	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	60.00
4	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
5	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
6	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
7	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	0.00
8	TRANSFER PARTS,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
9	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	1,200.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	1,000.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (\$\$)			4,260.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >