

ASS. REC. BY:

REF: es/FCI19002910/Uqd3

n2  
Special Instruction

Surveyor  
CWS

ASSIGNMENT (Office)

From (Person) Joanne Yong

of FCI

Date/Time 1:10pm @ 15/2/19

Estimated Cost: Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MVTCS

To Inspect Vehicle No. SGF 8424T

Insured SHC 8087L

at Workshop n/s Kah Motor

Tel. 81006303

of 15 ubi Rd 4

Policy No:

Claim No: D19001114MFST

Sum Insured:

Excess:

Make of Vch (Client's Record)

D.O.A 12/02/2019

CA / REV / REP. / REV 24 HRS (Ds)

18/2/19 @ 9:30am  
H.O.D. Endorsement

Date/Time 4:48pm @ 15/2/19

Person Contacted

Mr. Kim

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SGF 8424T-X
19/2/19 @ 4:55pm	SHC 8087L - es/FCI19007292 / Gqh3n2 revised to Joanne Yong by email. Don: 6/4/19

REF: FCI

ASSIGNMENT

Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD:  WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: **S6F8424T**  
 at Work/Shop no: **Kah Motor**  
 of: **15 Ubi Rd 4**  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claim No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
**9.30am.**  
 (Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: **62k.**  
 ID# / Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / DR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repair: **2** days Res.: Yes or No  
 Lum Sum: **13%** % 3 Val: Yes or No  
 GA / REV / REP. / 24 HRS: **AS.**  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

<input type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Veh No: **S6F8424T** Reg No: **8 18**  
 Type:  M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or **car**  
 Make: **Honda Jazz** CC: **1318**  
 Colour: **blue** AAC: Insured / Std / NI / NA  
 Sp. Reading: **5204** TRadio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: **JHM6K3850JX226682**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering: Insured / Jammed / Leaked / Burnt or  
 Brake: Insured / Jammed / Leaked / Burnt or  
 Mod: Nil / SRim / STD A/Rim or  
 Tyre Size: F: **175/65-R15**  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: **7** mm R/Bal: **7** mm  
 L/Bal: **7** mm L/Bal: **7** mm  
 D.O.A: **12/2/19** D.O.I: **18/2/19**  
 Survey held at: \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
**O/S Rear**  
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction  
**1743668**

**8/3/19 confirmed final by #1841-81 with MR Lian.**  
**(cost \$1600.92, 42%)**

RECEIVED 12 MAR 2019

Date/Time File Pass by:  : Preli. Report  
 : Final Report

Days Of Repair: **2**  
 Resurvey No. of Trip: **1**

Add Fee:  Site Insp. (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee:	130
Transportation:	50
Site Insp. (\$):	50
Interview (\$):	24
Tech. Invs (\$):	
Weekend (\$):	
<b>Total:</b>	<b>254</b>

Report Format: **TP**  
 Lump Sum / L.B.C. (\$): **(841-81)**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19001114MFSH

Date: 19 February 2019

Our Ref: CS/FCI19002910/Uqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SGF 8424T**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/02/2019 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,305.18</u>
Revised Estimate Amount	: S\$ <u>1,704.26</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the o/s rear portion.



Yours faithfully

CHUA KANG SENG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	14-02-2019	<b>Our Ref No.</b> D19001114MFSH
<b>Accident Date</b>	12-02-2019	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8087L	<b>Third Party Vehicle.</b> SGF8424T
<b>Survey Location</b>	15 UBI ROAD 4	
<b>Contact Person.</b>	LIM CHOU SIONG	
<b>Contact No.</b>	68465671/ 81006303	<b>Fax No.</b> 67480770
<b>Survey Type</b>	DIRECT SETTLEMENT:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	KAH MOTOR CO SDN BHD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	JOANNEY	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Tuesday, 19 February 2019 4:52 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Joanne Yong Lai fong'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D19001114MFSH/1  
**Attachments:** CSFCI19002910Uqd3.pdf; CSFCI19002910Uqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SGF 8424T.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 15 February 2019 5:00 PM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Joanne Yong Lai fong' <[Joanneyong@msfirstcapital.com.sg](mailto:Joanneyong@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D19001114MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer arrange on 18/02/2019.

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 15 February 2019 4:09 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Joanne Yong Lai fong <[Joanneyong@msfirstcapital.com.sg](mailto:Joanneyong@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D19001114MFSH/1

CHEAPEST CAR INSURANCE RENEWAL



Compare 10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Rare High Specs BMW 3 Series 335i Sedan On Sale !



Super Low Genuine Mileage Of Just 11000km, 1 Owner, Full PML Serviced Record ! Seng Hup Auto StarAd

HIN LUNG AUTO HoBee Group 30 years of car sale One Stop Car Hub Finance, Insurance, Workshop New and Used Cars

Browse by Category

Sort by Date Posted 20 results/page

1 vehicles

honda jazz

Advanced Search Submit

Table with columns: Make, Model, Price, Depreciation, Reg Date, Eng Cap, Mileage, Veh Type, Status. Row 1: honda jazz, Any, Any, 2018, Any, Any, Any, Any, Available. Row 2: Honda Jazz 1.3A LX, \$66,888, \$6,720 /yr, 27-Aug-2018, 1,318 cc, 11,000 km, Hatchback, Available. Includes description: Almost New. Comes With Additional Front/Back Camera And Paint Protector. 5 Years Warranty (Kah Motor), 5 More Free Servicing. Reliable, Fuel Efficient And Excellent Drive.

Save this search criteria, to get email alerts whenever a match is found.

Table with columns: Make, Model, Price, Depreciation, Reg Date, Eng Cap, Mileage, Veh Type, Status. Includes pagination: 20 results/page

For old advertisements, view Expired ads

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used honda jazz, honda jazz Singapore, used honda jazz Singapore, used honda jazz, used vehicles Singapore or even buy used honda jazz Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 5827B

### Vehicle Details

Vehicle No.: SGF8424T  
Vehicle to be Exported: No  
Intended Deregistration Date: 18 Feb 2019  
Vehicle Make: HONDA  
Vehicle Model: JAZZ 1.3 CVT  
Primary Colour: Blue  
Manufacturing Year: 2018  
Engine No.: L13B11031031  
Chassis No.: JHMGK3850JX226682  
Maximum Power Output: 73.0 kW (97 bhp)  
Open Market Value: \$15,625.00  
Original Registration Date: 24 Aug 2018  
First Registration Date: 24 Aug 2018  
Transfer Count: 0  
Actual ARF Paid: \$5,625.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 23 Aug 2028  
PARF Rebate Amount: \$4,218.00

### Intended COE Rebate Details

COE Expiry Date: 23 Aug 2028  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$34,110.00  
COE Rebate Amount: \$32,450.00  
**Total Rebate Amount: \$36,668.00**

The information contained herein is correct as at 18 Feb 2019

OK

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189); Motor Vehicles (Third-Party Risks And Compensation) Rules, 1960; Road Transport Act, 1987 (Malaysia); Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

<b>Name of Policyholder:</b> KHOO WEE BENG (QIU WEIMIN)	<b>Certificate No.:</b> SD18V09019/ VPC / R00
<b>Date of Issue:</b> 27 Aug 2018	<b>Effective Date of Commencement:</b> 24 Aug 2018 00:00
<b>Registration No.:</b> SGF8424T	<b>Chassis No.:</b> JHMGK3850JX226682
	<b>Date of Expiry:</b> 23 Aug 2019 23:59
	<b>Type of Certificate:</b> MX1

**Persons or Classes of Persons entitled to drive\*:**

- A) The Policyholder.
- B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

**Limitations as to use:**

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

**The Policy does not cover:**

- A) Use for hire or reward.
- B) Use for racing, pace-making, reliability trials or speed-testing.
- C) Use for the carriage of goods (other than samples) in connection with any trade or business.
- D) Use for any purpose in connection with the Motor Trade.

\*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).



For and on behalf of  
**LIBERTY INSURANCE PTE LTD**  
Approved Insurers

**For Information Only:**

Coverage(s):	Comprehensive, Unlimited Windscreen, NCD Protection
Sum Insured:	MARKET VALUE AT THE TIME OF LOSS
Excess:	Section I S\$600, Additional Excess for Young & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
Name of Finance Company:	OVERSEA-CHINESE BANKING CORPORATION LTD
Name of Producer:	KAH MOTOR COMPANY SDN BERHAD (A1572-4)



Name  
**KHOO WEE BENG**  
**(QIU WEIMIN)**  
**邱伟珉**  
Race  
**CHINESE**  
Date of birth      Sex  
**17-09-1977      M**  
Country of birth  
**SINGAPORE**

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7725827B**  
Name:  
**KHOO WEE BENG**  
**(QIU WEIMIN)**

Birth Date: **17 Sep 1977**  
Issue Date: **09 Jul 2003**

000642964H

3614530



NRIC No. **S7725827B**

Date of issue  
**01-09-2004**

APT BLK 52 LENGKOK BAHRU #04-291  
SINGAPORE 150052

NRIC No: **S7725827B**      Date: **22/02/2017**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS

	PASS DATE
Class 2B Motorcycles <= 200 CC	25 Jun 1998
Class 3 Motor cars <= 3500 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg	16 Sep 2005

S / No. 9000038765

S7725827B

NP 428A

Licence No: S7725827B



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange  
Surveyor To Survey this  
Vehicle Thanks*

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : MS FIRST CAPITAL INSURANCE  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

**Registration No** : SGF8424T

**Chassis No** : JHMGK3850JX226682

**Model** : JAZZ 1.3LXR CVT 18YM (EURO 6)

**Owner's Name** : KHOO WEE BENG

**Ins Policy No.** :

**Date of Accident** : 12/2/2019

**Document No.** : SQT19000700 Page 1

**Date** : 12. Feb 2019

**Customer No.** : WZF002

**Svc Advisor** : LIM CHOU SIONG

**Engine No** : L13B11031031

**Date | Time** : 12. Feb 2019 8:19:31 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: KHOO WEE BENG OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 12/2/2019 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHC8087L						
04715-T5A-J50ZZ	FACE,RR.BUMPER <i>Deep cut</i>	1	<del>492.70</del> <i>676.10</i>	25	369.52	25.87	395.39
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE <i>cut</i>	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE <i>11</i>	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER <i>neu</i>	7	2.30	25	12.07	0.84	12.91
74552-T5B-003	FENDER,R.RR.INNER <i>11</i>	1	79.00	25	59.25	4.15	63.40
91501-T2A-003	CLIPINNER FENDER <i>11</i>	2	0.40	25	0.60	0.04	0.64
91501-TR0-003	CLIP,INNER FENDER <i>11</i>	4	2.80	25	8.40	0.59	8.99
			<b>Sum Item</b>		<b>475.18</b>	<b>33.27</b>	<b>508.45</b>
BOSUN	SUNDRIES <i>neu</i>	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	100.00	<i>111 X</i>	100.00	7.00	107.00
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	130.00	<i>✓</i>	130.00	9.10	139.10
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	350.00	<i>150</i>	350.00	24.50	374.50
BKBU02R	REPLACE RR BUMPER, REPAIR RR R FENDER & OTHER	1	1200.00	<i>560</i>	1200.00	84.00	1284.00
BP02R	SPRAY PAINTING ON RR BUMPER & RR R FENDER	1	1000.00	<i>450</i>	1000.00	70.00	1070.00
			<b>Sum Labor</b>		<b>2830.00</b>	<b>198.10</b>	<b>3,028.10</b>

Survey By

*Morgan Hahn*  
*18/2/19 @ 9.30*

Date & Time

Excess

*not paid*  
*when job. before job.*  
*2 day.*

**Total Amount** 3,305.18 231.37 3,536.55

**Total (Inclusive of GST)** **3,536.55**

*3442.73*



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

Registration No : SGF8424T

Chassis No : JHMGK3850JX226682

Model : JAZZ 1.3LXR CVT 18YM (EURO 6)

Owner's Name : KHOO WEE BENG

Ins Policy No. :

Date of Accident : 12/2/2019

Document No. : SQT19000700 Page 2

Date : 12. Feb 2019

Customer No. : WZF002

Svc Advisor : LIM CHOU SIONG

Engine No : L13B11031031

Date | Time : 12. Feb 2019 8:19:31 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

Status

Signature

\_\_\_\_\_

\_\_\_\_\_

C S L M  
 810063026HP

LIK Auto Components hereby notify the Repairer of the following:

- To resurvey based on the survey printing;
- To allow the repairer to start during resurvey;
- Parts prices are subject to confirmation;
- The work to be done on a "Without Prejudice" basis;
- No legal proceedings to be allowed;
- Surveyor's report must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by repairer:  
 Signature:  
 Date:

Printed on 14/2/2019 6:26:46 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

 7/3/2019 Page 1/1  
 © SERVICE PRE-INVOICE

Attn: Marcus (L.K.K.)

GST Reg No.: M200050223

Company Ref. No.: S60FC1360G

2 days

<b>Customer:</b>	WZF002 / MS FIRST CAPITAL	<b>Document No:</b>	SVO19014224
<b>Chassis No:</b>	JHMGK3850JX226682	<b>Printed By:</b>	CSLIM
<b>License No:</b>	SGF8424T	<b>Order Date:</b>	5. March 2019
<b>Mileage:</b>	5727	<b>Order Time:</b>	9:49:47 AM
<b>Engine No:</b>	L13B11031031	<b>Service Advisor:</b>	LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incl	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 72275)							
	OWNER: KHOO WEE BENG							
	OWNER INSURER: LIBERTY INSURANCE PTE LTD							
	ACC DATE: 12/2/2019							
	SURVEYED BY: MARCUS (L.K.K.)							
	DATE: 18.02.2019 @ 09:30AM							
	REF NO: D19001114MFSH							
	TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED							
	TP VEH: SHC8087L							
71501-T5A-J60ZH	FACE RR.BUMPER	1	676.10	25	507.07	35.49	542.56	
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56	
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91	
	<b>SUM PARTS:</b>				<b>531.81</b>	<b>37.22</b>	<b>569.03</b>	
BOSUN	0760	1	20.00		20.00	1.40	21.40	
	SUNDRIES							
BA02R	EXT-YJ	1	130.00		130.00	9.10	139.10	
	REMOVE & INSTALL REVERSE							
	SENSORS-4 PCS (N)							
BMI03D	EXT-YJ	1	150.00		150.00	10.50	160.50	
	REMOVE & INSTALL REAR							
	COMPARTMENT LININGS							
	GARNISHES.(N)							
BKBU02R	EXT-YJ	1	580.00		580.00	39.20	599.20	
	REPLACE RR BUMPER & OTHER							
	DAMAGE PARTS.							
BP02R	EXT-YBH	1	450.00		450.00	31.50	481.50	
	SPRAY PAINTING ON RR BUMPER							
	<b>SUM LABOUR:</b>				<b>1,310.00</b>	<b>91.70</b>	<b>1,401.70</b>	
	<b>TOTAL SGD</b>				<b>1,841.81</b>	<b>128.92</b>	<b>1,970.73</b>	
	<b>Total Payable (SGD)</b>						<b>1,970.73</b>	

GST Amount is calculated from individual line(s)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19002910/Uqd3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-03-2019



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8087L	Veh. Inspected	SGF 8424T
Policy No.		Coverage (\$)	0.00
Claim No.	D19001114MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	15/02/2019

## 2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ (A)	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JHMGK3850JX226682	Colour	BLUE
Odometer	5204	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	7 mm
L/H Front Tyre	175/65 R15	DUNLOP	7 mm
R/H Rear Tyre	175/65 R15	DUNLOP	7 mm
L/H Rear Tyre	175/65 R15	DUNLOP	7 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	12/02/2019	Inspection Date	18/02/2019
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGF 8424T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FACE.RR BUMPER (SN)	DEEP CUT	507.07	507.07
1	SPACER.R.RR BUMPER SIDE (SN)	BENT	12.67	12.67
1	SPACER.L.RR BUMPER SIDE (SN)	NOT NECESSARY	12.67	-
7	CLIP,BUMPER (SN)	NECESSARY	12.07	12.07
1	FENDER.R.RR INNER (SN)	NOT NECESSARY	59.25	-
2	CLIPINNER FENDER (SN)	NOT NECESSARY	0.60	-
4	CLIP,INNER FENDER (SN)	NOT NECESSARY	8.40	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			662.73	551.81
<b>LABOUR</b>				
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.	NOT NECESSARY	100.00	-
	REMOVE & INSTALL REVERSE SENSORS-4 PCS.		130.00	130.00
	REMOVE & INSTALL REAR COMPARTMENT LININGS.		350.00	150.00
	REPLACE RR BUMPER,REPAIR RR R FENDER & OTHER.		1,200.00	560.00
	SPRAY PAINTING ON RR BUMPER & RR R FENDER.		1,000.00	450.00
			2,780.00	1,290.00
<b>GRAND TOTAL</b>			<b>3,442.73</b>	<b>1,841.81</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,841.81</b>

Report Ref No. CS/FC119002910/Uqd3n2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.