

CASE OWNER:

CC 4/15/2019 1900 2926, Apr 29, 2019

LKA:

IDAC

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler

Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher: (NO NEED)

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LOP

Repair Cost:

43 \$5,900

(9 days) Reduction:

39 %

Email

Call

FINAL SETTLEMENT

Date/Time: 25.11.19

Confirm with Pti Gen

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

Repair Cost:

\$5,900

Loss of Rental (LOR):

\$5,900

(9 days)

Loss of Use (LOU):

\$5,900

(\$ 80 x n days)

Loss of Income (LOI):

\$5,900

(\$ x n days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5,900

Medical:

\$5,900

Disbursement:

\$5,900

(e.g. Tow/ Independent)

Legal Cost

\$5,900

Total:

\$5,900

Global Sum SS:

FINAL PAYMENT

Date/Time: 25.11.19

Confirm with Pti Gen

Email

Call

Payee 1:

\$5,900

Name 1:

PROGRESSIVE CAR CARE PTE LTD

PROGRESSIVE CAR CARE PTE LTD

Payee 2: (Strike if N.A.)

\$5,900

Name 2:

Payee 3: (Strike if N.A.)

\$5,900

Name 3:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. _____

at Workshop m/s Progressive

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res: Yes or NoLum Sum: 80 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time _____ Action / Instruction

TP EQ.

COE Exp: 09/05/21

45 \$9400 with 9 repair days

MV: 16K.

PV: 10.3K.

Nett: 5.7K.

(Red = \$3436.76 / 397.)

Veh No: SD4724J Yr Regn: 2006 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic cc 1799Colour: White A/C: Insured / Std / NI / NASp. Reading 166/83 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMFD163065207896Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 15/02/19Survey held at Progressive (ubi)Des. of Damages: Frt / Rear O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

Date/Time, File Return to?

1)	2)
3)	4)
5)	6)
Prel. Report:	
Final Report:	

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S: EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD, #17-00

TOWER BLOCK MND COMPLEX

SINGAPORE 069110

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

Your Ref No: TP 0219-5397

Claim Type: Third Party

Accident Date: 12/02/2019

TP Veh Reg No: XD 9511 C

Estimate No: EST1504565

Date: 13 Feb 2019

Policy No: P10058067R00

Veh Reg No: SDU7244J

Make/Model: HONDA CIVIC 1.8L A

Chassis No: JHMFD16306S207896

Engine No: R18A11026745

Reg. Date: 10/05/2006

Estimate Repair Cost to Vehicle No : SDU7244J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Special Net				
1 ROCKER PANEL OUTER GARNISH - RH <i>to be</i>	800.00	1 PC	800.00 600	
2 TYRE RIM - RH <i>to be</i>	800.00	1 PC	800.00 480	
3 FRONT TYRE - RH <i>new</i>	280.00	1 PC	280.00	
4 PETE R STICKER <i>new</i>	180.00	1 PC	180.00 50	
5 SEALANT <i>new</i>	20.00	2 PC	40.00	
6 SPONGE TAPE <i>new</i>	20.00	1 PC	20.00	
				2,120.00

Spare Parts

7 ROCKER PANEL - RH <i>Rep</i>	180.00	1 PC	180.00	
8 REAR FENDER - RH <i>Dist</i>	480.00	1 PC	480.00	
9 REAR FENDER COWLING - RH <i>new</i>	15.00	1 PC	15.00	
10 REAR BUMPER <i>Dist</i>	185.00	1 PC	185.00	
11 REAR BUMPER CLIPS <i>new</i>	1.00	10 PC	10.00	
12 REAR BUMPER SIDE HOLDER - RH <i>new</i>	10.00	1 PC	10.00	
13 REAR BUMPER SIDE HOLDER - RH <i>new</i>	10.00	1 PC	10.00	
14 FRONT DOOR - RH <i>Dist</i>	430.00	1 PC	430.00	
15 FRONT DOOR PROTECTOR W/CHROME ASSY - RH <i>new</i>	50.00	1 PC	50.00	
16 FRONT DOOR RUBBER - RH <i>new</i>	75.00	1 PC	75.00	
17 FRONT DOOR OUTER CHANNEL MOULDING - RH <i>new</i>	55.00	1 PC	55.00	
18 FRONT DOOR STICKER - RH <i>new</i>	25.00	1 SET	25.00	
19 REAR DOOR - RH <i>Dist</i>	430.00	1 PC	430.00	
20 REAR DOOR PROTECTOR W/CHROME ASSY - RH <i>missing</i>	45.00	1 PC	45.00	
21 REAR DOOR RUBBER - RH <i>new</i>	55.00	1 PC	55.00	
22 REAR DOOR OUTER CHANNEL MOULDING - RH <i>new</i>	50.00	1 PC	50.00	
23 REAR DOOR STICKER - RH <i>new</i>	25.00	1 SET	25.00	
24 REAR DOOR OUTER CHANNEL MOULDING - RH <i>new</i>	55.00	1 PC	55.00	
25 REAR DOOR REGULATOR GEAR W/MOTOR - RH <i>new</i>	195.00	1 PC	195.00	
			2,380.00	
		Add 15%	357.00	2,737.00

Labour

26 TO KNOCK OUT DENTS, CUT/WELD RH ROCKER PANEL, REAR FENDER RH, REMOVE, REPLACE ACCIDENT PARTS	1,100.00	1 JOB	1,100.00 1000	
27 TO RESPRAY PAINT ON ACCIDENT PORTIONS	1,100.00	1 JOB	1,100.00 1000	
28 TO CHECK WIRING	20.00	1 JOB	20.00	

Progressive Car Care Pte Ltd

Bik 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : EQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD, #17-00

TOWER BLOCK MND COMPLEX

SINGAPORE 069110

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

Your Ref No: TP 0219-5397

Claim Type: Third Party

Accident Date: 12/02/2019

TP Veh Reg No: XD 9511 C

Estimate No: EST1504565

Date: 13 Feb 2019

Policy No: P10058067R00

Veh Reg No: SDU7244J

Make/Model: HONDA CIVIC 1.8L A

Chassis No: JHMFD16306S207896

Engine No: R18A11026745

Reg. Date: 10/05/2006

Estimate Repair Cost to Vehicle No : SDU7244J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
29 TO TRANSFER RH 2 DOORS AND DOOR FITTING	160.00	1 JOB	160.00 ✓	
30 TO REMOVE, REFIX REAR GARNISH	80.00	1 JOB	80.00 50	
31 TO REMOVE, REPLACE RH REAR TYRE RIM AND BALANCING	45.00	1 JOB	45.00 ✓	
32 TO REMOVE, REFIX REAR BOOT GLASS	120.00	1 JOB	120.00 ✓	
				2,625.00

2385 ✓

Total SS 7,482.00

Add GST @ 7% 523.74

Total Amount payable SS 8,005.74

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND AND FIVE AND CENTS SEVENTY FOUR ONLY

For Progressive Car Care Pte Ltd

Supplementary: 1300.50

total: 6771.50

1/5: 5.4K.

AUTHORISED SIGNATURE

Adrian Ling

1/5 15/02/19.

Not Authorised, 89 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408710
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@progressivecarcare.com.sg
 GST:201006949C RCB NO:201006949C

- Link Auto Consultants hence notify the following:
- Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

M/S : EQ INSURANCE COMPANY LIMITED
 5 MAXWELL ROAD, #17-00
 TOWER BLOCK MND COMPLEX
 SINGAPORE 069110

TEL: 62239433 FAX: 62243903

ATTN: Motor Claim Department

Your Ref No: TP 0219-5397

Claim Type: Third Party

Accident Date: 12/02/2019

TP Veh Reg No: XD 9511 C

Estimate No: EST1504565
 Acknowledged by Repairer
 Signature: _____
 Date: 19 Feb 2019
 Policy No: P10058067R00

Veh Reg No: **SDU7244J**
 Make/Model: HONDA CIVIC 1.8L A
 Chassis No: JHMFD16306S207896
 Engine No: R18A11026745
 Reg. Date: 10/05/2006

Estimate Repair Cost to Vehicle No : SDU7244J

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
Supplementary Parts to Repair				
Spare Parts				
1 REAR ABSORBER - RH <i>Best</i>	115.00	1 PC	115.00	✓
2 REAR KNUCKLE ARM - RH <i>Best</i>	195.00	1 PC	195.00	✓
3 REAR KNUCKLE ARM BEARING - RH <i>Best</i>	233.36	1 PC	233.36	✓
4 REAR TOP ARM - RH <i>Best</i>	65.00	1 PC	65.00	✓
5 REAR LOWER ARM - RH <i>Best</i>	265.00	1 PC	265.00	✓
			873.36	
			131.00	1,004.36
		Add 15%		
Labour				
6 TO 4 WHEEL ALIGNMENT	100.00	1 JOB	100.00	80
7 TO REMOVE, REPLACE R/R UNDERCARRIAGE	250.00	1 JOB	250.00	220
				350.00

Adrian Lj
 28/02/19.

Total SS 1,354.36
 GST Amount SS 94.81
 Total Amount payable SS 1,449.17

Supplementary. 1300.50

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

6887276



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER	PROGRESSIVE	DATE	Feb 20, 2019 3:12:40 PM
LICENSE NO.	SDU 7244 J		
MILEAGE	166188		
REFERENCE	CUSTOM	MODEL	HONDA CIVIC (FD)

Front Wheel SPECS DIAGNOSIS ADJUSTMENT

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			0.40				0.00		
PARTIAL TOE	-0.50	0.00	0.50		-2.50		2.90		0.00		0.00	
SET BACK	---	---	---			0"00"				0"00"		
CAMBER	-1°00'	0°00'	1°00'		-0°02'		0°02'	0°06"	-0°02'		0°00'	0°04"
CASTER	5°30'	6°30'	7°30'		6°32'		6°34'	0°02'	6°32'		6°34'	0°02"
KING-PIN	---	---	---		12°36'		12°56'	0°18"	12°36'		12°56'	0°18"
INCL ANGLE	---	---	---		12°32'		12°58'		12°32'		12°56'	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel SPECS DIAGNOSIS ADJUSTMENT

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			-0.70				1.90		
PARTIAL TOE	0.00	0.50	1.00		1.90		-2.70		0.90		0.90	
SET BACK	---	---	---			0"12"				0"12"		
CAMBER	-2°00'	-1°00'	0°00'		-1°58'		-2°04'	0°06"	-2°06'		-2°18'	0°12"
THRUST ANGLE	-0°08'	0.00	0°08'			0°22"				0°00"		



COMPUTERIZED ALIGNMENT SPECIALISTS

CUSTOMER PROGRESSIVE DATE Feb 18, 2019 5:30:19 PM
 LICENSE NO. SDU 7244 J
 MILEAGE 166186
 REFERENCE CUSTOM MODEL HONDA CIVIC (FD)

Front Wheel

SPECS

DIAGNOSIS

ADJUSTMENT

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	-1.00	0.00	1.00			0.50				0.40		
PARTIAL TOE	-0.50	0.00	0.50		-2.80		3.30		0.20		0.20	
SET BACK	---	---	---			0°00'				0°00'		
CAMBER	-1°00'	0°00'	1°00'		-0°06'		0°06'	0°14'	-0°08'		0°12'	0°20'
CASTER	5°30'	6°30'	7°30'		6°52'		6°44'	0°06'	6°52'		6°44'	0°06'
KING-PIN	---	---	---		12°54'		12°46'	0°06'	12°54'		12°46'	0°06'
INCL ANGLE	---	---	---		12°46'		12°54'		12°44'		13°00'	
Toe-out on turns	---	---	---		---		---		---		---	
STEERING IN	---	---	---		---		---		---		---	
STEERING OUT	---	---	---		---		---		---		---	

Rear Wheel

SPECS

DIAGNOSIS

ADJUSTMENT

	min	prv	max	Δ	L	total	R	Δ	L	total	R	Δ
TOTAL TOE	0.00	1.00	2.10			-2.70				-2.70		
PARTIAL TOE	0.00	0.50	1.00		1.70		-4.50		1.70		-4.50	
SET BACK	---	---	---			0°10'				0°10'		
CAMBER	-2°00'	-1°00'	0°00'		-2°06'		-3°14'	1°08'	-2°06'		-3°14'	1°06'
THRUST ANGLE	-0°08'	0.00	0°08'			0°30'				0°30'		

> Back to OneMotoring

-Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3325B
Vehicle Details	
Vehicle No.:	SDU7244J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	R18A11026745
Chassis No.:	JHMFD16306S207896
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,907.00
Original Registration Date:	10 May 2006
First Registration Date:	10 May 2006
Transfer Count:	1
Actual ARF Paid:	\$22,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	09 May 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$23,024.00
COE Rebate Amount:	\$10,280.00
Total Rebate Amount:	\$10,280.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 15 Feb 2019

OK



126 vehicles **Search** [Advanced Search](#)

Search Selection

[illegible]


☐ Honda Civic 1.8A VTI-S (COE till 01/2021)

\$19,800	\$10,090 /yr	22-Feb-2006	1,799 cc	165,000 km	Sedan	Available
----------	--------------	-------------	----------	------------	-------	-----------

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐

Honda Civic 2.0A (COE till 03/2026)

\$42,000

\$5,930 /yr

17-Mar-2006

1,998 cc

-

Sedan

Available

Current Owner Have Spend Tons Of Money To Rebuild His Vehicle. New Shock Absorbers, New Fuel Tank And Full Overhaul Gearbox At Specialist, New Paintwork With Bidded Number Plate. Next Owner Will Buy W...

Published: 25-Sep-2019
Tags:
2006 Honda Civic, 2006 Honda Civic, Honda Civic, Honda Civic, Honda Civic, Civic, Civic, Used Honda

 **Honda Civic 1.8A (COE till 05/2021)** \$19,800 \$8,890 /yr 09-May-2006 1,799 cc 229,500 km Sedan Available

Excellent Condition Vehicle. Can Last Till End Of COE Without Any Problem. Almost Every Part Changed And Repaired When Bought Over. Fuss Free And Major Servicing Done Up. No Need To Repair. Loan And I...

Product: 11 Jan 2016 Tags: 1800 Honda Civic, 1800 Honda Civic, Honda Civic, honda civic, Honda Civic, civic, Used Honda

Honda Civic 1.8A VTI (COE till 06/2021)	\$16,800	\$7,280 /yr	07-Jun-2006	1,799 cc	-	Sedan	Available
--	----------	-------------	-------------	----------	---	-------	-----------

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 14 February 2019 3:57 PM
To: assignments
Cc: Admin A
Subject: FW: PROGRESSIVE/TP/SDU 7244 J (XD 9511 C)/DOA 12.02.2019/EST \$7482.00
Attachments: 14022019141311.pdf; SAS2551644.PDF

12.16pm @ 15/2/19
person @ Lily
vehicle not in

Dear Catherine

Attach both parties report and estimate.

Please attend to the PRS as SJE and proceed to direct settle if possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Peiwen [mailto:peiwen@procarcare.com.sg] **On Behalf Of** Claims
Sent: Thursday, February 14, 2019 3:49 PM
To: Janet Tan <janet.tan@eqinsurance.com.sg>
Cc: Lily <bhlm@procarcare.com.sg>; Soo Leong Keat <lksoo@procarcare.com.sg>
Subject: RE: PROGRESSIVE/TP/SDU 7244 J (XD 9511 C)/DOA 12.02.2019/EST \$7482.00

Hi Janet,

We choose No 6 LKK Auto Consultants Pte Ltd.

Thank You.

Regards,

Pei Wen NG
Claims Advisory
Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 01-45/46 Singapore 408716
T: +65 6741 5336 | F: +65 6741 7208



**With effect from 1 Sep 2018, Progressive Automotive Pte Ltd has been rebranded as Progressive Car Care Pte Ltd. You may now reach us at our new email addresses (@procarcare.com.sg). We look forward to your continued support.*

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]
Sent: Thursday, February 14, 2019 3:34 PM
To: Peiwen
Cc: Lily; Soo Leong Keat
Subject: FW: PROGRESSIVE/TP/SDU 7244 J (XD 9511 C)/DOA 12.02.2019/EST \$7482.00

Without Prejudice
Save As To Costs

Dear Peiwen,

For pre repair survey request, please email to eqiprs@eqinsurance.com.sg

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please **revert within 2 working days** if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662

	Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
11) Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Regards,

Janet Tan
 Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Peiwen [<mailto:peiwen@procarcare.com.sg>] **On Behalf Of** Claims
Sent: Thursday, February 14, 2019 2:15 PM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: Lily <bhlim@procarcare.com.sg>; Soo Leong Keat <lksoo@procarcare.com.sg>
Subject: PROGRESSIVE/TP/SDU 7244 J (XD 9511 C)/DOA 12.02.2019/EST \$7482.00

Hi Sir,

Please refer to the attached and arrange survey.
Vehicle is IN workshop.

Thank You.

Regards,

Pei Wen NG
 Claims Advisory

Progressive Car Care Pte Ltd
Blk 3022A Ubi Road 1 01-45/46 Singapore 408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg



With effect from 1 Sep 2018, **Progressive Automotive Pte Ltd has been rebranded as **Progressive Car Care Pte Ltd**. You may now reach us at our new email addresses (@procarcare.com.sg). We look forward to your continued support.*

Asher Sng (LKKAUTO)

From: Peiwen <peiwen@procarcare.com.sg> on behalf of Claims <claims@procarcare.com.sg>
Sent: Friday, 22 November 2019 5:07 PM
To: Asher Sng (LKKAUTO)
Cc: Claims
Subject: RE: ACCIDENT INVOLVING SDU 7244J AND XD 9511C ON 12/02/2019

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Asher,

Further to your email below, We confirm acceptance.

Please proceed payment.

Thank You.

Regards,

Pei Wen NG

Claims Advisory

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 01-45/46 Singapore 408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg



IMPORTANT NOTICE: The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: Friday, November 22, 2019 12:40 PM
To: Claims; Peiwen
Subject: ACCIDENT INVOLVING SDU 7244J AND XD 9511C ON 12/02/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir,

We refer to the above matter.

ACCIDENT INVOLVING SDU 7244J AND XD 9511C ON 12/02/2019

We propose settlement as follows: -

1. Cost of Repair(w/GST)	\$ 5,778.00
2. Loss of Use (11 days x \$80)	\$ 880.00
3. LTA/GIA search fee	\$ 2.00
4. Towing Fee	\$ 120.00
TOTAL	<u>\$ 6,780.00</u>

Kindly let us have your acceptance.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



THIRD PARTY DISCHARGE VOUCHER

I / we Tin Choo Liang agreed to accept the sum of
S\$ 7000.00 in full and final
settlement of all claims that I / We or may hereafter have against the driver / owner of motor
vehicle no. XD9511C and / or HS Insurance Company Ltd
for damage / loss to motor vehicle no. SDU844J arising from an accident on
12/2/19 along Serangoon Road I / We hereby
authorized you to make payment without admission of liability on the part of
_____ or your insured direct to M/s **PROGRESSIVE CAR CARE PTE LTD**

PROGRESSIVE CAR CARE PTE LTD
Blk 3022A Ubi Road 1 #01-45/46
Singapore 408716
Tel: 6741 5336 Fax: 6741 7208
Email: claims@procarcare.com.sg

SIGNATURE OF CLAIMANT

NRIC

51513325B

SIGNATURE OF WITNESS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ119002926/Aea3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 11-12-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9511C	Veh. Inspected	SDU 7244J	
Policy No.	DMCPHQ18-00705	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	JANET	Assign Date	15/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMFD16306S207896	Colour	WHITE	
Odometer	166183	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	12/02/2019	Inspection Date	15/02/2019	
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDU 7244J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ROCKER PANEL -RH (WCP)	TO REPAIR SEE LABOUR	180.00	-
1	REAR FENDER -RH (WCP)	DISTORTED	480.00	480.00
1	REAR FENDER COWLING -RH (WCP)	NOT NECESSARY	15.00	-
1	REAR BUMPER (WCP)	DEFORMED	185.00	185.00
10	REAR BUMPER CLIPS @\$1.00 (WCP)	NECESSARY	10.00	10.00
1	REAR BUMPER SIDE HOLDER-RH (WCP)	NECESSARY	10.00	10.00
1	REAR BUMPER SIDE HOLDER -LH (WCP)	NOT NECESSARY	10.00	-
1	FRONT DOOR -RH (WCP)	DISTORTED	430.00	430.00
1	FRONT DOOR PROTECTOR W/CHROME ASSY -RH (WCP)	NOT NECESSARY	50.00	-
1	FRONT DOOR RUBBER -RH (WCP)	NOT NECESSARY	75.00	-
1	FRONT DOOR OUTER GARNISH MOULDING -RH (WCP)	NOT NECESSARY	55.00	-
1	SET FRONT DOOR STICKER -RH (WCP)	NECESSARY	25.00	25.00
1	REAR DOOR -RH (WCP)	DISTORTED	430.00	430.00
1	REAR DOOR PROTECTOR W/CHROME ASSY -RH (WCP)	MISSING	45.00	45.00
1	REAR DOOR RUBBER -RH (WCP)	NOT NECESSARY	55.00	-
1	REAR DOOR OUTER CHANNEL MOULDING -RH (WCP)	NOT NECESSARY	50.00	-
1	SET REAR DOOR STICKER -RH (WCP)	NECESSARY	25.00	25.00
1	REAR DOOR OUTER CHANNEL MOULDING -RH (WCP)	NOT NECESSARY	55.00	-
1	REAR DOOR REGULATOR GEAR W/MOTOR -RH (WCP)	NOT NECESSARY	195.00	-
1	REAR ABSORBER -RH (WCP) (ADDITIONAL)	BENT	115.00	115.00
1	REAR KNUCKLE ARM -RH (WCP) (ADDITIONAL)	BENT	195.00	195.00
1	REAR KNUCKLE ARM BEARING -RH (WCP) (ADDITIONAL)	NECESSARY	233.36	230.00
1	REAR TOP ARM -RH (WCP) (ADDITIONAL)	BENT	65.00	65.00
1	REAR LOWER ARM -RH (WCP) (ADDITIONAL)	BENT	265.00	265.00
	COST PLUS 15%		488.00	376.50
			3,741.36	2,886.50
SPECIAL NETT ITEMS				
1	ROCKER PANEL OUTER GARNISH -RH (SN)	TORN	800.00	600.00

Report Ref No. CC4/EQI19002926/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TYRE RIM -RH (SN)	CUT	800.00	480.00
1	FRONT TYRE -RH (SN)	NOT NECESSARY	280.00	-
1	PETER R STICKER (SN)	NECESSARY	180.00	50.00
2	SEALANT @\$20.00 (SN)	NECESSARY	40.00	40.00
1	SPONGE TAPE (SN)	NECESSARY	20.00	20.00
			2,120.00	1,190.00
	LABOUR			
	TO KNOCK OUT DENTS,CUT/WELD RH ROCKER PANEL ,REAR FENDER RH ,REMOVE ,REPLACE ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF ROCKER PANEL -RH.		1,100.00	1,000.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		1,100.00	1,000.00
	TO CHECK WIRING .		20.00	20.00
	TO TRANSFER RH 2 DOORS AND DOOR FITTING.		160.00	160.00
	TO REMOVE ,REFIX REAR GARNISH .		80.00	50.00
	TO REMOVE,REPLACE RH REAR TYRE RIM AND BALANCING.		45.00	45.00
	TO REMOVE ,REFIX REAR BOOT GLASS.		120.00	120.00
	TO 4 WHEEL ALIGNMENT. (ADDITIONAL)		100.00	80.00
	TO REMOVE,REPLACE R/R UNDERCARRIAGE. (ADDITIONAL)		250.00	220.00
			2,975.00	2,695.00
GRAND TOTAL			8,836.36	6,771.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,400.00

Report Ref No. CC4/EQ119002926/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.