



Case Details

Case Reference Number : TAX/02/19/2072
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6070S

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-5721-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : Lonpac Insurance Bhd
 Accident Date and Time : 13/02/2019 05:50 AM
 Vehicle Age(In Months) : 14

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair ▾	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give ▾	
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give ▾	
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	0	0	Not Give ▾	
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0	Not Give ▾	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0	Not Give ▾	
One Time Key In	Main			UNIT , HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0	Not Give ▾	
Total Spare Part Cost									4,439.80		Surveyor Total		0.00	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									4,439.80		Final Sur Total		0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	676.00	250	
Total:			676.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO RESPRAY FRONT FENDER RH	378.00	0	
Total:			756.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO WASH AND VACUUM	60.00	0	
Total:			240.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,439.80	0.00
Total Labour Cost	676.00	250.00
Total Spray Painting	756.00	200.00
Other	240.00	0.00
Overall Total	6,111.80	450.00
Lump Sum Repair Option		☐
Lump Sum Total	0.00	450.00
Surveyor Approved Amount		450.00
No of Repair Days*	5	2
Remarks	-	P/P REPAIR, PHOTO AFTER PAINT.
Surveyor Name		Hwee jie

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

15/02/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: