

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0187/2019/KK
Date : 12-Feb-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Muhammad Aadil Bin Dafir
Address : Blk 671A Edgefield Plains
#16-515
Singapore 821671
Telephone : HP +65 90127124
Type of Claim : Own Damage Claims
Policy No. : 1700050102
Vehicle No : **SLS 2279 H**
Model Code : A3 SEDAN 1.0 TFSI 8V
Model / Year : 14/9/2019
Engine No : CHV 513872
Chassis No : WAUZZZ8V7J1008297
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Feb-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLS 2279 H

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 360.00	✓
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00	✓
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	✓
6	To dismantle rear bumper, rear lid and lhs rear door. Cut out and weld lhs rear fender and lhs bottom plate. Inspect for further damages. Renew rear bumper and lhs rear door. Re-organize crash management components. Reinstall all parts removed.	\$ 7,800.00	3500
7	✓ To respray rear bumper, lhs rear fender, lhs rear door, lhs sill panel, door handle, lhs bottom plate, ✓ door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,500.00	\$3400 6 Main Pieces = 6x550 = 3300 Handle = 100
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
9	To carry out diagnostic check.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		\$ 18,004.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

8/5 22/9

Material List for Accident Vehicle Regn No. ~~SCU 6655-A~~

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER <i>Rehd</i>	\$ 1,793.00	✓
2	STICKY PAD <i>see me</i>	4 \$ 21.00	X
3	REAR BUMPER FIXING PARTS <i>see</i>	\$ 175.00	X
4	ADAPTER - LH ?	\$ 34.00	X ?
5	GUIDE SECTION - LH <i>Rehd</i>	\$ 15.00	✓
6	LOCKING MECHANISM ?	\$ 27.00	?
7	SPOILER - LH <i>see</i>	\$ 216.00	X
8	REAR LIGHT REFLECTOR - LH <i>see</i>	\$ 38.00	X
9	REAR GUIDE SECTION - LH <i>Rehd</i>	\$ 60.00	✓
10	SENSOR <i>see</i>	2 \$ 462.00	+
11	SEAL RING <i>see</i>	4 \$ 12.00	+
12	SIDE PANEL - LH <i>Disturbed</i>	\$ 2,110.00	—
13	REAR WINDOW <i>wh</i>	\$ 742.00	✓
14	SIDE WINDOW - LH <i>re</i>	\$ 520.00	✓
15	BOTTOM PLATE ?	\$ 177.00	?
16	WHEEL HOUSING LINER <i>tom</i>	\$ 223.00	✓
17	REAR WHEEL HOUSING LINER PARTS ?	\$ 81.00	?
18	SIDE DOOR <i>Dented</i>	\$ 2,279.00	✓
19	OUTER DOOR SEAL - LH <i>see</i>	\$ 146.00	✓
20	BONDING AGENT ?	\$ 45.00	?
SUB TOTAL SPARE PARTS CHARGES		\$ 9,176.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLS 2279 H

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	CLEANING SOLUTION ?	\$ 65.00 ?	
22	REAR DOOR ATTACHMENT PARTS ?	\$ 117.00 ?	
23	DOOR CATCH { new	\$ 85.00 x	
24	DOOR CATCH COVER	\$ 14.00 t.	
25	DOOR HANDLE - LH Rpr	\$ 331.00 x	
26	HOUSING - LH Rpr	\$ 47.00 x	
27	MOUTING BAR new	\$ 149.00 x	
28	REAR WINDOW SLOT SEAL TRIM STRIP new	\$ 270.00 t.	
29	TRIM PILLAR C - LH new	\$ 105.00 t.	
30	LED TAIL LIGHT - LH cracked	\$ 800.00 ✓	
31	TRIM TAIL LIGHT - LH new	\$ 27.00 t.	
32	ALUMINIUM RIM 6t	\$ 666.00 ✓	
33	RUBBER VALVE new	4 \$ 13.00 x	
34	ACRYLIC SEALANT 2	S/N \$ 180.00 ✓	
35	CAVITY WAX 2	S/N \$ 140.00 ✓	
36	STONE CHIP 2	S/N \$ 180.00 ✓	
37	METAL FILER POWDER 2	S/N \$ 280.00 ✓	
38	REAR WINDSCREEN SEALANT 2	S/N \$ 200.00 ✓	
39	1/4 GLASS SEALANT 2	S/N \$ 100.00 ✓	
40	SUNDRIES ?	\$ 1,000.00 ?	
TOTAL SPARE PARTS CHARGES		: \$ 13,945.00	
TOTAL LABOUR CHARGES		\$ 18,004.00	
GRAND TOTAL		\$ 31,949.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King
15/02/19.

: not Authorised, 14 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant