

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Md Ishak, Mohd Imran

Date: 26 Feb 2019

Preliminary Advice

Vehicle No	: SGK7733G	Accident Date	: 13/02/2019
Make	: AUDI A5 SPORTBACK	Policy No.	: 2100510672
Assignment Date	: 20/02/2019	Excess	: S\$800.00
Date of Inspection	: 15/02/2019	Est. Duration of Repair	: 18 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	112,435.00
Revised Amount	:S\$	78,914.50
Check Items (Estimated)	:S\$	19,198.50
Total	:S\$	98,113.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	190,000.00
Pre-Accident Value	:S\$	170,000.00
COE / PARF Rebate	:S\$	71,530.00
Salvage Value	:S\$	
Margin for Repair (New for Old Value)	:S\$	118,470.00
Margin for Repair		98,470.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Repairer able to undertake the repair cost not exceeding \$ 98,000.00 on part by part basis.