



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 15.02.2019

India International Insurance Pte Ltd
64 Cecil Street #04/#05
IOB Building
Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2333K TOYOTA VELLFIRE HYBRID (2016)

To Supply

1) 1pc	Rear bumper <i>DE</i> ✓	\$	1,780.57
2) 1set	Rear bumper clip <i>re</i> ✓	\$	30.00
3) 1pc	Rear right bumper tow hook cover <i>scr</i> ✓	\$	27.40
4) 1pc	Rear bumper right side retainer <i>re</i> ✓	\$	92.40
5) 1pc	Rear bumper right reflector <i>bro</i> ✓	\$	72.10
6) 1pc	Tail gate <i>me</i> ✓	\$	1,935.00
7) 1pc	Tail gate "Vellfire" emblem <i>re</i> ✓	\$	70.40
8) 1pc	Tail gate "E-Four" emblem <i>re</i> ✓	\$	77.50
9) 1pc	Tail gate "Hybrid Synergy Drive" emblem <i>re</i> ✓	\$	82.10
10) 1set	Tail gate glass moulding <i>re</i> ✓	\$	245.10
11) 1pc	Rear end panel top garnish <i>DE</i> ✓	\$	357.90
12) 1set	Rear end panel top garnish clip <i>re</i> ✓	\$	40.00
13) 1pc	Rear bumper center right parking sensor (Genuine) ?	\$	569.10
14) 1pc	Rear bumper center right parking sensor cover (Genuine) <i>re</i> ✓	\$	44.50
15) 1pc	Rear bumper right side parking sensor (Genuine) ?	\$	569.10
16) 1pc	Rear bumper right side parking sensor cover (Genuine) <i>re</i> ✓	\$	44.50
17) 1pc	Reverse sensor wire <i>X</i>	\$	228.67
18) 1pc	Right rear corner panel <i>DE</i> ✓	\$	278.50

Sub total parts	\$	6,544.84
Less: 25% discount	\$	1,636.21
	\$	4,908.63

To Supply S.Nett Parts

1) 1pc	Rear bumper top scuff plate <i>pa</i> ✓ <i>price?</i>	\$	461.40
---------	---	----	--------

2) 1tube Sealant

\$ 40.00 ✓

Sub total S.Nett Parts \$ 501.40

L/charges

1) To tuff kote

\$ 50.00 ✓

2) To remove & refit right & center right reverse sensor, reset reverse sensor light. Check wiring

\$ ~~120.00~~ 60

3) To remove and refit rear glass

\$ 120.00 ✓

4) To transfer tail gate trim cover, handle & mechanism part.

\$ ~~100.00~~ 60

5) To knock rear end panel & floor panel, straighten rear right chassis panel. Remove & replace rear bumper, tail gate & etc. Align & adjust rear bumper and tail gate

\$ ~~1,100.00~~ 800

6) To putty, respray painting rear bumper, end panel, right tail lamp corner panel, tail gate inlet & outer, floor panel, tow hook cover & reverse sensor cover in pearl white. To polish

\$ ~~1,300.00~~ 900

Sub total L/charges \$ 2,790.00

Estimated Grand total \$ 8,200.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068

8 days

P/P

15/02/19 @ 1535

Resy 64 paint