

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

Co Reg No : 199405410K

#### **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
	Cust No/Name	LCV07436/TAN SOK KIA (CHEN SHUJIA)		
TAN SOK KIA (CHEN SHUJIA)	Reg No/Reg Date	SMF7897Y / 26/11/201		
BLK 32 TELOK BLANGAH RISE	Date In/Mileage	/ 0		
#04-265	Chassis No KNAHU815VJ7212186			
SINGAPORE 090032	Engine No	D4FDJD025974		
Contact No	Make/Model	KIA/CARENS 1.7 A D SX FL DY6		
	Colour/Trim	9H BLACK CHERRY / WK SATURN BLACK		

Account No Terms D	Date/Time Prin	nted	CSE	Operator		WIP No		
LCV07436 CRDVCH 1	14/02/2019/	10:27	QUA	265 / AndreChow		44404		
	Description o	f Goods	/ Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMA LH SIDE SILL, LH RE		ON LH F	RONT DOOR,	REPAIR LH REAR D	000R,550			1925 2750.00
E PNT88000 REMOVE AND INSTALL	THE DOOR CO	MPONENTS	. FLECTRON	ITCS AND MECHANISM	1			275/ 550.00
A 54900099				The file the similar				179/ 150.00
CHECK WIRING AND CH A 10028901 TO CARRY OUT DIAGNO				TEST				200.00
USING HI-SCAN PRO E PNT98000 RESPRAY ACCIDENT DA REAR FENDER	TEST AMAGED PORTE	ON ON BO	H POOP	उर्देश हो हो हो है	460			1689/ 2100.00
The state of the s	Annual Property of the Control of th		and had	IIII		7		150.00
To Conduct Computer M SUNDRY								240/ 320.00
SUPPLY ANTI CORROS: M SUNDRY	ION FOR AFFE	CTED POR	RTIONS					160.00
SUPPLY BODY SEALAN' M SUNDRY	T FOR AFFECT	ED PORTI	ONS					30/40.00
SUNDRIES								30 / 40.00
M SUNDRY TRANSFER TYRE TO NE	EW SPORTS RI	М						370/ 400.00
M SUNDRY SUPPLY ZERTONA PAIN	NT PROTECTIO	N						400.00
M PANEL ASSY-FRONT DO					1.00	914.00	00.00	914.00 48.00
M W/STRIP ASSY-FR DR M W/STRIP ASSY-FR DR					1.00	105.00		105.00
M W/STRIP-FR DR BODY					1.00	139.00	00.00	139.00
M WHEEL ASSY-ALUMINI			Chie Cste	vechen@IKKauto.Co	m) 1.00	704.00	00.00	704.00
WHIL PAINSICC	SURVEYOR	NAME : _	TIEN COLO					
PIP 6 days	SURVEYOR S	SIGNATUR		831188	13			
Confirm & accepted by	DATE :	21/2/1	19 10.18	sam				
Resury before & ut-	REMARKS:				7% GST on	Net 8770.0		8,770.00 613.90
sping								1.00
					1	otal Payab	ie	9,383.90
Authorized signatory a	and company s	tamp				o cionatura i		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE KIA PTE LTD LENG KEE CUSTOMER SERVICE CENTRE



20 Leng Kee Road Singapore 159094 Tel: 64278800 Fax: 64278811

### TAX INVOICE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
TAN SOK KIA (CHEN SHUJIA)	Cust No/Name LCV07436/TAN SOK KIA (CHEN SHUJI	(A)		
TAN SOR ATA CONEN SHOOTING	Reg No/Reg Date SMF7897Y / 26/11/2018			
BLK 32 TELOK BLANGAH RISE	Date In/Mileage 02/01/2019/ 3137	-		
#04-265 SINGAPORE 090032	Chassis/Package KNAHU815VJ7212186 /KC17P			
SINGAPORE 090032	Engine No D4FDJD025974			
Contact No	Make/Model KIA/CARENS 1.7 A D SX FL DY6			
	Colour/Trim 9H BLACK CHERRY / WK SATURN	BLACK		

	Terms	Date/Time Printed	CSE	Operator		WIP No	THE OWNER OF THE OWNER OF THE OWNER, OR THE OWNER, OR THE OWNER,	e/Credit Note N
CV07436	CRDVCH	02/01/2019/ 16:16	FER	892 / Ferdin		61449	823889	996
SOLMEN AS		Description of Good	s / Services		Qty U	nit Price	Disc%	Amount
Lamp. U ZERTONA Z CARWASH	Total Pa Usual Pri PAINT PR	int Protection incluce: \$568.00 OTECTION COATING		ng for Headlamp & 1	1.00			265.4
COMPLIME		R WASH AND INTERIOR	VACUUM					
Complime	entary Ca	r Wash and Interior en served by Ferdina	vacuum.					
Pls cont KCP17CDC	tact him TP e Service	at 9339 3982 if you  Plan for Caren RP : Servicings:2 x Lubi	require fu		Major)			1387.8
	rice: \$18		- Cution, I	The state of the s				
		KC17P SVC PKG						
to note	that vr	hop such as C&C for warranty does not co	over damage	es/malfunctions				
caused	directly	or indirectly by imp	proper mair	ntenance & repairs				
caused	directly	or indirectly by imp	proper mair	ntenance & repairs				
caused	directly	or indirectly by im	proper mair	ntenance & repairs				
caused	directly	or indirectly by im	proper mair	ntenance & repairs				
caused	directly	or indirectly by imp	proper main	ntenance & repairs				
caused	directly	or indirectly by imp	proper main	ntenance & repairs				
caused		or indirectly by imp		ntenance & repairs				
caused		Guarantee your warro		ntenance & repairs	Carriage."	Nett		
Parts Labour	",	Guarantee your warro	anty, maint	ntenance & repairs		Net: 1653.27		
Parts Labour Standard	". Menu	Guarantee your warro	anty, maint	ntenance & repairs	Carriage." 7% GST on	1653.27	7	115.7
Parts Labour Standard Specialis	Menu st Job	Guarantee your warro	0.00 0.00 0.00 5.42 0.00	ntenance & repairs	Carriage." 7% GST on	1653.27	7 e	1,769.
Parts Labour Standard Specialis Diagnosti	Menu st Job ics Job	Guarantee your warro	0.00 0.00 0.00 5.42 0.00 0.00	ntenance & repairs	Carriage." 7% GST on	1653.27 al Payable Paid	7 e d	1,653.2 115.7 1,769.0 0.0
Parts Labour Standard Specialis	Menu st Job ics Job thers	Guarantee your warro	0.00 0.00 0.00 5.42 0.00 0.00	ntenance & repairs	Carriage." 7% GST on Tota	1653.27	7 e d	1,769.0 0.0



# Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP INDIA

DOA Emailed: TP INDIA 11.02.2019 10/06/19, 7pm

Date survey :

21.02.2019

	VEHICLE NO	: SMF 7897	Y		
	MODEL	: KIA CAREN	NS 1.7 A D SX		
	WIP	: 44404			
	Material	: \$	1,644.00		
	Labour	:_\$	5,130.00		
	Sub-Total	:_\$	6,774.00		
		:	-		
	Less Excess	:_\$	_		
	Total	:_\$	6,774.00		
	GST 7%	:_\$	474.18	1	
	Grand Total	:_\$	7,248.18		
	Finalise By/Date	:LOI/1	10/06/2019	4	
	***			A	•
			_		
<b>/</b>	REVERT BACK OTHERWISE W		S, WITH INVOICING		
	SURVEYOR'S R	EPORT REQUI	IRED		
<b>/</b>	REPAIR TOOK	6 WOR	KING DAYS +	2Days (_1_)	Weekends
	T-0		+	0 Days ( 0 )	Public Holiday
	10	TAL DAYS REF	PAIR TOOK =	8	
<b>/</b>	TP claim St	HA3193G			
	Claim GIA / LTA	fee			
1	Claim Loss of	∐Use / 📝	Rental		
	Claim Medical Fe	e / Others			
	Third Party Repor	rt			
	Timu Faity Repor				



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

#### PRO-FORMA INVOICE

Co Reg No : 199405410K

## THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
INDIA INTERNATIONAL INSURANCE P/L	Cust No/Name	LCV07436/TAN SOK KIA (CHEN SHUJIA)		
THOU THE THOUGHT I TO SHARE THE	Reg No/Reg Date	SMF7897Y / 26/11/2018		
64 CECIL STREET	Date In/Mileage	04/03/2019/ 8522		
#04/05 IOB BUILDING	Chassis/Package	KNAHU815VJ7212186 /KC17P		
SINGAPORE 049711	Engine No	D4FDJD025974		
Contact No	Make/Model	KIA/CARENS 1.7 A D SX FL DY6		
04/03/	Colour/Trim	9H BLACK CHERRY / WK SATURN BLACK		

CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY SUNDRIES M SUNDRY APPLY ZERIONA PAINT PROTECTION S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PANEL ASSY-FRONT DOOR,RH X WHEEL ASSY-ALUMINIUM 1.00 704.00 00.00 TO4.00 X TAPE-FR DR BLACK FRAME UPR,RH 7	Account No	Terms	Date/Time Printed	CSE	Operator	WIP	No		
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT DOOR, REPAIR RH REAR DOOR, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME  E PNT88000 REMOVE AND INSTALL RH FRONT DOOR COMPONENTS, ELECTRONICS AND MECHANISM TO NEW PANEL A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY SUNDRY APPLY ZERTONA PAINT PROTECTION SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PANEL ASSY-ALUMINIUM 1.00 704.00 704.0	CTP00080	Cash	10/06/2019/ 18:53	3 TLA	260 / AiTing	4440	4		
REPLACE DAMAGED PARTS, REPLACE RH FRONT DOOR, REPAIR RH REAR DOOR, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALION BODY GAPS ALIGNMENT TO THE SAME  E PNT88000  REMOVE AND INSTALL RH FRONT DOOR COMPONENTS, ELECTRONICS AND MECHANISM TO NEW PANEL  A 54900099  CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM  A 10028901  CONDUCT DIAGNOSTIC CHECK USING HI-SCAN-PRO TEST AND CLEAR TROUBLE CODE  E PNT98000  RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER  AFFECTED AREAS TO THE SAME  A WHEELALIGNMENTEP  CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT  M SUNDRY  SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  M SUNDRY  SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY  SUNDRY  SUNDRY  APPLY ZERTONA PAINT PROTECTION  S PECIALISTJOB  REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL  BALANCING  X PANEL ASSY-RLUMINIUM  X TAPE-FR DR BLACK FRAME UPR, RH  AND CLEAR TROUBLE CODE  1680.0  270.0  271.00  2			Description of Go	ods / Service	es e e e e e e e e e e e e e e e e e e	Qty Unit P	ice Disc%	An	nount
REMOVE AND INSTALL RH FRONT DOOR COMPONENTS, ELECTRONICS AND MECHANISM TO NEW PANEL A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY APPLY ZERTONA PAINT PROTECTION S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PAANCING X PARANCING X WHEEL ASSY-ALUMINIUM 1.00 704.00 12.00 704.00 12.00 704.00 12.00 704.00 12.00 704.00	REPLACE RH SIDE : ALIGN BO	SILL, RH	REAR FENDER, AND	ALL OTHER A		AND			
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE E PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS M SUNDRY SUNDRY SUNDRY APPLY ZERTONA PAINT PROTECTION SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PANEL ASSY-FRONT DOOR, RH X MHEEL ASSY-ALUMINIUM 1.00 704.00 00.00 12.00 TAPE-FR DR BLACK FRAME UPR, RH TEXT 1.00 1.00 14.00 00.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 14.00 15.00 1680.C	REMOVE AI		L RH FRONT DOOR C	OMPONENTS,	ELECTRONICS AND MECHAI	NISM			2/5.0
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE  PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME  A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT  M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY SUNDRIES  M SUNDRY APPLY ZERTONA PAINT PROTECTION S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PANEL ASSY-FRONT DOOR,RH X WHEEL ASSY-FRONT DOOR,RH X TAPE-FR DR BLACK FRAME UPR,RH APPLY APPLY APPLY ALDMINIUM 1.00 704.00 00.00 12.00 X TAPE-FR DR BLACK FRAME RR RH APPLY APPLY APPLY APPLY APPLY ADDRESSED TO TOOL OF THE APPLY APPLY APPLY APPLY ADDRESSED TO TOOL OF TOOL ON TOOL OF TOOL ON TAPE-FR DR BLACK FRAME RR RH  Z TEXT		RING AND	CHASSIS ELECTRICAL	SYSTEM					120.00
E PNT98000 RESPRAY ON BOTH RH DOORS, RH SIDE SILL, RH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME  A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT  M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY SUNDRIES  M SUNDRY APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING X PANEL ASSY-FRONT DOOR,RH X WHEEL ASSY-ALUMINIUM X TAPE-FR DR BLACK FRAME UPR,RH X TAPE-FR DR BLACK FRAME UPR,RH X TAPE-FR DR BLACK FRAME RR RH X TAPE-FR DR BLACK	A 10028901		10	100 / 100 /				V	200.00
A WHEELALIGNMENTBP CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT  M SUNDRY SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY SUNDRIES  M SUNDRY APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING  X PANEL ASSY-FRONT DOOR, RH X WHEEL ASSY-ALUMINIUM X TAPE-FR DR BLACK FRAME UPR, RH X TAPE-FR DR BLACK FRAME UPR, RH X TAPE-FR DR BLACK FRAME RR RH X TAPE-FR DR BLACK FRAME RR RR X 1.00 X TAPE-FR DR BLACK FRAME RR X 1.0	E PNT98000 RESPRAY (	ON BOTH F	RH DOORS, RH SIDE	(())		11116		1	1680.00
SUPPLY ANTI CORROSION FOR AFFECTED PORTIONS  M SUNDRY SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY SUNDRIES  M SUNDRY APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING  X PANEL ASSY-FRONT DOOR,RH  X WHEEL ASSY-ALUMINIUM X TAPE-FR DR BLACK FRAME UPR,RH X TAPE-FR DR BLACK FRAME RR RH X M/C  I 1.00  12.00  14.00  14.00  14.00  14.00  15.00  16.00  16.00  16.00  16.00  16.00  17.0	A WHEELALIGN	MENTBP		SNMENT				V	150.00
SUPPLY BODY SEALANT FOR AFFECTED PORTIONS  M SUNDRY SUNDRIES  M SUNDRY APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING  X PANEL ASSY-FRONT DOOR,RH X WHEEL ASSY-ALUMINIUM X TAPE-FR DR BLACK FRAME UPR,RH X TAPE-FR DR BLACK FRAME RR RH X TA		NTI CORRO	SION FOR AFFECTED	PORTIONS				~	240.00
SUNDRIES  M SUNDRY  APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB  REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL  BALANCING  X PANEL ASSY-FRONT DOOR, RH  X WHEEL ASSY-ALUMINIUM  X TAPE-FR DR BLACK FRAME UPR, RH  Z TEXT  320.0  30.0  10.0  914.00  00.00  914.00  10.0  10.0  10.0  11.0	SUPPLY BO	DDY SEALA	NT FOR AFFECTED PO	ORTIONS				V	
APPLY ZERTONA PAINT PROTECTION  S SPECIALISTJOB  REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL  BALANCING  X PANEL ASSY-FRONT DOOR,RH  X WHEEL ASSY-ALUMINIUM  X TAPE-FR DR BLACK FRAME UPR,RH  X TAPE-FR DR BLACK FRAME RR RH  Z TEXT  30.0  914.00  914.00  00.00  12.00  10.00  14.00  14.00  14.00  14.00  14.00								~	
REPLACE RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL  BALANCING  X PANEL ASSY-FRONT DOOR,RH  X WHEEL ASSY-ALUMINIUM  X TAPE-FR DR BLACK FRAME UPR,RH  X TAPE-FR DR BLACK FRAME RR RH  Z TEXT  1.00 914.00 00.00 914.00 00.00 12.00 12.00 12.00 12.00 14.		RTONA PAI	NT PROTECTION					1	320.00
X WHEEL ASSY-ALUMINIUM  X TAPE-FR DR BLACK FRAME UPR,RH 3  X TAPE-FR DR BLACK FRAME RR RH 3  Z TEXT  1.00	REPLACE F	RH FRONT	SPORTS RIM, REPLAC	CE TIRE VAL	VE, CONDUCT WHEEL			レ	30.00
X TAPE-FR DR BLACK FRAME UPR,RH 3 2 1.00 12.00 00.00 12.0 12.0 12.0 12.0								1	914.00
Z TEXT	X TAPE-FR	R BLACK	FRAME UPR, RH 7	ne				1	12.00
		OR BLACK	FRAME RR RH	bb. Vu		1.00 14	00.00		14.00
		INDIA SH	A3193G	,					
			——————————————————————————————————————		,	<del></del>	-		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

#### PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE P/L	Cust No/Name	LCV07436/TAN SOK KIA (CHEN SHUJIA)
THE THE CHATTOMAE THOU AND CONTROL TYPE	Reg No/Reg Date	SMF7897Y / 26/11/2018
64 CECIL STREET	Date In/Mileage	and the second section is the second section of the second section sec
#04/05 IOB BUILDING	Chassis/Package	KNAHU815VJ7212186 /KC17P
SINGAPORE 049711	Engine No	D4FDJD025974
Contact No	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
04/03/	Colour/Trim	9H BLACK CHERRY / WK SATURN BLACK

Account No	Terms	Date/Ti	ime Pri	nted 🐇			rator		WIP No	All Sections
TP00080	Cash		2019/		TLA		/ AiTing		44404	
		Descr	iption	of Good	ls / Serv	ices		Qty	Unit Price Disc	% Amount
DOA: 11 SURVEYOR REPAIR O	STEVE		1.02.19		$\bigcirc$		OF		3	
		, de la companya de		and be		L		T T T (		
		Vis					120 years. for more in	fo!		
Parts Labour Standard M	anu			1,644	.00			7% GST on	Nett 6774.00	6,774.0 474.1
Specialist Diagnostic	Job			30	.00			Tot	tal Payable	7,248.1

This is not an official tax invoice.
This is a computer generated document, no signature is required.



# Exceptional Journeys

INSURANCE CO.:

INDIA

Supplementary Parts For Registration No.: SMF 7897 Y

	Materials				C	ost (\$)
1 2 3	Tape-fr dr black frame upr, RH Tape-fr dr black frame RR RH	1	NPC NPC			12.00 14.00
				Total		26.00
				7% GST		1.82
				Grand total	\$	27.82

Thank You.

Yours faithfully

LOI AI TING

CUSTOMER SERVICE ADVISOR

KIA SERVICE CENTRE

DID: 6568 4556 / 6568 4501 FAX: 6567 5258 / 6565 1240