

**DING AUTOMOTIVE PTE LTD**

Blk 10 Sin Ming Industrial Estate Sector C

#01-20

Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

**ESTIMATE REPORT** 1ST Quotation

16/02/2019 9:54

JOB-NO: 50111419

**OWNER'S PARTICULARS**

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE  
SINGAPORE 575717 0

64739522

**VEHICLE DETAILS**

LICENSE NO: SHA8520M

TRANS: AUTO

CHASSIS: JTDKB3FU503557032

MAKE / MODEL: TOYOTA / Prius Hybrid 1.8 CVT

ENGINE: 2ZRS043383

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

**CLAIM DETAILS**

| DESCRIPTION                                                    | QTY  | QUOTED COSTS | DISCOUNT | DISC PRICE | IND | SUR.DISP | REV PRICE |
|----------------------------------------------------------------|------|--------------|----------|------------|-----|----------|-----------|
| <b>LABOUR</b>                                                  |      |              |          |            |     |          |           |
| 1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS                     | 1.00 | 1,600.00     | 0.00     | 1,600.00   | Y   |          | 400       |
| 2 R&R SPARE TYRE / CARPET / TRIM / BOARD & ETC                 | 1.00 | 180.00       | 0.00     | 180.00     | Y   |          | 60        |
| 3 R&R REAR EXHAUST PIPE & MUFFLER                              | 1.00 | 180.00       | 0.00     | 180.00     | Y   |          | 60        |
| 4 R&R REVERSE SENSOR                                           | 1.00 | 80.00        | 0.00     | 80.00      | Y   |          | 40        |
| 5 RUST PROOFING                                                | 1.00 | 120.00       | 0.00     | 120.00     | Y   |          | X         |
| 6 SUNDRIES                                                     | 1.00 | 80.00        | 0.00     | 80.00      | Y   |          | X         |
| 7 TO RESETING & RECORDING TAIL LAMP (LED)                      | 1.00 | 150.00       | 0.00     | 150.00     | Y   |          | X         |
| 8 CHECK WIRING & REPAIR WIRING & DIAGNOSTIC (CLEAR FAULT CODE) | 1.00 | 200.00       | 0.00     | 200.00     | Y   |          | 30        |
| 9 R&R ROOF LINING TO REPAIR REAR WINDSCREEN PILLAR LH          | 1.00 | 250.00       | 0.00     | 250.00     | Y   |          | X         |
| 10 TOWING SERVICE                                              | 1.00 | 120.00       | 0.00     | 120.00     | Y   |          | 40        |
| 11 RESPRAY REAR BUMPER                                         | 1.00 | 250.00       | 0.00     | 250.00     | Y   |          | 200       |
| 12 RESPRAY REAR BUMPER DIFFUSER EXTENSION LH                   | 1.00 | 150.00       | 0.00     | 150.00     | Y   |          | 80        |
| 13 RESPRAY REAR BUMPER DIFFUSER EXTENSION RH                   | 1.00 | 150.00       | 0.00     | 150.00     | Y   |          | 80        |
| 14 RESPRAY REAR END PANEL                                      | 1.00 | 250.00       | 0.00     | 250.00     | Y   |          | 200       |
| 15 RESPRAY SPARE TYRE PANEL                                    | 1.00 | 250.00       | 0.00     | 250.00     | Y   |          | 100       |
| 16 RESPRAY REAR WINDSCREEN PILLAR LH                           | 1.00 | 250.00       | 0.00     | 250.00     | Y   |          | X         |
| 17 RESPRAY REVERSE SENSOR                                      | 1.00 | 80.00        | 0.00     | 80.00      | Y   |          | X         |
| TOTAL:                                                         |      | 4,340.00     | 0.00     | 4,340.00   |     |          |           |

**MATERIALS**

|                                     |      |        |        |        |   |   |  |
|-------------------------------------|------|--------|--------|--------|---|---|--|
| 1 REAR BUMPER                       | 1.00 | 490.50 | 122.63 | 367.87 | L | Y |  |
| 2 REAR BUMPER REINFORCEMENT         | 1.00 | 318.80 | 79.70  | 239.10 | L | Y |  |
| 3 REAR BUMPER RETAINER LH           | 1.00 | 92.30  | 23.08  | 69.22  | L | Y |  |
| 4 REAR BUMPER RETAINER RH           | 1.00 | 92.30  | 23.08  | 69.22  | L | Y |  |
| 5 REAR BUMPER MUD-FLAPS LH          | 1.00 | 95.03  | 23.76  | 71.27  | L | Y |  |
| 6 REAR BUMPER DIFFUSER              | 1.00 | 558.30 | 139.58 | 418.72 | L | Y |  |
| 7 REAR BUMPER EXTENSION DIFFUSER LH | 1.00 | 119.90 | 29.98  | 89.92  | L | Y |  |
| 8 REAR BUMPER EXTENSION DIFFUSER RH | 1.00 | 119.90 | 29.98  | 89.92  | L | Y |  |
| 9 REAR BUMPER TOWING CAP            | 1.00 | 35.60  | 8.90   | 26.70  | L | Y |  |
| 10 REAR BUMPER LOWER COVER LH       | 1.00 | 154.60 | 38.65  | 115.95 | L | Y |  |
| 11 REAR BUMPER LOWER COVER RH       | 1.00 | 154.60 | 38.65  | 115.95 | L | Y |  |
| 12 REAR BUMPER LOWER CENTER         | 1.00 | 522.60 | 130.65 | 391.95 | L | Y |  |

## CLAIM DETAILS

| DESCRIPTION                              | QTY  | QUOTED COSTS | DISCOUNT | DISC PRICE | IND   | SUR.DISP | REV PRICE |
|------------------------------------------|------|--------------|----------|------------|-------|----------|-----------|
| 13 TAIL LAMP UPPER LH ?                  | 1.00 | 438.10       | 109.53   | 328.57     | L     | Y        |           |
| 14 TAIL LAMP BOTTOM LH ?                 | 1.00 | 486.80       | 121.70   | 365.10     | L     | Y        |           |
| 15 REAR EXHAUST PIPE & MUFFLER 100       | 1.00 | 854.10       | 213.53   | 640.57     | L     | Y        |           |
| 16 REAR EXHAUST MUFFLER HEATER SHIELD    | 1.00 | 320.25       | 80.06    | 240.19     | L     | Y        |           |
| 17 REAR EXHAUST PIPE GASKET              | 1.00 | 55.60        | 13.90    | 41.70      | L     | Y        |           |
| 18 REAR EXHAUST PIPE SUPPORT RUBBER LH X | 1.00 | 49.58        | 12.40    | 37.18      | L     | Y        |           |
| 19 REAR EXHAUST PIPE SUPPORT RUBBER RH   | 1.00 | 49.58        | 12.40    | 37.18      | L     | Y        |           |
| 20 REAR RIDE HEIGHT SENSOR ?             | 1.00 | 652.43       | 163.11   | 489.32     | L     | Y        |           |
| 21 REAR END PANEL x repair               | 1.00 | 629.80       | 157.45   | 472.35     | L     | Y        |           |
| 22 REAR BUMPER EXTENSION DIFFUSER        | 1.00 | 25.00        | 0.00     | 25.00      | 10 S  | Y        |           |
| RETAINER LH                              |      |              |          |            |       |          |           |
| 23 REAR BUMPER EXTENSION DIFFUSER        | 1.00 | 25.00        | 0.00     | 25.00      | 10 S  | Y        |           |
| RETAINER RH                              |      |              |          |            |       |          |           |
| 24 REAR BUMPER CLIP SET                  | 1.00 | 35.00        | 0.00     | 35.00      | 30 S  | Y        |           |
| 25 REAR BUMPER RUBBER PROTECTOR PAD      | 1.00 | 150.00       | 0.00     | 150.00     | 80 S  | Y        |           |
| 26 REAR REVERSE SENSOR                   | 1.00 | 230.00       | 0.00     | 230.00     | 200 S | Y        |           |
| 27 REAR BUMPER SCREW & GROMMET SET       | 1.00 | 35.00        | 0.00     | 35.00      | 20 S  | Y        |           |
| 28 REAR END PANEL SEALANT X              | 1.00 | 50.00        | 0.00     | 50.00      | S     | Y        |           |
| 29 REPAIR SPARE TYRE PANEL x repair      | 1.00 | 0.00         | 0.00     | 0.00       | S     | Y        |           |
| 30 SPARE TYRE PANEL INSULATOR PAD        | 1.00 | 200.00       | 0.00     | 200.00     | S     | Y        |           |
| 31 REPAIR REAR WINDSCREEN PILLAR LH      | 1.00 | 0.00         | 0.00     | 0.00       | S     | Y        |           |
| TOTAL:                                   |      | 7,040.67     | 572.72   | 5,467.95   |       |          |           |
| No Consistent to Accident.               |      |              |          |            |       |          |           |
| TOTAL PARTS & LABOUR :                   |      | 11,380.67    | 1,572.72 | 9,807.95   |       |          |           |

EXCESS/LOADING:\$ 0.00

No. Of Day: 5

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 18/12/19

SURVEYED BY: Guo Qiang. 4pm.

CONTACT NO: 82880282

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: