

Marius.

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

*not Authorised
lower
p/p #3388.31
Hdy.*

DATE 15/2/2019

M/S INDIA INTERNATIONAL INSURANCE PTE LTD

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GB48029E

List Items

1	1 PC	FRONT BUMPER	Dis	\$ 514.70	✓
2	1 PC	FRONT BUMPER CLIPS x10	see	\$ 50.00	✓
3	2PCS	FRONT BUMPER SIDE RETAINER	mscm	\$ 147.00	✓ c 73.50
4	1 PC	FRONT LH FOG LAMP	17	\$ 311.80	X
5	1 PC	FRONT LH HEADLAMP	17	\$ 366.40	X
6	1 PC	FRONT LH STEP GARNISH	To	\$ 44.30	✓
7	1 PC	FRONT LH DOOR	W/Bit	\$ 1,015.00	✓
8	1 PC	FRONT LH DOOR HINGE / inner	twi	\$ 56.10	✓
9	1 PC	FRONT LH WHEEL CAP	n	\$ 151.20	X
10	1 PC	FRONT OIL COOLER	Part/241	\$ 672.30	✓
				\$ 3,328.80	
			LESS 10% PARTS DISCOUNT	\$ (332.88)	
				\$ 2,995.92	
11		WHEEL ALIGNMENT		\$ 120.00	60
12		TUFF KOTE		\$ 120.00	30
13		To remove and refit wire electrical wiring and test for proper function		\$ 30.00	20
14		Labour charges to remove and replace the above damaged parts		\$ 880.00	400
15		To spray paint		\$ 860.00	600
				\$ 5,005.92	

16. Door sticker \$15 S-nett. see ✓

2-242590
102
P-218331
S.N-15.00
labu-1190.00
3388.31

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 3
Acknowledged by Repairer
Signature:
Date: