



# HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

HHTPClaims19-14

15 February 2019

India International Insurance Pte Ltd  
64 Cecil Street, IOB Building  
#04-00 / #05-00  
Singapore 049711

Attn: Motor Claims Department

### ACCIDENT INVOLVING SKM 3151 D & SHA 5064 H ON 13/02/2019 ALONG CHANGI AIRPORT T1 NEAR DEPARTURE DOOR 3 AT 1055 HRS

Insured : HUA HONG PTE. LTD.  
Vehicle Registration No : SKM 3151 D  
Vehicle Make : MERCEDES-BENZ  
Vehicle Model : E200 SEDAN (R18)  
Vehicle Chassis No : WDD2120342A921738  
Policy No : 5087272209-01  
Date of Accident : 13/02/2019

Type of Claim: Third Party

| S/N | Quantity | Description   | Unit Price S\$ | Amount S\$                            |
|-----|----------|---|----------------|---------------------------------------|
| 1   | 1        | Rear Door (LH) <i>DI</i>  |                | \$ 1,820.00 ✓                         |
| 2   | 1        | Rear Door Protector (LH) <i>NEC</i>   |                | \$ 145.00 ✓                           |
|     |          |   |                | \$ 1,965.00                           |
|     |          |   | Less 10%       | \$ (196.50)                           |
|     |          |   |                | \$ 1,768.50                           |
| 3   | 1        | Rear Sport Rim (LH) <i>Repair</i>   | NETT           | \$ 950.00 ✗                           |
|     |          | To dismantle & change rear LH door, knocking & pull straight rear LH fender and all area affected by accident |                | \$ <del>750</del> 900.00 ✓            |
|     |          | To perform wire checking  |                | \$ 20.00 ✓                            |
|     |          | To dismantle & refit rear cushion seat, inner trim to facilitate repair                                       |                | \$ <del>50</del> 100.00 ✓             |
|     |          | To dismantle & refit rear RH door fitting and mechanism to new door   |                | \$ <del>50</del> 60.00 ✓              |
|     |          | To dismantle & refit rear LH sport rim  |                | \$ 20.00 ✓                            |
|     |          | To perform 4 wheel alignment  |                | \$ <del>60</del> 100.00 ✓             |
|     |          | To spray rear LH door, rear LH fender and touch up rear bumper  |                | <i>500</i> \$ <del>450</del> 600.00 ✓ |
|     |          |   |                | \$ 4,518.50                           |
|     |          |   | 7% GST         | \$ 316.30                             |
|     |          |   | <b>Total</b>   | <b>\$ 4,834.80</b>                    |



Authorised by Claims Dept  
Mrs Tan @ 9639 9195

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*Hwee Jie - LKK*  
*19/2/19*  
*4/5 4days*  
*egw*