

CUSTOM SPRAY PAINTING PTE LTD

BLK 3019A, UBI ROAD 1, #01-32, SINGAPORE 408713

TEL: 6742 0982 FAX: 6748 8318

Email: csp.ubi@gmail.com

M/s: AIG Asia Pacific Insurance Pte Ltd.

78 Shenton Way,

#07-16.

Singapore 079120.

Date: 13-02-2019

Joy

Attn: Motor Claim Department

Dear Sir / Madam.

Regn No: SLD 1231 E MERCEDES-BENZ C200 AUTO 4 DOOR SALOON.

Re: Estimate Of Repair

With abovementioned vehicle the Estimate Of Repair as follow:-

		<u>Spare Parts Supply.</u>		\$
1pc	Front bumper	Rpr		* 1500.00 Sp Nett
1set	Front bumper clip	n/a		+ 80.00 Sp Nett
1pc	Front n/s sport rims	lt	850	<u>850</u> 1000.00 Sp Nett
				2580.00

Labour to Repair.

Labour to panel beating		500.00	200
Labour to remove and re-install electrical wiring, front bumper sensor assy, computerise scanning re-setting fault codes.		350.00	250 *
labour to remove, replace new sport rim assy, computerise tyre rim balancing	570	80.00	40
Labour to check and adjust 4 wheels computerise wheel alignment		180.00	80
Labour to spray painting		500.00	250
Total Estimate Of Repair		\$ 4,190.00	

This estimate is not inclusive of additional parts and repair at current status.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 28/02/19
03 hrs

total: 1420
L/S: 1.1K