## BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615 TEL: 6289 8800 FAX: 6858 2120 GST. REG NO: 201504834E

Your Vehicle: SLL 5849 E Our Vehicle: SLL 1164 Z

Date: 16/02/2019

M/s AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #07-16 Singapore 079120

Dear Sir,

## ACCIDENT INVOLVING <u>SLL 1164 Z & SLL 5849 E</u> ON <u>09/02/2019</u> ALONG <u>HDB CARPARK</u> <u>DRIVEWAY OF JURONG WEST STREET 65</u>.

We refer to the above matter.

Kindly let us have your list of surveyors for our consideration within the stipulated timeline under the NIMA protocol.

Please be informed that the said vehicle can be inspected at:

## 30 UBI ROAD 4 SINGAPORE 408615

Please note that if you fail to conduct the pre-repair inspection within the next 2 DAYS excluding any intervening Saturday, Sunday and/or Public Holiday, we will commence repairs thereafter without any further notice or reference to you.

Yours Faithfully,

Justin Ee

BW Workshop Service Pte Ltd