

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

*Xiao Tony***Estimate**

To : **AIG INSURANCE PTE LTD** DATE : **15/2/2019**
Attn : **Claims Officer**
CC : **1499** VEHICLE NO : **SLL 1164 Z**
YEAR : **2016** CHASSIS NO : **NHP1707069274**
MODEL : **TOYOTA SIENTA HYBRID 1.5 G** PAGE : **1 OF 1**

Please quote the following items listed.

Third Party Claims

S/NO	NETT ITEM	Qty	Price
1	Rear bumper trim - RH <i>wt</i>	1	\$155.00 ✓
2	Rear rims - RH <i>3w</i>	1	\$450.00 +
3	Rear tyre - 185/60R15 - Bridgestone <i>3w</i>	1	\$195.00 +
		<i>25.</i>	\$800.00
		Discount <i>10%</i>	\$80.00
		TOTAL :	\$720.00

*155**116.25*

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 5289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To	:	AIG INSURANCE PTE LTD	DATE	:	15/2/2019
Attn	:	Claims Officer			
CC	:	1499	VEHICLE NO	:	SLL 1164 Z
YEAR	:	2016	CHASSIS NO	:	NHP1707069274
MODEL	:	TOYOTA SIENTA HYBRID 1.5 G	PAGE	:	1 OF 1

Third Party Claims

S/NO	LABOURS	AMOUNT
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. @ \$300/Per Day's	\$ 300.00 <i>200</i>
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. @ \$280/Per Panel	\$ 600.00 <i>400</i>
3	TO CONDUCT REAR WHEEL ALIGNMENT TEST.	\$ 80.00 <i>+</i>
4	TO CONDUCT TYRE BALANCING TEST.	\$ 50.00 <i>+</i>

Working Days : 3 Days. *600*

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL	:	\$1,030.00
PARTS TOTAL	:	\$720.00
GRAND TOTAL	:	\$1,750.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim
*P/P 19/02/19**03 days**total: 716.25 ✓*
(P/P)