

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE: 18/2/2019

MS AIG INSURANCE

Dear sir

HYUNDAI ELANTRA

ESTIMATE REPAIR COST FOR SKU7762Y

NO	QTY	DESCRIPTION
1	1 PC	FRONT BUMPER
2	1 PC	FRONT BUMPER SPONGE
3	10 PCS	FRONT BUMPER CLIPS
4	1 PC	FRONT BUMPER REINFORCEMENT
5	1 PC	FRONT BUMPER SIDE RETAINER
6	1 PC	FRONT BUMPER BEAM
7	1 PC	FRONT HEADLAMP
8	1 PC	FRONT SUPPORT PANEL
9	1 PC	FRONT LH FENDER
10	1 PC	FRONT LH FENDER SHEILD
11	1 PC	FRONT LH FENDER CLIPS
12	1 PC	LH FOG LAMP

Dis	\$ 428.00
Torn	\$ 118.70
ru	\$ 40.00
Scp	\$ 515.00
Scp	\$ 41.00
Scp	\$ 168.50
cm	\$ 858.20
n	\$ 949.00
n	\$ 460.80
de	\$ 88.00
ru	\$ 20.00
one	\$ 223.00

\$3,910.20

\$ (391.02)

\$3,519.18

13	CHECK HARNESS
14	SPRAY PAINTING FOR DAMAGE PORTIONS
15	LABOUR CHARGE TO REPLACE /REPAIR DAMAGED
16	TUFF COAT

\$ 40.00	20
\$ 780.00	500
\$ 880.00	400
\$ 80.00	X

\$5,299.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer

Signature:

Date:

not Authorized
Hale
4/5 @ 2350
3 day.
18/2/19
Telenghe Hharap -

202

7- 2500.4
2000.32
2970.32