

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ZHAN YU TRANSPORT
BLK 275C JURONG WEST ST25
#12-79
S 643275

TPAXA
Joy

Date : 27.02.2019
Vehicle no : SKT 2171 R
Make/Model : VOLKSWAGEN TOUR
Accident date : 03.02.2019

No	DESCRIPTION	Qty	Amount (S\$)
<u>List Items</u>			
1	Front bumper <i>deformed</i>	1	\$ 836
2	Front bumper side holder @ \$55.00 <i>RH Dmg</i>	2	\$ 110 55
3	Front bumper RH side lower garnish <i>cracked</i>	1	\$ 242
4	Front bumper centre grille <i>Not Nec</i>	1	\$ 385 X
5	Front bumper sponge <i>cracked</i>	1	\$ 49.5
6	Front bumper reinforcement <i>Not Nec</i>	1	\$ 473 X
7	Front bumper clips (1set) <i>Not Nec</i>	1	\$ 60 30
8	Front RH fender <i>Dented</i>	1	\$ 467.5
9	Front RH fender inner shield <i>Not nec</i>	1	\$ 126.5 X
10	Front RH fender inner shield clips (1set) <i>Not nec</i>	1	\$ 60 X
11	Front RH head lamp <i>lit</i>	1	\$ 506
12	Front RH head lamp lower bracket <i>Not nec</i>	1	\$ 44 X
13	Front RH shock absorber <i>Best</i>	1	\$ 286
14	Front RH lower arm <i>Best</i>	1	\$ 308
15	Front RH knuckle arm <i>Best</i>	1	\$ 528
16	Front RH knuckle arm bearing <i>Not nec</i>	1	\$ 440
17	Front RH drive shaft <i>Not nec</i>	1	\$ 1980 X
18	Front grille <i>Not nec</i>	1	\$ 341 X
19	Front wiper tank <i>deformed</i>	1	\$ 121
20	Front engine lower cover <i>cracked</i>	1	\$ 220
21	Steering rack	1	\$ 4356 X
22	Front RH linkage	1	\$ 88 X
23	Front crossmember	1	\$ 1045 X
		Total	\$ 13072.5
<u>Special Nett Items</u>			
1	Front RH sport rim <i>cut</i>	1	\$ 880 450
2	Front RH tyre <i>Not Nec</i>	1	\$ 480 X
		Total	\$ 1360

4089
3680.10

450

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ZHAN YU TRANSPORT
BLK 275C JURONG WEST ST25
#12-79
S 643275

Date :27.02.2019
Vehicle no :SKT 2171 R
Make/Model :VOLKSWAGEN TOURAN
Accident date :03.02.2019

No	DESCRIPTION	Qty	Amount (S\$)
----	-------------	-----	--------------

Labour Cost

- 1 To check wheel alignment
- 2 Remove & reinstall front suspension
- 3 Remove, replace & repair consistent to the accident
- 4 Respray Painting

	\$	100 80
	\$	500 220
	\$	1600 500?
	\$	1200 500
Total	\$	3400
Grand Total	\$	17832.5

total 5430.10
L/S: 4.3K
04 Days