

195200

INS. CASE OWNER:

CCB / CTI1900 *Yuan, Uebz*

LKK:
IDAC:

Surveyor:

Marcus

DOI:

ASSIGNMENT

18/7/19

Date / Time:

18/7/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUM 1051K

Name of Insured:

MY LHO HOMG

Insured Tel No.:

HP:

Claim No.:

SUM1802008240211

Policy No.:

0006663116641800

Excess Sec II :SS

D.O.A.:

15/7/19

Make / Model:

KND 1

Is driver the owner? (YES / NO)

Nature of Accident:

Place of Accident:

AYE TMS ME

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

smg 1085H



INSRS:
WSP: *Fastech*
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
<i>3/7/19 @ 2.20pm khanchea</i>	Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI:	<i>7/3/7/19 klanchea</i>
<i>5/7/19</i>	Documentation Check List: Handler Typist	
<i>3/9/19</i>	Notification ltr (if non-pickup): After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice: LTA / GIA : Medical Bill: PIR: Mandate/Reject Instruction: LOD: Payment Breakdown Form:	<input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by:

Repair Cost: *45* SS 4,500 (5 days) Reduction: *70* % Email Call

FINAL SETTLEMENT Date/Time: *29/7/19* Confirm with: *JASON* Email Call

Final Liability: % *100* (Agreed / Assessed) BOLA S/N No. : *27*

Repair Cost: (w/gst) SS *4,815.00* If NO or B 28, Ass. Lia : *(OID REAR END TP)*

Loss of Rental (LOR): SS (- days)

Loss of Use (LOU): SS *400* (S *80* x *5* days)

Loss of Income (LOI): SS (S - x - days)

LOR only LOU only LOR + LOU LOR + LO (Tick only one)

GIA/LTA Search SS *2.00*

Medical: SS -

Disbursement: SS - (e.g. Tow/ Independent)

Legal Cost SS -

Total: SS *5,217.00* Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: SS *5,217.00* Name 1: *FASTECH AUTO PTE LTD*

Payee 2: (Strike if N.A.) SS Name 2:

Payee 3: (Strike if N.A.) SS Name 3:

5/1/19
CLAIM SETT
1) Claim status: *(Normal)* / Reject/Private Settle
2) Report Format: *IF400*
3) Survey fee:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0843G
Vehicle Details	
Vehicle No.:	SMG1085H
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	NISSAN
Vehicle Model:	X-TRAIL 2.0 CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	MR20388959C
Chassis No.:	JN1JANT32Z0011683
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$24,412.00
Original Registration Date:	03 Dec 2018
First Registration Date:	03 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$26,177.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Dec 2028
PARF Rebate Amount:	\$19,632.00
Intended COE Rebate Details	
COE Expiry Date:	02 Dec 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,302.00
COE Rebate Amount:	\$31,619.00
Total Rebate Amount:	\$51,251.00

The information contained herein is correct as at 18 Feb 2019

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S1810843G**

Name: **YEE TIONG MING**

Birth Date: **13 Feb 1967**

Issue Date: **15 Feb 2006**

0013998198




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1810843G**

Name: **YEE TIONG MING**

余长明

Race: **CHINESE**

Date of Birth: **13-02-1967** Sex: **M**

Country of Birth: **SINGAPORE**





YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

PASS DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 15 Feb 2006

Licence No: **S1810843G**

NP 428A



335110


S1810843G

NRIC No. **S1810843G**

Blood Group: **O1-04** Date of issue: **2003**

APT BLK 216A SOON LAY AVENUE #02-221 SINGAPORE 641210

NPIC No: **S1810843G** Date: **14/01/2019**






redefining / insurance

AXA Insurance Pte Ltd

1800 880 4888 (Within Singapore)

(65) 6880 4888 (International)

(65) 6880 4740

customer.care@axa.com.sg

www.axa.com.sg

Certificate of Insurance

account number

15423

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)
-Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

Policy details

Policyholder name	YEE TIONG MING	Certificate number	GA421066 / 1
Cover	Comprehensive	Chassis number	JDRNRRZT32EWAF
Plan name	Flexi	Engine number	MR20388959C
NCD applicable	0%		
Vehicle registration number	SMG1085H		
Period of insurance	from 03/12/2018 to 02/12/2019 (both dates inclusive)		
Finance loan company	DBS BANK LTD		

Persons or classes of persons entitled to drive*

- (a) The Policyholder
- (b) Any Named Driver as stated in the Policy:
 1. NG LAY HEOK
- (c) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	SGD 700.00
	Windscreen Excess	SGD 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

FASTECT AUTO PTE LTD
 BLK1 KAKI BUKIT AVE 6
 #01-46/48/50 AUTOBAY
 SINGAPORE 417883

Not Authorized
 Kaka
 1/2 #4500
 5/27

VEHICLE NO: SMG 1085H

QTY	PARTICULAR (NETT ITEM)			
1 PCS	REAR BUMPER	623.80	22/02	\$1,105.00
1 PCS	REAR BUMPER REINFORCEMENT	533.80	22	\$915.00
2 PCS	REAR BUMPER STAYS @\$185.00		11	\$370.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$85.00	35.80 x 2 = 71.60	22/02	\$170.00
2 PCS	REAR BUMPER REFLECTORS @\$150.00		11	\$300.00
1 PCS	REAR BUMPER LOWER SKIRTING		11	\$680.00
1 PCS	REAR BUMPER LOWER CHROME MOULDING		CR	\$399.00
1 SET	REAR BUMPER CLIPS		22	\$60.00
1 PCS	REAR BUMPER INNER KICKING SENSOR		CR	\$365.00
1 PCS	TAILGATE		11	\$4,200.00
1 PCS	TAILGATE REAR LOGO	89.70	22	\$105.00
1 PCS	TAILGATE X-TRAIL EMBLEM	101.30	22	\$102.00
1 PCS	TAILGATE WEATHERSTRIP		12	\$299.00
1 PCS	TAILGATE INNER LOCK		11	\$315.00
1 PCS	TAILGATE LOCK SENSOR		CR	\$265.00
1 PCS	REAR END PANEL	501.60	22	\$1,015.00
1 PCS	REAR END PANEL TOP GARNISH		11	\$310.00
2 PCS	REAR FENDER OUTER PROTECTOR @\$380.00		22/02	\$760.00
				\$11,735.00
	LABOUR CHARGES:			
	TO CHECK WIRING			\$80.00
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN		11	\$150.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY			\$150.00
	TO SPRAY RUST PROOFING			\$100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,200.00
	TO PUTTY & SPRAY PAINTING			\$1,500.00
				TO \$14,995.00

10%

LKK Auto Consultants hence notify the Repairer of the following:

- To remove & replace/repair painting
- To identify damaged part(s) during survey
- Price quote are subject to confirmation
- Third party survey on the "Without Prejudice" basis
- No litigation to be involved
- Supplies and materials to be provided and installed by the insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

4039.8
 3635.82
 2625.82

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Wednesday, 24 July 2019 5:27 PM
To: claimsdept@sg.cntaiping.com; alfred.toh@sg.cntaiping.com
Cc: Admin A
Subject: [MANDATE REQUEST]- Accident Involving SLM 1051K (OI : CTI - TBA) and SMG 1085H (TP :LKK REF - CC6/CTI19002994/Ukb3q2) on 15/02/2019
Attachments: LKK Adjustment Report.pdf; LKK Inspection Report.pdf; LKK REINSPECTION PHOTOS.pdf; LKK SURVEY PHOTOS.pdf; TP LOD.pdf

Your ref : SLM 1051K (Please advise)
Our ref : CC6/CTI19002994/Ukb3q2

Dear Sirs,

We refer to the above matter.

This is a head to rear collision.

We are of the opinion that BOLA scenario 27 is applicable for this matter. Liability is not in our insured's favour. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer "**FASTECH AUTO PTE LTD**" at \$ **5,317.00 (all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 16,044.65	\$ 4,815.00
2. Loss of Use (5 days x \$ 100)	\$ 500.00	\$ 500.00 (5days x \$100)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 16,546.65	\$ 5,317.00

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 29 July 2019 9:00 AM
To: jason@fastechauto.com.sg
Cc: Admin A
Subject: RE: MVA BETWEEN SMG1085H & SLM1051K (OI) ON 15/2/2019

YOUR REF: SMG1085H

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 4,815.00
2. Loss of Use (5days x \$80.00)	\$ 400.00
3. LTA/GIA Search Fee	\$ 2.00
TOTAL	\$ 5,217.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Tuesday, 23 July 2019 4:51 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: RE: MVA BETWEEN SMG1085H & SLM1051K ON 15/2/2019

Without Prejudice

Dear Khanchna,

As requested.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19002994/Ukb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 06-09-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 1051K	Veh. Inspected	SMG 1085H
Policy No.	DMPCSN3016641800	Coverage (\$)	0.00
Claim No.	SNM19D200834C02/1	Excess (\$)	0.00
Assign From		Assign Date	18/02/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN X-TRAIL (A)	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JN1JANT32Z0011683	Colour	RED
Odometer	6627	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R19	BRIDGESTONE	8 mm
L/H Front Tyre	225/55 R19	BRIDGESTONE	8 mm
R/H Rear Tyre	225/55 R19	BRIDGESTONE	8 mm
L/H Rear Tyre	225/55 R19	BRIDGESTONE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/02/2019	Inspection Date	18/02/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 1085H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DENTED / DEFORMED	1,105.00	623.80
1	REAR BUMPER REINFORCEMENT	DENTED	915.00	533.80
2	REAR BUMPER STAYS @\$185.00	NOT NECESSARY	370.00	-
2	REAR BUMPER SIDE RETAINERS @\$85.00	BENT / NECESSARY	170.00	71.60
2	REAR BUMPER REFLECTORS @\$150.00	NOT NECESSARY	300.00	-
1	REAR BUMPER LOWER SKIRTING	NOT NECESSARY	680.00	-
1	REAR BUMPER LOWER CHROME MOULDING	CRACKED	399.00	399.00
1	SET REAR BUMPER CLIPS	NECESSARY	60.00	60.00
1	REAR BUMPER INNER KICKING SENSOR	CRACKED	365.00	365.00
1	TAILGATE	TO REPAIR SEE LABOUR	4,200.00	-
1	TAILGATE REAR LOGO	NECESSARY	105.00	89.70
1	TAILGATE X-TRAIL EMBLEM	NECESSARY	102.00	101.30
1	TAILGATE WEATHERSTRIP	NECESSARY	299.00	299.00
1	TAILGATE INNER LOCK	NOT NECESSARY	315.00	-
1	TAILGATE LOCK SENSOR	CRACKED	265.00	265.00
1	REAR END PANEL	DENTED	1,015.00	501.60
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	310.00	-
2	REAR FENDER OUTER PROTECTOR @\$380.00	DEFORMED / TORN	760.00	760.00
	LESS 10% DISCOUNT		-	-406.98
			11,735.00	3,662.82
LABOUR				
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR .		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT ,CUSHION UPHOLSTERY.		150.00	80.00
	TO SPRAY RUST PROOFING.		100.00	50.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE .		1,200.00	880.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		1,500.00	900.00
			3,260.00	1,990.00
	GRAND TOTAL		14,995.00	5,652.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC6/CTI19002994/Ukb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.