

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG: 200707743D GST REG: 200707743D

14-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1215 A

2 pcs	Rear n/s & o/s tail lamp @\$321.30	n/s - con o/s x su	\$	642.60
2 pcs	Rear n/s & o/s reflector @\$295.10	- con	\$	590.20
1 pc	End panel	Replaced	\$	853.85
1 pc	Rear windscreen	Replaced	\$	497.90
1 pc	Rear windscreen moulding	Replaced	\$	64.10
1 pc	Tailgate	Replaced	\$	2,292.30
1 pc	Tailgate lower garnish	Replaced	\$	362.61
1 pc	Tailgate hinge @\$28.50	X su	\$	57.00
2 pcs	Tailgate trim	con	\$	431.12
1 pc	Tailgate side n/s & o/s trim @\$90.42	X su	\$	180.84
2 pcs	Tailgate license lamp @\$18.60	X su	\$	37.20
1 pc	Tailgate weatherstrip	X su	\$	276.98
1 pc	Emblem I30	con	\$	27.80
1 pc	Emblem CRDI	con	\$	29.40
1 pc	Emblem Hyundai	con	\$	29.40
1 pc	Rear bumper	Replaced	\$	811.11
1 pc	Rear bumper sponge	X su	\$	79.20
1 pc	Rear bumper reinforcement	Replaced	\$	815.64
1 pc	Rear bumper reinforcement centre	Replaced	\$	79.20
1 pc	Rear bumper n/s & o/s side bracket @\$52.20	X su	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	n/s / o/s x su	\$	215.00
1 pc	Rear n/s fender	Replaced	\$	1,525.73
1 pc	Rear n/s fender inner shield	X su	\$	205.29
1 pc	Front bumper	Replaced	\$	811.11
1 pc	Front bumper sponge	con	\$	218.03
1 pc	Front bumper reinforcement	Replaced	\$	636.40
2 pcs	Front n/s & o/s fog lamp cover @\$25.00	n/s - ut o/s x su	\$	50.00
1 pc	Front bumper tow cap	X	\$	60.10
2 pcs	n/s & o/s headlamp	n/s con o/s x su	\$	3,063.14
1 pc	Front Hyundai Logo	con	\$	29.40
1 pc	Bonnet grille	con	\$	566.46

157157

14-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1215 A

2 pcs	Front n/s & o/s side bracket @ \$32.51	n/s - crn o/s x 5m	\$ 65.02
1 pc	Bonnet	Butch	\$ 1,220.40
1 pc	Front n/s fender	Butch	\$ 514.02
1 pc	Front n/s fender inner shield	X m	\$ 176.72
1 pc	Support panel	crn	\$ 1,292.20
			<u>\$ 18,911.87</u>
		Less 20%	\$ 3,782.38
			<u>\$ 15,129.49</u>

S/NETT

1 set	Rear bumper clips	---	\$ 48.00
1 set	Reverse sensor	shaded	\$ 280.00 200
1 set	Tailgate sticker	---	\$ 100.00
1 set	Tailgate garnish clips	---	\$ 38.00
1 pc	Rear n/s fender sticker	---	\$ 60.00
1 pc	Rear no. plate	---	\$ 50.00 25
1 pc	Sealant	---	\$ 50.00
1 pc	Front bumper clips	---	\$ 48.00
1 pc	Front no. plate	---	\$ 50.00 35
1 pc	Front n/s fender sticker	---	\$ 30.00
	Towing Fee		\$ 50.00 50
	Sundry		\$ 50.00 20
	To dismantle and replace reverse sensor and test system		\$ 80.00 20
	To replace the rear windscreen into new shell tailgate		\$ 120.00 100
	To dismantle and refit the inner component into new tailgate, test wiper motor and water etc		\$ 120.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel, rear n/s fender. Including to knock-out, straighten, repair, reshape of the same etc		\$ 1,800.00 1,200
	To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, rear n/s fender, bonnet, front n/s fender		\$ 1,400.00 1,200
	To apply rustproofing on the repaired and replaced panels		\$ 250.00 50
	Total		<u>\$ 19,753.49</u>

Acknowledged by Repairer:
 Signature: *[Signature]*
 Date: *14/2/19*

14/2/19 16:35 hrs
12 Pop
PIP
Restone (not pld)

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-May-19

SUPPLEMENTARY REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1215 A

1 pc	Aircon condensor	<i>Red</i>	\$	745.10
1 pc	Floorboard panel	<i>Black</i>	\$	866.03
			\$	<u>1,611.13</u>
			Less 20%	\$ 322.23
			\$	<u>1,288.90</u>

S/NETT

1 set	Floorboard insulating padding	<i>red</i>	\$	120.00 100
	Top up gas		\$	120.00 50
	To heat/cut and weld on the floorboard panel, rear n/s fender to facilitate repair		\$	800.00 400
	To putty and spray painting on the Floorboard panel		\$	200.00 180
	Total		\$	<u>2,528.90</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

13/6/19

Calculated P/P \$17975.91 / 12 bn. P/P \$17975.91 / 12 bn

///