

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1215 A

2 pcs	Rear n/s & o/s tail lamp @\$321.30	n/s - o/s x	\$	642.60
2 pcs	Rear n/s & o/s reflector @\$295.10	/	\$	590.20
1 pc	End panel	/	\$	853.85
1 pc	Rear windscreen	/	\$	497.90
1 pc	Rear windscreen moulding	/	\$	64.10
1 pc	Tailgate	/	\$	2,292.30
1 pc	Tailgate lower garnish	/	\$	362.61
2 pcs	Tailgate hinge @\$28.50	x	\$	57.00
1 pc	Tailgate trim	/	\$	431.12
2 pcs	Tailgate side n/s & o/s trim @\$90.42	?	\$	180.84
2 pcs	Tailgate license lamp @\$18.60	?	\$	37.20
1 pc	Tailgate weatherstrip	?	\$	276.98
1 pc	Emblem I30	/	\$	27.80
1 pc	Emblem CRDI	/	\$	29.40
1 pc	Emblem Hyundai	/	\$	29.40
1 pc	Rear bumper	/	\$	811.11
1 pc	Rear bumper sponge	x	\$	79.20
1 pc	Rear bumper reinforcement	/	\$	815.64
1 pc	Rear bumper reinforcement centre	/	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @\$52.20	?	\$	104.40
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	n/s / o/s x	\$	215.00
1 pc	Rear n/s fender	x n/s	\$	1,525.73
1 pc	Rear n/s fender inner shield	x	\$	205.29
1 pc	Front bumper	/	\$	811.11
1 pc	Front bumper sponge	/	\$	218.03
1 pc	Front bumper reinforcement	/	\$	636.40
2 pcs	Front n/s & o/s fog lamp cover @\$25.00	n/s - o/s x	\$	50.00
1 pc	Front bumper tow cap	x	\$	60.10
2 pcs	n/s & o/s headlamp	n/s - o/s x	\$	3,063.14
1 pc	Front Hyundai Logo	/	\$	29.40
1 pc	Bonnet grille	/	\$	566.46

(A 1571.57)


14-Feb-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1215 A

2 pcs	Front n/s & o/s side bracket @\$32.51	<i>n/s - o/s</i>	\$	65.02
1 pc	Bonnet	<i>-</i>	\$	1,220.40
1 pc	Front n/s fender	<i>-</i>	\$	514.02
1 pc	Front n/s fender rinner shield	<i>X</i>	\$	176.72
1 pc	Support panel	<i>X n/s</i>	\$	1,292.20
			\$	<u>18,911.87</u>
			Less 20%	\$ 3,782.38
				<u>\$ 15,129.49</u>

S/NETT

1 set	Rear bumper clips	<i>-</i>	\$	48.00
1 set	Reverse sensor	<i>-</i>	\$	280.00 <i>200</i>
1 set	Tailgate sticker	<i>-</i>	\$	100.00
1 set	Tailgate garnish clips	<i>-</i>	\$	38.00
1 pc	Rear n/s fender sticker	<i>-</i>	\$	60.00
1 pc	Rear no. plate	<i>-</i>	\$	50.00 <i>25</i>
1 pc	Sealant	<i>-</i>	\$	50.00
1 pc	Front bumper clips	<i>-</i>	\$	48.00
1 pc	Front no. plate	<i>-</i>	\$	50.00 <i>25</i>
1 pc	Front n/s fender sticker	<i>-</i>	\$	30.00
	Towing Fee		\$	50.00 <i>50</i>
	Sundry		\$	50.00 <i>20</i>
	To dismantle and replace reverse sensor and test system		\$	80.00 <i>20</i>
	To replace the rear windscreen into new shell tailgate		\$	120.00 <i>100</i>
	To dismantle and refit the inner component into new tailgate, test wiper motor and water etc		\$	120.00 <i>50</i>
	To labour charge for dismantle and renew the accident damaged parts. To heat/cut and weld on the end panel, rear n/s fender. Including to knock-out, straighten, repair, reshape of the same etc		\$	1,800.00 <i>1200</i>
	To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel, rear n/s fender, bonnet, front n/s fender		\$	1,400.00 <i>1260</i>
	To apply rustproofing on the repaired and replaced panels		\$	250.00 <i>50</i>
	Total		\$	<u>19,753.49</u>



14/2/19 1625hrs
12 Pop
PIP
Restore front pld

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)