

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd

AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416
DEAR SIR / MADAM :

*Not Notarized
6/1/19/8?
Resurvey After Paint*

ACCIDENT REPAIR ON: SGR2174R
MODEL : NISSAN MURANO 2.5 CVT
POLICY NO : GA124888/1
CHASSIS NO : TZ51000923

Date: 19/02/2019

Page : 1 of 2

YEAR OF MANUFACTURE : 2010

DATE / TIME OF ACCIDENT: 30/01/2019 Time: 1200Hrs at Wheelock Place Car Park.

THIRD PARTY VEHICLE NO: SKP8954E

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Front fender RH	1	578.20	Dented	578.20 X
2	Front fender shield RH	1	90.40	Cut	90.40 X
3	Front fender shield clip	10	4.40	Necessary	44.00 ✓
4	Front door RH	1	1,254.80	Dented	1,254.80 ✓
5	Front door weatherstrip RH	1	142.60	Necessary	142.60 X
6	Front door hinge upper RH	1	67.90	Bented	67.90 X
7	Front door hinge lower RH	1	67.90	Bented	67.90 X
8	Front door window glass outer moulding RH	1	204.90	Necessary	204.90 X
9	Front door outer lower moulding chrome RH	1	211.90	Necessary	211.90 ✓
10	Front door frame pillar garnish RH	1	258.00	Necessary	258.00 X
11	Front door speaker RH	1	91.90	To Check	91.90 ?
12	Front door inner trim board RH	1	2,056.40	Kinked	2,056.40 X
13	Front door window glass regulator RH	1	144.20	To Check	144.20 X
14	Front door window glass regulator motor RH	1	524.40	To Check	524.40 X

Sub-Total: 5,737.50

Less: 30% discount - 1,721.25

Total Parts after 30% discount: 4,016.25

Special Nett Items

- 1 Anti-rust coating

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

80.00 160.00 301
160.00

Total Parts: 4,176.25

Labour Charges For RH Side Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. 1,000.00
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities 1,000.00
3 Provide skill labour to disconnect and check electrical wiring 60.00
4 Dismantle and transfer door fittings and mechanism to new door/facilitate repair 80.00

300
400
200
600

Total Labour:

2,140.00

Total Parts & Labour:

6,316.25

GST 7%

442.14

Grand Total:

6,758.39

Estimate Repair Duration

~~09~~ days

4 days

ACCIDENT VEHICLE OF : SGR2174R

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerly
Company : LKK
Date : 20/2/19
Time : 14.20pm
Contact No : 96910663
Email : _____