

15/5/2010

INS. CASE OWNER:

CC3 /AIG1900 2006

LKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

Date / Time:

18/1/19

Registered in Merimen:

18/1/19

Pre-assign / CCU / FTE

smf 62114



Insured Vehicle No.:

Name of Insured:

MUHAMMAD ALI BIN PRAMAD HATEB

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

47387882454

Policy No.:

1911108771

Make / Model:

Kia

Place of Accident:

Hillview Ave

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

CMF 7563K



INSRS:

WSP:

Tel:

Liability:

RMKS:

premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

cmf 7563K

smf 62114

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: WSP

Repair Cost:

P19

SS21,140.96

(17 days) Reduction:

41

%

Email

Call

FINAL SETTLEMENT

Date/Time: 21-08-19

Confirm with: NOEA

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

10

Repair Cost:

01103

SS29,040.83

Loss of Rental (LOR):

SS 1,400.00

(14 days) x 100

Loss of Use (LOU):

SS -

(5 x days)

Loss of Income (LOI):

SS 540.00

(56 x 9 days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS30,983.83

Global Sum SS:

FINAL PAYMENT

Date/Time: 21-08-19

Confirm with: NOEA

Email

Call

Payee 1:

SS30,983.83

Name 1:

PREMIUM AUTOMOBILES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+330

COPY SENT
19/8/19

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 17 days

Res.: Yes or No

Lum Sum: 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMF7563KYr Regn: 2018 / NovType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 SedanC.C. 1395Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 5046

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28VXK1003547Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/35 R15R: 235/35 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Achilles

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 21/02/19Survey held at PremiumDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

T1 A16MV: 1251CP.V: 43.6KNett:P/P \$ 27,140.96 Cred \$ 18,498.04 / 41%

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0227/2019/KN
Date : 20-Feb-19

Vehicle IN workshop.

Your Insured Vehicle No. : SMH 6211 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Eugene Ng Minghan
Address : 993 Bukit Timah Road
#03-16
Singapore 589631
Telephone : 96712612
Type of Claim : Third Party Claims
Policy No. : 1800140761
Vehicle No : **SMF 7563 K**
Model Code : Audi A3 1.4 SEDAN TFSI
Model / Year : 23/11/2018
Engine No : CZE 844557
Chassis No : WAUZZZ8VXK1003547
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Feb-19
Place of Accident : 83 HILLVIEW AVENUE MERAL LODGE S(669583)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 7563 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N AIG	✓
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
3	To dismantle LHS front suspension assy. Check function and renew accordingly.	S/N \$ 1,800.00	✓
4	To dismantle and renew front bumper, LHS front fender, LHS front door and LHS headlight. To repair LHS sill panel. Reorganize crash management components. Reinstall all parts removed.	\$ 6,900.00	1750 ✓
5	To respray front bumper, LHS front fender, LHS front door, LHS sill panel and LHS upper A-pillar.	\$ 3,800.00	2200 ✓
6	To renew LHS front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00	✓
7	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7563 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	RUBBER VALVE <i>new</i>	4 \$ 13.00	<i>1X</i>
2	ASSEMBLY CARRIER <i>Bent</i>	\$ 940.00	<i>751.60</i>
3	BONDED RUBBER BUSHES - UPPER/LOWER <i>Dmg</i>	\$ 151.00	<i>120.40</i>
4	TRACK CONTROL ARM - LH <i>Bent</i>	\$ 336.00	<i>268.80</i>
5	WHEEL BEARING HOUSING - LH <i>Damaged</i>	\$ 532.00	<i>475.60</i>
6	WHEEL BEARING ASSEMBLY PARTS - FRONT <i>Dmg</i>	\$ 442.00	<i>352.60</i>
7	GUIDE JOINT - LH <i>Bent</i>	\$ 117.00	<i>93.20</i>
8	COUPLING ROD <i>Bent</i>	\$ 88.00	<i>69.92</i>
9	LEVEL SENSOR WITH POLES - LH <i>new</i>	\$ 552.00	<i>X</i>
10	GAS SHOCK ABSORBER <i>Bent</i>	\$ 251.00	<i>200.80</i>
11	DEEP GROVE BALL THRUST BEARING <i>new</i>	\$ 43.00	<i>34.40</i>
12	RUBBER STOP FOR SHOCK ABSORBER <i>new</i>	\$ 51.00	<i>X</i>
13	SUSPENSION STRUT STORAGE <i>Dmg</i>	\$ 114.00	<i>91.20</i>
14	STEERING GEAR <i>Bent</i>	\$ 4,649.00	<i>3719.20</i>
15	REPAIR SET FOR STEERING BOX <i>new</i>	\$ 43.00	<i>34.00</i>
16	TRACK ROD <i>Bent</i>	\$ 86.00	<i>68.48</i>
17	TIE ROD END <i>Bent</i>	\$ 118.00	<i>94.40</i>
18	DRIVE SHAFT WITH COSTANT VELOCITY JOINT <i>NP</i>	\$ 2,005.00	<i>X</i>
SUB TOTAL SPARE PARTS		\$ 10,531.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>Rehd</i>	\$ 1,830.00 ✓	146.00
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 170.00 +	
3	FRONT BUMPER GUIDE SECTION - LH <i>Rehd</i>	\$ 35.00 ✓	27.52
4	CENTER GRILLE <i>neu</i>	\$ 146.00 +	
5	CLOSING ELEMENT - LOWER CENTER <i>neu</i>	\$ 488.00 +	
6	CLOSING ELEMENT - LH <i>neu</i>	\$ 270.00 ✓	216.00
7	COVER TRIM FOR GRILLE - LH <i>neu</i>	\$ 148.00 +	
8	ADAPTER FOR WHEEL HOUSING LINER - LH <i>neu</i>	\$ 34.00 ✗	
9	RADIATOR GRILLE <i>neu</i>	\$ 1,301.00 +	
10	CLOSING ELEMENT FOR RADIATOR GRILLE <i>neu</i>	\$ 174.00 +	
11	RADIATOR AIR GUIDE GRILLE - LH <i>neu</i>	\$ 171.00 +	
12	<i>Front Fender</i> AIR GUIDE GRILLE WING - LH <i>Rehd</i>	\$ 778.00 ✓	622.00
13	ATTACHMENT PARTS FOR FENDER <i>neu</i>	\$ 65.00 ✗	
14	BRACKET FOR FENDER - LH <i>But</i>	\$ 25.00 -	19.76
15	BRACKET FOR FENDER FOR WHEEL HOUSING LINER - LH <i>But</i>	\$ 35.00 -	27.76
16	BRACE <i>But</i>	\$ 88.00 -	69.84
17	CLOSING ELEMENT - LH <i>Rehd</i>	\$ 30.00 -	23.76
18	INSULATION FOR WING - LH <i>Rehd</i>	\$ 38.00 ✓	29.84
19	WHEEL HOUSING LINER - LH <i>Rehd</i>	\$ 158.00 ✓	126.00
20	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>neu</i>	\$ 81.00 ✗	
SUB TOTAL SPARE PARTS		\$ 6,065.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7563 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	LED HEADLIGHT - LH <i>lt</i>	\$ 5,029.00	<i>✓ 4023.20</i>
2	CONTROL UNIT FOR LED HEADLIGHT <i>new</i>	\$ 508.00	<i>+</i>
3	POWER MODULE FOR MAIN LIGHT ELECTRONICS <i>new</i>	\$ 693.00	<i>+</i>
4	LED WITH HEAT SINK - LH <i>new</i>	\$ 666.00	<i>+</i>
5	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>new</i>	\$ 128.00	<i>+</i>
6	FRONT DOOR - LH <i>Derby</i>	\$ 2,279.00	<i>✓ 1823.20</i>
7	FRONT DOOR OUTER DOOR SEAL - LH <i>pe</i>	\$ 146.00	<i>✓ 116.00</i>
8	BONDING AGENT <i>new</i>	\$ 45.00	<i>✓</i>
9	CLEANING SOLUTION <i>new</i>	\$ 65.00	<i>✓</i>
10	APPLICATOR <i>new</i>	\$ 7.00	<i>✓</i>
11	ATTACHMENT PARTS FOR FRONT DOOR <i>new</i>	\$ 218.00	<i>✓</i>
12	DOOR CATCH - LH/RH <i>new</i>	\$ 96.00	<i>+</i>
13	COVER FOR DOOR CATCH - LH/RH <i>new</i>	\$ 13.00	<i>+</i>
14	TRIM STRIP FOR WINDOW GUIDE - LH <i>new</i>	\$ 235.00	<i>+</i>
15	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>new</i>	\$ 282.00	<i>+</i>
16	FRONT NUMBER PLATE <i>new</i>	S/N \$ 25.00	<i>+</i>
17	STONE CHIP GUARD <i>new</i>	S/N \$ 180.00	<i>✓ 180.00</i>
18	LHS RIM <i>cut</i>	TBC	<i>✓ 1300.00</i>
19	LHS FRONT TYRE ACHILLES ATR SPORT 235/35/R19 <i>new</i>	TBC	<i>✓ 330.00</i>
20	SUNDRIES <i>Na</i>	\$ 1,000.00	<i>✓ 208.24</i>

TOTAL SPARE PARTS

\$ 28,211.00

TOTAL LABOUR CHARGES

\$ 13,332.00

GRAND TOTAL

\$ 41,543.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

43643

47644.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Lj

Surveyed Date

: 21/02/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10 days.
inclusive of undercarriage.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/TP/0227/2019/KN

8-Mar-19

CHANG

1 of 1

SMF 7563 K

Audi A3 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
labour			
1	To place vehicle on cellette bench S/N	\$ 1,200.00	\$ 1,200.00 ✓
2	To repair LHS A pillar, sill end cap and align to position	\$ 1,800.00	\$ 1,250.00 ✓
3	To reseal, respray A pillar	\$ 900.00	\$ 550.00 ✓
Parts		\$ 3,900.00	\$ 3,000.00
1	WASH WATER RESERVOIR <i>behind</i>	\$ 186.00	\$ 148.40 ✓
2	WATER RESERVOIR SEAL <i>near</i>	\$ 10.00	\$ 7.84 ✓
Materials		\$ 196.00	\$ 156.24
Labour		\$ 3,900.00	\$ 3,000.00
GRAND TOTAL :		\$ 4,096.00	\$ 3,156.24 ✓

For Premium Automobiles Pte Ltd

Adrian Ling -
sls.

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0227/2019/KN 6-Mar-19 CHANG 1 of 1 SMF 7563 K Audi A3 SEDAN 1.4 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	WASH WATER RESERVOIR	\$ 186.00	148.40
2	WATER RESERVOIR SEAL	\$ 10.00	7.84
GRAND TOTAL		\$ 196.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Handwritten signature
06/03/19

RAY-S
SPORT RIM CENTRE

114 Mackenzie Road
Singapore 0922
Tel: 339 6767
Fax: 339 0145

FACSIMILE TRANSMISSION

TO : Eugene Ng SMP7562K
DATE: 22/2/2019

FROM : RAY-S SPORT RIM

PAGES:

IPC	02	13 x 8	5-112	\$1550.00
IPC	FALKEN	18 INCH	225 40 18	\$550.00

If this transmission is illegible in any way, please contact us by telephone.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0227/2019/KN
Date : 20-Feb-19

Vehicle IN workshop.

Your Insured Vehicle No. : SMH 6211 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Hi Adrian

You recommended 10 days

We took 17 days exclude 3 Sundays

with c/bench additional repairs

jb 12 Apr 19

Owner's Name : Mr Eugene Ng Minghan
Address : 993 Bukit Timah Road
#03-16
Singapore 589631
Telephone : 96712612
Type of Claim : Third Party Claims
Policy No. : 1800140761
Vehicle No : **SMF 7563 K**
Model Code : Audi A3 1.4 SEDAN TFSI
Model / Year : 23/11/2018
Engine No : CZE 844557
Chassis No : WAUZZZ8VXK1003547
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Feb-19
Place of Accident : 83 HILLVIEW AVENUE MERAL LODGE S(669583)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 7563 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N	AIG	
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
3	To dismantle LHS front suspension assy. Check function and renew accordingly.	S/N	\$ 1,800.00	\$ 1,800.00
4	To dismantle and renew front bumper, LHS front fender, LHS front door and LHS headlight. To repair LHS sill panel. Reorganize crash management components. Reinstall all parts removed.		\$ 6,900.00	\$ 1,750.00
5	To respray front bumper, LHS front fender, LHS front door, LHS sill panel and LHS upper A-pillar.		\$ 3,800.00	\$ 2,200.00
6	To renew LHS front rim and tyre. To carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
6a	Added labour charges - see attached		\$3,900.00	\$ 3,000.00
7	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 17,232.00</u>	<u>\$ 9,582.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	RUBBER VALVE	4 \$ 13.00	
2	ASSEMBLY CARRIER	\$ 940.00	\$ 751.60 ✓
3	BONDED RUBBER BUSHES - UPPER/LOWER	\$ 151.00	\$ 120.40 ✓
4	TRACK CONTROL ARM - LH	\$ 336.00	\$ 268.80 ✓
5	WHEEL BEARING HOUSING - LH	\$ 532.00	\$ 425.60 ✓
6	WHEEL BEARING ASSEMBLY PARTS - FRONT	\$ 442.00	\$ 353.60 ✓
7	GUIDE JOINT - LH	\$ 117.00	\$ 93.20 ✓
8	COUPLING ROD	\$ 88.00	\$ 69.92 ✓
9	LEVEL SENSOR WITH POLES - LH	\$ 552.00	
10	GAS SHOCK ABSORBER	\$ 251.00	\$ 200.40 ✓
11	DEEP GROVE BALL THRUST BEARING	\$ 43.00	\$ 34.00 ✓
12	RUBBER STOP FOR SHOOCK ABSORBER	\$ 51.00	
13	SUSPENSION STRUT STORAGE	\$ 114.00	\$ 91.20 ✓
14	STEERING GEAR	\$ 4,649.00	\$ 3,719.20 ✓
15	REPAIR SET FOR STEERING BOX	\$ 43.00	\$ 34.00 ✓
16	TRACK ROD	\$ 86.00	\$ 68.48 ✓
17	TIE ROD END	\$ 118.00	\$ 94.40 ✓
18	DRIVE SHAFT WITH COSTANT VELOCITY JOINT	\$ 2,005.00	
SUB TOTAL SPARE PARTS		\$ 10,531.00	\$ 6,324.80 ✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
		C/F	\$ 6,324.80
1	FRONT BUMPER COVER	\$ 1,830.00	\$ 1,464.00 ✓
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH	\$ 35.00	\$ 27.52 ✓
4	CENTER GRILLE	\$ 146.00	
5	CLOSING ELEMENT - LOWER CENTER	\$ 488.00	
6	CLOSING ELEMENT- LH	\$ 270.00	\$ 216.00 ✓
7	COVER TRIM FOR GRILLE - LH	\$ 148.00	
8	ADAPTER FOR WHEEL HOUSING LINER - LH	\$ 34.00	
9	RADIATOR GRILLE	\$ 1,301.00	
10	CLOSING ELEMENT FOR RADIATOR GRILLE	\$ 174.00	
11	RADIATOR AIR GUIDE GRILLE - LH	\$ 171.00	
12	AIR GUIDE GRILLE WING - LH	\$ 778.00	\$ 622.00 ✓
13	ATTACHMENT PARTS FOR FENDER	\$ 65.00	
14	BRACKET FOR FENDER - LH	\$ 25.00	\$ 19.76 ✓
15	BRACKET FOR FENDER FOR WHEEL HOUSING LINER - LH	\$ 35.00	\$ 27.76 ✓
16	BRACE	\$ 88.00	\$ 69.84 ✓
17	CLOSING ELEMENT - LH	\$ 30.00	\$ 23.76 ✓
18	INSULATION FOR WING - LH	\$ 38.00	\$ 29.84 ✓
19	WHEEL HOUSING LINER - LH	\$ 158.00	\$ 126.00 ✓
20	ATTACHMENT PARTS FOR WHEEL HOUSING LINER	\$ 81.00	
SUB TOTAL SPARE PARTS		\$ 6,065.00	\$ 8,951.28

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMF 7563 K

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
		<i>c/f</i>	\$ 8,951.28
1	LED HEADLIGHT - LH	\$ 5,029.00	\$ 4,023.20 ✓
2	CONTROL UNIT FOR LED HEADLIGHT	\$ 508.00	
3	POWER MODULE FOR MAIN LIGHT ELECTRONICS	\$ 693.00	
4	LED WITH HEAT SINK -LH	\$ 666.00	
5	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM	\$ 128.00	
6	FRONT DOOR - LH	\$ 2,279.00	\$ 1,823.20 ✓
7	FRONT DOOR OUTER DOOR SEAL - LH	\$ 146.00	\$ 116.80 ✓
8	BONDING AGENT	\$ 45.00	
9	CLEANING SOLUTION	\$ 65.00	
10	APPLICATOR	\$ 7.00	
11	ATTACHMENT PARTS FOR FRONT DOOR	\$ 218.00	
12	DOOR CATCH - LH/RH	\$ 96.00	
13	COVER FOR DOOR CATCH - LH/RH	\$ 13.00	
14	TRIM STRIP FOR WINDOW GUIDE - LH	\$ 235.00	
15	WINDOW SLOT SEAL WITH TRIM STRIP - LH	\$ 282.00	
16	FRONT NUMBER PLATE	S/N \$ 25.00	
17	STONE CHIP GUARD	S/N \$ 180.00	\$ 180.00 ✓
18	LHS RIM	TBC	\$ 1,550.00 ✓
19	LHS FRONT TYRE ACHILLES ATR SPORT 235/35/R19	TBC	\$ 550.00 ✓
20	<i>Added parts - see attached</i>	\$ 196.00	\$ 156.24 ✓
21	SUNDRIES	\$ 1,000.00	\$ 208.24 ✓
TOTAL SPARE PARTS		\$ 28,407.00	\$ 17,558.96
TOTAL LABOUR CHARGES		\$ 17,232.00	\$ 9,582.00
GRAND TOTAL		\$ 45,639.00	\$ 27,140.96 ✓

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.