

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0227/2019/KN
Date : 20-Feb-19

Vehicle IN workshop.

Your Insured Vehicle No. : **SMH 6211 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Eugene Ng Minghan
Address : 993 Bukit Timah Road
#03-16
Singapore 589631
Telephone : 96712612
Type of Claim : Third Party Claims
Policy No. : 1800140761
Vehicle No : **SMF 7563 K**
Model Code : Audi A3 1.4 SEDAN TFSI
Model / Year : 23/11/2018
Engine No : CZE 844557
Chassis No : WAUZZZ8VXK1003547
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 17-Feb-19
Place of Accident : 83 HILLVIEW AVENUE MERAL LODGE S(669583)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMF 7563 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N AIG	✓
2	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
3	To dismantle LHS front suspension assy. Check function and renew accordingly.	S/N \$ 1,800.00	✓
4	To dismantle and renew front bumper, LHS front fender, LHS front door and LHS headlight. To repair LHS sill panel. Reorganize crash management components. Reinstall all parts removed.	\$ 6,900.00	1750
5	To respray front bumper, LHS front fender, LHS front door, LHS sill panel and LHS upper A-pillar.	\$ 3,800.00	2200
6	To renew LHS front rim and tyre. To carry out wheel alignment.	S/N \$ 280.00	✓
7	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 13,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	RUBBER VALVE ?	4 \$ 13.00 ?	
2	ASSEMBLY CARRIER ?	\$ 940.00 ?	
3	BONDED RUBBER BUSHES - UPPER/LOWER ?	\$ 151.00 ?	
4	TRACK CONTROL ARM - LH ?	\$ 336.00 ?	
5	WHEEL BEARING HOUSING - LH ?	\$ 532.00 ?	
6	WHEEL BEARING ASSEMBLY PARTS - FRONT ?	\$ 442.00 ?	
7	GUIDE JOINT - LH ?	\$ 117.00 ?	
8	COUPLING ROD ?	\$ 88.00 ?	
9	LEVEL SENSOR WITH POLES - LH ?	\$ 552.00 ?	
10	GAS SHOCK ABSORBER ?	\$ 251.00 ?	
11	DEEP GROVE BALL THRUST BEARING ?	\$ 43.00 ?	
12	RUBBER STOP FOR SHOCK ABSORBER ?	\$ 51.00 ?	
13	SUSPENSION STRUT STORAGE ?	\$ 114.00 ?	
14	STEERING GEAR ?	\$ 4,649.00 ?	
15	REPAIR SET FOR STEERING BOX ?	\$ 43.00 ?	
16	TRACK ROD ?	\$ 86.00 ?	
17	TIE ROD END ?	\$ 118.00 ?	
18	DRIVE SHAFT WITH COSTANT VELOCITY JOINT ?	\$ 2,005.00 ?	

SUB TOTAL SPARE PARTS: **\$ 10,531.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER COVER <i>Rehd</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>neu</i>	\$ 170.00	x
3	FRONT BUMPER GUIDE SECTION - LH <i>Rehd</i>	\$ 35.00	✓
4	CENTER GRILLE <i>neu</i>	\$ 146.00	x
5	CLOSING ELEMENT - LOWER CENTER <i>neu</i>	\$ 488.00	x
6	CLOSING ELEMENT - LH <i>neu</i>	\$ 270.00	+
7	COVER TRIM FOR GRILLE - LH <i>neu</i>	\$ 148.00	+
8	ADAPTER FOR WHEEL HOUSING LINER - LH ?	\$ 34.00	*
9	RADIATOR GRILLE <i>neu</i>	\$ 1,301.00	+
10	CLOSING ELEMENT FOR RADIATOR GRILLE <i>neu</i>	\$ 174.00	x
11	RADIATOR AIR GUIDE GRILLE - LH <i>neu</i>	\$ 171.00	x
12	<i>Front Fender</i> AIR GUIDE GRILLE WING - LH <i>Rehd</i>	\$ 778.00	✓
13	ATTACHMENT PARTS FOR FENDER ?	\$ 65.00	?
14	BRACKET FOR FENDER - LH <i>Rehd</i>	\$ 25.00	✓
15	BRACKET FOR FENDER FOR WHEEL HOUSING LINER - LH <i>Rehd</i>	\$ 35.00	✓
16	BRACE <i>Rehd</i>	\$ 88.00	✓
17	CLOSING ELEMENT - LH <i>Rehd</i>	\$ 30.00	✓
18	INSULATION FOR WING - LH ?	\$ 38.00	?
19	WHEEL HOUSING LINER - LH <i>Rehd</i>	\$ 158.00	✓
20	ATTACHMENT PARTS FOR WHEEL HOUSING LINER ?	\$ 81.00	?

SUB TOTAL SPARE PARTS: **\$ 6,065.00**

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMF 7563 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	LED HEADLIGHT - LH <i>cut</i>	\$ 5,029.00	✓
2	CONTROL UNIT FOR LED HEADLIGHT <i>me</i>	\$ 508.00	+
3	POWER MODULE FOR MAIN LIGHT ELECTRONICS <i>me</i>	\$ 693.00	+
4	LED WITH HEAT SINK - LH <i>me</i>	\$ 666.00	+
5	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>me</i>	\$ 128.00	+
6	FRONT DOOR - LH <i>Debit</i>	\$ 2,279.00	✓
7	FRONT DOOR OUTER DOOR SEAL - LH <i>me</i>	\$ 146.00	✓
8	BONDING AGENT ?	\$ 45.00	?
9	CLEANING SOLUTION ?	\$ 65.00	?
10	APPLICATOR ?	\$ 7.00	?
11	ATTACHMENT PARTS FOR FRONT DOOR ?	\$ 218.00	?
12	DOOR CATCH - LH/RH <i>me</i>	\$ 96.00	+
13	COVER FOR DOOR CATCH - LH/RH <i>me</i>	\$ 13.00	+
14	TRIM STRIP FOR WINDOW GUIDE - LH <i>me</i>	\$ 235.00	+
15	WINDOW SLOT SEAL WITH TRIM STRIP - LH <i>me</i>	\$ 282.00	+
16	FRONT NUMBER PLATE <i>me</i>	S/N \$ 25.00	+
17	STONE CHIP GUARD <i>me</i>	S/N \$ 180.00	✓
18	LHS RIM <i>cut</i>	TBC	✓
19	LHS FRONT TYRE ACHILLES ATR SPORT 235/35/R19 <i>Replaced</i>	TBC	✓
20	SUNDRIES ?	\$ 1,000.00	?

TOTAL SPARE PARTS	:	\$ 28,211.00
TOTAL LABOUR CHARGES		\$ 13,332.00
GRAND TOTAL		\$ 41,543.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian L

Surveyed Date

: 21/02/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 10 days.
inclusive of undercarriage.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant