

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19003049/GQD3S2
Date: 26/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80453734QMX
Claimant Vehicle No :	GBA816J	Insured Vehicle No :	SKV7394X
Date of Loss:	30/01/2019	Nature of Claim:	TP
		Claim No:	584032

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA816J	Engine No:	223B10005273931
Make & Model:	FIAT DOBLO, 1.9 D (M)	Chassis No:	ZFA22300005479118
Reg. Date:	07/02/2007 (Man. Year: 2006)	Odometer:	129155 km
Colour:	Red		
Engine Capacity:	1910 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,915.00	2,835.81	11,079.19	79.62
Miscellaneous Items	70.00	30.00	40.00	57.14
Paintwork Materials	189.82	179.81	10.01	5.27
Labour	762.50	350.00	412.50	54.10
Paintwork Labour	410.00	300.00	110.00	26.83
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,347.32	3,695.62	11,651.70	75.92
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	15,347.32	3,000.00	12,347.32	80.45
+ GST 7.00/7.00% (S\$)	1,074.31	210.00	864.31	80.45
Nett Amount (S\$)	16,421.63	3,210.00	13,211.63	80.45

INSPECTION

Date of Assignment:	15/02/2019	Present Location:	ComfortDelGro Engineering Pte Ltd (Pandan)
Date Inspected:	18/02/2019	Inspected At:	ComfortDelGro Engineering Pte Ltd (Pandan)
Estimated Period of Repair:	5.0 days		45 Pandan Road
			Singapore 609286

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2019)
Parts:	M1-MPV	FIAT DOBLO 1.9 D (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/GBA816J/26/09/2019 11:31	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		12,100.00 F	-
2	1		*FRONT BUMPER (WCP)	Not Necessary	-	*- F
3	1		*FRONT LOCK SUPPORT (WCP)	Not Necessary	-	*- F
4	1		*BONNET LOCK (WCP)	Not Necessary	-	*- F
5	1		*RIGHT HEADLAMP ASSY (WCP)	Not Necessary	-	*- F
6	1		*R/F WING (WCP)	Buckled	-	*450.00 F
7	1		*R/F WHEELHOUSE COVER (WCP)	Deformed	-	*150.00 F
8	1		*R/SLIDING DOOR (WCP)	Bent	-	*1,445.08 FS
9	1		*R/SLDG DOOR MOULDING (WCP)	Cut	-	*206.23 FS
10	1		*R/R BUMPER CORNER (WCP)	Cut	-	*180.00 F
11	1		*R/F TRACK CONT ARM (WCP)	Not Necessary	-	*- F
12	1		*R/F SHOCK ABSORBER (WCP)	Not Necessary	-	*- F
13	1		*R/F STEERING KNUCKLE (WCP)	Not Necessary	-	*- F
14	1		*R/F S-ABS BRKT (WCP)	Not Necessary	-	*- F
15	1		*R/INPUT SHAFT BRG (WCP)	Not Necessary	-	*- F
16	1		*R/F WHEEL HUB (WCP)	Not Necessary	-	*- F
17	1		*R/F WHEEL (WCP)	Cut	-	*250.00 F
18	1		*STEERING GEAR ASSY (WCP)	Not Necessary	-	*- F
19	1		*REAR AXLE SUBFRAME (WCP)	Not Necessary	-	*- F
20	1		*R/R WHEEL HUB (WCP)	Not Necessary	-	*- F
21	1		*R/R WHEEL (WCP)	Not Necessary	-	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	12,100.00	2,681.31
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,815.00	154.50
Total Parts (\$\$)	13,915.00	2,835.81

LKK Auto Consultants Pte Ltd/GBA816J/26/09/2019 11:31. Not valid without Reference section.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	MATERIAL COST	189.82	179.81
<u>Miscellaneous Items</u>				
2	1	SEALANT (NOT NECESSARY)	40.00	0.00
3	1	STICKER BODY LETTERING (NECESSARY)	30.00	30.00
Sub Total (\$\$)			259.82	209.81

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL OF LABOUR	New	410.00	300.00
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	762.50	350.00
Gross Labour Cost (\$\$)			1,172.50	650.00

LKK Auto Consultants Pte Ltd/GBA816J/26/09/2019 11:31. Not valid without Reference section.

< END OF ESTIMATES >