

22/03/2002

ASS. REC. BY:

REF:

CS/FCI19003050/End307

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person):

Joanne Yong (COS)

of

FCI

Date/Time:

18/2/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKQ 7898K

Insured:

SHC 8447G

at Workshop m/s

CAS Garage

Tel:

64842220 Allan

of

No. 1 Kaki Bukit Ave 6 #02-22

Policy No:

Claim No:

D19001116 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/1/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	SKQ 7898K-X
	SHC 8447G-X
19/2/19	Email preli revised to FCI
23/19	IS \$ 11,000 confirmed by email (Ref 15,122.H4, 58/9)

store

REG

FCI

SALES / SERVICE

Insured / Co-insured
 Type of Vehicle: SKQ 7898K
 Make: Mazda 3
 Colour: Red
 Cap / Reading: 64760
 Engine No.: JM 68 M 42A8 F 016 1067
 Gen. Cond: Good
 Steering: Order
 Brake: Order
 Mod.: Nil
 Tyre Size: 205/60R16
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.
 Bal. of Market Value:
 IDAC Accident Report: Consistent? Yes or No
 CIA / PR Score: Consistent? Yes or No
 Est. Repair: days Repair: Yes or No
 Est. Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: Person Contacted:
 Vehicle IN / OUT

26/12/14
 Type of Car / Motorcycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mazda 3
 Colour: Red
 Cap / Reading: 64760
 Engine No.: JM 68 M 42A8 F 016 1067
 Gen. Cond: Good
 Steering: Order
 Brake: Order
 Mod.: Nil
 Tyre Size: 205/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: R/Bal: 7 mm L/Bal: 7 mm D.O.A.: 12/2/19
 Rear: R/Bal: 7 mm L/Bal: 7 mm D.O.A.: 18/2/19
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: Action / Instruction:
 MV - 53,000 * Contact Mr Allan repair limit 11,000 (18/2/19, 6.00pm)
 PV - 43,011 * Discuss Action 11K finalize and 11 days 1/3/19 5pm
 NV - 9989

RECEIVED 05 MAR 2019

Date/Time: File Pass to: ☐ : Prel. Report ☐ : Final Report
 Date/Time: File Return to:
 Add Fee: ☐ Site Insp. (\$) ☐ Interview (\$) ☐ Tech. Insp. (\$) ☐ Witness (\$) ☐
 Report Format: CWS
 Lump Sum / L.B. E: 11,000/-
 Days Of Repair: 11
 Resurvey No. of Trip: 2
 Survey Fee: 170 + 240
 Transportation: 50
 Total: 50 + 50
185
580
53/15
745

MOTOR SURVEY ASSIGNMENT

Date	14-02-2019	Our Ref No. D19001116MFSH
Accident Date	12-02-2019	Claim Type. Third Party
Insured Vehicle	SHC8447G	Third Party Vehicle. SKQ7898K
Survey Location	NO.1 KAKI BUKIT AVE 6 #02-22	
Contact Person.	ALLAN GOH	
Contact No.	64842220/ 87827171	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CAS GARAGE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 19 February 2019 5:33 PM
To: 'CWS Motor Claims'
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19001116MFSH/1, SKQ 7898K
Attachments: SKQ 7898K PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKQ 7898K
Date of survey: 18/2/2019
Number of days : 8 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 18 February 2019 4:28 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19001116MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 18 February 2019 3:57 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19001116MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19001116MFSH

Our ref: CS/FCI19003050/Evd3

Date : 19/2/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKQ 7898K


We thank you for your instruction on 18/2/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/2/2019 at the premises of M/s CAS GARAGE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$26,122.44
Revised Estimate Amount	: S\$17,939.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

STEVE CHEN
Automotive Assessor

> Back to OneMotoring

81657

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3075B
Vehicle Details	
Vehicle No.:	SKQ7898K
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Feb 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	P520247749
Chassis No.:	JM6BM42A8F0161067
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,507.00
Original Registration Date:	26 Dec 2014
First Registration Date:	26 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2024
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$67,089.00
COE Rebate Amount:	\$39,261.00
Total Rebate Amount:	\$43,011.00

The information contained herein is correct as at 18 Feb 2019

OK

5/10



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

BMW X1 2017.



Manufacture Warranty.
Authorised Serviced. Well Kept.
Low Mileage. Accident Free
Direct Owner StarAd



HIN LUNG AUTO
HoBee Group

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category Save Search Print Sort by Date Posted 20 results/page

2 vehicles **Search** Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	mazda 3		Any	Any	2014	Any	Any	Any	Available



☐ **Mazda 3 1.5A Sunroof** **\$50,800** **\$9,030 /yr** **18-Jun-2014** **1,496 cc** **-** **Sedan** **Available**

Very Popular Car! Powerful, Responsive Yet Fuel Efficient. Only 1 Previous Owner. Flexible Loan Packages Available With Attractive Interest Rates. Welcome All Trade In. Call Our Friendly Representativ...

AL Autocar Pte Ltd

Posted: 26-Feb-2019 Tags: 2014 Mazda 3, 2014 mazda 3, Mazda 3, mazda 3, Mazda: 3, Used Mazda

PREMIUM AD



☐ **Mazda 3 1.5A Deluxe** **\$54,800** **\$9,470 /yr** **27-Jun-2014** **1,496 cc** **62,715 km** **Sedan** **Available**

1.98% Interest Rate Available. Buy It From Us With A Peace Of Mind, From A Company Accredited With Outstanding Awards And Professional After Sales Service Assured. Certified With Assurance And Quality...

Dickson Automobile

Posted: 24-Jan-2019 Tags: 2014 Mazda 3, 2014 mazda 3, Mazda 3, mazda 3, Mazda: 3, Used Mazda

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads


20 results/page

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Directory](#) [Products](#) [Insurance](#) [Article](#) [Forum](#) [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used mazda 3, mazda 3 Singapore, used mazda 3 Singapore, used mazda 3, used vehicles Singapore or even buy used mazda 3 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



[About Us](#) [Careers](#) [Contact Us](#) [Sitemap](#) [Terms of Service](#) [Privacy Policy](#) [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/02/2019 17:19
Date Of Accident	12/02/2019 21:30
Exact Location Of Accident	BEDOK NORTH RD & TAMPINES AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKQ7898K
Insured/Policyholder	
Name Of Registered Owner	TAN CHIEW PHENG
NRIC No	S0103075B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97344228
Alternative Phone No	OFFICE-97344228

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099812615
Cover Note Number	

Driver

Name of Driver	CHRIS TAN
NRIC No	S8316911G
Date Of Birth	30/05/1983
Occupation	OUTDOOR
Date Of Driving Pass	02/07/2002
Driving Experience	16 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87516626
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	15 SIGLAP DRIVE
Postcode	456145
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT: T/20190213/2110.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8447G
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	CHUNG CHEE LOONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKM8271H
Vehicle Make/Model/Colour
Details Of Properties VEHICLE C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLJ6545K
Vehicle Make/Model/Colour
Details Of Properties VEHICLE D
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHRIS TAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKQ7898K
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CAS BRIDGE

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to the police report 712019021312110

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Clon x

Policyholder's Signature
Date & Time:

Clon

Driver's Signature
(If driver is not the policyholder)
Date & Time:

13/2/19 4.05pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190213/2110

1 of 4

Report No. T/20190213/2110

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/02/2019 14:27	Vide Report No.:	Station Diary No.: 32
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHRIS TAN			Address: 15 SIGLAP DRIVE SINGAPORE 456145	
ID Type / ID No.: NRIC NO / S8316911G			Contact No.: Home/Office: Mobile: 87516626	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 35	Date of Birth: 30/05/1983	Type of Informant: Driver	
Race: Chinese		Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 12/02/2019 21:20	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 BEDOK NORTH ROAD TAMPINES AVENUE 10 Travelling along Bedok North Road towards Tampines Avenue 10				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHC8447G	Car				Seriously Damaged	0
SKM8271H	Car				Slightly Damaged	3
SKQ7898K	Car				Seriously Damaged	0
SLJ6545K	Car				Slightly Damaged	0

Sketch Plan #4 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190213/2110

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

2 of 4

Report No. T/20190213/2110

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	Chung Chee Leong	ID No.	S1268469Z
Related Vehicle	SHC8447G (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	Lim Swee Kin	ID No.	S1251949D
Related Vehicle	SKM8271H (Car)	Contact No.	93299986
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	CHRIS TAN	ID No.	S8316911G
Related Vehicle	SKQ7898K (Car)	Contact No.	87516626
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	13/02/2019	Date Discharge	13/02/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Sketch Plan #5 Pg. 1



**SINGAPORE
POLICE FORCE**



T/20190213/2110

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

3 of 4

Report No. T/20190213/2110

CONTINUATION OF REPORT

Driver:			
Name	Joseph Loy Chee Sum	ID No.	S7720947F
Related Vehicle	SLJ6545K (Car)	Contact No.	97463108
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 12/02/2019, at around 2120hrs, I was driving along Bedok North Road towards the direction of Tampines Avenue 10. I was driving on the second lane from the right. I had applied brakes to my vehicles as the traffic light in front had turned red, and my vehicle had come to a stop for around 15-20 seconds, I felt an impact coming from the back of my vehicle, and my vehicle moved forward as a result of the impact and collided with the vehicle in front of me (SKM8271H). After the collision, I got out of the vehicle and did an inspection of my vehicle and notice that it had suffered major dents on the front and rear bumper of the vehicle, and the vehicle that collided with me from the rear was a taxi (SHC8447G), and it had suffered serious dents on the front bumper of the taxi. The vehicle in front of me (SKM8271H) had suffered slight dents from the rear bumper due to the collision with my vehicle, and also slight dents on the front bumper as the vehicle had also collided with another vehicle in front (SLJ6545K). SLJ6545K had also suffered slight dents on the rear bumper of the vehicle. All the involved drivers had exchanged particulars. From what I know, none of the involved parties were injured, but I had felt slight pain on my neck, left hip and back. However, no Police or Ambulance had attended to the accident. I had also contacted my workshop (Gas Garage Pte Ltd, Tel: 6484 2220), and my vehicle was towed away.

I have an in-car camera installed in my car and I believe that the incident was being recorded down, however when I handed over my memory card to my workshop yesterday, they were unable to read the file.

I had also sought medical attention on 13/02/2019 at around 0000hrs, and was given 5 days of medical certificate leave for the pain on my neck, back and left hip, as the pain became more intense as time pass.

I am unsure what is the repair cost for the damage on my vehicle as the repair cost and insurance claims were handled by my workshop directly.

Sketch Plan #6 Pg. 1

**SINGAPORE
POLICE FORCE**

T/20190213/2110

Police Station Of Origin:
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428999

4 of 4

Report No. T/20190213/2110

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 JEREMY GOH ZEN KIAT

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

13/02/2019 14:27

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG-HOCK

Contact No.: 65476436

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE

Steve LANN
18/2/19 5-15 pm
L/S
Rok Ah spy & dismantle

[Signature]

20/2/19



CAS GARAGE PTE LTD

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company:

Address:

Telephone:

64616555

Fax:622

Email

emailus@sompo.com.sg

Make/ Model :

MAZDA 3

Date:

12.02.2019

Chassis No :

JM6BM42A8F0161067

Vehicle No:

SKQ7898K

Date/Time of Acci

12.02.2019/ 2130

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISC	FINAL PRICE \$
1	BOOTLID / OD	1	\$ 956.70	20%	\$ 765.36
2	BOOTLID HINGES RH / LH / BT	2	\$ 212.80	20%	\$ 170.24
3	BOOTLID INNER TRIM X NN	1	\$ 256.40	20%	\$ 205.12
4	BOOTLID INNER HANDLE X NN	1	\$ 42.10	20%	\$ 33.68
5	BOOTLID REFLECTORS RH / CUT LH / BR 2	2	\$ 603.80	20%	\$ 483.04
6	BOOTLID LOWER LOCK X NN	1	\$ 45.60	20%	\$ 36.48
7	BOOTLID INNER LOCK / BT	1	\$ 189.70	20%	\$ 151.76
8	BOOTLID LOGO / NEC	1	\$ 73.10	20%	\$ 58.48
9	BOOTLID EMBLEM "MAZDA" / NEC	1	\$ 56.90	20%	\$ 45.52
10	BOOTLID EMBLEM "SKYACTIVE" / NEC	1	\$ 123.50	20%	\$ 98.80
11	BOOTLID STOPPER LH / RH X MISSING	2	\$ 68.40	20%	\$ 54.72
12	BOOTLID TOP LOCK MOTOR X NN	1	\$ 243.10	20%	\$ 194.48
13	BOOTLID DETECTOR X NN	1	\$ 289.70	20%	\$ 231.76
14	BOOTLID DETECTOR BRACKET X NN	1	\$ 85.60	20%	\$ 68.48
15	BOOTLID WEATHERSTRIP / CR4	1	\$ 156.30	20%	\$ 125.04
16	REAR BUMPER / BR	1	\$ 1,023.60	20%	\$ 818.88
17	REAR BUMPER SIDE RETAINER LH / RH	2	\$ 86.40	20%	\$ 69.12
18	REAR BUMPER REFLECTORS RH / LH ?	2	\$ 95.20	20%	\$ 76.16
19	REAR BUMPER BRACKET X NN 47.60	1	\$ 78.90	20%	\$ 63.12
20	REAR BUMPER REINFORCEMENT / DO	1	\$ 512.30	20%	\$ 409.84
21	REAR SILENCER BOX ?	1	\$ 857.70	20%	\$ 686.16
22	REAR SILENCER BOX MOUNTING ?	2	\$ 98.60	20%	\$ 78.88
23	REAR SILENCER BOX PROTECTOR ?	1	\$ 197.20	20%	\$ 157.76
24	TAILAMPS RH / LH / BR	2	\$ 1,106.80	20%	\$ 885.44
25	TAILAMPS PANEL RH ? LH ?	2	\$ 1,208.20	20%	\$ 966.56

26	REAR FENDER RH X R LH X R	2	\$ 1,985.70	20%	\$ 1,588.56
27	REAR FENDER INNER TRIM RH X LH X NH	2	\$ 512.60	20%	\$ 410.08
28	REAR FENDER INNER COWLING RH X LH X 2 NH	2	\$ 298.70	20%	\$ 238.96
29	REAR FENDER AIR VENT ?	2	\$ 142.80	20%	\$ 114.24
30	REAR WINDSCREEN MOLDING X NH	1	\$ 78.20	20%	\$ 62.56
31	REAR END PANEL / 00	1	\$ 509.70	20%	\$ 407.76
32	REAR END PANEL TOP GARNISH / CR	1	\$ 89.30	20%	\$ 71.44
33	REAR FLOOR PANEL ?	1	\$ 823.80	20%	\$ 659.04
34	REAR FLOOR PANEL TOP BOARD ?	1	\$ 367.20	20%	\$ 293.76
35	FRONT BONNET / 00	1	\$ 1,023.70	20%	\$ 818.96
36	FRONT BONNET SEAL X NH	1	\$ 95.80	20%	\$ 76.64
37	BONNET STOPPER X NH	2	\$ 40.20	20%	\$ 32.16
38	BONNET HINGES X NH	2	\$ 96.20	20%	\$ 76.96
39	BONNET LOCK / BT	1	\$ 202.10	20%	\$ 161.68
40	BONNET LOCK BRACE PANEL ?	1	\$ 52.30	20%	\$ 41.84
41	FRONT BUMPER / BR	1	\$ 978.90	20%	\$ 783.12
42	FRONT BUMPER TOP GRILLE / 00	1	\$ 186.90	20%	\$ 149.52
43	FRONT BUMPER INNER SEAL ?	1	\$ 105.30	20%	\$ 84.24
44	FRONT BUMPER FOGLAMP COVERS RH ? LH X	2 1	\$ 106.80	20%	\$ 85.44
45	FRONT BUMPER FOGLAMP HOUSING RH ? LH X	2 1	\$ 40.20	20%	\$ 32.16
46	FRONT BUMPER UNDER COVER ?	1	\$ 102.30	20%	\$ 81.84
47	FRONT BUMPER TOWING COVER X NH	1	\$ 40.60	20%	\$ 32.48
48	FRONT BUMPER SIDE RETAINER RH / LH / 2 BR	2	\$ 46.40	20%	\$ 37.12
49	FRONT BUMPER REINFORCEMENT ?	1	\$ 554.60	20%	\$ 443.68
50	FRONT FENDERS LH X RH X	2	\$ 1,065.80	20%	\$ 852.64
51	FRONT FENDER COWLING RH ? LH X	2	\$ 356.60	20%	\$ 285.28
52	HEADLAMPS LH ? RH ?	2	\$ 1,685.80	20%	\$ 1,348.64
53	HEADLAMPS BRACKETS LH ? RH ?	2	\$ 107.60	20%	\$ 86.08
54	FRONT GRILLE / BR	1	\$ 586.10	20%	\$ 468.88
55	FRONT GRILLE CHROME / RH / LH BR	2	\$ 186.00	20%	\$ 148.80
56	FRONT GRILLE LOGO / NEC	1	\$ 56.30	20%	\$ 45.04
57	FRONT SUPPORT PANEL ?	1	\$ 185.00	20%	\$ 148.00
58	FRONT SUPPORT PANEL LOWER ?	1	\$ 85.60	20%	\$ 68.48
59	WIPER WASHER TANK X NH	1	\$ 102.60	20%	\$ 82.08
60	WIPER WASHER TANK MOTOR X NH	1	\$ 165.70	20%	\$ 132.56
61	FRONT RADIATOR ?	1	\$ 402.30	20%	\$ 321.84
62	FRONT RADIATOR FAN COWLING X NH	1	\$ 354.60	20%	\$ 283.68
63	FRONT RADIATOR FAN BLADE X NH	1	\$ 156.70	20%	\$ 125.36
64	FRONT RADIATOR FAN COWLING X NH	1	\$ 297.60	20%	\$ 238.08
65	FRONT RADIATOR TOP HOSE X NH	1	\$ 58.60	20%	\$ 46.88
66	FRONT RADIATOR LOWER HOSE X NH	1	\$ 48.20	20%	\$ 38.56
67	FRONT RADIATOR SPARE TANK X NH	1	\$ 204.60	20%	\$ 163.68
68	FRONT CONDENSER ?	1	\$ 388.70	20%	\$ 310.96
69	FRONT AIR CON FAN BLADE X NH	1	\$ 186.70	20%	\$ 149.36
70	FRONT CONDENSER SIDE GARNISH ?	2	\$ 85.60	20%	\$ 68.48
71	FRONT AIR INTAKE AIR DUCT X NH	1	\$ 168.70	20%	\$ 134.96
Total List Price Cost					\$ 19,267.44

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING / <i>CR</i>	1 SET	\$ 50.00	<i>35 n</i>	\$ 50.00
2	FRONT NUMBER PLATE / <i>BR</i>	1	\$ 35.00		\$ 35.00
3	FRONT SUPPORT PANEL CLIPS / <i>NEC</i>	1 SET	\$ 30.00	<i>20 n</i>	\$ 30.00
4	REAR BUMPER CLIPS / <i>NEC</i>	1 SET	\$ 30.00	<i>20 n</i>	\$ 30.00
5	FRONT BUMPER CLIPS / <i>NEC</i>	1 SET	\$ 30.00	<i>20 n</i>	\$ 30.00
6	REAR FENDER COWLING CLIPS X <i>NN</i>	1 SET	\$ 30.00		\$ 30.00
7	REAR REVERSE SENSORS / <i>BR</i>	1 SET	\$ 280.00	<i>240 n</i>	\$ 280.00
8	REVERSE SENSORS HARDNESS ?	1 SET	\$ 350.00		\$ 350.00
9	END PANEL SEALANT / <i>NEC</i>	2	\$ 80.00	<i>20 n</i>	\$ 80.00
10	FLOOR PANEL SEALANT / <i>NEC</i>	2	\$ 80.00	<i>20 n</i>	\$ 80.00
11	BOOTLID INNER TRIM CLIPS / <i>NEC</i>	1 SET	\$ 30.00	<i>20 n /</i>	\$ 30.00
12	REAR FENDER INNER TRIM CLIPS X <i>NN</i>	2 SET	\$ 60.00		\$ 60.00
13	REAR FENDER COWLING CLIPS X <i>NN</i>	2 SET	\$ 60.00		\$ 60.00
14	END PANEL TOP GARNISH CLIPS / <i>NEC</i>	1 SET	\$ 30.00	<i>20 n</i>	\$ 30.00
Total Special Nett Items					\$ 1,175.00
Labour Works/ Panel Beating Related Works					
Job Scope					Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL					\$ 2,200.00
					<i>1400</i>
Spray Painting					
Job Scope					Quotation
TO RESPRAY AFFECTED AREAS					\$ 2,400.00
					<i>1600</i>
Others Cost (Accident Repair Related Expenses)					
Job Scope					Quotation
TO TUFFCOAT AFFECTED AREA					<i>100</i> \$ 300.00
TO REMOVE/ REFIT WIRING CHECKS					<i>30</i> \$ 120.00
TO REMOVE/ RENEW CONDENSER AND TOP UP AIR-CON GAS					<i>100</i> \$ 120.00
TO CONDUCT WATER LEAKAGE TEST					<i>X</i> \$ 150.00
TO REMOVE/ REPLACE REAR SILENCER BOX ?					\$ 120.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING					<i>30</i> \$ 150.00
TO REMOVE AND REPLACE TAILGATE MECHANISM					<i>30</i> \$ 120.00
Total Others Cost					\$ 1,080.00
GRAND TOTAL					\$ 26,122.44

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax : 6509 9501
TEL: 64842220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company:

Address:

Telephone:

64616555

Fax:622

Email:

Make/ Model :

MAZDA 3

Date:

12.02.2019

Chassis No :

JM6BM42A8F0161067

Vehicle No:

SKQ7898K

Date/Time of Acci

12.02.2019/ 2130

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISC	FINAL PRICE \$
1	BOOTLID / DD	1	\$ 956.70	20%	\$ 765.36
2	BOOTLID HINGES RH / LH / BT	2	\$ 212.80	20%	\$ 170.24
3	BOOTLID INNER TRIM X NN	1	\$ 256.40	20%	\$ 205.12
4	BOOTLID INNER HANDLE X NN	1	\$ 42.10	20%	\$ 33.68
5	BOOTLID REFLECTORS RH / CUT LH / BR	2	\$ 603.80	20%	\$ 483.04
6	BOOTLID LOWER LOCK X NN	1	\$ 45.60	20%	\$ 36.48
7	BOOTLID INNER LOCK / BT	1	\$ 189.70	20%	\$ 151.76
8	BOOTLID LOGO / NEC	1	\$ 73.10	20%	\$ 58.48
9	BOOTLID EMBLEM"MAZDA" / NEC	1	\$ 56.90	20%	\$ 45.52
10	BOOTLID EMBLEM"SKYACTIVE" / NEC	1	\$ 123.50	20%	\$ 98.80
11	BOOTLID STOPPER LH / RH X MIS	2	\$ 68.40	20%	\$ 54.72
12	BOOTLID TOP LOCK MOTOR X NS	1	\$ 243.10	20%	\$ 194.48
13	BOOTLID DETECTOR X NN	1	\$ 289.70	20%	\$ 231.76
14	BOOTLID DETECTOR BRACKET X NN	1	\$ 85.60	20%	\$ 68.48
15	BOOTLID WEATHERSTRIP / CR4	1	\$ 156.30	20%	\$ 125.04
16	REAR BUMPER / BR	1	\$ 1,023.60	20%	\$ 818.88
17	REAR BUMPER SIDE RETAINER LH / RH	2	\$ 86.40	20%	\$ 69.12
18	REAR BUMPER REFLECTORS RH / LH	2	\$ 95.20	20%	\$ 76.16
19	REAR BUMPER BRACKET X NN	1	\$ 78.90	20%	\$ 63.12
20	REAR BUMPER REINFORCEMENT / DD	1	\$ 512.30	20%	\$ 409.84
21	REAR SILENCER BOX / DD	1	\$ 857.70	20%	\$ 686.16
22	REAR SILENCER BOX MOUNTING / TN	2	\$ 98.60	20%	\$ 78.88
23	REAR SILENCER BOX PROTECTOR / BT	1	\$ 197.20	20%	\$ 157.76
24	TAILAMPS RH / LH / BR	2	\$ 1,106.80	20%	\$ 885.44
25	TAILAMPS PANEL RH / LH / DD	2	\$ 1,208.20	20%	\$ 966.56

26	REAR FENDER RH X R LH X R	2	\$ 1,985.70	20%	\$ 1,588.56
27	REAR FENDER INNER TRIM RH X LH X	2	\$ 512.60	20%	\$ 410.08
28	REAR FENDER INNER COWLING RH X LH X NN	2	\$ 298.70	20%	\$ 238.96
29	REAR FENDER AIR VENT LH X RH X	2	\$ 142.80	20%	\$ 114.24
30	REAR WINDSCREEN MOLDING X NN	1	\$ 78.20	20%	\$ 62.56
31	REAR END PANEL / DD	1	\$ 509.70	20%	\$ 407.76
32	REAR END PANEL TOP GARNISH / CRH	1	\$ 89.30	20%	\$ 71.44
33	REAR FLOOR PANEL / DD	1	\$ 823.80	20%	\$ 659.04
34	REAR FLOOR PANEL TOP BOARD / CRH	1	\$ 367.20	20%	\$ 293.76
35	FRONT BONNET / DD	1	\$ 1,023.70	20%	\$ 818.96
36	FRONT BONNET SEAL X NN	1	\$ 95.80	20%	\$ 76.64
37	BONNET STOPPER X NN	2	\$ 40.20	20%	\$ 32.16
38	BONNET HINGES X NN	2	\$ 96.20	20%	\$ 76.96
39	BONNET LOCK / BT	1	\$ 202.10	20%	\$ 161.68
40	BONNET LOCK BRACE PANEL / BT	1	\$ 52.30	20%	\$ 41.84
41	FRONT BUMPER / BR	1	\$ 978.90	20%	\$ 783.12
42	FRONT BUMPER TOP GRILLE / DD	1	\$ 186.90	20%	\$ 149.52
43	FRONT BUMPER INNER SEAL X NN	1	\$ 105.30	20%	\$ 84.24
44	FRONT BUMPER FOGLAMP COVERS RH X LH X	2	\$ 106.80	20%	\$ 85.44
45	FRONT BUMPER FOGLAMP HOUSING RH X LH X	2	\$ 40.20	20%	\$ 32.16
46	FRONT BUMPER UNDER COVER / TN	1	\$ 102.30	20%	\$ 81.84
47	FRONT BUMPER TOWING COVER X NN	1	\$ 40.60	20%	\$ 32.48
48	FRONT BUMPER SIDE RETAINER RH X LH X	2	\$ 46.40	20%	\$ 37.12
49	FRONT BUMPER REINFORCEMENT / DD	1	\$ 554.60	20%	\$ 443.68
50	FRONT FENDERS LH X RH X NN	2	\$ 1,065.80	20%	\$ 852.64
51	FRONT FENDER COWLING RH X LH X	2	\$ 356.60	20%	\$ 285.28
52	HEADLAMPS LH X RH X BR	2	\$ 1,685.80	20%	\$ 1,348.64
53	HEADLAMPS BRACKETS LH X RH X	2	\$ 107.60	20%	\$ 86.08
54	FRONT GRILLE / BR	1	\$ 586.10	20%	\$ 468.88
55	FRONT GRILLE CHROME / RH X LH X BR	2	\$ 186.00	20%	\$ 148.80
56	FRONT GRILLE LOGO / NEC	1	\$ 56.30	20%	\$ 45.04
57	FRONT SUPPORT PANEL / BR	1	\$ 185.00	20%	\$ 148.00
58	FRONT SUPPORT PANEL LOWER / CRH	1	\$ 85.60	20%	\$ 68.48
59	WIPER WASHER TANK X NN	1	\$ 102.60	20%	\$ 82.08
60	WIPER WASHER TANK MOTOR X NN	1	\$ 165.70	20%	\$ 132.56
61	FRONT RADIATOR / DD	1	\$ 402.30	20%	\$ 321.84
62	FRONT RADIATOR FAN COWLING X NN	1	\$ 354.60	20%	\$ 283.68
63	FRONT RADIATOR FAN BLADE X NN	1	\$ 156.70	20%	\$ 125.36
64	FRONT RADIATOR FAN COWLING X NN	1	\$ 297.60	20%	\$ 238.08
65	FRONT RADIATOR TOP HOSE X NN	1	\$ 58.60	20%	\$ 46.88
66	FRONT RADIATOR LOWER HOSE X NN	1	\$ 48.20	20%	\$ 38.56
67	FRONT RADIATOR SPARE TANK X NN	1	\$ 204.60	20%	\$ 163.68
68	FRONT CONDENSER / DD	1	\$ 388.70	20%	\$ 310.96
69	FRONT AIR CON FAN BLADE X NN	1	\$ 186.70	20%	\$ 149.36
70	FRONT CONDENSER SIDE GARNISH / BR	2	\$ 85.60	20%	\$ 68.48
71	FRONT AIR INTAKE AIR DUCT / BR	1	\$ 168.70	20%	\$ 134.96
Total List Price Cost					\$ 19,267.44

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR NUMBER PLATE WITH CASING	1 SET	\$ 50.00	35/ BR	\$ 50.00
2	FRONT NUMBER PLATE /	1	\$ 35.00	20/ BR	\$ 35.00
3	FRONT SUPPORT PANEL CLIPS /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
4	REAR BUMPER CLIPS /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
5	FRONT BUMPER CLIPS /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
6 front	REAR FENDER COWLING CLIPS * /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
7	REAR REVERSE SENSORS /	1 SET	\$ 280.00	20 n BR	\$ 280.00
8	REVERSE SENSORS HARDNESS * X	1 SET	\$ 350.00	NS	\$ 350.00
9	END PANEL SEALANT /	21	\$ 80.00	20 n NEC	\$ 80.00
10	FLOOR PANEL SEALANT /	21	\$ 80.00	20 n NEC	\$ 80.00
11	BOOTLID INNER TRIM CLIPS /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
12	REAR FENDER INNER TRIM CLIPS * /	2 SET	\$ 60.00	40/ NEC	\$ 60.00
13	REAR FENDER COWLING CLIPS * X	2 SET	\$ 60.00	NN	\$ 60.00
14	END PANEL TOP GARNISH CLIPS /	1 SET	\$ 30.00	20 n NEC	\$ 30.00
Total Special Nett Items					\$ 1,175.00
Labour Works/ Panel Beating Related Works					
Job Scope					Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL					\$ 2,200.00
Spray Painting					1400 1600
Job Scope					Quotation
TO RESPRAY AFFECTED AREAS					\$ 2,400.00
Others Cost (Accident Repair Related Expenses)					1600
Job Scope					Quotation
TO TUFFCOAT AFFECTED AREA					100 \$ 300.00
TO REMOVE/ REFIT WIRING CHECKS					30 \$ 120.00
TO REMOVE/ RENEW CONDENSER AND TOP UP AIR-CON GAS					100 \$ 120.00
TO CONDUCT WATER LEAKAGE TEST					30 / * \$ 150.00
TO REMOVE/ REPLACE REAR SILENCER BOX * /					80 \$ 120.00
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING					30 \$ 150.00
TO REMOVE AND REPLACE TAILGATE MECHANISM					30 \$ 120.00
Total Others Cost					\$ 1,080.00
GRAND TOTAL					\$ 26,122.44

CAS GARAGE PTE LTD

Person Incharge: Allan
 Direct Contact: +65 8782 7171
 Email: allangoh.cas@gmail.com
 Fax : 6509 9501
 TEL: 64842220

Steve Chen (LKK Auto)

From: Allan Goh <allangoh.cas@gmail.com>
Sent: Saturday, March 02, 2019 1:18 PM
To: Steve Chen (LKK Auto)
Cc: Cher Yip
Subject: Re: SKQ7898K Finalize

Dear Steve,

We will accept the finalized amount of \$11k and 11 days repair.

Thank You.

Regards,
Allan

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Tel: 6484 2220
Mobile: 8782 7171

On Sat, Mar 2, 2019 at 9:55 AM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Allan,

As per our communication yesterday regarding the above vehicle finalize \$11k and 11 days repair.

Kindly revert.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19003050/Evd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8447G	Veh. Inspected	SKQ 7898K
Policy No.		Coverage (\$)	0.00
Claim No.	D19001116MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	18/02/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JM6BM42A8F0161067	Colour	RED
Odometer	64760	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	TOYO	7 mm
L/H Front Tyre	205/60 R16	TOYO	7 mm
R/H Rear Tyre	205/60 R16	TOYO	7 mm
L/H Rear Tyre	205/60 R16	TOYO	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2019	Inspection Date	18/02/2019
Survey held at	CAS GARAGE PTE LTD-1 KAKI BUKIT AVE 6 #02-22		
Repairer	-		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	11 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 7898K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED	956.70	956.70
2	BOOTLID HINGES	BENT	212.80	212.80
1	BOOTLID INNER TRIM	NOT NECESSARY	256.40	-
1	BOOTLID INNER HANDLE	NOT NECESSARY	42.10	-
2	BOOTLID REFLECTORS	O/S CUT / N/S BROKEN	603.80	603.80
1	BOOTLID LOWER LOCK	NOT NECESSARY	45.60	-
1	BOOTLID INNER LOCK	BENT	189.70	189.70
1	BOOTLID LOGO	NECESSARY	73.10	73.10
1	BOOTLID EMBLEM "MAZDA"	NECESSARY	56.90	56.90
1	BOOTLID EMBLEM "SKYACTIVE"	NECESSARY	123.50	123.50
2	BOOTLID STOPPER	N/S MISSING	68.40	34.20
1	BOOTLID TOP LOCK MOTOR	NO SUCH PARTS	243.10	-
1	BOOTLID DETECTOR	NOT NECESSARY	289.70	-
1	BOOTLID DETECTOR BRACKET	NOT NECESSARY	85.60	-
1	BOOTLID WEATHERSTRIP	CRUMPLED	156.30	156.30
1	REAR BUMPER	BROKEN	1,023.60	1,023.60
2	REAR BUMPER SIDE RETAINER	BROKEN	86.40	86.40
2	REAR BUMPER REFLECTORS	BROKEN	95.20	95.20
1	REAR BUMPER BRACKET	NOT NECESSARY	78.90	-
1	REAR BUMPER REINFORCEMENT	DENTED	512.30	512.30
1	REAR SILENCER BOX	DENTED	857.70	857.70
2	REAR SILENCER BOX MOUNTING	TORN	98.60	98.60
1	REAR SILENCER BOX PROTECTOR	BENT	197.20	197.20
2	TAILLAMPS	BROKEN	1,106.80	1,106.80
2	TAILLAMPS PANEL	DENTED	1,208.20	1,208.20
2	REAR FENDER	TO REPAIR SEE LABOUR	1,985.70	-
2	REAR FENDER INNER TRIM	TORN	512.60	512.60
2	REAR FENDER INNER COWLING	NOT NECESSARY	298.70	-
2	REAR FENDER AIR VENT	BROKEN	142.80	142.80

Report Ref No. CS/FCI19003050/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN MOLDING	NOT NECESSARY	78.20	-
1	REAR END PANEL	DENTED	509.70	509.70
1	REAR END PANEL TOP GARNISH	CRUMPLED	89.30	89.30
1	REAR FLOOR PANEL	DENTED	823.80	823.80
1	REAR FLOOR PANEL TOP BOARD	CRUMPLED	367.20	367.20
1	FRONT BONNET	DENTED	1,023.70	1,023.70
1	FRONT BONNET SEAL	NOT NECESSARY	95.80	-
2	BONNET STOPPER	NOT NECESSARY	40.20	-
2	BONNET HINGES	NOT NECESSARY	96.20	-
1	BONNET LOCK	BENT	202.10	202.10
1	BONNET LOCK BRACE PANEL	BENT	52.30	52.30
1	FRONT BUMPER	BROKEN	978.90	978.90
1	FRONT BUMPER TOP GRILLE	DENTED	186.90	186.90
1	FRONT BUMPER INNER SEAL	NOT NECESSARY	105.30	-
2	FRONT BUMPER FOGLAMP COVERS	O/S BROKEN	106.80	53.40
2	FRONT BUMPER FOGLAMP HOUSING	NO SUCH PARTS	40.20	-
1	FRONT BUMPER UNDER COVER	TORN	102.30	102.30
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	40.60	-
2	FRONT BUMPER SIDE RETAINER	BROKEN	46.40	46.40
1	FRONT BUMPER REINFORCEMENT	DENTED	554.60	554.60
2	FRONT FENDERS	NOT NECESSARY	1,065.80	-
2	FRONT FENDER COWLING	O/S TORN	356.60	178.30
2	HEADLAMPS	BROKEN	1,685.80	1,685.80
2	HEADLAMPS BRACKETS	BROKEN	107.60	107.60
1	FRONT GRILLE	BROKEN	586.10	586.10
2	FRONT GRILLE CHROME	BROKEN	186.00	186.00
1	FRONT GRILLE LOGO	NECESSARY	56.30	56.30
1	FRONT SUPPORT PANEL	BROKEN	185.00	185.00
1	FRONT SUPPORT PANEL LOWER	CRUMPLED	85.60	85.60
1	WIPER WASHER TANK	NOT NECESSARY	102.60	-
1	WIPER WASHER TANK MOTOR	NOT NECESSARY	165.70	-
1	FRONT RADIATOR	DENTED	402.30	402.30
1	FRONT RADIATOR FAN COWLING	NOT NECESSARY	354.60	-

Report Ref No. CS/FCI19003050/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR FAN BLADE	NOT NECESSARY	156.70	-
1	FRONT RADIATOR FAN COWLING	NOT NECESSARY	297.60	-
1	FRONT RADIATOR TOP HOSE	NOT NECESSARY	58.60	-
1	FRONT RADIATOR LOWER HOSE	NOT NECESSARY	48.20	-
1	FRONT RADIATOR SPARE TANK	NOT NECESSARY	204.60	-
1	FRONT CONDENSER	DENTED	388.70	388.70
1	FRONT AIR CON FAN BLADE	NOT NECESSARY	186.70	-
2	FRONT CONDENSER SIDE GARNISH	BROKEN	85.60	85.60
1	FRONT AIR INTAKE AIR DUCT	BROKEN	168.70	168.70
	LESS 20% DISCOUNT		-4,816.86	-3,471.00
			19,267.44	13,884.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR NUMBER PLATE WITH CASING (SN)	BROKEN	50.00	35.00
1	FRONT NUMBER PLATE (SN)	BROKEN	35.00	20.00
1	SET FRONT SUPPORT PANEL CLIPS (SN)	NECESSARY	30.00	20.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT FENDER COWLING CLIPS (SN)	NECESSARY	30.00	20.00
1	SET REAR REVERSE SENSORS (SN)	BROKEN	280.00	200.00
1	SET REVERSE SENSORS HARDNESS (SN)	NO SUCH PARTS	350.00	-
2	END PANEL SEALANT (SN)	NECESSARY-1PC ONLY	80.00	20.00
2	FLOOR PANEL SEALANT (SN)	NECESSARY-1PC ONLY	80.00	20.00
1	SET BOOTLID INNER TRIM CLIPS (SN)	NECESSARY	30.00	20.00
2	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	60.00	40.00
2	SET REAR FENDER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
			1,175.00	455.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL. INCLUSIVE OF THE REPAIR OF REAR FENDER.		2,200.00	1,600.00
	TO RESPRAY AFFECTED AREAS.		2,400.00	1,600.00

Report Ref No. CS/FCI19003050/Evd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TUFFCOAT AFFECTED AREA.		300.00	100.00
	TO REMOVE / REFIT WIRING CHECKS.		120.00	30.00
	TO REMOVE / RENEW CONDENSER AND TOP UP AIR-CON GAS.		120.00	100.00
	TO CONDUCT WATER LEAKAGE TEST.		150.00	30.00
	TO REMOVE / REPLACE REAR SILENCER BOX.		120.00	80.00
	TO REMOVE / REPLACE REVERSE SENSORS AND DISTANCE SETTLING.		150.00	30.00
	TO REMOVE AND REPLACE TAILGATE MECHANISM.		120.00	30.00
			5,680.00	3,600.00
GRAND TOTAL			26,122.44	17,939.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00
---	--	--	--	-----------

Report Ref No. CS/FCI19003050/Evd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.