

ASS. REC. BY:

REF:

CS/TP19003053/Ktd302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLJ 4500C Yr Regn: 12, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle c.c. 1495Colour: M. Grey A/C: Insured / Std / NI / NASp. Reading: 153286 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GKR 1100510Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Davanti

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 6 mmL/Bal. 8 mm L/Bal. 6 mmD.O.A. 8/2/19 D.O.I. 12/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

SLJ 4500C-X

11 Km @ 835d Ured. 3627.48, 36%

RECEIVED 26 FEB 2019

Date/Time, File Pass to?

1) 26/2/19 ☐ : Prell. ReportDate/Time, File Return to? ☒ : Final Report

2) _____

Days Of Repair: 6Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) 6350/-

170
50
50+50
36
80
436

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/02/2019 14:22
Date Of Accident	08/02/2019 07:10
Exact Location Of Accident	ALONG BT BATOK ST 21 TURNING TO BLK 205 CARPARK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLJ4500C
Insured/Policyholder	
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
Co Reg No	199904194N
Email Address	SANDY@SKYWAY.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64168550
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE 1.5G CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A 28795104 MCX
Cover Note Number	
Driver	
Name of Driver	YEE YEW WENG SIMON
NRIC No	S1428964Z
Date Of Birth	14/12/1960
Occupation	OUTDOOR
Date Of Driving Pass	21/12/1982
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98536888
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: *Boi*
NRIC/FIN No.:

辉 阳 汽 车 有 限 公 司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

08/02/2019

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SLJ4500C

1pc	rear tailgate	R	\$ 1,193.70	—
1pc	rear tailgate "H" logo	mc	\$ 58.00	—
1pc	rear tailgate "SHUTTLE" emblem	mc	\$ 55.00	—
1pc	rear tailgate chrome		\$ 383.10	7
1pc	rear tailgate LH reflector		\$ 340.80	7
1pc	rear tailgate inner lock	mc	\$ 289.40	—
1pc	rear tailgate inner rubber	DIHWT	\$ 188.50	—
1pc	rear tailgate inner garnish	mc	\$ 358.50	—
1pc	rear LH taillamp	mc	\$ 520.50	—
2pcs	rear taillamp lower bracket @\$89.50	mc	\$ 179.00	X
1pc	rear bumper	R	\$ 1,150.60	—
2pcs	rear bumper side retainer @\$38.50	mc	\$ 77.00	X
1pc	rear bumper LH reflector		\$ 65.00	7
1pc	rear bumper LH reflector garnish	mc	\$ 85.00	—
1pc	rear end panel	R	\$ 601.50	—
1pc	rear end panel outer sensor		\$ 190.50	7
1pc	rear end panel inner sensor		\$ 185.00	7
1pc	rear end panel LH side panel		\$ 385.50	7
1pc	rear end panel inner garnish	mc	\$ 295.20	—
1pc	rear end panel inner garnish cover	mc	\$ 158.50	—
1pc	rear froot panel garnish box	mc	\$ 495.80	—
1pc	rear froot panel sponge	mc	\$ 181.95	X
1pc	rear LH fender inner garnish	mc	\$ 658.80	—

less 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Scratch repair (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1set	rear parking sensor	mc	s.nett	\$ 280.00	2005A
1set	rear windscreen glass moulding	mc	s.nett	\$ 120.00	—
1set	rear number plate & casing	mc	s.nett	\$ 50.00	X

remove & refit rear windscreen glass	\$ 150.00	1201
wiring	\$ 120.00	201
tuffkote	\$ 180.00	601
spray painting	\$ 1,200.00	8001
labour charges	\$ 1,400.00	8001
Total	\$ 9,977.48	



1 more spraying.
Pending for date.

Not Authorise
11 Bay & 35d
Punong After Pain
6 days

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

08/02/2019

Owner: SKYWAY MOTOR PTE LTD

ESTIMATE TO REPAIR HONDA SHUTTLE - SLJ4500C

1pc	rear tailgate
1pc	rear tailgate "H" logo
1pc	rear tailgate "SHUTTLE" emblem
1pc	* rear tailgate chrome
1pc	* rear tailgate LH reflector
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear LH taillamp
2pcs	rear taillamp lower bracket @\$89.50
1pc	rear bumper
2pcs	rear bumper side retainer @\$38.50
1pc	* rear bumper LH reflector
1pc	rear bumper LH reflector garnish
1pc	rear end panel
1pc	* rear end panel outer sensor
1pc	rear end panel inner sensor
1pc	* rear end panel LH side panel
1pc	rear end panel inner garnish
1pc	rear end panel inner garnish cover
1pc	rear float panel garnish box
1pc	rear float panel sponge
1pc	rear LH fender inner garnish

Ry	\$ 1,193.70	—
mc	\$ 58.00	—
mc	\$ 55.00	—
mg	\$ 383.10	✓
nd/l	\$ 340.80	✓
nd	\$ 289.40	—
nd	\$ 188.50	—
mg	\$ 358.50	—
mc	\$ 520.50	—
mc	\$ 179.00	X
Ry	\$ 1,150.60	—
mc	\$ 77.00	X
mc	\$ 65.00	✓
nd	\$ 85.00	—
Ry	\$ 601.50	—
mc	\$ 190.50	X
mc	\$ 185.00	X
Ry	\$ 385.50	✓
mg	\$ 295.20	—
nd	\$ 158.50	—
mc	\$ 495.80	—
mc	\$ 181.95	X
mc	\$ 658.80	—
\$ 8,096.85		
\$ 1,619.37		
\$ 6,477.48		

1set	rear parking sensor
1set	rear windscreen glass moulding
1set	rear number plate & casing

nd	s.nett	\$ 280.00	2005A
mc	s.nett	\$ 120.00	—
mc	s.nett	\$ 50.00	X

remove & refit rear windscreen glass

wiring
tuffkote
spray painting
labour charges
Total

\$ 150.00	1201
\$ 120.00	201
\$ 180.00	601
\$ 1,200.00	8001
\$ 1,400.00	8001
\$ 9,977.48	

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (if any) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HUI YANG MOTOR PTE LTD		Ref : CS/TP19003053/Ktd3e2		
BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARESINGAPORE 575721		Date : 01-03-2019		
ON BEHALF OF SKYWAY MOTOR PTE LTD		Code : TP034		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SLJ 4500C	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		12/02/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	GK81100510	Colour	METALLIC GREY	
Odometer	153286	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	DAVANTI	8 mm	
L/H Front Tyre	185/60 R15	DAVANTI	8 mm	
R/H Rear Tyre	185/60 R15	DAVANTI	6 mm	
L/H Rear Tyre	185/60 R15	DAVANTI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2019	Inspection Date	12/02/2019	
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 4500C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,193.70	1,193.70
1	REAR TAILGATE "H" LOGO	NECESSARY	58.00	58.00
1	REAR TAILGATE "SHUTTLE" EMBLEM	NECESSARY	55.00	55.00
1	REAR TAILGATE CHROME	MTG CRACKED	383.10	383.10
1	REAR TAILGATE LH REFLECTOR	DENTED / CUT	340.80	340.80
1	REAR TAILGATE INNER LOCK	DENTED	289.40	289.40
1	REAR TAILGATE INNER RUBBER	DISTORTED / CUT	188.50	188.50
1	REAR TAILGATE INNER GARNISH	MTG DISTORTED	358.50	358.50
1	REAR LH TAILLAMP	CUT	520.50	520.50
2	REAR TAILLAMP LOWER BRACKET @\$89.50	SERVICEABLE	179.00	-
1	REAR BUMPER	BENT	1,150.60	1,150.60
2	REAR BUMPER SIDE RETAINER @\$38.50	SERVICEABLE	77.00	-
1	REAR BUMPER LH REFLECTOR	CUT	65.00	65.00
1	REAR BUMPER LH REFLECTOR GARNISH	DENTED	85.00	85.00
1	REAR END PANEL	BENT	601.50	601.50
1	REAR END PANEL OUTER SENSOR	SERVICEABLE	190.50	-
1	REAR END PANEL INNER SENSOR	SERVICEABLE	185.00	-
1	REAR END PANEL LH SIDE PANEL	BENT	385.50	385.50
1	REAR END PANEL INNER GARNISH	MTG DISTORTED	295.20	295.20
1	REAR END PANEL INNER GARNISH COVER	DENTED	158.50	158.50
1	REAR FLOOT PANEL GARNISH BOX	CRACKED	495.80	495.80
1	REAR FLOOT PANEL SPONGE	SERVICEABLE	181.95	-
1	REAR LH FENDER INNER GARNISH	CRACKED	658.80	658.80
	LESS 20% DISCOUNT		-1,619.37	-1,456.68
			6,477.48	5,826.72
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR PARKING SENSOR (SN)	DENTED	280.00	200.00
1	SET REAR WINDSCREEN GLASS MOULDING (SN)	NECESSARY	120.00	120.00
1	SET REAR NUMBER PLATE & CASING (SN)	SERVICEABLE	50.00	-
			450.00	320.00
<u>LABOUR</u>				
	REMOVE & REFIT REAR WINDSCREEN GLASS.		150.00	120.00
	WIRING.		120.00	20.00

Report Ref No. CS/TP19003053/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFFKOTE.		180.00	60.00
	SPRAY PAINTING.		1,200.00	800.00
	LABOUR CHARGES.		1,400.00	800.00
			3,050.00	1,800.00
GRAND TOTAL			9,977.48	7,946.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,350.00

Report Ref No. CS/TP19003053/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.