

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5295S****AAD1902-114***Not Notarized**Resurvey Bepaint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHD 5295S**

JTDKB3FU303079127

RENAULT

LATITUDE

15.2.2019

**AIG**

17/1/2019

**PART****LIST**

|    |                                            |    |      |          |   |
|----|--------------------------------------------|----|------|----------|---|
| 1  | 1 FRONT BUMPER                             | \$ | N    | 499.90   |   |
| 2  | 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING | \$ | SL   | 101.20   |   |
| 3  | 1 REINFORCEMENT, FRONT BUMPER              | \$ | N    | 696.40   |   |
| 4  | 1 ABSORBER, FRONT BUMPER, LOWER            | \$ | SL   | 130.20   |   |
| 5  | 1 ABSORBER, FRONT BUMPER ENERGY            | \$ | SL   | 78.10    |   |
| 6  | 1 FRONT BUMPER SIDE RETAINER LH            | \$ | SL   | 78.00    |   |
| 7  | 1 FRONT BUMPER SUPPORT                     | \$ | SL   | 81.70    |   |
| 8  | 1 EXTENSION, FRONT BUMPER, LH              | \$ | N    | 117.80   |   |
| 9  | 1 FRONT LED LAMP (LOWER)                   | \$ | SL   | 907.75   |   |
| 10 | 1 FRONT HEADLAMP                           | \$ | SL   | 2,909.04 |   |
| 11 | 1 FRONT FENDER                             | \$ | B    | 945.30   | ✓ |
| 12 | 1 EXTENSION, FRONT FENDER, LH              | \$ | SL   | 48.80    | X |
| 13 | 1 COVER SUB-ASSY, FRONT PILLAR, UPR LH     | \$ | SL   | 98.30    | X |
| 14 | 1 LINER, FRONT FENDER, LH                  | \$ | D11  | 200.70   | ✓ |
| 15 | 1 FRONT FENDER EMBLEM                      | \$ | M    | 86.50    | ✓ |
| 16 | 1 SEAL, FENDER APRON MUDGUARD, LH          | \$ | SL   | 50.90    | X |
| 17 | 1 PANEL, FRONT DOOR, OUTER LH              | \$ | SL   | 361.00   | X |
| 18 | 1 PANEL SUB-ASSY, FRONT DOOR, LH           | \$ | B    | 1,264.00 | ✓ |
| 19 | 1 PANEL SUB-ASSY, REAR DOOR, LH            | \$ | N    | 1,258.30 | X |
| 20 | 1 REAR BUMPER SIDE LH                      | \$ | N    | 232.00   | X |
| 21 | 1 REAR FENDER LH                           | \$ | N    | 817.50   | X |
| 22 | 1 REAR BUMPER                              | \$ | Nell | 458.60   | ✓ |
| 23 | 1 REAR BUMPER RE-INFORCEMENT               | \$ | N    | 318.80   | X |
| 24 | 1 REAR BUMPER TOWING COVER                 | \$ | SL   | 14.70    | X |
| 25 | 1 REAR BUMPER UNDER COVER (BLACK)          | \$ | SL   | 552.60   | X |
| 26 | 1 REAR BUMPER SIDE RETAINER LH             | \$ | SL   | 112.70   | X |
| 27 | 1 REAR BUMPER SIDE RETAINER RH             | \$ | SL   | 112.70   | X |

**Trans-cab Auto Services Pte Ltd**

AAD1902-114

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5295S

|     |    |           |
|-----|----|-----------|
|     | \$ | 12,533.49 |
| 25% | \$ | 3,133.37  |
|     | \$ | 9,400.12  |

**Specical Nett**

|   |                                  |    |                |
|---|----------------------------------|----|----------------|
| 1 | 1 FRONT WHEEL RIM                | \$ | Del 1,570.55 ✓ |
| 2 | 1 FRONT WHEEL RIM COVER          | \$ | Sn 175.80 X    |
| 3 | 1 CLIP, FRONT FENDER LINER       | \$ | na 22.00 ✓     |
| 4 | 1 FRONT DOOR STICKER 'Trans-cab' | \$ | na 80.00 601   |

**TOTAL \$ 1,848.35****TOTAL PARTS \$ 11,248.47****LABOUR**

|                                                                                                                           |    |               |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 3,000.00 154d |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 3,000.00 70d  |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$ | 170.00 601    |
| To transfer of Fender fittings, attachments and perform water seepage test.                                               | \$ | na 170.00 X   |
| To transfer of Door fittings, attachments and perform water seepage test.                                                 | \$ | 170.00 601    |
| To transfer of Front Bumper fittings, attachments and perform water seepage test.                                         | \$ | na 170.00 X   |
| To transfer of front windscreen fittings and conduct water seepage test.                                                  | \$ | na 170.00 X   |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 220.00 601    |

**Trans-cab Auto Services Pte Ltd****AAD1902-114**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5295S**

|                                                                                 |    |                    |
|---------------------------------------------------------------------------------|----|--------------------|
| To vacuum, replace, refix and recharge air condenser                            | \$ | <i>nn</i> 380.00 X |
| To replace, refix and top up coolant for radiator                               | \$ | <i>nn</i> 170.00 X |
| To vacuum, replace, refix and recharge Air Intercooler                          | \$ | <i>nn</i> 170.00 X |
| To dismantle and refit aircon assy and attachment,<br>vacuum and charge-in-gas. | \$ | <i>nn</i> 380.00 X |

**TOTAL \$ 8,170.00****Over All Total \$ 28,818.59****(PART-BY-PART) Repair Days 10-DAYS***5 days*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: