

195200

INS. CASE OWNER:

CC 4 /AIG1900

LKK:

IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

19/1/19

Date / Time:

18/1/19

Registered in Merimen:

19/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBB 3675K

Name of Insured:

REMIKIL INTIAU(S) PIV

Insured Tel No.:

HP:

D.O.A:

19/1/19

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LEE Fook Wah

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

471753 676754

Policy No.:

10837464

Make / Model:

Mitsubishi

Place of Accident:

Kg Kampur RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBD 9405K



INSRS:

WSP:

Tel:

Liability:

RMKS:

96
MOTORSPORTS

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/1/19
Kanchra30/12/19
Kanchra

GBD 9405K - 4

File pass to type mandate.

File pass to Shu pet to close

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45

SS 13,700

(14 days) Reduction:

61 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

566

Repair Cost:

SS

14,659

Loss of Rental (LOR):

SS

2,889

(15 days)

x \$160.50

Loss of Use (LOU):

SS

-

(S - x - days)

Loss of Income (LOI):

SS

-

(S - x - days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45 + 29 = 36.45

Medical:

SS

Disbursement:

SS

70

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

17,654.45

Global Sum SS:

16,300

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

16,300

Name 1:

96 MOTORSPORTS PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

REF:

ASSIGNMENT

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT
Person Contacted: _____Veh No: G8D990SK Yr Regn: 2015 AugustType: Motor / M.Cycle / Bus / Van / Motor / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2982Colour: white A/C: Insured / Std / NI / NASp. Reading: 164959 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA T35720/C204676Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / SRim / STD A/Rim orTyre Size: F: 195R15CR: 155R12CBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 10/02/19Survey held at 96 MotorsportsDes. of Damages FR / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP A16.CLIS \$13,700 (Red \$ 24,632.30 / 64 / .)MV: 45KPV: 9.3KNett: 357K.14 days + 2 Sundays + 2 PRS = 18 days

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:



96 MOTORSPORTS PTE LTD

64 Kaki Bukit Ave 6 Singapore (417893)

Email: Sheela.sim@96motorsports.com

Tel: 86840506

VEHICLE NUM:

GBD 9905 K

MAKE & MODEL:

TOYOTA DYNA

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

TPALG.
Asher.
Adnan Lj
Revised 26/02/19.
JTFAT35/20K204676

ATTN:				
NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	FRONT PANEL <i>Dented</i>	1	\$ 982.40	✓
2	FRONT PANEL EMBLEM (DYNA) <i>new</i>	1	\$ 86.00	✓
3	FRONT TOP PANEL <i>Dented</i>	1	\$ 524.30	✓
4	FRONT APRON GARNISH <i>Dented</i>	1	\$ 371.40	✓
5	FRONT APRON SIDE GARNISH LH <i>Dented</i>	1	\$ 141.40	✓
6	FRONT APRON GARNISH CLIP <i>new</i>	10	\$ 30.00	✓
7	FRONT GRILLE <i>Cracked</i>	1	\$ 581.90	✓
8	FRONT GRILLE BADGE <i>new</i>	1	\$ 75.90	✓
9	FRONT GRILLE CLIP <i>new</i>	10	\$ 30.00	✓
10	HEAD LAMP L+R <i>Both Cracked</i>	2	\$ 1,948.00	2 633.30
11	HEAD LAMP CLIP <i>new</i>	10	\$ 20.00	10
12	FRONT BUMPER <i>Bent</i>	1	\$ 698.60	✓
13	FRONT BUMPER BRACKET L+R <i>Bent</i>	2	\$ 242.60	✓
14	FRONT CORNER PANEL LH <i>Distorted</i>	1	\$ 427.50	✓
15	FRONT CORNER PANEL INNER BRACKET LH <i>new</i>	1	\$ 60.00	✓
16	FRONT WINDSCREEN RUBBER <i>new</i>	1	\$ 384.00	✓
17	FRONT SIDE MIRROR LH <i>new</i>	1	\$ 695.70	✓
18	FRONT SIDE MIRROR BRACKET WITH MOTOR LH <i>new</i>	1	\$ 1,273.00	✓
19	FRONT PARKING MIRROR LH <i>new</i>	1	\$ 137.90	✓
20	FRONT SIDE MIRROR BOTTOM COVER LH <i>Dented</i>	1	\$ 324.70	✓
21	FRONT DOOR PILLAR OUTER LH <i>Bent</i>	1	\$ 923.90	2 789.
22	FRONT DOOR PILLAR INNER LH <i>Repair</i>	1	\$ 764.20	✓
23	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,540.00	1 1460.
24	FRONT DOOR QUARTER GARNISH LH <i>new</i>	1	\$ 98.20	✓
25	FRONT DOOR OUTER MOULDING LH <i>new</i>	1	\$ 121.50	✓
26	FRONT DOOR GLASS LH <i>new</i>	1	\$ 462.60	✓
27	FRONT DOOR OUTER HANDLE LH <i>new</i>	1	\$ 132.60	✓
28	FRONT DOOR HINGE LH <i>Bent</i>	2	\$ 156.80	✓
29	FRONT DOOR CHECKER LH <i>Bent</i>	1	\$ 68.90	✓
30	FRONT DOOR INNER LOCK <i>Turned</i>	1	\$ 260.20	✓
31	FRONT DOOR LOCK CATCH <i>new</i>	1	\$ 46.00	✓
32	FRONT DOOR WEATHETSTRIP LH <i>new</i>	1	\$ 158.70	✓

[illegible]

SPECIAL NETT		QTY	PRICE	PRICE
1	FRONT NUMBER PLATE <i>Bent</i>	1	\$ 120.00	30
2	FRONT DOOR COMPANY LETTERING LH <i>me</i>	1	\$ 60.00	30
3	FRONT DOOR COMPANY LOGO LH <i>me</i>	1	\$ 250.00	150.
4	REAR CARRIER INNER ALUMINIUM PLATE <i>me</i>	1	\$ 2,500.00	x
5	REAR SIDE GATE INNER ALUMINIUM PLATE LH <i>me</i>	1	\$ 1,000.00	x
6	REAR SIDE GATE TOP RAILING LH <i>me</i>	1	\$ 1,400.00	x
7	REAR CANOPY ASSY <i>me</i>	1	\$ 4,000.00	x
8	REAR CANOPY RETRACTABLE CLOTH LH <i>me</i>	1	\$ 600.00	x
9	RIVET <i>me</i>	1	\$ 200.00	60
10	FRONT RIM LH <i>cut</i>	1	\$ 350.00	180
11	FRONT TYRE LH <i>cut</i>	1	\$ 250.00	180
12	BODY PANEL JOINT SEALANT	1	\$ 120.00	80
SPECIAL NETT 1			\$ 10,850.00	\$ -
LABOUR		QTY	PRICE	PRICE
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	1	\$ 2,200.00	1600
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	1	\$ 1,800.00	1400
3	TO RUST PROOF ACCIDENT AFFECTED AREA	1	\$ 120.00	80
4	TO R & R FRONT WINDSCREEN	1	\$ 150.00	120
5	TO R & R CARPET, SEAT AND UPHOLSTERY	1	\$ 250.00	150
6	TO R & R DASH BOARD	1	\$ 450.00	220
7	TO R & R FRONT DOOR PART	1	\$ 150.00	80
8	TO R & R REAR CARRIER	1	\$ 600.00	x
9	TO R & R FUEL TANK	1	\$ 150.00	x
10	TO R & R FRONT UNDER CARRIAGE	1	\$ 450.00	220
11	TO CHECK AND ALIGN FOUR WHEEL ALIGNMENT	1	\$ 120.00	80
12	TO RESET AND REPROGRAM FAULT CODE	1	\$ 600.00	x
13	TO CHECK AND REFIX ACCIDENT AFFECTED AREA WATER LIKING	1	\$ 120.00	x
LABOUR TOTAL			\$ 7,160.00	\$ -
GRAND TOTAL COST			\$ 38,332.30	\$ -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PAGE 2 OF 2

Adrian Ling. total: 17143.07
w/s 19/02/19. h/s: 13.7k
14 Days.

42834.92

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	8413W
Vehicle Details	
Vehicle No.:	GBD9905K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Feb 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2505710
Chassis No.:	JTFAT35Y20K204676
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	06 Aug 2015
First Registration Date:	06 Aug 2015
Transfer Count:	1
Actual ARF Paid:	\$1,393.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Aug 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$14,352.00
COE Rebate Amount:	\$9,267.00
Total Rebate Amount:	\$9,267.00

The information contained herein is correct as at 21 Feb 2019

OK

ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year

Your Satisfaction Is Our Success

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad
 Advertiser Login
 Ways of Selling

New 5 Years Coe Renewal Toyota Wish 1.8A

2.38% P.A. Lowest Interest @ Gv
 Cars Financing \$3800
 Downpayment Monthly From
 \$738
 Gv Credit Pte Ltd StarAd

CERTIFIED PRE-OWNED MERCEDES-BENZ

[View our cars](#)

Browse by Category

Save Search
 Print

Sort by Date Posted

20 results/page

13 vehicles
 Search Toyota Dyna
 Advanced Search
 Search
 View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Toyota Dyna	Any	Any	2015	Any	Any	Any	Any	Available
------------------	-------------	-----	-----	------	-----	-----	-----	-----	-----------

☐ **Toyota Dyna 150**

\$42,800

\$7,160 /yr

11-Feb-2015

2,982 cc

68,000 km

Truck

Available

Fuel Type: Diesel

The Most Reliable And Popular 10 Feet Lorry In The Market. 1 Owner, Low Mileage Done. Comes With Full Checker Plate And Full Canopy. New Paintwork, 100% Accident Free. Immaculate Condition. Call Us Fo...

Posted: 20-Feb-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

☐ **Toyota Dyna 150**

\$45,900

\$7,550 /yr

20-Mar-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Half Canopy, Checkerd Plate. Call Now!

Posted: 30-Jan-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

☐ **Toyota Dyna 150**

\$44,800

\$7,270 /yr

20-Apr-2015

2,982 cc

91,000 km

Truck

Available

Fuel Type: Diesel

The Most Reliable And Popular Lorry For Your Commercial Needs. Engine, Gearbox & Interior In Perfect Condition. Low Diesel Consumption & Maintenance. Only 1 Owner With Low Mileage Clocked. Flexible Lo...

Tan Wei Auto Pte Ltd

Posted: 09-Feb-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

☐ **Toyota Dyna 150**

\$45,800

\$7,400 /yr

30-Apr-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

10 Feet Lorry With Canopy. Good Condition, New Paintwork, Servicing Done, No Repairs Needed. Easy Approval For Loan. Price Negotiable. Call Now To Test Drive! Call Now!

ABWIN (1994) Pte Ltd

Posted: 15-Jan-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Door Visor

2017 Toyota CHR Door Visor

More info about this product

☐ **Toyota Dyna 150**

\$47,800

\$7,330 /yr

28-Aug-2015

2,982 cc

84,358 km

Truck

Available

Fuel Type: Diesel

Think One Automobile & Trading

Posted: 15-Feb-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

☐ **Toyota Dyna 150**

\$47,800

\$7,250 /yr

23-Sep-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

One Of The Best Selling And Reliable 10ft Lorry In Town. 1 Careful Owner. Servicing Done, Wear And Tear Replaced. No Repairs Needed. 100% Loan/High Trade Available. Call Us For Appointment To View The...

ABWIN (1994) Pte Ltd

Posted: 20-Feb-2019
 Tags: 2015 Toyota Dyna, 2015 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

☐ **Toyota Dyna 150**

\$50,800

\$7,610 /yr

23-Oct-2015

2,982 cc

-

Truck

Available

Fuel Type: Diesel

1 Owner! Low Mileage! Comes With Full Chequered Plate. Stock Condition. Original Paintwork. Please Call Now To View This Vehicle. Full Cash /

SHORTLISTED
 HISTORY

Compare

- Pre repair inspection request - GBD9905K VS GBB3628K (OI) DOA: 15/02/2019

Adrian 19/2/19

From: Azlan, Syazairdina
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinrul
Sent: Monday, 18 February, 2019 9:37:45 AM

Hi,

Please refer to the enclosed request from **96 MOTORSPORTS**. 6702 6996

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Adrian Ling as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto
SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com www.aig.sg

From: claims@96motorsports.com [mailto:claims@96motorsports.com]
Sent: Friday, February 15, 2019 5:15 PM
To: Azlan, Syazairdina
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul
Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB3628K AND GBD9905K ON 15/02/2019

Dear Sir/Mdm,

We would like Adrian Ling from LKK to survey the car

Thank you,

Jade

From: Azlan, Syazairdina
Sent: Fri, 15 Feb 2019 06:31:40 +0000
To: claims@96motorsports.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinrul
Subject: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBB3628K AND GBD9905K ON 15/02/2019

Without Prejudice

Veh In

Your Reference : GBD9905K
Our Reference : GBB3628K

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 10 December 2019 1:08 PM
To: Tan, Bennie-WZ
Cc: Admin A
Subject: RE: AIG Ref: 4713536267SG-003 || Mandate request

Dear Mr. Bennie,

We refer to the above and your e-mail below.

As requested, our comments on the recommendation for repairs to these parts are below, please refer to Merimen for the photos:

1. FRONT SIDE MIRROR LH	44-45
2. FRONT SIDE MIRROR BOTTOM COVER LH	44-45
3. FRONT DOOR GLASS LH	13-14
4. FRONT DOOR CHECKER LH	13-14
5. FRONT DOOR INNER LOCK	JAMMED
6. FRONT DOOR REGULATOR MOTOR LH	104-107
7. FRONT DOOR REGULATOR GEAR LH	104-107
8. FRONT DOOR INNER TRIM LH	108-110
9. REAR SIDE GATE LH	23-27
10. FRONT LOWER ARM LH	84-99
11. FRONT KNUCKLE ARM LH	84-99
12. FRONT WHEEL BEARING LH	84-99
13. FRONT TYRE LH	35-41

Breakdown to 14 repair days in detail based on the required repair on the parts:-

- To repair and re-fix – 8 days
- To respray – about 5-6 days

Please be informed that our insured confirmed that they have withdrawn the third party claim and they had bear their own repair cost.

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Monday, 2 December 2019 12:11 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: AIG Ref: 4713536267SG-003 || Mandate request

Hi Khanchna

Please let us have your further comments on the recommendation for repairs to these parts:

1. **FRONT SIDE MIRROR LH**
2. **FRONT SIDE MIRROR BOTTOM COVER LH**
3. **FRONT DOOR GLASS LH**
4. **FRONT DOOR CHECKER LH**
5. **FRONT DOOR INNER LOCK**
6. **FRONT DOOR REGULATOR MOTOR LH**
7. **FRONT DOOR REGULATOR GEAR LH**
8. **FRONT DOOR INNER TRIM LH**
9. **REAR SIDE GATE LH**
10. **FRONT LOWER ARM LH**
11. **FRONT KNUCKLE ARM LH**
12. **FRONT WHEEL BEARING LH**
13. **FRONT TYRE LH**

Also, let us have a breakdown to 14 repair days in detail based on the required repair on the parts.

Separately, OI indicated lodging Third Party claim. Kindly advise any updates to OI's counterclaim.

Thank you.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

Khanchna (LKK Auto)

From: Tan, Bennie-WZ <Bennie-WZ.Tan@aig.com>
Sent: Monday, 2 December 2019 12:11 PM
To: Khanchna (LKK Auto)
Subject: AIG Ref: 4713536267SG-003 || Mandate request

Hi Khanchna

Please let us have your further comments on the recommendation for repairs to these parts:

1. FRONT SIDE MIRROR LH
2. FRONT SIDE MIRROR BOTTOM COVER LH } 44-45
3. FRONT DOOR GLASS LH } 13-14
4. FRONT DOOR CHECKER LH
5. FRONT DOOR INNER LOCK - JAMMED
6. FRONT DOOR REGULATOR MOTOR LH } 104-107
7. FRONT DOOR REGULATOR GEAR LH
8. FRONT DOOR INNER TRIM LH 108-110
9. REAR SIDE GATE LH 23-27
10. FRONT LOWER ARM LH
11. FRONT KNUCKLE ARM LH } 84-89
12. FRONT WHEEL BEARING LH
13. FRONT TYRE LH 33-41

Also, let us have a breakdown to 14 repair days in detail based on the required repair on the parts.

Separately, OI indicated lodging Third Party claim. Kindly advise any updates to OI's counterclaim.

Thank you.

Best Regards

Bennie Tan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1718

Bennie-WZ.Tan@aig.com | www.aig.sg

8-9 DAY.
TO REPAIR AND REPR - 8 DAY.
TO REPR RESPRAY - ABOUT 6 DAYS.
5-6

SPRAY

SPRAY

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Feb 2019 14:58	Clim Veh Model Changed	(206086) ADIVA AD1 200 190cc 3W.	[A] Lau Shu Pei
2	19 Feb 2019 14:58	Clim Created	Reg No: GBD9905K. Acct Date: 2019/02/15. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Workshop: 96 Motorsports Pte Ltd (HQ)	[A] Lau Shu Pei
3	19 Feb 2019 14:58	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	19 Feb 2019 14:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/02/28	[A] Lau Shu Pei
5	19 Feb 2019 14:58	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Shu Pei
6	19 Feb 2019 14:58	Clim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
7	19 Feb 2019 14:59	Label Added	(19):Fastlane.	[A] Lau Shu Pei
8	19 Feb 2019 14:59	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] Lau Shu Pei
9	21 Feb 2019 16:33	Clim Veh Model Changed	(206086) -> (204575) TOYOTA DYNA 150 3.0 D (M).	[A] Lau Shu Pei
10	04 Nov 2019 17:54	Adj Rpt Initiated		[A] NUR SHAQILAH BTE ABDOL WAHAB
11	04 Nov 2019 17:54	Clim Dtl Modified	JPJ Reg. Date: -> 2015/08/06.	[A] NUR SHAQILAH BTE ABDOL WAHAB
12	04 Nov 2019 17:54	Clim Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAB
13	06 Nov 2019 14:40	Adj Mandate Request	Cur,Req:17654.45:Insured driver turning and Third party going straight. Liability is down against Insured. BOLA 5 (b). ** 14 days recommendation for repair + 2 Sunday + 2 PRS = 18 days	[A] Khanchna Pothuraj

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2334886	04 Nov 2019 17:54:27	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBD9905K	GBB3628K	11.77

Khanchna (LKK Auto)

From: Royce <claims@96motorsports.com>
Sent: Monday, 30 December 2019 4:19 PM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: RE: Direct Settlement- OFFER - for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K
Attachments: GBD9905K DV.pdf

Dear Khanchna,

Please refer to the attached DV

Thank you

Royce

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]
Sent: Monday, 30 December 2019 3:42 PM
To: claims@96motorsports.com
Cc: Admin A
Subject: RE: Direct Settlement- OFFER - for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims@96motorsports.com <claims@96motorsports.com>

Sent: Monday, 30 December 2019 12:10 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement- OFFER - for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Dear Khanchna,

Can I have the DV please?

Thank you

Jade

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Sent: Monday, 23 December, 2019 11:10 AM

To: claims@96motorsports.com

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement- OFFER - for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum for **\$16,300.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims@96motorsports.com <claims@96motorsports.com>
Sent: Monday, 7 October 2019 2:51 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Dear Khanchna,

Kindly let us have an update on the claim and the offer amount

Thank you

Royce Phua

96 MOTORSports

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: claims@96motorsports.com <claims@96motorsports.com>
Sent: Tuesday, 10 September, 2019 2:59 PM
To: 'Khanchna (LKK Auto)' <khanchna@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>
Subject: RE: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Dear Khanchna,

Kindly refer to the amended attachment

Thank you

Royce Phua

96 MOTORSports

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Sent: Tuesday, 10 September, 2019 2:26 PM

To: claims@96motorsports.com

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

**Without Prejudice
(save as to costs)**

Dear Sirs/Mdm,

Kindly assist to amend your tax invoice for COR to \$13,700.00 (before GST) and e-mail us the soft copy for our further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Sent: Monday, 9 September 2019 12:17 PM

To: claims@96motorsports.com; Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Khanchna,

Kindly assist.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims@96motorsports.com <claims@96motorsports.com>

Sent: Monday, 9 September 2019 11:52 AM

To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: FW: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Without Prejudice

Dear Asher,

Kindly refer to the LOD attached for settlement.

Please expedite on the matter so that we can close this case on both our end.

Do let us know if you require any other documents from our end, otherwise we see no reason for the delay on this matter.

We hope for your most favourable reply at the soonest.

Thank you,

Jade Lim



62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : claims@96motorsports.com

Website: www.96motorsports.com

From: claims@96motorsports.com <claims@96motorsports.com>

Sent: Saturday, June 15, 2019 12:46 PM

To: 'Asher Sng (LKKAuto)' <AsherSng@lkkauto.com>

Subject: FW: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Dear Asher,

Please refer to the attached for settlement.

Thank you,

Royce Phua

96 MOTORSPORTS

62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Operation@96motorsports.com

Website: www.96motorsports.com

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Monday, 8 April, 2019 5:48 PM

To: claims@96motorsports.com

Cc: Gary 96 <gary.chang@96motorsports.com>; Andyson <andysonckl@yahoo.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: FW: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Please note that: -

LKK ref	Officer in charge
CC4/AIG19003062/Aeb3	Asher

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: claims@96motorsports.com <claims@96motorsports.com>

Sent: Monday, 8 April 2019 12:40 PM

To: Admin A <admin-a@lkkauto.com>

Cc: Gary 96 <gary.chang@96motorsports.com>; Andyson <andysonckl@yahoo.com>

Subject: Direct Settlement- LOD for GBD 9905K (ref: 96M-19-347); Your insured GBB 3628K

WITHOUT PREJUDICE

Dear Sir/Mdm,

Kindly refer to the attached LOD for direct settlement.

Please let us have your DV if any.

Thank you

Jade Lim



62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : claims@96motorsports.com

Website: www.96motorsports.com

From: alan.chan@96motorsports.com <alan.chan@96motorsports.com>

Sent: Monday, March 18, 2019 6:33 PM

To: adrianling@lkkauto.com

Cc: claims@96motorsports.com

Subject: GBD9905K estimate and finalisation TP - AIG

Dear adrian,

Please confirm on the repair limit of \$14000 – 16 days

Thank you and Best Regards,

Alan

From: alan.chan@96motorsports.com <alan.chan@96motorsports.com>

Sent: Thursday, 7 March, 2019 8:38 PM

To: adrianling@lkkauto.com

Cc: claims@96motorsports.com

Subject: GBD9905K after paint photo

Dear Adrian,

GBD9905K after paint photo.

Thank you,

Alan.

Alan Chan

Estimator



62/64 Kaki Bukit Avenue 6

Ark @ KB Singapore 417893

Tel : 6702 6996

Fax : 6384 6996

Email : Claims@96motorsports.com

Website: www.96motorsports.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2019 Edit Reg		18 Feb 2019 00:00 Edit Adj Rpt	S\$13,700.00 Edit Estimates	S\$13,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	RENTOKIL INITIAL SINGAPORE PTE LTD, Co. Reg. No.: 195900145N		
Main Claimant:	GATEWAY CONSTRUCTION & ENGINEERING PTE LTD, Co. Reg. No.: 201128413W		
Vehicle Reg. No.:	GBD9905K	Date of Loss:	15/02/2019 00:00 - :59 [42 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4713536267SG	Policy/Cover Note No.:	0999994346 (Comprehensive)
Vehicle Reg. No. (Insured):	GBB3628K	Policy No. (Claimant):	5094625283-01
		Excess:	
Repairer:	96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB, 417893 Kaki Bukit - Tel: 6702 6996		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 28/02/2019]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (20/12/2019): Alert - Adj Mandate Approved (S\$16300.00) - GBD9905K - Claim Handler: Tan, Benni...
- AIG_SG_EXPRESS (02/12/2019): Alert - Adj Mandate Maintained - GBD9905K - Claim Handler: Tan, Bennie-WZ
- AIG_SG (20/02/2019): Request to upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBD9905K (4713536267SG)**
[GBB3628K]

TP

GATEWAY CONSTRUCTION & ENGINEERING PTE LTD

Feb 15 2019 12:00AM

[RENTOKIL INITIAL SINGAPORE PTE LTD]

96 Motorsports Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences											1 per page			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	(Draft)		Third Party Express Settlement – Payment Breakdown									Edit		
Photos/Images											3 per page			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	22/03/19 10:45		General View									Load JPG		
2	22/03/19 10:45		General View									Load JPG		
3	22/03/19 10:45		General View									Load JPG		
4	22/03/19 10:45		General View									Load JPG		
5	22/03/19 10:45		General View									Load JPG		
6	22/03/19 10:45		General View									Load JPG		
7	22/03/19 10:45		General View									Load JPG		
8	22/03/19 10:45		General View									Load JPG		
9	22/03/19 10:45		General View									Load JPG		
10	22/03/19 10:45		General View									Load JPG		
11	22/03/19 10:45		General View									Load JPG		
12	22/03/19 10:45		General View									Load JPG		
13	22/03/19 10:45		General View									Load JPG		
14	22/03/19 10:45		General View									Load JPG		
15	22/03/19 10:45		General View									Load JPG		
16	22/03/19 10:45		General View									Load JPG		
17	22/03/19 10:45		General View									Load JPG		
18	22/03/19 10:45		General View									Load JPG		
19	22/03/19 10:45		General View									Load JPG		
20	22/03/19 10:45		General View									Load JPG		
21	22/03/19 10:45		General View									Load JPG		
22	22/03/19 10:45		General View									Load JPG		
23	22/03/19 10:45		General View									Load JPG		
24	22/03/19 10:45		General View									Load JPG		
25	22/03/19 10:45		General View									Load JPG		
26	22/03/19 10:45		General View									Load JPG		
27	22/03/19 10:45		General View									Load JPG		
28	22/03/19 10:45		General View									Load JPG		
29	22/03/19 10:45		General View									Load JPG		
30	22/03/19 10:45		General View									Load JPG		
31	22/03/19 10:45		General View									Load JPG		
32	22/03/19 10:45		General View									Load JPG		
33	22/03/19 10:45		General View									Load JPG		
34	22/03/19 10:45		General View									Load JPG		
35	22/03/19 10:45		General View									Load JPG		
36	22/03/19 10:45		General View									Load JPG		
37	22/03/19 10:45		General View									Load JPG		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/03/19 10:45	General View	 Load JPG	☒
39	22/03/19 10:45	General View	 Load JPG	☒
40	22/03/19 10:45	General View	 Load JPG	☒
41	22/03/19 10:45	General View	 Load JPG	☒
42	22/03/19 10:45	General View	 Load JPG	☒
43	22/03/19 10:45	General View	 Load JPG	☒
44	22/03/19 10:45	General View	 Load JPG	☒
45	22/03/19 10:45	General View	 Load JPG	☒
46	22/03/19 10:45	General View	 Load JPG	☒
47	22/03/19 10:45	General View	 Load JPG	☒
48	22/03/19 10:45	General View	 Load JPG	☒
49	22/03/19 10:45	General View	 Load JPG	☒
50	22/03/19 10:45	General View	 Load JPG	☒
51	22/03/19 10:45	General View	 Load JPG	☒
52	22/03/19 10:45	General View	 Load JPG	☒
53	22/03/19 10:45	General View	 Load JPG	☒
54	22/03/19 10:45	General View	 Load JPG	☒
55	22/03/19 10:45	General View	 Load JPG	☒
56	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
57	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
58	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
59	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
60	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
61	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
62	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
63	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
64	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
65	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
66	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
67	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
68	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
69	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
70	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
71	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
72	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
73	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
74	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
75	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
76	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
77	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
78	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
79	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
80	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
81	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
82	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
83	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
84	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
85	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
86	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
87	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
88	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
89	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
90	22/03/19 10:46	Reinspection Photo	Load JPG	☒

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
92	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
93	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
94	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
95	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
96	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
97	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
98	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
99	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
100	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
101	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
102	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
103	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
104	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
105	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
106	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
107	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
108	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
109	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
110	22/03/19 10:46	Reinspection Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/02/19 14:59	EMAIL FROM AIG DD 18022019	 Load PDF	
2	21/02/19 19:06	TP GIA REPORT	 Load PDF	
3	08/07/19 11:05	LETTER TO OI	 Load PDF	
4	05/11/19 17:37	GIA LTA SEARCH	 Load PDF	
5	05/11/19 17:37	LOD	 Load PDF	
6	05/11/19 17:37	TOWING FEE	 Load PDF	
7	10/01/20 13:36	Authorisation to Act	 Load PDF	
8	10/01/20 13:36	EMAIL	 Load PDF	
9	10/01/20 13:36	Release Voucher	 Load PDF	
10	10/01/20 13:36	RENTAL RECEIPT	 Load PDF	
11	10/01/20 13:36	WORKSHOP INVOICE	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/02/19 16:30	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBB3628K (Insd veh)	Model:	TOYOTA DYNA 150 3.0 D (M)
	GBD9905K (TP veh)		
Date of Accident:	15/02/2019		

Global Sum Settlement	:	[X]	Yes	[]	No	
Repair Estimate	:	\$				45,833.36
Final Repair Cost	:	\$				16,300.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				18 days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				16,300.00
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	96 Motorsports Pte Ltd	:	\$ 16,300.00
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

10 Jan
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19003062/AKB3S2
Date: 10/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994346
 Claimant Vehicle No: GBD9905K Insured Vehicle No: GBB3628K
 Date of Loss: 15/02/2019 Nature of Claim: TP Claim No: 4713536267SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBD9905K Engine No: 1KD2505710
 Make & Model: TOYOTA DYNA 150, 3.0 D (M) Chassis No: JTFAT35Y20K204676
 Reg. Date: 06/08/2015 (Man. Year: 2015) Odometer: 164959 km
 Colour: White
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 155 R12C
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,554.92	13,211.62	22,343.30	62.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,280.00	4,030.00	3,250.00	44.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	42,834.92	17,241.62	25,593.30	59.75
Approved Total (Overridden) (S\$)		13,700.00		
(S\$)	42,834.92	13,700.00	29,134.92	68.02
+ GST 7.00/7.00% (S\$)	2,998.44	959.00	2,039.44	68.02
Nett Amount (S\$)	45,833.36	14,659.00	31,174.36	68.02
+ Car Rental (18.0 x S\$160.50/day) (S\$)		2,889.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		70.00		
Nett Liability (S\$)		17,654.45		
Global Sum Settlement (S\$)		16,300.00		

INSPECTION

Date of Assignment: 18/02/2019
 Date Inspected: 19/02/2019 Inspected At: 96 Motorsports Pte Ltd (HQ)
 62 Kaki Bukit Avenue 6, The Ark@KB
 Singapore 417893
 Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	982.40 FL	*982.40 FL
2	1		*FRONT PANEL EMBLEM (DYNA)	Necessary	86.00 FL	*86.00 FL
3	1		*FRONT TOP PANEL	Dented	524.30 FL	*524.30 FL
4	1		*FRONT APRON GARNISH	Deformed	371.40 FL	*371.40 FL
5	1		*FRONT APRON SIDE GARNISH LH	Deformed	141.40 FL	*141.40 FL
6	10		*FRONT APRON GARNISH CLIP	Necessary	30.00 FL	*30.00 FL
7	1		*FRONT GRILLE	Cracked	581.90 FL	*581.90 FL
8	1		*FRONT GRILLE BADGE	Necessary	75.90 FL	*75.90 FL
9	10		*FRONT GRILLE CLIP	Necessary	30.00 FL	*30.00 FL
10	1		*HEAD LAMP L+R	O/S Cracked	1,948.00 FL	*633.30 FL
11	10		*HEAD LAMP CLIP	Necessary	20.00 FL	*10.00 FL
12	1		*FRONT BUMPER	Bent	698.60 FL	*698.60 FL
13	2		*FRONT BUMPER BRACKET L+R	Bent	242.60 FL	*242.60 FL
14	1		*FRONT CORNER PANEL LH	Distorted	427.50 FL	*427.50 FL
15	1		*FRONT CORNER PANEL INNER BRACKET LH	Not Necessary	60.00 FL	*- FL
16	1		*FRONT WINDSCREEN RUBBER	Necessary	384.00 FL	*384.00 FL
17	1		*FRONT SIDE MIRROR LH	Cut	695.70 FL	*695.70 FL
18	1		*FRONT SIDE MIRROR BRACKET WITH MOTOR LH	Not Necessary	1,273.00 FL	*- FL
19	1		*FRONT PARKING MIRROR LH	Not Necessary	137.90 FL	*- FL
20	1		*FRONT SIDE MIRROR BOTTOM COVER LH	Deformed	324.70 FL	*324.70 FL
21	1		*FRONT DOOR PILLAR OUTER LH	Bent	923.90 FL	*789.00 FL
22	1		*FRONT DOOR PILLAR INNER LH	Repair	764.20 FL	*- FL
23	1		*FRONT DOOR LH	Distorted	1,540.00 FL	*1,460.00 FL
24	1		*FRONT DOOR QUARTER GARNISH LH	Cut	98.20 FL	*98.20 FL
25	1		*FRONT DOOR OUTER MOULDING LH	Cut	121.50 FL	*121.50 FL
26	1		*FRONT DOOR GLASS LH	Cut	462.60 FL	*462.60 FL
27	1		*FRONT DOOR OUTER HANDLE LH	Cut	132.60 FL	*132.60 FL
28	2		*FRONT DOOR HINGE LH	Bent	156.80 FL	*156.80 FL
29	1		*FRONT DOOR CHECKER LH	Bent	68.90 FL	*68.90 FL
30	1		*FRONT DOOR INNER LOCK	Jammed	260.20 FL	*260.20 FL
31	1		*FRONT DOOR LOCK CATCH	Not Necessary	46.00 FL	*- FL
32	1		*FRONT DOOR WEATHERSTRIP LH	Cut	158.70 FL	*158.70 FL
33	1		*FRONT DOOR BOTTOM RUBBER LH	Cut	97.50 FL	*97.50 FL
34	1		*FRONT DOOR REGULATOR MOTOR LH	Damaged	326.40 FL	*326.40 FL
35	1		*FRONT DOOR REGULATOR GEAR LH	Damaged	194.80 FL	*194.80 FL
36	1		*FRONT DOOR INNER TRIM LH	Cracked	560.40 FL	*560.40 FL
37	10		*FRONT DOOR INNER TRIM CLIP	Necessary	30.00 FL	*30.00 FL
38	1		*FRONT DOOR LOWER STEP GARNISH LH	Cut	261.00 FL	*261.00 FL
39	1		*CABIN REAR PILLAR LH	Dented	564.00 FL	*564.00 FL
40	1		*CABIN REAR PILLAR EMBLEM (D4D)	Necessary	110.00 FL	*110.00 FL
41	1		*FRONT FLOOR PANEL	Repair	1,897.40 FL	*- FL
42	1		*FRONT FLOOR PANEL INSULATOR CATCH	Not Necessary	876.40 FL	*- FL
43	1		*CABIN OPENER HANDLE	Bent	274.30 FL	*274.30 FL
44	2		*CABIN UPPER LOCK L+R	Not Necessary	624.60 FL	*- FL
45	1		*CABIN UPPER LOCK LINK	Not Necessary	247.00 FL	*- FL
46	1		*FRONT MUDGUARD LH	Deformed	457.80 FL	*457.80 FL
47	1		*FRONT MUDGUARD MUDFLAP LH	Not Necessary	225.00 FL	*- FL
48	1		*DASH BOARD	Not Necessary	1,123.40 FL	*- FL
49	1		*DASH BOARD BOTTOM	Not Necessary	876.00 FL	*- FL
50	1		*DASH BOARD GLOVE BOX	Not Necessary	426.00 FL	*- FL
51	1		*DASH BOARD SIDE SPEAKER LH	Not Necessary	210.00 FL	*- FL
52	1		*DASH BOARD CROSS MEMBER	Not Necessary	458.20 FL	*- FL
53	1		*DASH BOARD SIDE TOP TRIM LH	Not Necessary	135.70 FL	*- FL
54	1		*REAR SIDE GATE LH	Dented	1,842.70 FL	*1,842.70 FL
55	1		*REAR SIDE GATE FRONT OPENER HANDLE LH	Bent	131.40 FL	*131.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	6		*REAR SIDE GATE HINGE LH	Not Necessary	480.00 FL	*- FL
57	1		*REAR SIDE GATE BOTTOM CROSSMEMBER LH	Not Necessary	897.50 FL	*- FL
58	1		*REAR CARRIER BACK GATE	Repair	1,896.40 FL	*- FL
59	1		*FRONT ABSORBER LH	Bent	422.50 FL	*422.50 FL
60	1		*FRONT LOWER ARM LH	Bent	697.00 FL	*697.00 FL
61	1		*FRONT UPPER ARM LH	Not Necessary	1,450.00 FL	*- FL
62	1		*FRONT KNUCKLE ARM LH	Bent	647.50 FL	*647.50 FL
63	1		*FRONT WHEEL BEARING LH	Necessary	210.00 FL	*210.00 FL
64	1		*FRONT ANTI ROLL BAR	Not Necessary	465.80 FL	*- FL
65	2		*FRONT ANTI ROLL BAR BUSH L+R	Not Necessary	80.00 FL	*- FL
66	1		*FRONT ANTI ROLL BAR LINK LH	Not Necessary	134.30 FL	*- FL
67	1		*FRONT NUMBER PLATE	Bent	120.00 FS	*30.00 FS
68	1		*FRONT DOOR COMPANY LETTERING LH	Necessary	60.00 FS	*30.00 FS
69	1		*FRONT DOOR COMPANY LOGO LH	Necessary	250.00 FS	*150.00 FS
70	1		*REAR CARRIER INNER ALUMINIUM PLATE	Not Necessary	2,500.00 FS	*- FS
71	1		*REAR SIDE GATE INNER ALUMINIUM PLATE LH	Not Necessary	1,000.00 FS	*- FS
72	1		*REAR SIDE GATE TOP RAILING LH	Not Necessary	1,400.00 FS	*- FS
73	1		*REAR CANOPY ASSY	Not Necessary	4,000.00 FS	*- FS
74	1		*REAR CANOPY REACTABLE CLOTH LH	Not Necessary	600.00 FS	*- FS
75	1		*RIVET	Necessary	200.00 FS	*60.00 FS
76	1		*FRONT RIM LH	Cut	350.00 FS	*180.00 FS
77	1		*FRONT TYRE LH	Cut	250.00 FS	*180.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	43,829.90	17,405.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	8,274.98	4,193.88
Total Parts (\$\$)	35,554.92	13,211.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	BODY PANEL JOINT SEALANT.	New	120.00	80.00
2	KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA.	New	2,200.00	1,600.00
3	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA.	New	1,800.00	1,400.00
4	TO RUST PROOF ACCIDENT AFFECTED AREA.	New	120.00	80.00
5	TO R&R FRONT WINDSCREEN.	New	150.00	120.00
6	TO R&R CARPET, SEAT AND UPHOLSTERY.	New	250.00	150.00
7	TO R&R DASHBOARD.	New	450.00	220.00
8	TO R&R FRONT DOOR PART.	New	150.00	80.00
9	TO R&R REAR CARRIER.	New	600.00	0.00
10	TO R&R FUEL TANK.	New	150.00	0.00
11	TO R&R FRONT UNDER CARRIAGE.	New	450.00	220.00
12	TO CHECK AND ALIGN FOUR WHEEL ALIGNMENT.	New	120.00	80.00
13	TO RESET AND REPROGRAM FAULT CODE.	New	600.00	0.00
14	TO CHECK AND REFIX ACCIDENT AFFECTED AREA WATER LIKING.	New	120.00	0.00
Gross Labour Cost (\$\$)			7,280.00	4,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >