

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.  
6 Temasek Boulevard  
#18-01 Suntec Tower 4  
Singapore 038986

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 21 Feb 2019

## **Preliminary Advice**

Insured Vehicle No	: FBL5210R	Accident Date	: 01/02/2019
TP Vehicle No	: FBL9177C	Assignment Date	: 19/02/2019
Make	: HONDA CB400X	Est. Duration of Repair	: 3/Days
Date of Inspection	: 20/02/2019		
Inspection At	: BAN HOCK HIN CO.PTE LTD		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...O/S Body.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,383.00
Revised Amount	:S\$	1,542.30
Check Items (Estimated)	:S\$	572.40
Total	:S\$	2,114.70

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.