

22/03/2002

ASS. REC. BY:

REF:

CS/1CR19003070/Ked302

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Azlan Syazairdina of AIG.Date/Time: 15/2/2019.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBE 23JInsured: SLG 4142Tat Workshop m/s Siong Lee MotorTel: 64531255of 160 slm #02-07

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/2/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle **IN / OUT**

Date/Time

Action/Instruction (✓) Estimate


GBE 23J - X.

SLG 4142T - X.

5/3 11 Lm @ 5200 email. & confirm
 (\$ 5,782.00 Red - 53%)

AIG

Date: _____
 Insured's Name: _____
 Vehicle No: **GBE 23J**
 at Work: **Strong Lee Motor**
 at: **160 s/m #02-07**
 Insured: _____
 Policy No: _____
 Claim No: _____
 Amount Insured: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Report: _____
 Consistent? Yes or No: _____
 CIA / PR Seen: _____
 Consistent? Yes or No: _____
 Est Repair: **05** days Rest: Yes or No: _____
 Lump Sum: **20** % 3 Val: Yes or No: _____
 CA / REV / REP / 24 HRS: **WP**
 Date: _____ Person Contacted: _____
 Vehicle IN / OUT: _____



Sub No: **GBE 23J** 12 14
 Type: **M/Car / M/Cycle / Bus / Van / Lorry / Light / Prime Mover /**
 Truck / Trailer or
 Make: **Toy Hiac** 2982
 Colour: **White** Insured / Std / NI / NA
 Sp Reading: **107523** Insured / Std / NI / NA
 Eng No: _____
 C No: **KOH 201 0146398**
 Gen Cond: **Good** / Fair / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Mod: **Std** / SRim / STD ARim or
 Tyre Size: **F: 195R15X8**
R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: **7** mm R/Bal: **7** mm
 L/Bal: **7** mm L/Bal: **7** mm
 D.O.A: **14/2/19** D.O.I: **19/2/19**
 Survey held at: _____
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: **19/2** Action / Instruction: **Tailgate jammed.**

No policy / claim no, direct submit file

RECEIVED 06 MAR 2019

Date/Time File Passed to: **06/03/19**
 to: **Typ 4**
 Date/Time File Returned to: _____
☐ : Prelim. Report
☒ : Final Report

Days Of Repair: **5**
 Resurvey No. of Trip: **1**

Add Fees: ☐ Late Insp. (k)
☐ Interview (k)
☐ Team Insp. (k)
☐ Weekend (k)

Survey Fee:

Transportation:

Photocopy:

Photo:

Other:

Total:

250
10
260

Report Format:

Lump Sum / L.B. F.B. **5,200/- HS**

Catherine Chong (LKK Auto)

From: Azlan, Syazairdina <Syazairdina.Azlan@aig.com>
Sent: Friday, 15 February, 2019 4:38 PM
To: admin-a@lkkauto.com; assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul
Subject: - Pre repair inspection request - GBE23J VS SLG4142T (OI) DOA 14/02/2019
Attachments: SecureMessageAtt.html



This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-02-22 16:37 +08 to read your message.
After that, open the attachment.

[More Info](#)

18/2/19 @ 4:40pm Kwee Pin Veh IN
Survey on 19/2/19 "WP"
Est provided

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved

- Pre repair inspection request - GBE23J VS SLG4142T (OI) DOA 14/02/2019

From: Azlan, Syazairdina

To: admin-a@lkkauto.com, assignments@lkkauto.com

Cc: Fong, Andy-SY, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Chan, Yoke Shi, Kaur, Baljit, Hor, Yinrul

Sent: 2/15/2019 4:37:31 PM

Attachments:  SKMBT_C364e19021514060.pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Claim no : 9922863157SG

Case Owner : JEFFREY SAY KIAT NG

If you have any queries/concerns, please let us know.

Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg**From:** Cheonghoh Law [mailto:mail@cheonghoh.sg]**Sent:** Friday, February 15, 2019 4:19 PM**To:** Azlan, Syazairdina**Cc:** Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Hor, Yinrul**Subject:** Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG4142T AND GBE23J ON 14/02/2019

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong of LKK Auto Consultants Pte Ltd named in paragraph 2 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be contact our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722 for the survey of GBE 23 J.

Contact Person : Mr Tan / Ms Kwee Pin
Telephone : 6453 1255

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sgOn 15 Feb 2019, at 2:43 PM, Azlan, Syazairdina <Syazairdina.Azlan@aig.com> wrote:

<logo.jpeg>

<lock.gif>

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-02-22 14:43 +08 to read your message.
After that, open the attachment.

[More Info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption. Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

<SecureMessageAtt.html>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairdina.Azlan@aig.com

To: mail@cheonghoh.sg

Cc: Andy-SY.Fong@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Imran.Ishak@aig.com ,ShengYang.Lim@aig.com ,Aashweenjeetkaur.Mithoosingh@aig.com ,yokeshi.chan@aig.com ,Baljit.Kaur@aig.com ,Yinrul.Hor@aig.com

Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLG4142T AND GBE23J ON 14/02/2019

Date: Fri, 15 Feb 2019 06:43:10 +0000

Without Prejudice

Your Reference : LCH.lg/SMSL-90149.19

Our Reference : 9922863157SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan

AIG

Express Claims Adjuster II, Singapore FNOL, Claims Operations – Auto

SG Claims Operations | AIG Shared Services

Syazairdina.Azlan@aig.com | www.aig.sg

From: Lim, Sheng Yang

Sent: Friday, February 15, 2019 2:19 PM

To: Azlan, Syazairdina

Subject: FW: PRS for GBE 23 J Involving SLG 4142 T along Airport Road Towards Kallang (Paya Lebar Expressway) Our ref: LCH.lg/SMSL-90149.19)

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Friday, February 15, 2019 2:13 PM

To: Supramaniam, Darshene; Loo, Kar Yong

Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Chan, Yoke Shi

Subject: Re: PRS for GBE 23 J Involving SLG 4142 T along Airport Road Towards Kallang (Paya Lebar Expressway) Our ref: LCH.lg/SMSL-90149.19)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: cheonghoh@singnet.com.sg

Subject: Message from KMBT_C364e

Date: 15 February 2019 at 2:06:51 PM SGT

To: mail@cheonghoh.sg

Reply-To: cheonghoh@singnet.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/02/2019 13:59
Date Of Accident	14/02/2019 17:50
Exact Location Of Accident	AIRPORT RD TWDS KALLANG-PAYA LEBAR EXPRESSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE23J
Insured/Policyholder	
Name Of Registered Owner	HEMUS PACIFIC PRIVATE LIMITED
Co Reg No	200512640E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90217953

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5069661931-04
Cover Note Number	

Driver

Name of Driver	SEAH KWEE SENG (SHE GUISENG)
NRIC No	S7903993D
Date Of Birth	03/02/1979
Occupation	OUTDOOR
Date Of Driving Pass	20/04/2015
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90217953
Fax Number	
Contact Number	OFFICE-90217953
Email Address	NOEMAIL

Address	APT BLK 242 KIM KEAT LINK #01-179 SINGAPORE
Postcode	310242
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG4142T
Vehicle Make/Model/Colour	MAZDA 3
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HENG HIAN KWANG
NRIC/Passport Number	S1103052A
Contact Number	97508156
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by Interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 15/2/19

2.00 pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 15/2/19


3.00 pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I driving at Airport Road towards KPE tunnel at 5.50pm
 14 FEB 2019. Sunny day with no rain, slow moving traffic. The vehicle B
 did not see that I have come to complete stop and just knocked
 onto my rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 15/8/19
 3.00 pm

GIARMC SketchPlanForm_V3

Driver's Signature

(If driver is not the policyholder)

Date & Time: 15/8/19
 3.00 pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



松 利 摩 哆
SIOG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

18 February 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: HEMUS PACIFIC PRIVATE LIMITED

H/P: 9021 7953

Dear Sirs / Madam,

Accident Claim for Vehicle No.GBE 23 J, Involving Vehicle No.SLG 4142 T.
Accident on 14 FEBRUARY 2019, AT AIRPORT ROAD TOWARDS KALLANG-
PAYA LEBAR EXPRESSWAY

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BOOTLID	1PC	\$ 2,191.75
2	REAR BOOTLID EMBLEM	1PC	\$ 66.90
3	REAR BOOTLID HANDLE	1PC	\$ 189.20
4	REAR BOOTLID LOCK	1PC	\$ 294.70
5	REAR BOOTLID LOCK CATCH	1PC	\$ 153.20
6	REAR BOOTLID ABSORBER	2PCS	\$ 658.80
7	REAR BOOTLID HINGES	2PCS	\$ 171.40
8	REAR BOOTLID RUBBER	1PC	\$ 455.20
9	REAR BOOTLID TRIMBOARD	1PC	\$ 252.10
10	REAR BUMPER	1PC	\$ 496.20
11	REAR BUMPER STEP PANEL	1PC	\$ 365.10
12	REAR BUMPER RETIANER	2PCS	\$ 95.70
13	REAR END PANEL	1PC	\$ 389.70
14	REAR END INNER PANEL	1PC	\$ 994.50
15	REAR SPARE TYRE TRAY	1PC	\$ 240.80
16	REAR EXHAUST BOX	1PC	\$ 758.70
17	TAILLAMP	2PCS	\$ 570.40
	TOTAL LIST PRICE		\$ 8,344.35
	LESS 20% 25%		\$ (1,668.87)
	TOTAL AMOUNT		\$ 6,675.48

*Not Ashish
11 Sep 8?
Paying Aka Point
5 days*

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE	
1	REAR NUMBER PLATE	1PC	\$ <i>RM</i> 30.00	X
2	REAR BOOTLID STICKER 'TOYOTA HIACE'	1PC	\$ <i>RM</i> 53.70	✓
3	REAR BOOTLID STICKER '70KM/H'	1PC	\$ <i>RM</i> 10.00	✓
4	REAR BOOTLID STICKER '8PAX'	1PC	\$ <i>RM</i> 10.00	✓
5	REAR WINDSCREEN SEALANT	1PC	\$ <i>RM</i> 40 <i>RM</i> 80.00	
6	REAR BUMPER REVERSE SENSOR	1PC	\$ <i>RM</i> 200 <i>RM</i> 240.00	
	TOTAL SPECIAL NETT PRICE		\$ 423.70	

	LABOUR :		
2	LABOUR TO SPRAY PAINT	\$	<i>600</i> 800.00
3	LABOUR TO PANEL BEATING	\$	<i>600</i> 900.00
4	LABOUR TO DISMANTLE AND REFIX TAILGATE GLASS.	\$	<i>120</i> 160.00
9	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$	<i>60</i> 150.00
	TOTAL LABOUR	\$	2,010.00
	TOTAL AMOUNT	\$	9,109.18

THANK YOU

FROM:
SIONG LEE MOTOR
 Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the followings:

- To resurvey before finalising quotation
- To display part-price list for customer survey
- Parts prices are subject to part price list
- Third party survey is on a "Minimum Reproduce" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be authorised and is subject to final approval from insurance Company

Acknowledged by Repairer:
 Signature:
 Date:



松 利 摩 哆
Siong Lee Motor

Company Reg. No.: 100838/00J

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

18 February 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: HEMUS PACIFIC PRIVATE LIMITED

H/P: 9021 7953

Dear Sirs / Madam,

Accident Claim for Vehicle No.GBE 23 J, Involving Vehicle No.SLG 4142 T.
Accident on 14 FEBRUARY 2019, AT AIRPORT ROAD TOWARDS KALLANG-
PAYA LEBAR EXPRESSWAY

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BOOTLID <i>2451.60 2121-75</i>	1PC	\$ <i>B1</i> 2,191.75
2	REAR BOOTLID EMBLEM	1PC	\$ <i>Mr</i> 66.90
3	REAR BOOTLID HANDLE	1PC	\$ <i>nd</i> 189.20
4	REAR BOOTLID LOCK <i>266.00</i>	1PC	\$ <i>Tr</i> 294.70
5	REAR BOOTLID LOCK CATCH	1PC	\$ <i>R</i> 153.20
6	REAR BOOTLID ABSORBER	2PCS	\$ <i>Sm</i> 658.80
7	REAR BOOTLID HINGES	2PCS	\$ <i>R</i> 171.40
8	REAR BOOTLID RUBBER <i>391.20 1440N</i>	1PC	\$ <i>195.60N (1) ?</i> 455.20
9	REAR BOOTLID TRIMBOARD	1PC	\$ <i>CPM</i> 252.10
10	REAR BUMPER <i>428.10</i>	1PC	\$ <i>B1</i> 496.20
11	REAR BUMPER STEP PANEL	1PC	\$ <i>B1</i> 365.10
12	REAR BUMPER RETIANER	2PCS	\$ <i>Sm</i> 95.70
13	REAR END PANEL	1PC	\$ <i>B1</i> 389.70
14	REAR END INNER PANEL	1PC	\$ <i>B1</i> ? 994.50
15	REAR SPARE TYRE TRAY	1PC	\$ <i>DR</i> ? 240.80
16	REAR EXHAUST BOX	1PC	\$ <i>R</i> 758.70
17	TAILLAMP <i>215 50N</i>	2PCS	\$ <i>285.20</i> 570.40
	TOTAL LIST PRICE		\$ 8,344.35
	LESS 20% <i>25%</i>		\$ (1,668.87)
	TOTAL AMOUNT		\$ 6,675.48

Not Notarized
11 Pm 8 5200h
Perjury After Print
19/2/19
12.30 pm
5 days

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE	
1	REAR NUMBER PLATE	1PC	\$ <i>30.00</i>	X
2	REAR BOOTLID STICKER 'TOYOTA HIACE'	1PC	\$ <i>53.70</i>	✓
3	REAR BOOTLID STICKER '70KM/H'	1PC	\$ <i>10.00</i>	✓
4	REAR BOOTLID STICKER '8PAX'	1PC	\$ <i>10.00</i>	✓
5	REAR WINDSCREEN SEALANT	1PC	\$ <i>80.00</i>	
6	REAR BUMPER REVERSE SENSOR	1PC	\$ <i>240.00</i>	
	TOTAL SPECIAL NETT PRICE		\$ 423.70	

	LABOUR :			
2	LABOUR TO SPRAY PAINT		\$ <i>800.00</i>	
3	LABOUR TO PANEL BEATING		\$ <i>900.00</i>	
4	LABOUR TO DISMANTLE AND REFIX TAILGATE GLASS.		\$ <i>160.00</i>	
9	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS		\$ <i>150.00</i>	
	TOTAL LABOUR	\$	2,010.00	
	TOTAL AMOUNT	\$	9,109.18	

THANK YOU

FROM:
SIONG LEE MOTOR
 Mr Tan Leng Huat

10,932 / -

10981.90



松 利 摩 哆
SIONG LEE MOTOR

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

18 February 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: HEMUS PACIFIC PRIVATE LIMITED

H/P: 9021 7953

Dear Sirs / Madam,

Accident Claim for Vehicle No.GBE 23 J, Involving Vehicle No.SLG 4142 T.
Accident on 14 FEBRUARY 2019, AT AIRPORT ROAD TOWARDS KALLANG-
PAYA LEBAR EXPRESSWAY

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR FLOOR BOARD PANEL	1PC	\$ 980.20
2	REAR FLOOR BOARD WOOD COVER	1PC	\$ 580.90
3	REAR END PANEL TOP GARNISH	1PC	\$ 154.80
	TOTAL LIST PRICE		\$ 1,715.90
	LESS 20%	25%	\$ (343.18)
	TOTAL AMOUNT		\$ 1,372.72

	LABOUR :	
1	LABOUR TO DISMANTLE AND REFIX FLOOR BOARD PANEL	\$ 500.00
	TOTAL LABOUR	\$ 500.00
	TOTAL AMOUNT	\$ 1,872.72

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Feb 2019 Edit Reg		15 Feb 2019 00:00 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF Pte Ltd , Co. Reg. No.: NA									
Main Claimant: HEMUS PACIFIC PRIVATE LIMITED , Co. Reg. No.: 200512640E									
Vehicle Reg. No.: GBE23J		Date of Loss: 14/02/2019 17:00 - :59 [49 Months and 19 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 9922863157SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SLG4142T		Policy No. (Claimant):							
		Excess:							
Repairer: Siong Lee Motor 160 Sin Ming (HQ) 160 Sin Ming Drive, #02-07 AutoCity, 575722 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Jeffrey-SK] Jeffreysaykiat.Ng@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/03/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (07/03/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE23J (9922863157SG)**
[SLG4142T]
TP
HEMUS PACIFIC PRIVATE LIMITED
Feb 14 2019 5:00PM
[LCRF Pte Ltd]
Siong Lee Motor 160 Sin Ming

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
2	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
3	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
4	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
5	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
6	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
7	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
8	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
9	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
10	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
11	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
12	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
13	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
14	06/03/19 11:26	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>		
15	06/03/19 11:26	General View													Load JPG	<input checked="" type="checkbox"/>		
16	06/03/19 11:26	Chassis Number													Load JPG	<input checked="" type="checkbox"/>		
17	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
18	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
19	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
20	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
21	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
22	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
23	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
24	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
25	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
26	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
27	06/03/19 11:28	Reinspection Photo													Load JPG	<input checked="" type="checkbox"/>		
Documentation															1 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	07/03/19 11:39	Supplementary													Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail	Print		
1	07/03/19 10:39	OI GIA REPORT													Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
----------------------------	--------------------------------------	-------------------------------------	--------------------------------------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR19003070/KSD3E2

Date: 07/03/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle
No : GBE23J

Insured Vehicle No : SLG4142T

Date of Loss: 14/02/2019

Nature of Claim: TP

Claim No: 9922863157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE23J	Engine No:	1KD2427931
Make & Model:	TOYOTA HIACE, 3.0 D DX (A)	Chassis No:	KDH2010146398
Reg. Date:	26/12/2014 (Man. Year: 2014)	Odometer:	107523 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,471.90	4,824.91	3,646.99	43.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,510.00	1,680.00	830.00	33.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,981.90	6,504.91	4,476.99	40.77
Approved Total (Overridden) (S\$)		5,200.00		
(S\$)	10,981.90	5,200.00	5,781.90	52.65
+ GST 7.00/7.00% (S\$)	768.73	364.00	404.73	52.65
Nett Amount (S\$)	11,750.63	5,564.00	6,186.63	52.65

INSPECTION

Date of Assignment: 15/02/2019

Date Inspected: 19/02/2019 Inspected At:

Siong Lee Motor 160 Sin Ming (HQ)
160 Sin Ming Drive, #02-07 AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	2,191.75 FL	*2,121.75 FL
2	1		*REAR BOOTLID EMBLEM	Necessary	66.90 FL	*66.90 FL
3	1		*REAR BOOTLID HANDLE	Dented	189.20 FL	*189.20 FL
4	1		*REAR BOOTLID LOCK	Jammed	294.70 FL	*266.00 FL
5	1		*REAR BOOTLID LOCK CATCH	Repair	153.20 FL	*- FL
6	2		*REAR BOOTLID ABSORBER	Serviceable	658.80 FL	*- FL
7	2		*REAR BOOTLID HINGES	Repair	171.40 FL	*- FL
8	1		*REAR BOOTLID RUBBER (\$391.20) (50%)	Cut	364.16 FS	*195.60 FS
9	1		*REAR BOOTLID TRIMBOARD	Cracked	252.10 FL	*252.10 FL
10	1		*REAR BUMPER	Bent	496.20 FL	*428.10 FL
11	1		*REAR BUMPER STEP PANEL	Bent	365.10 FL	*365.10 FL
12	2		*REAR BUMPER RETIANER	Serviceable	95.70 FL	*- FL
13	1		*REAR END PANEL	Bent	389.70 FL	*389.70 FL
14	1		*REAR END INNER PANEL	Bent	994.50 FL	*994.50 FL
15	1		*REAR SPARE TYRE TRAY	Distorted	240.80 FL	*240.80 FL
16	1		*REAR EXHAUST BOX	Repair	758.70 FL	*- FL
17	1		*TAILLAMP	N/S Scratched	570.40 FL	*285.20 FL
18	1		*REAR NUMBER PLATE	Serviceable	30.00 FS	*- FS
19	1		*REAR BOOTLID STICKER TOYOTA HIACE	Necessary	53.70 FS	*53.70 FS
20	1		*REAR BOOTLID STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
21	1		*REAR BOOTLID STICKER 8PAX	Necessary	10.00 FS	*10.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*REAR BUMPER REVERSE SENSOR	Dented	240.00 FS	*200.00 FS
24	1		*REAR FLOOR BOARD PANEL	Repair	980.20 FL	*- FL
25	1		*REAR FLOOR BOARD WOOD COVER	Serviceable	580.90 FL	*- FL
26	1		*REAR END PANEL TOP GARNISH	Bent	154.80 FL	*154.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,392.91	6,263.45
- List Item Discount on L Items 20.00/25.00% (\$\$)	1,921.01	1,438.54
Total Parts (\$\$)	8,471.90	4,824.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO SPRAY PAINT	New	800.00	600.00
2	LABOUR TO PANEL BEATING	New	900.00	600.00
3	LABOUR TO DISMANTLE AND REFIX TAILGATE GLASS	New	160.00	120.00
4	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	New	150.00	60.00
5	LABOUR TO DISMANTLE AND REFIX FLOOR BOARD PANEL	New	500.00	300.00
Gross Labour Cost (S\$)			2,510.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >