

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

18/02/2019

TPAXA
Joy

Accident date: 08/02/2019

Estimated repair cost for vehicle no: SJN7571E TOYOTA VIOS E 1.5 A '09

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Rim <i>lit</i>	480.00	\$680.00
2	1	Front R/H Tyre <i>new</i>	350.00	\$350.00
3	1	Front R/H Fender <i>Painted</i>	287.65	\$287.65
4	1	Front R/H Fender Vvti Logo <i>new</i>	41.10	\$41.10
5	1	Front R/H Fender Cowling <i>Painted</i>	145.10	\$145.10
6	8	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00
7	1	Front R/H Side Mirror Assy <i>lit</i>	363.60	\$363.60
8	1	Front R/H Door <i>Painted</i>	981.45	\$981.45
9	2	Front R/H Door Hinge <i>new</i>	\$82.10	\$164.20
10	1	Front R/H Door Protector <i>lit</i>	121.45	\$121.45
11	1	Front R/H Door Protector Moulding <i>new</i>	171.60	\$171.60
12	1	R/H Rocker Panel <i>Repair</i>	688.00	\$688.00

Subtotal :- \$4,046.15

988.90

741.67

S.N: 480

Labour charges

To remove & refit front R/H door, glass, gear motor, lock, rubber
& trim board

~~\$280.00~~ 80

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$60.00~~ 30

Tuff kote

~~\$100.00~~ X

Panel beating

1290
~~\$800.00~~ 500

Spray painting

~~\$1,200.00~~ 600

Subtotal :- \$2,590.00

Total:- \$6,636.15

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
H/S 21/02/19.
04 Dyp.

total: 2511.67

H/S: 2K

2.1C