

INS. CASE OWNER: Lyndia | CCU AXA1900 2016 Niss LKK: IDAC:

Surveyor: UPS DOI: 11/1/19 Date / Time: 11/2/19 Registered in Merimen:

Pre-assign / CCU / FTE: YN 1144A
Insured Vehicle No.: PN CONTRACT VII Claim No.: CA MUECH 92004
Name of Insured: PN CONTRACT VII Policy No.: PN 17373
Insured Tel No.: HP: 11/1/19 Make / Model: NISSAN
Excess Sec II :SS D.O.A.: 11/1/19 Place of Accident: KJE
Is driver the owner? (YES / NO) Nature of Accident: 11/1/19
If NO, Driver Name / Age: BORHATHAN KAMALLOS OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO
Driver Tel No.: (V/L- YES / NO) Insured Liability: % Final ? Yes / No

GBF 76111
INSRS: WSP: Li's INSRS: WSP: INSRS: WSP: INSRS: WSP:
Tel: bro Tel: Tel: Tel:
Liability: Liability: Liability: Liability:
RMKS: RMKS: RMKS: RMKS:

Date/ Time	STAGE	DATE / PIC
<u>16-4-19 @ 351 w/ WENDY (OIC)</u>	Non-Reporting hr (1st):	
<u>AGREED & WAIVE</u>	Non-Reporting hr (2nd):	
<u>NCN ISSUE.</u>	Non-Reporting hr (Final):	
	Notification hr (if non-pickup):	
	Call OI:	<u>204 16419</u>
	After call hr to OI:	
	Documentation Check List: Handler Typist	
	Notification hr (if non-pickup)	☒
	After call hr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE Date/Time: Sent By:	
FINALIZATION Date/Time: Confirm with: Confirm by: Email: Call:	
Repair Cost: \$5	(days) Reduction:
FINAL SETTLEMENT Date/Time: <u>10-6-19</u> Confirm with: <u>SUSAN</u> Email: Call:	
Final Liability: %	(Agreed / Assessed) BOLA S/N No.: <u>27</u>
Repair Cost: \$5 <u>13,850</u>	
Loss of Rental (LOR): \$5	(days)
Loss of Use (LOU): \$5 <u>720</u>	(<u>60</u> x <u>12</u> days)
Loss of Income (LOI): \$5	(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐	[Tick only one]
GIA/LTA Search: \$5 <u>7.45</u>	
Medical: \$5	
Disbursement: \$5 <u>64.20</u>	(e.g. <u>05</u> Independent)
Legal Cost: \$5	
Total: \$5 <u>14,641.65</u>	Global Sum \$5: <u>14,600.XX</u>
FINAL PAYMENT Date/Time: Confirm with: Email: Call:	
Payee 1: \$5 <u>14,600.XX</u>	Name 1: <u>LIU'S BROTHER AUTO ENGINEERING WORK SH</u>
Payee 2: (Strike if N.A.) \$5 <u>X</u>	Name 2: <u>X</u>
Payee 3: (Strike if N.A.) \$5	Name 3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 613F3611

at Workshop m/s 14's 50

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 481k.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 10

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LIA 3619

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: 613F3611C

Yr Regn: 9116

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: FIAT Doblo cargo

c.c.

1598

Colour: white

A/C:

Insured / Std / NI / NA

Sp. Reading: 61048

T/Radio:

Insured / Std / NI / NA

Eng/No: _____

C/No: 2FA 2630000. 6003065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

195/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5

mm

R/Bal. 5

mm

L/Bal. 5

mm

L/Bal. 5

mm

D.O.A. _____

D.O.I. 19/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 8 ft ?

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S \$13,850

R (\$25,221.50/65%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

Site Insp (\$

) \$ + RS. \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

**LIU'S BROTHER AUTO ENGINEERING WORKS**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 47,

ROB No: 532017931. Tel: 6741-1730 / 731. Fax: 6744-5746. Email: liusbroy@mail.com

Invoice/Ref No: GBF36uL90218

Estimate

Customer

Page 01 - 03

Name: AXA Insurance Singapore Pte Ltd

Date: 18-02-19

Address: Motor Claims Department

Vehicle No: GBF36uL

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 0688u

Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate <i>20/32/17</i>	\$ 1,895.90	
2	Tailgate Hinge 02 pcs (@ \$5166.30) <i>11</i>	\$ 332.60	X
3	Tailgate Weatherstrip <i>Torn</i>	\$ 297.00	
4	Tailgate Inner Handle <i>11</i>	\$ 189.40	X
5	Tailgate Inner Trim Board <i>CNE</i>	\$ 297.80	
6	Tailgate Inner Trim Board Clips 1 set <i>rec 50</i>	\$ 127.20	
7	Tailgate Lock Top <i>11</i>	\$ 189.30	X
8	Tailgate Lock Lower <i>twi/gm</i>	\$ 192.90	
9	Tailgate "FIAT" Emblem Outer Garnish <i>11</i>	\$ 369.80	X
10	Tailgate "FIAT Logo" Emblem <i>11</i>	\$ 115.70	X
11	Tailgate "Professional" Emblem <i>rec</i>	\$ 163.50	
12	Tailgate "6 PAX" Sticker <i>rec</i>	\$ 12.00	SN 105.2
13	Tailgate Glass Sealant <i>rec</i>	\$ 80.00	SN 405.2
14	Rear Lh Tailgate <i>30/50</i>	\$ 2,395.00	
15	Tailgate Hinge 02 pcs (@ \$5166.30) <i>11</i>	\$ 332.60	X
16	Tailgate Lock <i>twi/gm</i>	\$ 331.00	
17	Tailgate Weatherstrip <i>Torn</i>	\$ 344.50	X
18	Tailgate Outer Handle <i>11</i>	\$ 556.40	X
19	Tailgate Handle Outer Garnish <i>cro</i>	\$ 369.80	
20	Tailgate Number Plate Outer Garnish <i>ns</i>	\$ 154.40	X
21	Tailgate Number Plate Lamp 02 pcs (@ \$551.50) <i>11</i>	\$ 103.00	X
22	Tailgate Number Plate and Base <i>Best</i>	\$ 48.00	SN 405.2
23	Tailgate Inner Trim Board <i>2e/cro</i>	\$ 384.90	
24	Tailgate Inner Trim Board Clips 1 set <i>rec 50</i>	\$ 164.50	
25	Tailgate "MultiJet" Emblem <i>rec</i>	\$ 119.60	
26	Tailgate "90" Emblem <i>rec</i>	\$ 97.50	
27	Tailgate "Doblo" Emblem <i>rec</i>	\$ 118.00	
28	Tailgate "Maxi" Emblem <i>rec</i>	\$ 86.00	
29	Tailgate "70 KM/H" Sticker <i>rec</i>	\$ 12.00	SN 105.2
30	Tailgate Windscreen Glass <i>slab</i>	\$ 841.50	
31	Tailgate Windscreen Glass Sealant <i>rec</i>	\$ 80.00	SN 405.2
32	Tailgate Wiper Motor <i>cro/gm</i>	\$ 428.00	
33	Tailgate Wiper Link <i>11</i>	\$ 165.30	X
34	Tailgate Wiper Rubber <i>rec</i>	\$ 98.00	
35	- Tailgate "Corporate" Advertisement & Art Work <i>rec</i>	\$ 300.00	SN 5.2
C/F Balance --->		\$ 11,793.10	

Not Available

19/2/19
13850
10 day



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBF3611190218

Estimate

Customer	Page 02 - 03
Name: AXA Insurance Singapore Pte Ltd	Date: 18-02-19
Address: Motor Claims Department	Vehicle No: GBF3611
8 Shenton Way #27-01	Model/Make: Fiat Doblo Cargo
AXA Tower Singapore 068811	Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->	\$ 11,793.10	
36	Rear Lh Fender (Body Panel) <i>(5070)</i>	\$ 2,850.00	X
37	Fender Cowling <i>11</i>	\$ 230.00	X
38	Fender Cowling Clips 1 set <i>11</i>	\$ 65.00	X
39	Body Panel "Corporate Advertisement" Sticker <i>11</i>	\$ 380.00	SN ✓ <i>5.00</i>
40	Rear Bumper <i>2.5</i>	\$ 745.00	✓
41	Bumper Clips 1 set <i>11</i>	\$ 65.00	✓
39	Bumper Sponge <i>11</i>	\$ 87.60	X
42	Bumper Reflector 02 pcs (@ \$517.60) <i>2.5</i>	\$ 235.20	12C
43	Bumper Reinforcement <i>2.5</i>	\$ 475.30	✓
44	Bumper Side Bracket 02 pcs (@ \$558.10) <i>5.0</i>	\$ 116.20	✓
45	Bumper Reverse Sensor 1 set <i>5.0</i>	\$ 220.00	SN 2005.00
46	End Panel <i>5.0</i>	\$ 430.00	✓
47	End Panel Top Garnish <i>2.5</i>	\$ 347.70	✓
48	End Panel Top Garnish Clips 1set <i>11</i>	\$ 58.00	SN 305.00
49	End Panel Sealant <i>11</i>	\$ 50.00	SN ✓ <i>5.00</i>
50	Tail Lamp 02 pcs (@ \$462.70) <i>0.5</i>	\$ 925.40	12C
51	Floor Panel Garnish <i>11</i>	\$ 1,379.80	X
52	Front Bumper <i>766</i>	\$ 1,245.50	✓
53	Bumper Clips 1 set <i>11</i>	\$ 60.00	✓
	Bumper Top <i>6.7</i>	\$ 864.10	✓
	Bumper Bottom <i>7.0</i>	\$ 737.10	✓
54	Bumper Reinforcement <i>5.0</i>	\$ 868.00	✓
55	Bumper Sponge <i>7.0</i>	\$ 117.00	✓
56	Bumper Towing Cover <i>11</i>	\$ 60.00	X
57	Bumper Centre Grille <i>11</i>	\$ 187.00	X
58	Bumper Side Grille <i>11</i>	\$ 160.00	X
59	Bumper Lower Garnish <i>11</i>	\$ 685.00	X
60	Grille <i>11</i>	\$ 484.70	X
61	Grille Emblem <i>5.0</i>	\$ 142.10	✓
62	Aircon Condenser <i>11</i>	\$ 1,278.80	X
63	Radiator <i>11</i>	\$ 754.30	X
64	Radiator Coolant <i>11</i>	\$ 50.00	SN X
65	<i>Boat</i> <i>1406</i>	\$ 3,640.00	✓
66	Fog Lamp Cover 02 pcs (@ \$23.60) <i>11</i>	\$ 47.20	X
67	HeadLamp 02 pcs (@ \$862.40) <i>11</i>	\$ 1,724.80	✓
68	<i>inter cooler garnish</i> <i>one</i>	\$ 352.60	✓
	C/F Balance -->	\$ 33,911.50	



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF36u190218

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Page 01 - 02

Date:

18-02-19

Vehicle No:

GBF36u1

Model/Make:

Fiat Doblo Cargo

Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->	\$ 33,911.50	
	To trace & check wiring and lighting	\$ 100.00	30
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 120.00	211
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 180.00	112
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	1400
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	1600
	Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repair	\$ 240.00	120
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 180.00	112
	Remove and replace rear Floor Aluminium Board to facilitate repairs	\$ 300.00	112
	To check all wiring & electrical component for proper function	\$ 120.00	112
	Remove and refix rear reverse sensor	\$ 100.00	50
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 220.00	150

Total Parts & Labour of estimate for damaged vehicle

\$ 39,071.50

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks



P-183881
 502
 P-9179.05
 S.N 1100
 1000-3590
 13809

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBF3611L
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	263A50007669020
Chassis No.:	ZFA26300006D03065
Maximum Power Output:	-
Open Market Value:	\$18,536.00
Original Registration Date:	22 Sep 2016
First Registration Date:	22 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$927.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,824.00
COE Rebate Amount:	\$3,659.00
Total Rebate Amount:	\$3,659.00

The information contained herein is correct as at 20 Feb 2019

OK



ANNOUNCING Carway

as sgCarMart Premium Dealer for the 2nd Consecutive Year



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Jan 2014 E200 R18 Avantgarde \$100,666, Agent Maintain.



6 Months Warranty/High Trade
In. Call Now!
Privilege Motors [StarAd](#)



Browse by Category ▼

Sort by Date Posted

10 vehicles

Fiat Doblo

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Fiat Doblo		Any	Any	2016	Any	Any	
	Fiat Doblo Cargo Maxi 1.6A		\$48,000	\$6,520 /yr	30-Jun-2016	1,598 cc	37,800 km	
Fuel Type: Diesel Accident Free. No Scratches No Dents. Very Low Mileage. No Additional Drivers, Only Driven By Myself For Personal Usage. In Very New								
Posted: 19-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat								
	Fiat Doblo Cargo Maxi 1.6A		\$46,800	\$6,490 /yr	09-May-2016	1,598 cc	-	
Fuel Type: Diesel Auto Medium Size Van Just For You. 1 Owner. Low Mileage. Vehicle In Tip Top Condition. Original Paint Work. Door Step Viewing Can B								
ABWIN (1994) Pte Ltd								
Posted: 18-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat								
	Fiat Doblo Cargo Maxi 1.6M		\$40,800	\$5,750 /yr	28-Mar-2016	1,598 cc	80,260 km	
Fuel Type: Diesel 1 Owner, Still Under Agent Warranty 3 Years Or 100K Km Whichever Come First. Buy With Peace Of Mind, Low Depreciation, Cheaper T								
Van, Please Call For Viewing.								
Posted: 18-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat								
	Fiat Doblo Cargo Maxi 1.6A		\$48,800	\$6,630 /yr	29-Jun-2016	1,598 cc	-	
Fuel Type: Diesel Super Value Deal. Monthly \$764 & Down \$3500 Only. Cheaper Than Rent. Well Maintain Exterior And Interior Like New Condition. Fully								
Agent Since Day 1. Flexible In House Loan Available. View ...								
ABWIN Bus Pte Ltd								
Posted: 14-Feb-2019 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat								
	Pro-Jex V2D Auto Pte Ltd - Specialty Workshops Power up for excellent performance with PRO-JEX V2D, your one-stop automobile solution provider. More info about this shop							
	Fiat Doblo Cargo Maxi 1.6A		\$44,800	\$6,470 /yr	21-Jan-2016	1,598 cc	89,826 km	
Fuel Type: Diesel In The Market, For Personal Usage Only, No Cargos Etc. Hence The Car Looks And Drive Like New. No Scratches Etc. Conditio								

Compare

« Service Request Details

Claim

S9M01ECH

Reference

None ✎

Loss Date

February 18, 2019

Request Date

February 19, 2019

Due Date

February 26, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration

GBF3611L

Make

TPVD FIAT

Model

DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Service Address

vehicle in.
* minus capter.



Re:MANDATE IA

Type

 Question

Message

APPROVED

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVENUE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 4/4/2019

Survey Details:

Date of loss	18-Feb-19
Date of appointment	19-Feb-19
Date of survey	19-Feb-19
Location of survey	LIU'S BROTHER

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBF 3611C
Make and Model	FIAT DOBLO 1598CC
Date of registration	22.09.16
Excess	
Market Value	\$ 48,000.00
Part Rebate	\$ 3,659.00
Nett Loss	\$ 44,341.00

Repair details:

Initial Estimate	39,071.50
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 10,279.05
Check items (estimate)	\$ -
Labour	\$ 3,590.00
Total	\$ 13,869.05
Lump Sum(if applicable)	\$ 13,850.00

Number of days for repair	<u>10DAYS</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

HEAD TO REAR ; OIC CONFIRMED NO DAMAGE TO THE REPORTED
1ST CAR AND IT JUST DROVE AWAY

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	13,850.00
Loss of USE	\$	720.00
Towing fee	\$	64.20
LTA search fees	\$	7.45
Proposed Total	\$	14,641.65

Our Ref: GBF3611L190218

Date: 06/03/2019

Your Ref:

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01
AXA Tower
Singapore 068811

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG KJE TOWARDS TUAS BEFORE EXIT 2 WEST SPRING PRIMARY SCHOOL
INVOLVING GBF 3611L AND YN1944A ON 18/02/2019**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**, the registered owners of m/vehicle – **GBF 3611L** at all material times of the above accident. Our/my vehicle was surveyed by "AXA" authorized appraiser and we/I based our/my claims on his recommendation for **S\$13,850-00** being the repair for **10 Days** (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **YN1944A** when the same was involved in the aforesaid accident with our/my m/vehicle – **GBF 3611L**.

We/I whereby you are the insurers of m/vehicle **YN1944A** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **GBF 3611L** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	13,850-00
(b) LOU for pre-repair notice 02 days @ S\$80-00		160-00
(c) LOU Fee for 10 days @S\$80-00		800-00
(d) GIA / LTA search fee		7-45
(e) Towing Fee (Work Order No: 1208323)		64-20

Total Amount

S\$ 14,881-65

We/I enclose herewith copies of the supporting documents for vehicle no. **GBF3611L** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,



The owner of m/vehicle **GBF3611L**
Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engrg Ws

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Tuesday, 16 April 2019 4:18 PM
To: wendy@pjicon.com.sg; pjicon@singnet.com.sg
Cc: Admin A
Subject: ACCIDENT INVOLVING YN 1944A AND GBF 3611L ALONG KJE ON 18.02.2019

PJI CONTRACT PTE LTD

Policy Holder

Dear Sir/Madam,

OUR REF : CC4/ASM19003076/Ujb3
YOUR REF : YN 1944A

ACCIDENT INVOLVING YN 1944A AND GBF 3611L ALONG KJE ON 18.02.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s LIU'S BROTHER AUTO ENGINEERING WORKSHOP, acting on behalf of the owner of GBF 3611L against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit Third Party vehicle from the rear. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at joyirene@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

Authorization To Act

Attn: Motor Claims Department

AXA Insurance Singapore Pte Ltd

8 Shenton Way #27-01

AXA Tower

Singapore 068811

I / We, Messers Goldbell Leasing Pte Ltd ("the third party claimant") of No. 18 Tuas Avenue 10 Singapore 639142 (address), owner of GBF3611L (vehicle no.) hereby authorize Liu's Brother Auto Engineering Workshop ("the workshop") to act for me / us with respect to my / our claim for repair costs and / or rental and / or loss of use ("claim") for my / our vehicle no. GBF3611L that was damaged pursuant to the accident which occurred on 18/02/2019 (date) along KJE Towards Tuas Before Exit 2 West Spring Primary School (location) involving YN1944A ("the accident").

I / We further authorize the workshop to settle my / our above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my / our claim with payment cheque / s being made in favour of the workshop.

I / We further acknowledge that any settlement the workshop may reach on my / our behalf is on a without prejudice and without admission of liability basis insofar as the driver / owner / insurers of the other vehicle / s is concerned.

Dated this 10th day of June (month) 20 19 (year)

3rd Party Claimant:

Workshop:

Signature: 

Name: Goldbell Leasing Pte Ltd

Address: No. 18 Tuas Avenue 10

Singapore 639142

Nric/ROC No: 199001196N

Signature: 

Name: Liu's Brother Auto Engrg Workshop

Address: 1 Kaki Bukit Avenue 6 #01-01

AutoBay @ Kaki Bukit

Singapore 417883

ROB No: 53291793J



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	YN 1944A	(Insd veh)	Model: FIAT DOBLO
	GBF 3611L	(TP veh)	
Date of Accident/ Time:	18/02/2019		

Repair Estimate:	\$ 39,071.50	
Final Repair Cost	\$	
Loss of Use	\$	days at \$ per day
Rental (if any)	\$	days at \$ per day
LTA / GIA Search Fee	\$	
Others:	\$	
Final Settlement Sum	\$ 14,600.00 GLOBAL SUM	
Payee Name: LIU'S BROTHER AUTO ENGINEERING WORKSHOP		
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)		
A)	For Non GIA Registered Workshop:	Agreed Liability: 100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario: No
	RCHA Liability: (%)	Assessed Liability: (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		
Remarks:		

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and/or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

 	 
Signature of workshop representative / Workshop stamp	Signature of Witness / Workshop stamp (if applicable)
Name of Representative: LIU'S BROTHER AUTO ENGINEERING WORKSHOP	Name of Witness: Low Siew Yian - S1543134B
Date: 10 JUN 2019	Date: 10 JUN 2019
ROB No. 53291793J	


Signature of AXA's surveyor/representative:
Name of AXA's surveyor / Representative:
Date:

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 | Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF36uL190218

Final Bill

Customer	Page 01 - 03
Name: AXA Insurance Singapore Pte Ltd	Date: 05-03-19
Address: Motor Claims Department	Vehicle No: GBF36uL
8 Shenton Way #27-01	Model/Make: Fiat Doblo Cargo
AXA Tower Singapore 0688u	Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate	\$ 1,895.90	\$ -
2	Tailgate Hinge 02 pcs (@ \$8166.30)	\$ 332.60	\$ -
3	Tailgate Weatherstrip	\$ 297.00	\$ -
4	Tailgate Inner Handle	\$ 189.40	\$ -
5	Tailgate Inner Trim Board	\$ 297.80	\$ -
6	Tailgate Inner Trim Board Clips 1 set	\$ 127.20	\$ -
7	Tailgate Lock Top	\$ 189.30	\$ -
8	Tailgate Lock Lower	\$ 192.90	\$ -
9	Tailgate "FIAT" Emblem Outer Garnish	\$ 369.80	\$ -
10	Tailgate "FIAT Logo" Emblem	\$ 115.70	\$ -
11	Tailgate "Professional" Emblem	\$ 163.50	\$ -
12	Tailgate "6 PAX" Sticker	\$ 12.00 SN	\$ -
13	Tailgate Glass Sealant	\$ 80.00 SN	\$ -
14	Rear Lh Tailgate	\$ 2,395.00	\$ -
15	Tailgate Hinge 02 pcs (@ \$8166.30)	\$ 332.60	\$ -
16	Tailgate Lock	\$ 331.00	\$ -
17	Tailgate Weatherstrip	\$ 344.50	\$ -
18	Tailgate Outer Handle	\$ 556.40	\$ -
19	Tailgate Handle Outer Garnish	\$ 369.80	\$ -
20	Tailgate Number Plate Outer Garnish	\$ 154.40	\$ -
21	Tailgate Number Plate Lamp 02 pcs (@ \$51.50)	\$ 103.00	\$ -
22	Tailgate Number Plate and Base	\$ 48.00 SN	\$ -
23	Tailgate Inner Trim Board	\$ 384.90 SN	\$ -
24	Tailgate Inner Trim Board Clips 1 set	\$ 164.50 SN	\$ -
25	Tailgate "Multijet" Emblem	\$ 119.60 SN	\$ -
26	Tailgate "90" Emblem	\$ 97.50 SN	\$ -
27	Tailgate "Doblo" Emblem	\$ 118.00	\$ -
28	Tailgate "Maxi" Emblem	\$ 86.00	\$ -
29	Tailgate "70 KM/H" Sticker	\$ 12.00 SN	\$ -
30	Tailgate Windscreen Glass	\$ 841.50	\$ -
31	Tailgate Windscreen Glass Sealant	\$ 80.00 SN	\$ -
32	Tailgate Wiper Motor	\$ 428.00	\$ -
33	Tailgate Wiper Link	\$ 165.30	\$ -
34	Tailgate Wiper Rubber	\$ 98.00	\$ -
35	Tailgate "Corporate" Advertisement & Art Work	\$ 300.00 SN	\$ -
36	Fender (Body Panel)	\$ 2,850.00	\$ -
37	Fender Cowling	\$ 230.00	\$ -
	C/F Balance --->	\$ 14,873.10	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 | Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBF36uL190218

Final Bill

Customer	Page 02 - 03
Name: AXA Insurance Singapore Pte Ltd	Date: 05-03-19
Address: Motor Claims Department	Vehicle No: GBF36uL
8 Shenton Way #27-01	Model/Make: Fiat Doblo Cargo
AXA Tower Singapore 0688u	Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 14,873.10	\$ -
38	Rear Lh Fender Cowling Clips 1 set	\$ 65.00	\$ -
39	Body Panel "Corporate Advertisement" Sticker	\$ 380.00 SN	\$ -
40	Rear Bumper	\$ 745.00	\$ -
41	Bumper Clips 1 set	\$ 65.00 SN	\$ -
39	Bumper Sponge	\$ 87.60	\$ -
42	Bumper Reflector 02 pcs (@ \$517.60)	\$ 235.20	\$ -
43	Bumper Reinforcement	\$ 475.30	\$ -
44	Bumper Side Bracket 02 pcs (@ \$58.10)	\$ 116.20	\$ -
45	Bumper Reverse Sensor 1 set	\$ 220.00 SN	\$ -
46	End Panel	\$ 430.00	\$ -
47	End Panel Top Garnish	\$ 347.70	\$ -
48	End Panel Top Garnish Clips 1set	\$ 58.00 SN	\$ -
49	End Panel Sealant	\$ 50.00 SN	\$ -
50	Tail Lamp 02 pcs (@ \$462.70)	\$ 925.40	\$ -
51	Floor Panel Garnish	\$ 1,379.80	\$ -
52	Front Bumper	\$ 1,245.50	\$ -
53	Bumper Clips 1 set	\$ 60.00 SN	\$ -
54	Bumper Top	\$ 864.10	\$ -
55	Bumper Bottom	\$ 737.10	\$ -
56	Bumper Reinforcement	\$ 868.00	\$ -
57	Bumper Sponge	\$ 117.00	\$ -
58	Bumper Towing Cover	\$ 60.00	\$ -
59	Bumper Centre Grille	\$ 187.00	\$ -
60	Bumper Side Grille	\$ 160.00	\$ -
61	Bumper Lower Garnish	\$ 685.00	\$ -
62	Grille	\$ 484.70	\$ -
63	Grille Emblem	\$ 142.10	\$ -
64	Aircon Condenser	\$ 1,278.80	\$ -
65	Radiator	\$ 754.30	\$ -
66	Radiator Coolant	\$ 50.00 SN	\$ -
67	Inter Cooler	\$ 3,640.00	\$ -
68	Fog Lamp Cover 02 pcs (@ \$23.60)	\$ 47.20	\$ -
69	HeadLamp 02 pcs (@ \$862.40)	\$ 1,724.80	\$ -
70	Head Lamp Outer Garnish 02 pcs (@ \$176.30)	\$ 352.60	\$ -
	C/F Balance --->	\$ 33,911.50	\$ -



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF36uL190218

Final Bill**Customer**

Page 03 - 03

Name: AXA Insurance Singapore Pte Ltd

Date: 05-03-19

Address: Motor Claims Department

Vehicle No: GBF36uL

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MTJ

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance --->	\$ 33,911.50	\$ -
	To trace & check wiring and lighting	\$ 100.00	\$ -
	To remove & refix air con, re-fill air con gas & test for leakages	\$ 120.00	\$ -
	Remove and replace rear exhaust pipe system to facilitate repairs	\$ 180.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	\$ -
	Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs	\$ 240.00	\$ -
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 180.00	\$ -
	Remove and replace rear Floor Aluminium Board to facilitate repairs	\$ 300.00	\$ -
	To check all wiring & electrical component for proper function	\$ 120.00	\$ -
	Remove and refix rear reverse sensor	\$ 100.00	\$ -
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 220.00	\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 39,071.50

Total amount in Lump Sum Basis for repaired vehicle

\$ 13,850.00

SDLS: Thirteen Thousand Eight Hundred Fifty Only



M/s Liu's Brother Auto Engrg Wks



ISLAND RECOVERY SERVICES

Bill: 7026, Ubi Road 1 #04-146 Singapore 408719
 Tel: 6747 7400 Email: islandrecovery@gmail.com
 Facsimile: 6844 7233 Web: www.islandrecovery.com.sg
 GST Reg. No. M90370499P Co. Reg. 53120055L

Cash Sales/ Work Order
 NO. 1208323
 Date 18.2.19



HOTLINE: 9182 8211

M/S: Miss Brother Selo Workshop

Vehicle No: GPE 3642 Model: Red Polo

From: 1 Trud club Ave Time Start: 10:05

To: 148 Ave 6 or 07 Time End: 11:04

Remarks:

- ☐ Change Tyres / Jump Start
- ☐ Basement / Multi Carpark
- ☐ Using King Dolly

☐ Accident

☐ Crane Up / Winch Out

☐ Dismantle Shaft / Brake

☐ Use Car Carrier

☐ Open Door

☐ Locked

AMOUNT S\$ 60.00

GST S\$ 4.20

TOTAL S\$ 64.20

bigSAFE₃

Handwritten signature

Received By

Important Note:

Island Recovery Services

Vehicle is transported at owner's risk. The company accepts no responsibility for damaged or other misdeemeanour to your vehicle whilst being transported.

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 18 Feb 2019 / 16:11:44
Receipt Date/Time : 18 Feb 2019 / 16:11:44

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190218-002746
Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YN1944A As at 18 Feb 2019/07:30:00 Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - YN1944A Enquiry Fee 20190218161019354918	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559	Credit Card Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19003076/Ujb3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA LOH		Date : 10-07-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 1944A	Veh. Inspected	GBF 3611L
Policy No.	P2067333	Coverage (\$)	0.00
Claim No.	S9M01ECH	Excess (\$)	0.00
Assign From		Assign Date	19/02/2019
2. Vehicle Particulars & Condition			
Make & Model	FIAT DOBLO CARGO	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	ZFA26300006D03065	Colour	WHITE
Odometer	61048	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R16	PIRELLI	5 mm
L/H Front Tyre	195/60 R16	PIRELLI	5 mm
R/H Rear Tyre	195/60 R16	PIRELLI	5 mm
L/H Rear Tyre	195/60 R16	PIRELLI	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/02/2019	Inspection Date	19/02/2019
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 3611L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH TAILGATE (CONSISTENT)	DENTED / BENT	1,895.90	1,895.90
2	REAR RH TAILGATE HINGE @\$166.30 (CONSISTENT)	NOT NECESSARY	332.60	-
1	REAR RH TAILGATE WEATHERSTRIP (CONSISTENT)	TORN	297.00	297.00
1	REAR RH TAILGATE INNER HANDLE (CONSISTENT)	NOT NECESSARY	189.40	-
1	REAR RH TAILGATE INNER TRIM BOARD (CONSISTENT)	CRACKED	297.80	297.80
1	SET REAR RH TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NECESSARY	127.20	50.00
1	REAR RH TAILGATE LOCK TOP (CONSISTENT)	NOT NECESSARY	189.30	-
1	REAR RH TAILGATE LOCK LOWER (CONSISTENT)	TWISTED / JAMMED	192.90	192.90
1	REAR RH TAILGATE 'FIAT' EMBLEM OUTER GARNISH (CONSISTENT)	NOT NECESSARY	369.80	-
1	REAR RH TAILGATE 'FIAT LOGO' EMBLEM (CONSISTENT)	NOT NECESSARY	115.70	-
1	REAR RH TAILGATE 'PROFESSIONAL' EMBLEM (CONSISTENT)	NECESSARY	163.50	163.50
1	REAR LH TAILGATE (CONSISTENT)	BADLY DENTED	2,395.00	2,395.00
2	REAR LH TAILGATE HINGE @\$166.30 (CONSISTENT)	NOT NECESSARY	332.60	-
1	REAR LH TAILGATE LOCK (CONSISTENT)	TWISTED / JAMMED	331.00	331.00
1	REAR LH TAILGATE WEATHERSTRIP (CONSISTENT)	TORN	344.50	344.50
1	REAR LH TAILGATE OUTER HANDLE (CONSISTENT)	NOT NECESSARY	556.40	-
1	REAR LH TAILGATE HANDLE OUTER GARNISH (CONSISTENT)	CRACKED	369.80	369.80
1	REAR LH TAILGATE NUMBER PLATE OUTER GARNISH (CONSISTENT)	NO SUCH PARTS	154.40	-
2	REAR LH TAILGATE NUMBER PLATE LAMP @\$51.50 (CONSISTENT)	NOT NECESSARY	103.00	-
1	REAR LH TAILGATE INNER TRIM BOARD (CONSISTENT)	DEFORMED / CRACKED	384.90	384.90
1	SET REAR LH TAILGATE INNER TRIM BOARD CLIPS (CONSISTENT)	NECESSARY	164.50	50.00
1	REAR LH TAILGATE 'MULTIJET' EMBLEM (CONSISTENT)	NECESSARY	119.60	119.60
1	REAR LH TAILGATE '90' EMBLEM (CONSISTENT)	NECESSARY	97.50	97.50
1	REAR LH TAILGATE 'DOBLO' EMBLEM (CONSISTENT)	NECESSARY	118.00	118.00
1	REAR LH TAILGATE 'MAXI' EMBLEM (CONSISTENT)	NECESSARY	86.00	86.00

Report Ref No. CC4/ASM19003076/Ujb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR LH TAILGATE WINDSCREEN GLASS (CONSISTENT)	SHORTED	841.50	841.50
1	REAR LH TAILGATE WIPER MOTOR (CONSISTENT)	CRACKED / JAMMED	428.00	428.00
1	REAR LH TAILGATE WIPER LINK (CONSISTENT)	NOT NECESSARY	165.30	-
1	REAR LH TAILGATE WIPER RUBBER (CONSISTENT)	NECESSARY	98.00	98.00
1	REAR LH FENDER (BODY PANEL) (CONSISTENT)	TO REPAIR SEE LABOUR	2,850.00	-
1	REAR LH FENDER COWLING (CONSISTENT)	NOT NECESSARY	230.00	-
1	SET REAR LH FENDER COWLING CLIPS (CONSISTENT)	NOT NECESSARY	65.00	-
1	REAR BUMPER (CONSISTENT)	DISTORTED	745.00	745.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	65.00	65.00
1	REAR BUMPER SPONGE (CONSISTENT)	NOT FITTED	87.60	-
2	REAR BUMPER REFLECTOR @\$117.60 (CONSISTENT)	O/S BROKEN	235.20	117.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	DISTORTED	475.30	475.30
2	REAR BUMPER SIDE BRACKET @\$58.10 (CONSISTENT)	BENT	116.20	116.20
1	REAR END PANEL (CONSISTENT)	BADLY DENTED	430.00	430.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED / TORN	347.70	347.70
2	REAR TAIL LAMP @\$462.70 (CONSISTENT)	O/S CRACKED	925.40	462.70
1	REAR FLOOR PANEL GARNISH (CONSISTENT)	NOT NECESSARY	1,379.80	-
1	FRONT BUMPER (CONSISTENT)	DENTED / DEFORMED	1,245.50	766.00
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
1	FRONT BUMPER TOP (CONSISTENT)	CUT	864.10	864.10
1	FRONT BUMPER BOTTOM (CONSISTENT)	TORN	737.10	737.10
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	868.00	868.00
1	FRONT BUMPER SPONGE (CONSISTENT)	TORN	117.00	117.00
1	FRONT BUMPER TOWING COVER (CONSISTENT)	NOT NECESSARY	60.00	-
1	FRONT BUMPER CENTRE GRILLE (CONSISTENT)	NOT NECESSARY	187.00	-
1	FRONT BUMPER SIDE GRILLE (CONSISTENT)	NOT NECESSARY	160.00	-
1	FRONT BUMPER LOWER GARNISH (CONSISTENT)	NO SUCH PARTS	685.00	-
1	FRONT GRILLE (CONSISTENT)	NOT NECESSARY	484.70	-
1	FRONT GRILLE EMBLEM (CONSISTENT)	SCRATCHED	142.10	142.10
1	FRONT AIRCON CONDENSER (CONSISTENT)	NOT NECESSARY	1,278.80	-

Report Ref No. CC4/ASM19003076/Ujb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR (CONSISTENT)	NOT NECESSARY	754.30	-
1	FRONT BONNET (CONSISTENT)	BUCKLED	3,640.00	1,406.00
2	FRONT FOG LAMP COVER @\$23.60 (CONSISTENT)	NOT NECESSARY	47.20	-
2	FRONT HEADLAMP @\$862.40 (CONSISTENT)	CRACKED	1,724.80	1,724.80
1	FRONT INTER COOLER GARNISH (CONSISTENT)	CRACKED	352.60	352.60
	LESS 50% DISCOUNT		-	-9,179.05
			32,621.50	9,179.05
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH TAILGATE '6 PAX' STICKER (CONSISTENT) (SN)	NECESSARY	12.00	10.00
1	REAR RH TAILGATE GLASS SEALANT (CONSISTENT) (SN)	NECESSARY	80.00	40.00
1	REAR LH TAILGATE NUMBER PLATE AND BASE (CONSISTENT) (SN)	BENT	48.00	40.00
1	REAR LH TAILGATE '70KM/H' STICKER (CONSISTENT) (SN)	NECESSARY	12.00	10.00
1	REAR LH TAILGATE WINDSCREEN GLASS SEALANT (CONSISTENT) (SN)	NECESSARY	80.00	40.00
1	REAR LH BODY PANEL 'CORPORATE ADVERTISEMENT' STICKER (CONSISTENT) (SN)	NECESSARY	380.00	380.00
1	SET REAR BUMPER REVERSE SENSOR (CONSISTENT) (SN)	SHORTED	220.00	200.00
1	SET REAR END PANEL TOP GARNISH CLIPS (CONSISTENT) (SN)	NECESSARY	58.00	30.00
1	REAR END PANEL SEALANT (CONSISTENT) (SN)	NECESSARY	50.00	50.00
1	FRONT RADIATOR COOLANT (CONSISTENT) (SN)	NOT NECESSARY	50.00	-
1	REAR LH TAILGATE 'CORPORATE' ADVERTISEMENT & ART WORK (CONSISTENT) (SN)	NECESSARY	300.00	300.00
			1,290.00	1,100.00
	<u>LABOUR</u>			
	TO TRACE & CHECK WIRING AND LIGHTING.		100.00	30.00
	TO REMOVE & REFIX AIR CON ,RE-FILL AIR CON GAS & TEST FOR LEAKAGES.	NOT NECESSARY	120.00	-
	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-

Report Ref No. CC4/ASM19003076/Ujb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETC.S.INCLUSIVE OF THE REPAIR OF REAR LH FENDER (BODY PANEL).		1,800.00	1,400.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		1,800.00	1,600.00
	REMOVE & REINSTALL REAR RH & LH WINDSCREEN GLASS TO FACILITATE REPAIRS.		240.00	240.00
	REMOVE AND REFIX REAR RH & LH TAILGATE COMPONENTS & WIPER MECHANISMS.		180.00	120.00
	REMOVE AND REPLACE REAR FLOOR ALUMINIUM BOARD TO FACILITATE REPAIRS.	NOT NECESSARY	300.00	-
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR REVERSE SENSOR .		100.00	50.00
	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA.		220.00	150.00
			5,160.00	3,590.00
GRAND TOTAL			39,071.50	13,869.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,850.00

Report Ref No. CC4/ASM19003076/Ujb3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

