LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd. From: LKK Auto Consultants Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Josey Loh Date: 25 Feb 2019

Preliminary Advice

Vehicle No : SLU5803P Accident Date : 07/02/2019

: MERCEDES-BENZ AMG E43 Policy No. : PNPV2018-00014351 Make

Assignment Date : 19/02/2019 **Excess** : S\$0.00 Date of Inspection : 25/02/2019 Est. Duration of Repair : 2 days

Inspection At : Optima Werkz Pte Ltd (HQ)

9A Serangoon North Ave 5 Singapore 554500

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,933.10
Revised Amount	:S\$	2,583.25
Check Items (Estimated)	:S\$	149.85
Total	:S\$	2,733.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 323,000.00 COE / PARF Rebate 156,258.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 166,742.00

Remarks

X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments: