

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/TP/0012/2019/GW
Date : 22-Feb-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your insured vehicle no : SLR 720 T

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Brian Arthur Sherry
Address : 37 Sixth Crescent
Singapore 276446
Telephone : (HP)+65 90620661
Type of Claim : Third Party Claim
Policy No. : 5074453236-03
Vehicle No : **SKN 153 M**
Model Code : Mercedes B180
Model / Year : May-14
Engine No :
Chassis No : WDD2462422J230648
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Feb-19
Place of Accident : Car Park Behind Ghim Moh Market New Century Café

Premium Autocare Centre

24 Benoi Sector, Singapore 629857

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SKN 153 M

S/n	Nature of Jobs	Estimated Charges	remarks
1	To remove and transfer front wire harness for headlights, foglamps horns and outside temperature sensor.	S/N \$ 150.00 /	
2	To check and rectify electrical wiring, sockets including adjusting the focus area / level of the headlight.	S/N \$ 120.00 /	
3	To dismantle and renew front bumper, headlight lhs, radiator grille. Reorganise front crash management components. Reinstall all parts removed.	\$ 1,100.00 600 /	
4	To respray front bumper.	\$ 600.00 300 /	
5	To carry out diagnostic check.	S/N \$ 150.00 /	
TOTAL LABOUR CHARGES		: \$ 2,120.00	

Premium Autocare Centre

24 Benoi Sector, Singapore 629857
Tel: 6474 3323 Fax: 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SKN 153 M

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>X R</i>	\$ 1,518.00	
2	FRONT BUMPER INNER BRACKET <i>X</i>	\$ 669.00	
3	FRONT BUMPER CHROME MOULDING-LH/RH <i>LH / RH /</i>	2 \$ 238.00	
4	FRONT BUMPER AIR GUIDE GRILLE -LH/RH <i>X NN</i>	2 \$ 80.00	
5	FRONT BUMPER PARKING AID SENSOR-INNER LH/RH <i>?</i>	4 \$ 600.00	
6	FRONT BUMPER PARKING AID SENSOR SEAL RING <i>/ NEC</i>	4 \$ 44.00	
7	FRONT BUMPER PLATE BASE <i>X NF</i>	\$ 2,676.00	
8	RADIATOR GRILLE <i>/ CUT</i>	\$ 811.00	
9	HEADLIGHT-LH <i>?</i>	TBC	
10	FRONT BUMPER RETAINER RIVET <i>/ NEC</i>	4 \$ 28.00	
17	FRONT NO PLATE WITH HOLDER <i>/ QR</i>	S/N \$ 35.00	
18	SUNDRIES <i>/ NEC</i>	\$ 200.00 <i>SO /</i>	
TOTAL SPARE PARTS CHARGES		: \$ 6,899.00	
TOTAL LABOUR CHARGES		: \$ 2,120.00	
GRAND TOTAL		: <u>\$ 9,019.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Steve 1/3/19
have price