

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

To Survey by LKK

VEHICLE NO : SHC 8179E

DATE : 18.02.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>Painted</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>HL</i>		\$ 41.00	\$ 82.00
	Bonnet Lock <i>HL</i>			\$ 36.90
	Bonnet Insulator <i>HL</i>			\$ 196.50
	Bonnet Insulator Clips <i>HL</i>			\$ 8.40
	Radiator Grille <i>Out</i>			\$ 1,110.10
	Radiator Grille H Emblem <i>HL</i>			\$ 120.30
	Front Bumper Cover <i>Crack / broken</i>			\$ 1,052.20
	Front Bumper Sponge <i>torn</i>			\$ 99.20
	Front Bumper Reinforcement <i>HL</i>			\$ 402.10
	Front Bumper Bracket Top (RH) <i>HL</i>			\$ 22.40
	Front Bumper Bracket (RH) <i>HL</i>			\$ 24.60
	Headlamp Support Top Cover <i>HL damaged</i>			\$ 222.60
	Headlamp Support Panel Assy <i>Crack / broken</i>			\$ 907.40
	Headlamp (LH/RH) <i>o/s broken N/S mostly broken</i>		\$ 1,388.00	\$ 2,776.00
	Radiator <i>HL + / punctured</i>			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy <i>HL</i>			\$ 792.95
	Radiator Bracket (RH) <i>HL</i>			\$ 6.50
	Radiator Guard <i>HL</i>			\$ 20.00
	Horn Unit (RH) <i>broken</i>			\$ 73.80
	Front Fender (RH) <i>Painted</i>			\$ 566.30
	Front Fender Apron Panel (RH) <i>Painted</i>			\$ 637.00
	Front Fender Shield (RH) <i>HL</i>			\$ 174.90
	Aircon Condenser <i>HL + / punctured</i>			\$ 927.50
	Aircon Suction & Liquid Hose <i>HL</i>			\$ 624.00
	Aircon Discharge Hose <i>HL</i>			\$ 162.60
	Aircon Compressor <i>HL</i>			\$ 2,578.00
	Inter Cooler <i>HL</i>			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) <i>HL</i>			\$ 25.90
SUB TOTAL				\$ 17,646.85
LESS 20%				\$ 3,529.37
DISCOUNTED TOTAL				\$ 14,117.48
	Labour Charge			
	Panel Beating <i>19/02/2019 @ 1630hrs</i>			\$ 1,500.00
	Spray Painting Charge <i>N/A</i>			\$ 1,000.00
	Wiring Charge <i>HL</i>			\$ 50.00
	Tuff Kote <i>HL</i>			\$ 100.00
	Towing Charge <i>1 hr</i>			\$ 50.00
	Remove/Refix Aircon & Refill Gas <i>LKK</i>			\$ 150.00
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
TOTAL LABOUR				\$ 3,330.00
ESTIMATE TOTAL				\$ 17,447.48

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.