

ASS. REC. BY:

REF: EQ1

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Wei Lee

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJP 40666 Yr Regn: 24/03 09Type: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Avanza c.c. 1591Colour: White A/C: Insured / Std / Nil / NASp. Reading: 136750 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: KMH0U41BR9U711626Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45.8 R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 1/2/19

Rear

R/Bal. 4 mmL/Bal. 4 mmD.O.A. 18/2/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to49 \$1,200.00Cemo: \$3,470.40 (78%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

\$ - RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

*Not Authorised
L1 Lmp & ?
Resony After Paint
4 days*

12, Feb 2019

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
S 069110

Attn Motor claim dept-3rd party claim

Claiming against your insured vehicle no: GBH5471A

Accident involving vehicle no: SJP4066G/GBH5471A/SLU37

DOA: 01/02/2019 AT Slip Rd Fm Upp Thomson Rd Twds SLE(BKE)

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SJP4066G

To supply--

Description	Qty	Amount
Lid	1	907.00
Lid H logo	1	47.10
Lid-avante emblem	1	52.60
Lid lock	1	119.10
Lid reflector @155.70	2	311.40
Boot weather strip	1	96.40
End panel	1	573.40
End panel top garnish	1	111.40
Taillamp @294.30	2	588.60
Rear bumper	1	491.80
Rear bumper enforcement	1	242.80
Rear bumper retainer @42	2	84.00
Parts		3,625.60
Parts less 20%		725.12
		2,900.48

Reverse sensor

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis.

Replace/align all parts into position.

To spray paint.

Ref 220.00 2 coats

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before and after painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

850.00 *500*
700.00 *540*

4,670.48



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/EQI19003082/Kha3

Date: 19/02/2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SJP 4066G


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/02/2019 at the premises of M/s Wei Lee Motor Works - Sin Ming and have the following to report:-

Workshop Estimate Amount	: S\$	4,670.48
Revised Estimate Amount	: S\$	2,902.08
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	2,902.08
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4.0 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Mei Kwan (LKKAuto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 20 February, 2019 4:33 PM
To: Mei Kwan (LKKAuto)
Cc: Vic (LKKAuto); Admin A
Subject: FW: Direct Settlement - Accident Involving (OI GBH5471A: EQI - DM19HO00357/JT) and SJP4066G (TP : LKK REF - CC6/EQI19003082/Kha3) on 01/02/2019
Attachments: Preliminary Advice.pdf; TP ESTIMATE - MARKED.pdf; TP GIA REPORT.pdf; SAS2546855.pdf

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

Our insured vehicle should be GBH5471A.

OI report as attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, February 20, 2019 11:46 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Cc: Joel Goh <joel.goh@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: Direct Settlement - Accident Involving SLU3784Z (OI : EQI - TBA) and SJP4066G (TP : LKK REF - CC6/EQI19003082/Kha3) on 01/02/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir/ Madam,

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

06,MAR 2019

EQ Insurance Company Ltd

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: GBH5471A

Accident involving vehicle no:SJP4066G/GBH5471A/SLU3784Z

ON 01/02/2019 AT Slip Road Fm Upp Thomson Road twds SLE(BKE)

Dear officer incharge

We are the workshop for the owner of vehicle no: SJP4066G

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SJP4066G as follow:-

Cost of repair to SJK4783R	\$ 1,284.00	finalised with your surveyor
Loss of use	\$ 320.00	\$80x04d
LTA search fee	\$ 7.45	
	<hr/>	
	\$ 1,611.45	

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/EQ119003082/Kha3

14 MARCH 2019

IWERKZ PTE LTD
8 TOA PAYOH INDUSTRIAL PARK
#01-1237
SINGAPORE 319060
ATTN: TO THE MANAGEMENT

Dear Sir/Madam,

ACCIDENT INVOLVING GBH 5471A / SJP 4066G / OTHERS ON 01/02/2019

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal EQ INSURANCE COMPANY LIMITED.

Please call us if you have further queries.

Yours faithfully,

Vic Alpeh Sanghlan
Case Handler
DID: 6841 2096
FAX: 6741 4108
Email: vicalpeh@lkkauto.com

c.c. *EQ INSURANCE COMPANY LIMITED*
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, KH Leasing Pte Ltd ("the third party claimant")
of 261 A Upp Thomson Rd (address),
owner of 8SP 4066 G (vehicle no.) hereby authorize
Wei Lee Motor Works
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. 8SP 4066 G that was
damaged pursuant to the accident which occurred on 1/2/2019 (date) along
Slip Road Fin Upp Thomson Feds SLE (BRE) (location)
involving vehicle no/s GBH 5471A / 3CU 3784 Z ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 10 day of Feb (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

威利摩哆
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-28,
SINGAPORE 575644.
TEL: 6459 9830 FAX: 6458 0128
Business Regn No: 269436/00J
GST Regn No: 26-943600-J

TAX INVOICE

M/S : EQ Insurance Company Ltd

NO : WL03734

Vehicle No : SJP4066G

Date : 06-MAR-2019

<u>Quantity</u>	<u>Particulars</u>	<u>Unit Price</u>	<u>Amount Incl.</u> <u>GST</u>
SJP4066G			
1.00	Accident involving vehicle no: SJP4066G/GBH5471A/SLU3784Z DOA: 01/02/2019		
1.00	Cost of repair for vehicle no: SJP4066G Lump sum repaired as recommended by LKK Auto Consultants	\$1,200.00	\$1,200.00
1.00	GST 7%	\$84.00	\$84.00
Total Amount Incl. GST			\$1,284.00
Standard Rate GST Amount (7.00%)		\$84.00	
Total Amount Before GST		\$1,200.00	



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Feb 2019 / 18:35:08

Receipt Date/Time : 12 Feb 2019 / 18:35:08

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190212-003264

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - GBH5471A				
As at 01 Feb 2019/15:45:00				
Insurance Co: EQ INSURANCE COMPANY LTD				
1	Insurance Enquiry - GBH5471A Enquiry Fee 20190212183415378666	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20190212183426618	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 24/05/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBH 5471A (Insd Veh)	Your Ref. No. : DM19HO00357/JT
	SJP 4066G (TP Veh)	Our Ref. No. : CC6/EQI19003082/Kha3q2
Date of Accident	1/2/2019	

Liability	100%	
Final Repair Cost	: \$ 1,284.00	
Loss of Use	: \$ 240.00	4 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	1,531.45	
Final Settlement Sum	: \$ 1,531.45	
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	WEI LEE MOTOR WORKS	: \$ 1,531.45
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ16022787/Kwb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-11-2017



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 9831E	Veh. Inspected	SLA 4127U
Policy No.	DMCPHQ16-000173	Coverage (\$)	0.00
Claim No.	DM16HIO02454/WY	Excess (\$)	0.00
Assign From		Assign Date	30/11/2016

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JF1SJGK85GG067187	Colour	METALLIC SILVER
Odometer	10778	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/50 R18	YOKOHAMA	9 mm
L/H Front Tyre	245/50 R18	YOKOHAMA	9 mm
R/H Rear Tyre	245/50 R18	YOKOHAMA	9 mm
L/H Rear Tyre	245/50 R18	YOKOHAMA	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/11/2016	Inspection Date	15/12/2016
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ19003082/Kha3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 24-05-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 5471A	Veh. Inspected	SJP 4066G
Policy No.	DMCPHQ18-004226	Coverage (\$)	0.00
Claim No.	DM19HO00357/JT	Excess (\$)	0.00
Assign From		Assign Date	18/02/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KMHU41BR9U711626	Colour	WHITE
Odometer	136750	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45Z R17	BRIDGESTONE	4 mm
L/H Front Tyre	215/45Z R17	BRIDGESTONE	4 mm
R/H Rear Tyre	215/45Z R17	BRIDGESTONE	4 mm
L/H Rear Tyre	215/45Z R17	BRIDGESTONE	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/02/2019	Inspection Date	18/02/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 4066G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LID	BUCKLED	907.00	907.00
1	LID H LOGO	NECESSARY	47.10	47.10
1	LID -AVANTE EMBLEM	NECESSARY	52.60	52.60
1	LID LOCK	TO REPAIR SEE LABOUR	119.10	-
2	LID REFLECTOR @\$155.70	SERVICEABLE	311.40	-
1	BOOT WEATHER STRIP	SERVICEABLE	96.40	-
1	END PANEL	TO REPAIR SEE LABOUR	573.40	-
1	END PANEL TOP GARNISH	SERVICEABLE	111.40	-
2	TAILLAMP @\$294.30	N/S CRACKED	588.60	294.30
1	REAR BUMPER	BUCKLED	491.80	491.80
1	REAR BUMPER ENFORCEMENT	CRACKED	242.80	242.80
2	REAR BUMPER RETAINER @\$42.00	N/S DISTORTED	84.00	42.00
	LESS 20% DISCOUNT		-725.12	-415.52
			2,900.48	1,662.08
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR (SN)	DENTED	220.00	200.00
			220.00	200.00
	<u>LABOUR</u>			
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS CUT N WELD DAMAGED PANEL. STRAIGHTEN REAR CHASSIS.REPLACE/ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID LOCK AND END PANEL.		850.00	500.00
	TO SPRAY PAINT.		700.00	540.00
			-	-
			-	-
			-	-
			1,550.00	1,040.00
	GRAND TOTAL		4,670.48	2,902.08

Report Ref No. CC6/EQ119003082/Kha3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	----------

Report Ref No. CC6/EQ119003082/Kha3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Friday, 31 May 2019 2:58 PM
To: 'eqiprs@eqinsurance.com.sg'
Cc: 'Vic (LKKAuto)'
Subject: TP Direct Settlement - Accident Involving GBH 5471A (OI) and SJP 4066G (TP) on 01/02/2019
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933