

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

12, Feb 2019

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
S 069110

Attn Motor claim dept-3rd party claim

Claiming against your insured vehicle no: GBH5471A

Accident involving vehicle no: SJP4066G/GBH5471A/SLU37

DOA: 01/02/2019 AT Slip Rd Fm Upp Thomson Rd Twds SLE(BKE)

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SJP4066G

To supply--

Description	Qty	Amount
Lid	1	907.00
Lid H logo	1	47.10
Lid-avante emblem	1	52.60
Lid lock	1	119.10
Lid reflector @155.70	2	311.40
Boot weather strip	1	96.40
End panel	1	573.40
End panel top garnish	1	111.40
Taillamp @294.30	2	588.60
Rear bumper	1	491.80
Rear bumper enforcement	1	242.80
Rear bumper retainer @42	2	84.00
Parts		3,625.60
Parts less 20%		725.12
		2,900.48

Reverse sensor

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis.

Replace/align all parts into position.

To spray paint.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

850.00 500k

700.00 540k

4,670.48

Rd 220.00 2 cash

Not Authorised
C/Lmp 8?
Recovery After Paint
4 days