

15/5/2019

INS. CASE OWNER:

CC 4/LPC1900 3084, R210152

LKK:

IDAC:

Surveyor:

Rasm

DOI:

ASSIGNMENT

12/5/19

Date / Time :

18/11/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

SUE 6540A

Name of Insured :

TAM WEI PUN.

Insured Tel No. :

HP:

Excess Sec II :SS

D.O.A :

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

18/11/19/UP05/01416

215UP0501908

MAYORA

PIE TMS LIANA

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SUE 589RE

SUE 6540A

SUE 1253C

SMA 1407H

INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

01

INSRS:
WSP:
Tel :
Liability :
RMKS:Accord
TPINSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☒ ☐
	Release Voucher:	☒ ☐
	Final Repair Bill:	☒ ☐
	Car Rental Invoice:	☒ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA :	☒ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☒ ☐
	LOD	☒ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☒ ☐
	Others:	☐ ☐
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by: <u>PUNE</u>
Repair Cost: <u>PP \$518,446.89</u> (<u>16</u> days) Reduction: <u>43 %</u>	Email ☒ Call ☐	
FINAL SETTLEMENT Date/Time: <u>24.09.19</u> Confirm with <u>CEVA</u>	Email ☐ Call ☐	
Final Liability: % <u>100</u> (Agreed / Assessed) BOLA S/N No. : <u>28</u>	If NO or B 28, Ass. Lia : <u>0%</u>	
Repair Cost: <u>\$19,741.67</u>	<u>calc</u> <u>5 veh C.C. OI was 4th veh.</u>	
Loss of Rental (LOR): <u>\$5,800.00</u> (<u>20</u> days) x <u>4140</u>		
Loss of Use (LOU): <u>\$5 -</u> (<u>\$</u> x <u> </u> days)		
Loss of Income (LOI): <u>\$5 -</u> (<u>\$</u> x <u> </u> days)		
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]		
GIA/LTA Search: <u>\$57.45</u>		
Medical: <u>\$5 -</u>		
Disbursement: <u>\$5 -</u> (e.g. Tow/ Independent)		
Legal Cost: <u>\$5 -</u>		
Total: <u>\$523,599.12</u> Global Sum \$:		
FINAL PAYMENT Date/Time: <u>24.09.19</u> Confirm with: <u>CEVA</u>	Email ☒ Call ☐	
Payee 1: <u>\$523,599.12</u> Name 1: <u>ACCORD AUTO SERVICES PTE LTD</u>		
Payee 2: (Strike if N.A.) <u>\$5</u> Name 2:		
Payee 3: (Strike if N.A.) <u>\$5</u> Name 3:		


Pass

REF:

39080

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **SLT 1353C**
 at Workshop n/s: **Accord Auto**
 of: **Pulkit Mehta**
 Insured: **LPC**
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bat. or Market Value: **102K**
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repair: $\frac{1}{2}$ days Res: Yes or No
 Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: **SLT 1353C** Yr Reg: **2017 OUT**
 Type: ☒ 14 Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **Honda Odyssey 2-4** C.C. **2356**
 Colour: **WHITE** A/C: Insured / Std / Nil / NA
 Sp Reading: **043623** T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: **JH MRC 18904C 203920**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: ☒ order / Jammed / Leaked / Burnt or
 Brake: ☒ order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **215/55R17**
 R: _____
 BS: ☒ BOUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **12/02/19** D.O.I: **19/02/19**
 Survey held at: **Accord Auto**
 Des. of Damag: ☒ Fr / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

PIP: 10,496.89 (RED: 13,850.85 43%)

Date/Time: File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1. \$400.00

2. \$100.00

3. \$100.00

4. \$100.00

Total

Report Format :

Lump Sum / I.B.F. (\$)

Add Fee:

☐ Site Insp. (\$)
☐ Interview (\$)
☐ Tech. Insp. (\$)
☐ Weekend (\$)

Survey Fee:
 Transportation
 1. \$400.00
 2. \$100.00
 3. \$100.00
 4. \$100.00
 Total

ACCORD AUTO SERVICES PTE LTD

Asheer

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715913, 62717433, FAX: 62745715

ESTIMATE REPAIR

Pg 1

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Claim Type: Third Party Claim

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Chassis No: JHMRC1890HC203920

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

DOA: 12.2.2019

No	Description	Unit	List (\$)
1	FRONT BONNET <i>BT /</i>	1	\$ 750.40
2	FRONT BONNET HINGE <i>PA /</i>	2	\$ 294.80
3	FRONT BONNET LOCK <i>PA /</i>	1	\$ 176.22
4	FRONT GRILLE TOP BASE <i>CRS ? CR</i>	1	\$ 289.10
5	FRONT GRILLE TOP (OUTER) <i>CRS /</i>	1	\$ 315.90
6	FRONT GRILLE LOGO <i>M /</i>	1	\$ 80.00
7	FRONT GRILLE BASE (CENTER) <i>CRS /</i>	1	\$ 365.32
8	FRONT GRILLE (Outer Top) <i>CRS /</i>	1	\$ 180.65
9	FRONT GRILLE (Outer Lower) <i>CRS /</i>	1	\$ 180.65
10	FRONT GRILLE (Outer LH & RH) <i>SCA -</i>	2	\$ 288.40
11	FRONT LOWER GRILLE <i>? de /</i>	1	\$ 288.70
12	FRONT HEADLAMP LH <i>? CR</i>	1	\$ 2201 2,581.90
13	FRONT HEADLAMP RH <i>? X m X</i>	1	\$ 2,581.90 X
14	FRONT HEADLAMP LOWER BRACKET <i>? X m X</i>	2	\$ 120.00 X
15	FRONT REINFORCEMENT <i>? btr</i>	1	\$ 354.70
16	FRONT SUPPORT PANEL <i>repair</i>	1	\$ 520.80 X R
17	FRONT BUMPER <i>DE /</i>	1	\$ 880.00
18	FRONT BUMPER SIDE RETAINER <i>M /</i>	2	\$ 110.00
19	FRONT BUMPER LOWER SIDE SKIRT LH & RH <i>X m X</i>	2	\$ 440.00 X
20	FRONT NUMBER PLATE GARNISH <i>CRS /</i>	1	\$ 80.00
21	FRONT FOGLAMP GARNISH <i>? X m X</i>	2	\$ 230.00 X
22	FRONT FOGLAMP <i>X CR</i>	2 <i>1pc</i>	\$ 280 560.00
23	FRONT FENDER LH <i>repair</i>	1	\$ 680.00 X R
24	FRONT FENDER RH <i>repair</i>	1	\$ 680.00 X R
25	REAR TAILGATE <i>CR</i>	1	\$ 803 1,380.80
26	REAR TAILGATE ABSORBER <i>X m</i>	2	\$ 390.00 X
Total (A) :			\$ 14,800.24
Less 20%			\$ 2,960.05
Total:			\$ 11,840.19

7918.84

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715113 62717433 FAX: 62745718

ESTIMATE REPAIR

Pg 2

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Claim Type: Third Party Claim

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Chassis No: JHMRC1890HC203920

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

DOA: 12.2.2019

5246.41

No	Description	Unit	List (\$)
27	REAR TAILGATE LOGO <i>me /</i>	1	\$ 80.00
28	REAR TAILGATE CENTER "ODYSSEY" CHROME <i>CRP # 7.34 X</i>	1	\$ 280.00
29	REAR TAILGATE LAMP LH <i>CRA /</i>	1	\$ 400.00
30	REAR TAILGATE LAMP RH <i>CRA /</i>	1	\$ 400.00
31	REAR TAIL GATE CHROME *under number plate <i>CRA /</i>	1	\$ 215.98
32	REAR TAILGATE NUMBER PLATE LIGH <i>X SUC X</i>	SET	\$ 85.00
33	REAR TAILGATE WINDSCREEN MOULDING <i>me /</i>	1	\$ 188.18
34	REAR TAILGATE INNER TRIM BOARD <i>CRA /</i>	1	\$ 330.00
35	REAR TAILGATE INNER TRIM BOARD CLIPS <i>me /</i>	SET	\$ 70.00
36	REAR LAMP LH <i>? cra /</i>	1	\$ 850.00
37	REAR LAMP RH <i>? cra /</i>	1	\$ 850.00
38	REAR LAMP LOWER BRACKET <i>X SUC X</i>	2	\$ 130.00
39	REAR BUMPER <i>DE /</i>	1	\$ 665 768.30
40	REAR BUMPER SIDE RETAINER <i>me. LH - me /</i>	1pc	\$ 70 140.00
41	REAR BUMPER REFLECTOR <i>? X SUC X</i>	2	\$ 140.00
42	REAR BUMPER REFLECTOR GARNISH LH <i>DE /</i>	1	\$ 155.00
43	REAR BUMPER REFLECTOR GARNISH RH <i>DE /</i>	1	\$ 155.00
44	REAR BUMPER SIDE LH <i>cut /</i>	1	\$ 185.47
45	REAR BUMPER SIDE RH <i>cut /</i>	1	\$ 185.47
46	REAR TAILGATE LOCK <i>me /</i>	1	\$ 265.35
47	REAR TAILGATE STRICK <i>X SUC X</i>	1	\$ 35.00
48	REAR TAILGATE WEATHERSHIP <i>me /</i>	1	\$ 180.96
49	REAR TAILGATE HANDLE SWITCH <i>X 1 X</i>	1	\$ 188.00
50	REAR FENDER SHIELD LH <i>X 1 X</i>	1	\$ 145.65
51	REAR FENDER SHIELD RH <i>X 1 X</i>	1	\$ 145.65
52	REAR FLOOR PANEL <i>repair</i>	1	\$ 1,280.00

Total (B) : \$ 7,849.01

Less 20% \$ 1,962.25

Total: \$ 5,886.76

[illegible]

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL: 62715133 62715433 FAX: 62745715

Pg 4

DOA: 12.2.2019

[illegible]

TEL: 62715433 62715433 FAX: 62745715

Pg 5

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Claim Type: Third Party Claim

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Chassis No: JHMRC1890HC203920

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

DOA: 12.2.2019

[illegible]

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before / after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Resin
4p 90010068
16 days
P/P
19/02/19 @ 1730
Resin 64 paint

31602.05
32347.74%

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 / 62717433 FAX: 62745715

SUPPLEMENTARY ESTIMATE REPAIR

Pg 1

Lonpac Insurance BHD

Date: 28.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

Claim Type: Third Party Claim

Chassis No: JHMRC1890HC203920

DOA: 12.2.2019

No	Description	Unit	List (\$)
1	AIRCON CONDENSER <i>bj ✓</i>	1	\$ 580.00
2	AIRCON CONDENSER MOUNTING <i>nu ✓</i>	1	\$ 15.00
3	BONNET STAND CLIP <i>de ✓</i>	2	\$ 12.00
Total:			\$ 607.00
Less 20%			\$ 121.40
			\$ 485.60
Labour			
1	To Remove / Replace Aircon Condenser (Refix Piping, Hose, Top Up Aircon Gas, etc...)	1	\$ <i>100 ✓</i> 200.00
<i>Tanpin 28/2/19 130 pm</i>			
<i>P- 12706.20</i>			
<i>S/N - 505.00</i>			
<i>L - 4640.00</i>			
<i>Suppl-p - 545.69</i>			
<i>Suppl-L - 100.00</i>			
<i>T - 18,496.89</i>			Total (A): \$ 685.60

16 days P/P

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

HL 62715133 62717433 LAN 62745715

SUPPLEMENTARY ESTIMATE REPAIR

Pg 1

Lonpac Insurance BHD

Date: 28.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Claim Type: Third Party Claim

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Chassis No: JHMRC1890HC203920

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

DOA: 12.2.2019

[illegible]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC19003084/R1pb3

Date: 20.02.2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLT1353C

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.02.2019 at the premises of M/s Accord Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	30,953.81
Revised Estimate Amount	: S\$	13,895.12
"Check" Items Amount	: S\$	7,772.09
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 16 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715133 62717433 FAX: 62745715

ESTIMATE REPAIR

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

Claim Type: Third Party Claim

Chassis No: JHMRC1890HC203920

DOA: 12.2.2019

Pg 1

No	Description	Unit	List (\$)
1	FRONT BONNET <i>BT /</i>	1	\$ 750.40
2	FRONT BONNET HINGE <i>TA /</i>	2	\$ 294.80
3	FRONT BONNET LOCK <i>TA /</i>	1	\$ 176.22
4	FRONT GRILLE TOP BASE <i>CRS /</i>	1	\$ 289.10
5	FRONT GRILLE TOP (OUTER) <i>CRS /</i>	1	\$ 315.90
6	FRONT GRILLE LOGO <i>m /</i>	1	\$ 80.00
7	FRONT GRILLE BASE (CENTER) <i>CRS /</i>	1	\$ 365.32
8	FRONT GRILLE (Outer Top) <i>CRS /</i>	1	\$ 180.65
9	FRONT GRILLE (Outer Lower) <i>CRS /</i>	1	\$ 180.65
10	FRONT GRILLE (Outer LH & RH) <i>SEA -</i>	2	\$ 288.40
11	FRONT LOWER GRILLE <i>?</i>	1	\$ 288.70
12	FRONT HEADLAMP LH <i>?</i>	1	\$ 2,581.90
13	FRONT HEADLAMP RH <i>?</i>	1	\$ 2,581.90
14	FRONT HEADLAMP LOWER BRACKET <i>?</i>	2	\$ 120.00
15	FRONT REINFORCEMENT <i>?</i>	1	\$ 354.70
16	FRONT SUPPORT PANEL <i>repair /</i>	1	\$ 520.80
17	FRONT BUMPER <i>TA /</i>	1	\$ 880.00
18	FRONT BUMPER SIDE RETAINER <i>m /</i>	2	\$ 110.00
19	FRONT BUMPER LOWER SIDE SKIRT LH & RH <i>X</i>	2	\$ 440.00
20	FRONT NUMBER PLATE GARNISH <i>CRS /</i>	1	\$ 80.00
21	FRONT FOG LAMP GARNISH <i>?</i>	2	\$ 230.00
22	FRONT FOG LAMP <i>X</i>	2	\$ 560.00
23	FRONT FENDER LH <i>repair</i>	1	\$ 680.00
24	FRONT FENDER RH <i>repair</i>	1	\$ 680.00
25	REAR TAILGATE <i>repair</i>	1	\$ 1,380.80
26	REAR TAILGATE ABSORBER <i>X</i>	2	\$ 390.00
Total (A) :			\$ 14,800.24
Less 20%			\$ 2,960.05
Total:			\$ 11,840.19

3378.51
1.5157.00

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 67151333 67117432 FAX: 67148715

ESTIMATE REPAIR

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

Claim Type: Third Party Claim

Chassis No: JHMRC1890HC203920

DOA: 12.2.2019

Pg 2

No	Description	Unit	List (\$)
27	REAR TAILGATE LOGO <i>me /</i>	1	\$ 80.00
28	REAR TAILGATE CENTER "ODYSSEY" CHROME <i>extra?</i>	1	\$ 280.00
29	REAR TAILGATE LAMP LH <i>CRA /</i>	1	\$ 400.00
30	REAR TAILGATE LAMP RH <i>CRA /</i>	1	\$ 400.00
31	REAR TAIL GATE CHROME *under number plate <i>CRA /</i>	1	\$ 215.98
32	REAR TAILGATE NUMBER PLATE LIGH <i>X</i>	SET	\$ 85.00
33	REAR TAILGATE WINDSCREEN MOULDING <i>me /</i>	1	\$ 188.18
34	REAR TAILGATE INNER TRIM BOARD <i>CRA /</i>	1	\$ 330.00
35	REAR TAILGATE INNER TRIM BOARD CLIPS <i>me /</i>	SET	\$ 70.00
36	REAR LAMP LH <i>?</i>	1	\$ 850.00
37	REAR LAMP RH <i>?</i>	1	\$ 850.00
38	REAR LAMP LOWER BRACKET <i>X</i>	2	\$ 130.00
39	REAR BUMPER <i>DE -</i>	1	\$ 768.30
40	REAR BUMPER SIDE RETAINER <i>me - LH - me /</i>	<i>1pc /</i>	\$ 140.00
41	REAR BUMPER REFLECTOR <i>?</i>	2	\$ 140.00
42	REAR BUMPER REFLECTOR GARNISH LH <i>DE /</i>	1	\$ 155.00
43	REAR BUMPER REFLECTOR GARNISH RH <i>DE /</i>	1	\$ 155.00
44	REAR BUMPER SIDE LH <i>cut /</i>	1	\$ 185.47
45	REAR BUMPER SIDE RH <i>cut /</i>	1	\$ 185.47
46	REAR TAILGATE LOCK <i>me /</i>	1	\$ 265.35
47	REAR TAILGATE STRICK <i>X</i>	1	\$ 35.00
48	REAR TAILGATE WEATHERSHIP <i>me /</i>	1	\$ 180.96
49	REAR TAILGATE HANDLE SWITCH <i>X</i>	1	\$ 188.00
50	REAR FENDER SHIELD LH <i>X</i>	1	\$ 145.65
51	REAR FENDER SHIELD RH <i>X</i>	1	\$ 145.65
52	REAR FLOOR PANEL <i>repair</i>	1	\$ 1,280.00
Total (B) :			\$ 7,849.01
Less 20%			\$ 1,962.25
Total:			\$ 5,886.76

22919.22
1696

TEL: 62715133 62717433 FAX: 62745715

[illegible]

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL: 62715433 62717433 FAX: 62745715

ESTIMATE REPAIR

Lonpac Insurance BHD

Date: 18.2.2019

Owner's Name : Ooi Eng Hoe

Vehicle No : SLT1353C

Vehicle Make & Model : Honda Odyssey 2.4 EXV-S CVT SR (A)

Claim Type: Third Party Claim

Chassis No: JHMRC1890HC203920

Registration Date : 19 Oct 2017 (YOM 2017) COE Expiry Date 18 Oct 2027

DOA: 12.2.2019

Pg 4

[illegible]

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3908B
Vehicle Details	
Vehicle No.:	SLT1353C
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2019
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	K24W72041390
Chassis No.:	JHMRC1890HC203920
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$30,986.00
Original Registration Date:	19 Oct 2017
First Registration Date:	19 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$35,381.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Oct 2027
PARF Rebate Amount:	\$26,535.00
Intended COE Rebate Details	
COE Expiry Date:	18 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$44,163.00
Total Rebate Amount:	\$70,698.00

The information contained herein is correct as at 20 Feb 2019

OK

102,000
 70,698

 31,302

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 18 February 2019 12:18 PM
To: Accord Claims(AV); MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]
Attachments: SAS2551945.pdf

Lonpac External - General

Resend

Catherine/Nivitha

Pls acknowledge receipt.

Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Friday, 15 February, 2019 4:50 PM
To: Accord Claims(AV); MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]

Lonpac External - General

Without Prejudice
Save as to Costs

Dear Celia

Please see the list of surveyors below and liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Catherine/Nivitha


Please follow up.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	

9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Accord Claims(AV) [<mailto:avclaims@mycarworkshop.com.sg>]
Sent: Friday, 15 February, 2019 4:44 PM
To: MT_Claim_SG
Subject: PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A

Dear Officer In Charge,

Kindly arrange survey as above mentioned and please provide us 10 surveyor name list.

Thank you!

Kind regards,
Celia Lai

Accord Auto Services Pte Ltd
Blk 1009 Bukit Merah Lane 3
#01-80
Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

Shu Pei (LKKAuto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 21 February 2019 9:09 AM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG; Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]
Attachments: SLE6540A 120219.PDF

Lonpac External - General

Dear Shu Pei

Please see attached for our Insured's GIA report.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 20 February, 2019 6:56 PM
To: ONG LI LI; GERALD POH WEE BIN
Cc: MT_Claim_SG; Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

We have inspected TP vehicle SLT 1353C at M/s Accord Auto Services Pte Ltd on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Monday, 18 February 2019 3:45 PM

To: 'ONG LI LI' <llong@lonpac.com>; 'Accord Claims(AV)' <avclaims@mycarworkshop.com.sg>; 'MT_Claim_SG' <mt_claim@lonpac.com>; 'assignments@lkkauto.com' <assignments@lkkauto.com>

Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]

Dear Celia,

Thank you for the assignment.

Shiau Chan on behalf of G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Monday, 18 February 2019 12:18 PM

To: Accord Claims(AV) <avclaims@mycarworkshop.com.sg>; MT_Claim_SG <mt_claim@lonpac.com>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]

Lonpac External - General

Resend

Catherine/Nivitha

Pls acknowledge receipt.

Lonpac External - General data is for internal / external use.

From: ONG LI LI

Sent: Friday, 15 February, 2019 4:50 PM

To: Accord Claims(AV); MT_Claim_SG; assignments@lkkauto.com; Admin-D (LKKAuto)

Subject: RE: Our Ref: 18/19/19/VP05/021416 PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A [External General]

Lonpac External - General

Without Prejudice

Save as to Costs

Dear Celia

Please see the list of surveyors below and liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Catherine/Nivitha

Please follow up.

No.	Name	Please tick ✓
1	Kalvin Ang	
2	Xing Guo Qiang	
3	Mohamad Taufikh	
4	Bryan Ang	
5	Adrian Ling	
6	Mohammed Rasul	
7	Marcus Chua	
8	Kenneth Kong	
9	Muhammad Nazril Bin Abdullah	
10	Sathya Sai Kathirrasen	

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Accord Claims(AV) [<mailto:avclaims@mycarworkshop.com.sg>]

Sent: Friday, 15 February, 2019 4:44 PM

To: MT_Claim_SG

Subject: PRI SLT1353C DOA:12.2.2019 Your Ref:SLE6540A

Dear Officer In Charge,

Kindly arrange survey as above mentioned and please provide us 10 surveyor name list.

Thank you!

Kind regards,

Celia Lai

Accord Auto Services Pte Ltd

Blk 1009 Bukit Merah Lane 3

#01-80

Singapore 159723

Mobile: (65) 9274 0999

Tel : (65) 6271 7433

Fax : (65) 6274 5715

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC19003084/R1eb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 09-10-2019	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLE 6540A	Veh. Inspected	SLT 1353C
Policy No.	Z18VP05019088	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021416	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	18/02/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY 2.4	c.c	2356
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRC1890HC203920	Colour	WHITE
Odometer	043623	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	DUNLOP	6 mm
L/H Front Tyre	215/55 R17	DUNLOP	6 mm
R/H Rear Tyre	215/55 R17	DUNLOP	6 mm
L/H Rear Tyre	215/55 R17	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/02/2019	Inspection Date	19/02/2019
Survey held at	ACCORD AUTO SERVICES PTE LTD BLK 1009 BUKIT MERAH LANE 3 #01-80 SINGAPORE 159723		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 1353C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	750.40	750.40
2	FRONT BONNET HINGE	BENT	294.80	294.80
1	FRONT BONNET LOCK	BENT	176.22	176.22
1	FRONT GRILLE TOP BASE	CRACKED	289.10	289.10
1	FRONT GRILLE TOP (OUTER)	CRACKED	315.90	315.90
1	FRONT GRILLE LOGO	NECESSARY	80.00	80.00
1	FRONT GRILLE TOP BASE (CENTER)	CRACKED	365.32	365.32
1	FRONT GRILLE (OUTER TOP)	CRACKED	180.65	180.65
1	FRONT GRILLE (OUTER LOWER)	CRACKED	180.65	180.65
2	FRONT GRILLE (OUTER LH & RH)	SCRATCHED	288.40	288.40
1	FRONT LOWER GRILLE	DEFORMED	288.70	288.70
1	FRONT HEADLAMP LH	CRACKED	2,581.90	2,201.00
1	FRONT HEADLAMP RH	NOT NECESSARY	2,581.90	-
2	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	120.00	-
1	FRONT REINFORCEMENT	BENT	354.70	354.70
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	520.80	-
1	FRONT BUMPER	DEFORMED	880.00	880.00
2	FRONT BUMPER SIDE RETAINER	NECESSARY	110.00	110.00
2	FRONT BUMPER LOWER SIDE SKIRT LH & RH	NOT NECESSARY	440.00	-
1	FRONT NUMBER PLATE GARNISH	CRACKED	80.00	80.00
2	FRONT FOGLAMP GARNISH	NOT NECESSARY	230.00	-
2	FRONT FOGLAMP	CRACKED 1PC ONLY	560.00	280.00
1	FRONT FENDER LH	TO REPAIR SEE LABOUR	680.00	-
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	680.00	-
1	REAR TAILGATE	BUCKLED	1,380.80	803.00
2	REAR TAILGATE ABSORBER	NOT NECESSARY	390.00	-
1	REAR TAILGATE LOGO	NECESSARY	80.00	80.00
1	REAR TAILGATE CENTER "ODYSSEY" CHROME	NOT NECESSARY	280.00	-

Report Ref No. CC4/LPC19003084/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE LAMP LH	CRACKED	400.00	400.00
1	REAR TAILGATE LAMP RH	CRACKED	400.00	400.00
1	REAR TAILGATE CHROME	CRACKED	215.98	215.98
1	SET REAR TAILGATE NUMBER PLATE LIGHT	SERVICEABLE	85.00	-
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	188.18	188.18
1	REAR TAILGATE INNER TRIM BOARD	CRACKED	330.00	330.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	70.00	70.00
1	REAR LAMP LH	CRACKED	850.00	850.00
1	REAR LAMP RH	CRACKED	850.00	850.00
2	REAR LAMP LOWER BRACKET	SERVICEABLE	130.00	-
1	REAR BUMPER	DEFORMED	768.30	665.00
2	REAR BUMPER SIDE RETAINER	N/S NECESSARY	140.00	70.00
2	REAR BUMPER REFLECTOR	SERVICEABLE	140.00	-
1	REAR BUMPER REFLECTOR GARNISH LH	DEFORMED	155.00	155.00
1	REAR BUMPER REFLECTOR GARNISH RH	DEFORMED	155.00	155.00
1	REAR BUMPER SIDE LH	CUT	185.47	185.47
1	REAR BUMPER SIDE RH	CUT	185.47	185.47
1	REAR TAILGATE LOCK	BENT	265.35	265.35
1	REAR TAILGATE STRICK	SERVICEABLE	35.00	-
1	REAR TAILGATE WEATHERSTRIP	NECESSARY	180.96	180.96
1	REAR TAILGATE HANDLE SWITCH	SERVICEABLE	188.00	-
1	REAR FENDER SHIELD LH	SERVICEABLE	145.65	-
1	REAR FENDER SHIELD RH	SERVICEABLE	145.65	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,280.00	-
1	REAR FLOOR INNER TRIM BOARD	SERVICEABLE	680.96	-
1	REAR END PANEL	BENT	770.50	685.00
1	REAR END PANEL GARNISH	CUT	340.40	250.00
6	REAR END PANEL GARNISH CLIPS	NECESSARY	36.00	36.00
1	REAR ANTENNA SENSOR	CRACKED	180.50	180.50
1	REAR EXHAUST (OUTER)	SERVICEABLE	709.70	-
1	REAR LH FENDER INNER COMPARTMENT	DEFORMED	880.20	748.00
1	REAR RH FENDER INNER COMPARTMENT	DEFORMED	880.20	748.00

Report Ref No. CC4/LPC19003084/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR FENDER INNER COMPARTMENT CLIPS	NECESSARY	70.00	70.00
1	REAR LH TAILGATE LH SIDE COMPARTMENT	SERVICEABLE	280.00	-
1	UNDER BRACKET SPARE TYRE PANEL	SERVICEABLE	287.35	-
1	AIRCON CONDENSER (ADDITIONAL)	BENT	580.00	580.00
1	AIRCON CONDENSER MOUNTING (ADDITIONAL)	NECESSARY	15.00	15.00
2	BONNET STAND CLIP (ADDITIONAL)	DEFORMED	12.00	12.00
1	FRONT RH FOGLAMP HOUSING (ADDITIONAL)	CRACKED	75.11	75.11
	LESS 20% DISCOUNT		-5,689.43	-3,312.97
			22,757.74	13,251.89
	SPECIAL NETT ITEMS			
2	CAR PLATE NUMBER WITH FRAME (SN)	SCRATCHED	100.00	35.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	380.00	250.00
1	SET FRONT BONNER CLIPS (SN)	NECESSARY	35.00	35.00
1	SET FRONT GRILLE CLIPS / SCREW (SN)	NECESSARY	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
2	SET FRONT FENDER SHIELD CLIPS (SN)	NECESSARY	70.00	40.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
2	SET REAR FENDER SHIELD CLIPS (SN)	NOT NECESSARY	70.00	-
			840.00	505.00
	LABOUR			
	SPRAY PAINTING ALL AFFECTED AREAS.		2,800.00	2,000.00
	LABOUR REMOVE / REFIX ACCIDENT DAMAGES PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL, FRONT FENDER LH, FRONT FENDER RH AND REAR FLOOR PANEL.		2,600.00	1,700.00
	CHECK WIRING SYSTEM & LIGHT.		100.00	60.00
	ANTI RUST TREATMENT.		120.00	80.00
	TO CHECK & ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO REMOVE / REFIX REAR INNER COMPARTMENT & CARPET TO FACILITATE REPAIR.		280.00	100.00
	TO REMOVE / REFIX / REPLACE FRONT CAMERA.		180.00	60.00
	TO REMOVE / REFIX REAR TAILGATE GLASS TO NEW TAILGATE.		120.00	80.00

Report Ref No. CC4/LPC19003084/R1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REPLACE REAR REVERSE CAMERA.		180.00	60.00
	TO REMOVE / REPLACE REAR REVERSE SENSOR.		180.00	60.00
	TO CHECK WATER LEAKING.		150.00	30.00
	TO REMOVE / REFIX / REPLACE REAR TAIL GATE INNER COMPARTMENT, MECHANISM & ASSY TO NEW TAIL GATE.		200.00	80.00
	TO REMOVE / REFIX / REPLACE EXHAUST PIPE.	NOT NECESSARY	250.00	-
	TO REMOVE / REFIX REAR WINDSCREEN TO NEW TAIL GATE.		220.00	120.00
	TO REMOVE / REFIX / REPLACE SEAT BELT & BUCKLE.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX / ADJUST REAR CHAIR ROLL BAR.	NOT NECESSARY	200.00	-
	TO REMOVE / REFIX REAR TOP TAILGATE SPOILER.		100.00	60.00
	UPHOLSTERY DETAILS CLEANING.	NOT NECESSARY	220.00	-
	COMPUTER DIAGNOSTIC.		350.00	150.00
	TO REMOVE / REPLACE AIRCON CONDENSER (REFIX PIPING, HOSE, TOP UP AIRCON GAS, ETC....) (ADDITIONAL)		200.00	100.00
			8,750.00	4,740.00
GRAND TOTAL			32,347.74	18,496.89
RECOMMENDED COST OF REPAIRS				18,496.89

Report Ref No. CC4/LPC19003084/R1eb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.