

Trans-cab Auto Services Pte Ltd

AAD1902-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9822E

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB 9822E

VF1ABL15AUC273311

RENAULT

LATITUDE

14.2.2019

AIG

20/8/2013

PART**LIST**

1	1	BUMPER COVER FRT
2	1	BUMPER SPOILER FRT
3	1	BUMPER ABSORBER FRT
4	1	BUMPER RETAINER FRT LH
5	1	BUMPER SUPPORT FRT
6	1	BUMPER RETAINER FRT RH
7	1	BUMPER SUPPORT FRT
8	1	BUMPER UNDERTRAY FRT
9	1	BUMPER GRILLE LOWER FRT
10	1	BUMPER FOG LAMP GRILLE LH
11	1	BUMPER FOG LAMP GRILLE RH
12	1	BUMPER BEAM FRT
13	1	TOW COVER FRT
14	1	RADIATOR GRILLE
15	1	RADIATOR GRILLE BADGE 'RENAULT'
16	1	RADIATOR GRILLE FRAME
17	1	FRAME FULL SUPPORT PANEL
18	1	FRAME FULL SUPPORT BRACKET
19	1	HEADLAMP LH
20	1	HEADLAMP RH
21	1	HEADLAMP PANEL FRT LH
22	1	HEADLAMP PANEL FRT RH
23	1	BONNET
24	1	BONNET INSULATOR
25	1	BONNET STRUT LH
26	1	BONNET STRUT RH
27	1	BONNET HINGE LH
28	1	BONNET HINGE RH

\$	Bu	1,259.42	✓
\$	Sn	181.75	
\$	Sn	394.68	
\$	Sn	151.41	
\$	Sn	123.88	
\$	Sn	150.77	
\$	Sn	123.88	
\$	Sn	472.83	
\$	Sn	266.80	
\$	Sn	207.21	
\$	Sn	207.21	
\$	R	914.08	
\$	Sn	28.61	
\$	cm	1,707.78	✓
\$	Ru	225.36	✓
\$	Sn	1,353.75	X
\$	R	615.90	X
\$	R	89.79	X
\$	Sn	1,184.43	X
\$	m/c cm	1,184.43	✓
\$	R	152.15	
\$	R	152.15	
\$	R	1,941.63	
\$	Sn	405.73	
\$	Sn	88.61	
\$	Sn	88.61	
\$	R	348.31	
\$	R	348.31	

Trans-cab Auto Services Pte Ltd**AAD1902-098**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9822E

29	1	BONNET CABLE COVER	\$	161.03 X
30	1	BONNET SEAL OUTER	\$	92.36 X
31	1	BONNET SEAL INNER	\$	157.28 X

TOTAL	\$	14,780.15
10%	\$	1,478.01
	\$	13,302.13

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
7	1	TOW COVER FRT	\$	14.50
8	1SET	RADIATOR GRILLE SCREW	\$	16.00 X
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
21	1	Windscreen moulding	\$	100.00
22	1SET	Front licence plate with holder	\$	80.00

TOTAL	\$	562.50
TOTAL PARTS	\$	13,864.63

Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts,
adjust and realign the same

\$ 3,000.00

To apply paint protection system (PPS) maintain
and enhancement

\$ 380.00 X

2001

Trans-cab Auto Services Pte Ltd

AAD1902-098

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9822E

Putty and spray painting of the affected portion.	\$	3,000.00	220/
To rust-proofing of the affected areas.	\$	na 170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	na 380.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	na 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na 380.00	X
To vacuum, replace, refix and recharge air condenser	\$	na 380.00	X
To replace, refix and top up coolant for radiator	\$	na 170.00	X
To vacuum, replace, refix and recharge Air Intercooler	\$	na 170.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TOTAL \$ 9,140.00**Over All Total \$ 23,004.63****(LUMP SUM) Repair Days****10 DAYS**
2 days