

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia

Date: 20 Feb 2019

Preliminary Advice

Vehicle No	: SKP7889S	Accident Date	: 31/01/2019
Make	: JAGUAR XF	Policy No.	: DMPCSN1427631804
Assignment Date	: 18/02/2019	Excess	: S\$750.00
Date of Inspection	: 19/02/2019	Est. Duration of Repair	: 6.00
Inspection At	: WEARNES AUTOMOTIVE PTE LTD (LENG KEE) 28 LENG KEE ROAD SINGAPORE 159105		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,847.90
Revised Amount	:S\$	18,571.00
Check Items (Estimated)	:S\$	8,066.00
Total	:S\$	26,637.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	98,000.00
COE / PARF Rebate	:S\$	84,437.00
Salvage Value	:S\$	
Margin for Repair	:S\$	13,563.00

Remarks

Brake System : In Order
Steering System : In Order
Tyre Condition (Front) : 6/6 mm
Tyre Condition (Rear) : 6/6 mm

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :