LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Melvin Ye Date: 20 Feb 2019

Preliminary Advice

Insured Vehicle No : GBC3395B

TP Vehicle No : SHC5053D Accident Date : 15/02/2019 Make : RENAULT LATITUDE Assignment Date : 18/02/2019 : 19/02/2019 Est. Duration of Repair Date of Inspection : 7 days

Inspection At : Trans-cab Auto Services (HQ)

NO. 2 ANG MO KIO ST 63

Singapore 569111

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 49,053.30 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 9,900.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 9,900.00 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
| | | Kindly let us have your authorisation. |

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP