

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccare.com.sg
GST:201006949C RCB NO:201006949C

M/S: O S ELECTRONICS (S) PTE LTD
33 TANNERY LANE #05-01
SINGAPORE 347789

ATTN: CHINA TAIPING

Your Ref No: TP 0219-5396
Claim Type: Third Party
Accident Date: 12/02/2019
TP Veh Reg No: SKS 757 U

Estimate No: EST1504561
Date: 19 Mar 2019
Policy No: 8VPCP1820930
Veh Reg No: SKV4851M
Make/Model: HONDA ODYSSEY 2.4
EX-S CVT
Chassis No: JHMRC1880FC203192
Engine No: K24W71011582
Reg. Date: 21/09/2015

Estimate Repair Cost to Vehicle No :SKV4851M

Description	U/Price	Quantity	Price S\$	Amount S\$
Supplementary Parts to Repair				
List Price				
1 REAR BUMPER BUZZLE SENSOR / DM	85.4000	1 PC	85.40 ✓	
			85.40	
		Less 20%	17.08	68.32
		Total		S\$ 68.32
		GST Amount		S\$ 4.78
		Total Amount Payable		S\$ 73.10

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

SUPP 68.32

PARTS 1660.80

SN 260.00

LAB. 1450.00

3439.12

43-2750